SDMS US EPA Region V

Imagery Insert Form

Document ID:

176044	

Some images in this document may be illegible or unavailable in SDMS. Please see reason(s) indicated below:

	Specify Type of Document(s) / Comments:
MAPS	
Includes C	OLOR or RESOLUTION variations.
	oted, these pages are available in monochrome. The source document page(s) is more legible thal document is available for viewing at the Superfund Records Center.
	Specify Type of Document(s) / Comments:
Confidential Provi	La Company (CDI)
This document co	ness Information (CBI). Intains highly sensitive information. Due to confidentiality, materials with such information are solution to contact the EPA Superfund Records Manager if you wish to view this document.
	, common mo 21,11 ou per man 21,000 mon 10 m
	Specify Type of Document(s) / Comments:
	· · · · · · · · · · · · · · · · · · ·
Unscannable Mat	Specify Type of Document(s) / Comments:
Unscannable Mat Oversized	Specify Type of Document(s) / Comments: erial: or Format.
Oversized Due to certain sca	Specify Type of Document(s) / Comments: erial:
Oversized Due to certain sca	erial: or Format. unning equipment capability limitations, the document page(s) is not available in SDMS. The or able for viewing at the Superfund Records center.
Oversized Due to certain sca	Specify Type of Document(s) / Comments: erial: or Format. unning equipment capability limitations, the document page(s) is not available in SDMS. The or
Oversized Due to certain sca	erial: or Format. unning equipment capability limitations, the document page(s) is not available in SDMS. The or able for viewing at the Superfund Records center.
Oversized Due to certain sca document is availa	erial: or Format. unning equipment capability limitations, the document page(s) is not available in SDMS. The or able for viewing at the Superfund Records center. Specify Type of Document(s) / Comments:
Oversized Due to certain sca document is availa	erial: or Format. unning equipment capability limitations, the document page(s) is not available in SDMS. The or able for viewing at the Superfund Records center.

Rev. 07/10/02

176044





Knowledge, and the Creativity to Use It 44808 It in 8: Primone MI 48170 - (313) 484-1100 | Fax 484-1233

REMEDIAL INVESTIGATION AND BASELINE RISK ASSESSMENT DRAFT REPORT

HI-MILL MANUFACTURING HIGHLAND, MI

Prepared by:

Techna Corporation 44808 Heim Street Plymouth, Michigan 48170

HI-MILL MANUFACTURING COMPANY

DRAFT REMEDIAL INVESTIGATION REPORT

AND

BASELINE RISK ASSESSMENT

Prepared by:

Techna Corporation 44808 Helm Street Plymouth, Michigan 48170

TABLE OF CONTENTS

1.0	INTRODUCTION			
	1.1	Purpose of Report		
	1.2	Site Background 1		
		1.2.1 Site Description		
		1.2.2 Site History		
		1.2.3 Previous Investigations		
	1.3	Report Organization		
2.0	STUI	DY AREA INVESTIGATION		
	2.1 <u>I</u>	Field Activities		
		2.1.1 Surface Features		
		2.1.2 Surface-Water and Sediment Investigations		
		2.1.3 Soil Investigations/Chemical Characteristics		
		2.1.4 Soils Investigation/Physical Characteristics		
		2.1.5 Groundwater Investigation/Chemical Characteristics		
		2.1.6 Groundwater Investigation		
	2.2	Technical Memorandum		
3.0	PHY	SICAL CHARACTERISTICS OF THE STUDY AREA		
	3.1	Surface Features 36		
	3.2	Surface Water Hydrology 37		
	3.3	<u>Geology</u> 43		
	3.4	<u>Soils</u>		
	3.5	Hydrogeology		
4.0	NAT	NATURE AND EXTENT OF CONTAMINATION		
	4.1	<u>Soils</u>		
		4.1.1 Inorganics		
		4.1.2 TCL Volatile Organics		
		4.1.3 TCL Organics		
	4.2	Groundwater 71		
		4.2.1 Inorganics		
		4.2.2 TCL Volatile Organics		

		4.2.3 TCL Organics
	4.3	Surface Water and Sediments
		4.3.1 Inorganics
		4.3.2 Sediments
	4.4	Summary and Conclusions
		4.4.1 Soils 82
		4.4.2 Groundwater
5.0	CON	TAMINANT FATE AND TRANSPORT 88
	5.1	Potential Routes of Migration
	5.2	Contaminant Persistence
	5.3	Contaminant Migration
6.0	BASI	ELINE RISK ASSESSMENT 91
	6.1	Introduction
		6.1.1 Purpose and Scope
		6.1.2 Contents of the Baseline Risk Assessment
	6.2	Exposure Assessment
		6.2.1 Site Soils: Nature and Extent of Contamination
		6.2.2 Groundwater: Nature and Extent of Contamination
		6.2.3 Surface Water: Nature and Extent of Contamination
		6.2.4 Sediments: Nature and Extent of Contamination
		6.2.5 Evaluation and Selection of Chemicals of Concern
		6.2.6 Exposure Pathways 114
		6.2.7 Exposed Population Analysis: Current Use
		6.2.8 Exposed Population Analysis: Alternate Future Use
		6.2.9 Intake Estimates: Exposure Concentrations
		6.2.10 Intake Estimates: Factors Used in Predicting Exposures
	6.3	Toxicity Assessment
		6.3.1 Toxicity Effects: Non-Carcinogenic Effects
		6.3.2 Toxicity Effects: Carcinogenic Effects
	6.4	Risk Characterization
		6.4.1 Site Cancer Risk Estimates
		6.4.2 Non-Carcinogens: Potential Health Effects Risk Estimates 139
		6.4.3 Risk Quantitation

6.5	Enviro	nmental Risk Assessment	144
	6.5.1	Objective of the Assessment	144
	6.5.2	Scope of the Assessment	144
	6.5.3	Site/Study Area Description	144
	6.5.4	Contaminants of Concern	146
	6.5.5	Exposure Pathways	146
	6.5.6	Risk Characterization	147

•

APPENDICES

4	Surface Water Master Data Table
3	Sediment Sample Master Data Table
C	Soil Sample Master Data Table
D	Groundwater Sample Master Data Table
Е	Technical Memorandum Table of Contents
F	Boring and Well Construction Logs
G	Physical Soil Characteristic and Slug Test Analysis Results
Н	Summary of Short List Metal Analysis Results-Soils
Ī	Summary of TAL Inorganic Analysis Results-Soils
J	Summary of TCL Volatile Organic Analysis Results (Species Detected)-Groundwater
K	Summary of TAL Inorganic Analysis Results (Species Detected)-Groundwater
L	Summary of Short List Metals Analysis Results-Groundwater
M	Summary of Ammonia and Nitrate/Nitrite Analysis Results-Groundwater
Ν	Summary of Temperature, Specific Conductivity and pH Measurements-Groundwater
0	MDNR Biological, Surface Water and Sediments Survey (April 1984)

LIST OF FIGURES

Figure 1-1	Site Location Map
Figure 1-2	Site Feature Map
Figure 2-1	Background Soil, Off-Grid Soil, Surface Water and Sediment Sample Point Map
Figure 2-2	TAL Inorganics and Short List Metal Soil Sample Point Map
Figure 2-3	TCL Volatile Organic and TCL organic Soil Sample Point Map
Figure 2-4	Monitor Well, Staff Gauge Location Map
Figure 3-1	Conceptual Geologic Cross Section
Figure 3-2	Soil-Clay Interface Elevation Contour Map
Figure 3-3	Shallow Well Potentiometric-Surface Contour Map (May 11, 1990 Data)
Figure 3-4	Intermediate Well Potentiometric-Surface Contour Map (June 8, 1990 Data)
Figure 3-5	Deep Well Potentiometric-Surface Trend Map (June 8, 1990 Data)
Figure 4-1	Isoconcentration Map of Copper Concentrations in Surface Soil Samples
Figure 4-2	Isoconcentration Map of Copper Concentrations in Clay Interface Soil Samples
Figure 4-3	Isoconcentration Map of Chromium Concentrations in Surface Soil Samples

LIST OF TABLES

- Table 3-1 Water Level Elevations
- Table 4-1 Summary of Background Concentrations and Statistical Data for Short List Metals in Soils
- Table 4-2 Summary of Soil Samples with Short List Metal Concentrations Above Background
 Criteria (Mean + 2s)
- Table 4-3 Summary of Background Concentrations and Statistical Data for TAL Inorganics in Soils
- Table 4-4 Summary of TCL Volatile Organic Analysis Results for Soil Samples
 (Species Detected Without B, J, or BJ Flags)
- Table 4-5 Summary of TCL Organic Analysis for Soil Samples (Species Detected)
- Table 4-6 Summary of Short List Metals Analysis Results for Groundwater Samples (Species Detected Without U, B, and/or N Flags)
- Table 4-7 Summary of TCL Volatiles Analysis Results for Groundwater Samples (Species Detected)
- Table 4-8 Summary of Short List Metal Concentrations for Sediment Samples
- Table 6-1 Species in Soils of Potential Concern
- Table 6-2 Species in Groundwater of Potential Concern
- Table 6-3 Species in Sediments of Potential Concern
- Table 6-4 Species in Surface Water of Potential Concern
- Table 6-5 Matrix of Potential Exposures

HI-MILL MANUFACTURING COMPANY REMEDIAL INVESTIGATION AND BASELINE RISK ASSESSMENT DRAFT REPORT

1.0 INTRODUCTION

1.1 Purpose of Report

The purpose of this Draft Remedial Investigation and Baseline Risk Assessment Report is to document the Remedial Investigation at the Hi-Mill National Priorities List (NPL) site as conducted in accordance with the Remedial Investigation Work Plan and to provide a basis for the Feasibility Study and other actions that may be required at the Hi-Mill site as consistent with the National Contingency Plan. This documentation includes a detailed description of field activities, a compilation or direct reference for all data collected during the Remedial Investigation, an analysis of data related to the Hi-Mill site, including the type and extent of contaminants, and an evaluation of the risks associated with the species and concentrations of contamination determined to be present at the Hi-Mill site.


Subsection 1.2 of this section provides background information related to the site including a complete site description and summaries of previous investigations relevant to the Hi-Mill site. Subsection 1.3 of this section describes the overall organization of the remainder of this report.

1.2 Site Background

1.2.1 Site Description

The Hi-Mill Site is located in Highland Township, Oakland County, Michigan, approximately 1.5 miles east of the town of Highland (Figure 1-1). The plant address is 1704 Highland Road (M-59), which is located within Section 23, T7N R18W. The site occupies an irregularly shaped property of approximately 4.5 acres in size (Figure 1-2) which lies at an elevation of approximately 1010 feet above National Geodetic Vertical Datum (NGVD).

Figure 1-1. Site Location Map.



The Hi-Mill building and parking area occupy most of the site (Figure 1-2). The building lies in the northwest part of the property and is irregularly shaped, having been expanded severaltimes since its original construction in 1946. It houses the corporate and administrative offices, tubing production facilities and raw material storage and preparation areas. Paved parking areas occupy all of the property northeast of the production/office building and part of the site southwest of the building. The remainder of the property is covered with vegetation.

The Hi-Mill property is bounded to the northwest by Highland Road (M-59), a four-lane, divided highway. It is bounded on all other sides by the Highland State Recreation Area, which is owned and maintained by the Michigan Department of Natural Resources. A marsh/pond of approximately 8 - 10 acres in size lies east of the Hi-Mill property. A slightly elevated, vegetated plain and woodlands area lies south of the Hi-Mill property. Waterbury Lake lies approximately 900 - 1000 feet south of the Hi-Mill property, just beyond the slightly elevated plain.


The immediate area around Hi-Mill is sparsely populated and rural in nature. The nearest dwellings lie approximately 2000 feet east and southeast of the site, along Waterbury Road. Numatics, Inc., 2000 Highland Road East, a manufacturer of metal air control valve parts, is located approximately 1000 feet northeast of the Hi-Mill property. Numatics, Inc. discharges process wastewater to a drain and tile field located on their property.

Highland Township is a rural/suburban area with a population of approximately 17,000 - 19,000. The rural/suburban nature of the township is reflected in the lack of large population or commercial centers and the absence of many city services. A majority of inhabitants obtain drinking water from domestic water wells and dispose of sewage through individual septic systems.

Surface topography and associated soil deposits in this region of southeastern Michigan result from glacial processes occurring during the Wisconsin Glacial Stage of the Pleistocene Series. Glacial action has deposited a mantle of glacial debris (soil), ranging in thickness from 225 feet to more than 300 feet. The stratigraphy of the glacial deposit is quite complex and represents materials deposited during successive advancements and retreats of the ice front(s).

The surface topography of the region is generally representative of the interlobate morainic system which lies on a northeast-southwest axis extending from approximately Jackson to Oxford. This morainic system results from interaction of the Saginaw, Huron and Erie Lobes. The Saginaw lobe

Figure 1-2. Site Features Map



advanced from the northwest, joining the Huron Lobe which advanced from the northeast and the Erie Lobe which advanced from the east.

Surface formations within the study area were formed primarily during retreat of these glacial ice lobes with the subsequent meltwater influencing much of the topography and near-surface soil deposits. Much of the area contains outwash material at the surface, deposited by glacial meltwaters.

Many closed depressions (kettles) dot the outwash sediments. These formed as a result of large blocks of ice, left behind by the rapidly receding glacier front, which were surrounded and covered by outwash sediments. As the buried or partially buried ice blocks melted, the sediments slumped into the resultant voids. This phenomenon is responsible for the pitted outwash topography evident in the study area. Kettles serve as basins for the numerous lakes and swamps found throughout the region.

The subsurface stratigraphy in the region is complex and is representative of variable climatic conditions throughout the period of glaciation. Soils encountered within the profile may be well-sorted granular materials representative of a period of rapid melting, lacustrine clay indicating the presence of a lake near the ice margin, ground moraines indicating a period of ice advance, as well as buried recessional moraines. Therefore, throughout most of the area, the general stratigraphy of the glacial deposits consists of regionally discontinuous interbedded layers of lacustrine clay, unsorted moraines and outwash deposits.

In general, the region can be characterized as having well defined surface moraines with moderate permeability, ground laid moraines and lacustrine clays with low permeability and outwash deposits ranging from moderate to high permeability. Where present, the finer grained soils serve as an aquiclude that provides a bottom seal for an unconfined surface aquifer. The clay aquicludes also serve as the top confining seal for some artesian aquifers within the general region.

Mississippian age Coldwater Shale underlies the glacial soil at estimated depths of 225 feet to 300 feet.

1.2.2 Site History

Since its formation in 1946, Hi-Mill Manufacturing Company has fabricated copper, aluminum and brass tubing parts and fittings. Production operations have included cutting, machining, forming, shaping and soldering of the raw tubing and fabricated tubing components. Support operations have included nitric and sulfuric acid cleaning and brightening, chromic acid washing, and chlorinated solvent degreasing. All soldering operations have used silver solder or aluminum bar brazing; no tin-lead solder has been used in Hi-Mill's operations. Hi-Mill typically employs between 40 and 60 persons in a single eight-hour shift five days per week.

Wastewater discharges occurred historically to two lagoons located southeast of the Hi-Mill building. From prior to 1960 (exact date unknown) until 1981, process wastewaters were discharged to an unlined lagoon approximately 90 x 90 feet square. The base of the lagoon, reportedly, was excavated approximately six feet into the underlying clay stratum. Process waters, consisting mainly of acid brightening solutions and acid brightening rinse waters, were discharged to the lagoons. In the Fall of 1976, Hi-Mill constructed a second smaller lagoon south of the original lagoon. This second lagoon received overflow waters from the original lagoon. Between 1981 and 1983 Hi-Mill attempted to evaporate the water remaining in the lagoons by intermittently discharging it through spray nozzles attached to the roof of the production building and to portions of the eight-foot high fence that surrounds the rear (south) of the Hi-Mill property.

In September 1983 Hi-Mill requested permission from the MDNR to remove the sludge from the larger lagoon, excavate surrounding soils, and backfill the area with clean fill. This was accomplished in November and December 1983 by General Oil Company of Livonia, Michigan. Contaminated soils were removed from the sides and bottom of the large lagoon, and then an additional one foot of clay was excavated from the bottom of the lagoon to ensure removal of all contaminated soils. Excavated sludges and soils were transported and properly disposed off-site by landfilling in a properly permitted facility. All activities were monitored by representatives of the MDNR, and the excavated site was inspected by the MDNR prior to backfilling. The excavation contractor has indicated that the smaller lagoon was not apparent during the excavation; the fate of this impoundment is not known.

Hi-Mill Manufacturing currently obtains process and drinking water from a water supply well located on the eastern edge of the east pavement area. This water supply well was installed in January 1989 by Layman Well Drilling and Repair. A six (6) inch diameter well screen was placed

between 107' - 99'. Historically, water was drawn from two other supply wells that were located on the property. One former water supply well, lying immediately west of the production building, was set at 50' below grade, and the other former water supply well, lying immediately east of the production building was set at a depth of 89'. These wells were abandoned by Jim Layman of Layman Drilling in December 1989 as directed by the MDNR in order to prevent the potential downward migration of volatile organic compounds through the annular space. Abandonment was accomplishing by fracturing the well casings and then filling the entire cavity with grout under pressure.

Hi-Mill Manufacturing uses a septic system, located south of the main building, to dispose of sanitary sewage.

1.2.3 Previous Investigations

Seven contamination identification, assessment and/or control projects have been conducted at the Hi-Mill site to date. The activities and results of the projects are summarized below. Copies of reports discussed below (except for the November 1989 MDPH sampling of residential wells) are included in Appendix A of the Hi-Mill Manufacturing Company, RI/FS Work Plan, Revision 2, October 26, 1989.

Pre-1978 - MDNR Data

This report stated that a second lagoon was constructed in fall of 1976 and that direct overflows to the marsh occurred in December, 1976 and November, 1977. In April 1972 the MDNR staff investigated an employee complaint that the plant water wells might be contaminated. Samples of the groundwater from the two wells and surface water from the marsh were collected and analyzed. "Slightly elevated" (no comparison standard was presented) levels of copper (0.38 mg/l) were measured in one well, and elevated levels of copper and nitrates were measured in the marsh waters located immediately adjacent to the Hi-Mill property.

The MDNR collected additional samples of the marsh water on October 9, 1975. Analyses of these samples indicated elevated levels of copper, aluminum, zinc, chromium, and nitrates.

In May, November and December 1976, MDNR personnel collected and analyzed samples of the wastewaters contained in the two ponds. The mean concentrations of the parameters measured in these samples are presented below:

Parameter	Concentration (mg/l)	
Copper	5.23	
Aluminum	24.50	
Chromium (total)	1.29	
Chromium (hexavalent)	0.28	
Nickel	0.02	
pН	5.08	
N (NH ₃)	13.67	
N (NO ₂)	0.42	
N (NO ₃)	59.67	

Based on available data, there is no indication whether or not the samples were filtered or that background or QA/QC samples were collected or analyzed to validate the data collected in any of these early studies.

November 1978 - MDNR Study of Adjoining Marsh Area

In April 1976, staff of the MDNR Water Quality Division undertook a study of the water and sediments in the marsh, water in the lagoon, and groundwater from one of Hi-Mill's water wells to assess contamination potential. The well selected for sampling was the one identified in the 1972 study as having elevated levels of copper. Background sediment samples were collected from Pontiac Lake.

The chemical analysis results indicated no metals contamination in the Hi-Mill water well sample. Elevated levels of nitrate, nitrite, ammonia, chromium, copper, zinc and aluminum were measured in water samples from the lagoon and marsh waters immediately adjacent to the Hi-Mill property. Since no background water samples were analyzed, it is not clear if results from a mid-marsh sample is reflect normal or elevated levels of chemical species measured. It is not known if the surface water samples were filtered to remove suspended sediment subsequent to collection.

Elevated levels of total chromium, copper and aluminum were measured in sediment samples collected from the lagoon and marsh. Slightly elevated levels of lead and zinc were also reported. No nickel contamination was reported.

August 1982 - MDNR Hydrogeological Study

In August 1982 the MDNR Water Quality Division performed a hydrogeological study at the Hi-Mill plant site. This study consisted of the installation of six, 1 1/4" PVC groundwater monitoring wells along the east and south property lines (adjacent to the Highland State Recreation Area), measurement of groundwater elevations, and sampling and analysis of groundwater samples. The monitoring wells were set at depths of 4' - 7' below grade in saturated surficial clayey soils of low permeability (MDNR conclusion based on soil type and well recharge time).

The flow of the perched water was determined to be generally in a southeasterly direction toward to marsh. Elevated levels (2 - 10 times background) of copper, chromium (total), zinc and aluminum were found in samples from monitoring wells located east and southeast of the lagoon. Concentrations of lead and nickel were found not to be above background levels. It is not known if the groundwater samples were filtered to remove suspended sediment subsequent to collection.

November 1983 - Removal of Lagoons

In September 1983 Hi-Mill requested permission from the MDNR to remove the sludge from the large lagoon, excavate surrounding soils, and backfill the area with clean fill. This was accomplished in November and December 1983 by General Oil Company of Livonia, Michigan. The contractor has stated that contaminated soils were removed from the sides and bottom of the lagoon, and then an additional one foot of clay was excavated from the bottom of the lagoon to ensure removal of all contaminated soils. Excavated sludges and soils were transported and properly disposed off-site in a licensed landfill. Manifests show that the following amounts of material were removed: 142 yards of contaminated soils, 34,400 gallons of contaminated sludge, and 63,300 gallons of water. All activities were monitored by representatives of the MDNR, and the excavated site was inspected by the MDNR prior to backfilling. The excavation contractor reported that the small

lagoon observed in historical aerial photos was not in evidence at the time of excavation. The fate of the small lagoon is unknown.

April 1984 - MDNR Biological, Surface Water and Sediment Survey

In April 1984 personnel of the MDNR Surface Water Quality Division performed a limited biological, surface water and sediment survey of the marsh east of Hi-Mill, of Hi-Mill's roof and parking lot run-off areas and of the nearby Waterbury Lake. Water and sediment samples were collected and analyzed for aluminum, arsenic, iron, mercury, zinc, cadmium, chromium (total), copper, nickel and lead. Benthic and phytoplankton organisms were collected and identified visually on-site and by laboratory microscopy.

The chemical analyses of water samples indicated that concentrations of zinc, chromium and copper in marsh waters were lower than those measured in 1978, but still elevated in comparison to the background samples collected from Waterbury Lake. The levels of chromium and zinc did not exceed freshwater aquatic life criteria, but the levels of copper (50 - 200 μ g/l) exceeded the chronic criteria (33 μ g/l) for warm water fish. Elevated levels of copper, zinc, chromium and aluminum were also found in the run-off from the roof drainage and parking lot; the levels of copper in these samples exceeded the acute and chronic criteria for aquatic life. It is not known if the surface water samples were filtered to remove suspended sediment subsequent to collection.

Elevated levels (2 - 100 times those in sediments from Waterbury Lake) of aluminum, zinc, chromium (total), and copper were measured in sediments from the marsh and from parking lot and roof run-off drainage areas. Levels of arsenic, mercury, cadmium, nickel and lead were not found to be significantly different from the levels in Waterbury Lake samples.

The biological survey revealed few benthic or other bottom-dwelling organisms. Insufficient data were available to determine if this was a result of the significant marsh water level fluctuations or from metals contamination. Zooplankton were present at both sampling stations in the marsh. Daphnia sp., a copper sensitive organism, were abundant at the marsh sampling station where copper concentrations in the water were highest. The presence of a variety of filamentous green algae, flagellates, other algae and macrophytes indicated that the contamination did not have much impact on these aquatic plants.

The MDNR report concluded that 1) Waterbury Lake was not connected with the marsh east of Hi Mill Manufacturing and was not impacted by Hi Mill Manufacturing surface water discharges. 2) Marsh waters generally contained higher concentrations of heavy methods than the background stations in Waterbury Lake. 3) Concentrations of copper in marsh waters exceeded the chronic criteria for warm water species of fresh water aquatic life. 4) Sediment heavy metal concentrations in the marsh exceeded background concentrations in Waterbury Lake and in many cases mean concentrations in Waterbury Lake and in many cases mean concentrations downstream of industrial and municipal discharges. 5) Algar and 200 Plankton were abundant in marsh waters but bottom dwelling organisms were limited to pollution tolerant forms. The lack of additional species may be due to limited water in the dry season or the nutrient enriched condition of the marsh waters.

April - October 1987 - Numatics, Inc. Discharge Permit Data

Numatics, Inc. purchased the existing plant and property owned by the Highland Precision Company to manufacturer small stainless steel parts. Numatics, Inc. has been discharging wastewaters from metal finishing rinse tanks to a drain tile field under a MDNR groundwater discharge permit obtained in 1974. The permit established rinse water treatment criteria for nickel, chromium, nitrate, plus nitrite, and pH. In response to Numatics' most recent application to renew the discharge permit, the MDNR required a soils and groundwater assessment to determine if past discharge practices had negatively impacted the environment. The result of the soils investigation in the area of the drain field indicated that elevated levels of chromium and hexavalent chromium had accumulated in subsurface soils. Data from one round of samples from groundwater monitoring wells did not reveal significant levels of pollutants. No field or trip blanks were analyzed and no laboratory quality assurance data is available to assess the validity of results. The groundwater flow direction was determined to be southwest toward the wetland pond east and south of Hi-Mill. Depth to groundwater in the water table aquifer was approximately 17 feet below the surface. The area was identified as a recharge zone.

March - November 1988 - Oakland County Health Department Process Well Survey

The Oakland County Health Department and the Michigan State Department of Health sampled and analyzed water samples from Hi-Mill's two production water wells seven times during the period March 22, 1988 through November 2, 1988. Initially, samples were analyzed for water quality

parameters, trace metals and volatile solvents; later analyses were confined to volatile solvents. All samples were analyzed by the Michigan Department of Health laboratories in Lansing, Michigan. No field or trip blanks were analyzed, and no laboratory quality assurance data is available to assess the validity of results.

All samples were found to contain "not detected" or acceptable levels of metals and other water quality parameters. The sample from March 1988 (composite of the two wells) was found to contain 41 μ g/1 trihalomethanes and 1 μ g/1 (method detection limit) benzene. No volatile organics were measured in a June 29, 1988 composite sample. On July 14, 1988, trichloroethylene was measured at 1 μ g/1 (method detection limit) in the west well, and benzene was measured at 4 μ g/1 in the east well. No organics were identified in a composite sample collected on September 1, 1988. Another set of samples was collected on October 4, 1988; trichloroethylene was measured in both the east and west wells (3 μ g/1 and 24 μ g/1 respectively), and cis-1,2-dichloroethylene was measured (2 μ g/1) in the west well.

Analyses of samples collected on October 12, 1988 indicated the presence of trichloroethylene and cis-1,2-dichloroethylene in the west well at levels of 3 μ g/l and 2 μ g/l respectively. Trichloroethylene was measured in the east well at 12 μ g/l.

A sample collected from the west well on November 11, 1988 was found to contain 7 μ g/l trichloroethylene and 2 μ g/l cis-1,2-dichloroethylene. The sample from the east well was found to contain 3 μ g/l trichloroethylene.

The Michigan Department of Health notified Hi-Mill on November 7, 1988 that the analysis results indicated that the water from the process wells was not acceptable for human consumption. Hi-Mill was instructed to warn employees not to drink the water, to provide bottled drinking water, abandon both existing wells, and to install a new well to provide potable water to the facility.

November 1988 - Techna Corporation Hydrogeological Study

Techna performed a limited hydrogeological assessment of the Hi-Mill site in November 1988 in response to the findings of chlorinated solvents in the Hi-Mill process wells.

The hydrogeological assessment accomplished the following objectives: 1) determine subsurface stratigraphy to a depth of approximately 100'; 2) sample and analyze groundwater samples to determine extent of possible solvent contamination; 3) determine approximate direction of groundwater flow in the deeper aquifer(s); 4) evaluate connectivity between multiple, deeper saturated zones if any were found; and 5) evaluate the potential for contaminants in surficial saturated zones near the process wells.

Three boreholes were advanced at the Hi-Mill site to an approximate depth of 100' below the existing ground surface. Boreholes were placed at the northeast corner of the property, at the west corner of the property, and south of the production building in the area of the former lagoon. Soil types were logged during the drilling operations, and temporary, 2" diameter PVC monitoring wells were placed in each location.

The general subsurface stratigraphy at the site consists of 1.5' - 3' of fill underlain by 26' - 45' of stiff, moist, silty blue clay. This layer was contiguous in the northeast and south borings; however, in the west boring a layer (5' \pm 2') of fine silty sand was found in the clay stratum between the depths of 12' and 17', and a compact sandy silt layer (3' \pm 1') was found between the depths of 24' and 27'.

In the northeast borehole, a wet sand stratum was encountered between the depths of 45' and 63'. This was underlain by a 21.5' thick layer of extremely stiff blue clay, which was in turn underlain by a wet layer of sand and gravel extending from 91' below ground level (BGL) to the terminus of the boring at 105.6'.

In the west borehole, the clay layer was underlain by various wet sand strata to a depth of 113' BGL, the terminus of the boring. The underlying sand strata were interspersed with layers of blue clay (64.5 - 66.5' BGL and 96.5 - 101' BGL) and extremely compact sand and silt (76' - 92' BGL).

The south boring initially encountered approximately 8' of sand fill in the are of the former lagoon. This was underlain by the same clay stratum (26' thick) found in the other borings. The upper clay layer was underlain sequentially by compact to extremely compact wet sand (34' - 49.5' BGL), extremely stiff blue clay (49.5' - 59' BGL), wet gray sand (59' - 65.5' BGL), extremely stiff blue clay (65.5' - 87' BGL) and wet sand and gravel (87' - 100' BGL) to the end of the boring.

Temporary groundwater monitoring wells were then set in separate boreholes at the 1) Northeast property corner - one screen was set at 55' BGL in the uppermost saturated zone, and one was set at 105' in the lower saturated zone; 2) West property corner - one well was set at 56' BGL in the uppermost significant saturated zone; and 3) South of production building - one well was set at 50' BGL in the uppermost saturated zone, and one well was set at 93' BGL in the lower saturated zone. The wells were fitted with 5' screens, and the bottom of the screens were placed at the depths listed above. After installation, the wells were developed and allowed to reach equilibrium.

Groundwater elevation measurements revealed that the static water levels in all wells were the same within an absolute variance interval of \pm 0.6' about the mean elevation. The groundwater was determined to be flowing in a generally southeast direction.

Groundwater samples were collected from each temporary monitoring well and analyzed for the Priority Pollutant volatile organic species. No contaminants were found in any of the samples.

Soil samples were collected in the surficial fill materials (found to be dry or slightly moist) near each process well and analyzed for the presence of chlorinated solvents. One sample was collected approximately 8' - 10' north of the east well, and one sample was collected approximately 8' -10' southwest of the west well. No chlorinated solvents were found in either sample.

MDPH November 1989 Public Supply Well Sampling

The Michigan Department of Public Health (MDPH) sampled seven residential wells along the west side of Waterbury Road in early November 1989. These wells are the closest known residential wells to the Hi-Mill site. Groundwater from these wells was analyzed for metals and some volatile organic compounds. No volatile organic compounds were detected and metals were all below established drinking water guidelines. The MDPH concluded that these samples indicate that there is no contamination in the seven wells tested.

October 26, 1989 Hi-Mill Manufacturing Company Remedial Investigation/Feasibility Study Work Plan/Site Safety Plan /OAPP

The Remedial Investigation was performed in accordance with the Hi-Mill Manufacturing Company Remedial Investigation/Feasibility Study Work Plan, Site Safety Plan and QAPP which were submitted to the U.S. EPA as Revision 2 on October 26, 1989 and subsequently amended and approved in January 1990.

Remedial Investigation activities were funded by Hi-Mill Manufacturing Company as agreed under Administrative Order of Consent, U.S. EPA Docket Number V-W-88-C-127. Field activities were performed by Techna Corporation and their subcontractors as presented in the Remedial Investigation Work Plan. Field activity oversight was provided by the U.S. EPA, contractors to the U.S. EPA and the Michigan Department of Natural Resources.

1.3 Report Organization

This report has been divided into seven sections in accordance with the recommendations of the U.S. EPA guidance presented in "Guidance for Conducting Remedial Investigations and Feasibility Studies under CERCLA". Contents of the remaining six sections are summarized below.

Section 2.0 describes and documents the various types of investigations that were performed during the Remedial Investigation. These various investigation categories are surface features, contaminant sources, surface waters and sediments, soils, and groundwater. Section 2.0 also presents a brief summary of the June 1, 1990 "Phase I Data Completeness Technical Memorandum".

Section 3.0 describes the physical characteristics of the site as developed from information collected during the Remedial Investigation. Physical characteristics of surface features, surface water, geology, soils and hydrogeology are described.

Section 4.0 presents and assessment of the nature and extent of contamination in soils, groundwater, surface water and sediments based upon the Remedial Investigation data. Summaries of all analytical results are presented in this section.

Section 5.0 discusses the fate and transport of significant contaminants identified in Section 4.0. Potential routes of migration and persistence of the contaminants are discussed.

Section 6.0 presents the baseline risk assessment. This section identifies the harm that the contaminants could cause if no remedial action is taken. This section analyses potential human exposure, toxicity to humans, the risk to human health and potential adverse effects on the environment.

Section 7.0 presents a summary of the nature and extent of contamination, fate and transport of the contaminants and the assessment of risk. Conclusions related to data limitations, recommendations for future work and recommended remedial action objectives are also presented.

2.0 STUDY AREA INVESTIGATION

Remedial Investigation field activities are described in Section 2.1. A brief summary of the June 1, 1990 Data Completeness Evaluation Technical Memorandum is presented in Section 2.2.

2.1 Field Activities

Investigation of the study area was performed by Techna Corporation between November 6, 1989 and May 11, 1990. Field oversight was provided by U.S. EPA contractor GZA/Donahue and their subcontractor Soil Testing Services, Inc. The Michigan Department of Natural Resources performed a limited field oversight role.

Field activities are summarized in the following subsections: Subsection 2.1.1, Surface Features; Subsection 2.1.2, Surface Water and Sediment Investigations; Subsection 2.1.3, Soil Investigations/Chemical Characteristics; Subsection 2.1.4, Soil Investigations/Physical Characteristics; Subsection 2.1.5, Groundwater Investigation/Chemical Characteristics; and Subsection 2.1.6, Groundwater Investigation/Physical Characteristics.

2.1.1 Surface Features

Surface features at the Hi-Mill site are of both man-made and natural origin. Abrahms Aerial Survey Corporation performed an aerial survey of the site in May 1989. The photographic survey resulted in a topographic map of the study area with a scale of one inch equals fifty feet and a contour interval of two feet. This survey located site boundaries, fences, roads, drainage ditches, tile fields, wetlands, lakes, buildings and vegetated areas. This topographic, site feature map reduced to approximately one inch equals one hundred feet, is presented as Plate I in the map pocket of this report.

Site features and utilities near the Hi-Mill facility were surveyed by Ayers, Lewis, Norris, and May Inc. along with actual boring and well locations and well elevations. Site features and utilities are shown schematically on Figure 1-2.

Historic aerial photographs from May 3, 1949, May 7, 1956, May 23, 1961, April 25, 1967 and spring of 1965, 1974, 1980 and 1985 have been examined. Plates II and III are prints from aerial photographs obtained through Oakland County. These photos document the site features as they appeared in 1985 and 1980. Property boundaries are shown on the 1985 photo. The 1980 photo shows the location of two wastewater lagoons south of the Hi-Mill building, the Target Wetland at a relatively low water level, State Road M-59 prior to widening and several structures that are no longer present.

Two wastewater lagoons referenced in previous reports related to the Hi-Mill site are shown on the 1980 photo. These lagoons are no longer present but their former locations were the target for soil sample locations that are discussed in Section 2.4 of this report.

The 1980 photograph shows that directly to the west of Hi-Mill is a small structure that at one time was part of a small private airport, directly across M-59 from the Hi-Mill facility are two residences and a building that was at one time a gas station. These buildings were removed during the period when M-59 was expanded to a four-lane, divided highway in the early 1980s.


2.1.2 Surface-Water and Sediment Investigations

Purpose and Scope

Samples of surface waters and sediments from the Target Wetland, Waterbury Lake and the Background Pond were collected from the locations shown in Figure 2-1. All samples were analyzed for copper, chromium, aluminum, silver, nickel and zinc to evaluate the levels and distribution of contaminants. Three sediment and water samples at locations shown on Figure 2-1 were analyzed for the TAL inorganic parameters to ensure that other contaminants are not present in the wetland area.

Sediment samples were collected from ten stations in the wetland, two stations in Waterbury Lake and one station north of M-59. Surface water samples were collected from all thirteen stations. Background samples were collected from a background wetland, of the same classification (Soil Conservation Service) as the marsh, located approximately 1000' southwest of Waterbury Lake. Four water and four sediment samples were collected from evenly distributed locations in the background wetland.

Figure 2-1. Background Soil, Off-Grid Soil, Surface Water and Sediment Sample Point Map



The Remedial Investigation resulted in the collection and analysis of the following surface water samples: 12 samples for short list metals, including 1 field duplicate and 1 field blank; 5 samples for TAL inorganics, including 1 field duplicate and 1 field blank; 17 samples for hexavalentchromium, including 2 field duplicates and 2 field blanks; 9 samples for ammonia and nitrate/nitrite, including 1 field duplicates and 1 field blanks.

The Remedial Investigation resulted in the collection and analysis of the following sediment samples: 22 samples for short list metals, including 3 field duplicates; 5 samples for TAL inorganics, including 1 field duplicate; and 25 samples for hexavalent chromium, including 3 field duplicates.

Master data tables for surface water and sediment samples are presented as Appendices A and B respectively. The surface water and sediment master data tables present station, sample ID, ENCOTEC sample number, sample collection date, project east location coordinate, project north location coordinate, elevation and sample type for each surface water sample point.

Methodology

All sampling and testing procedures conformed to either approved Remedial Investigation protocols or subsequently approved (U.S. EPA RPM) field modification. Surface water and sediment samples were collected from separate holes cut through approximately three to eight inches of ice which covered the lakes and wetlands. Before sample collection, pieces of ice were removed from the ice hole. One sediment sample (TP-12) was collected in the target pond by wading into the lake.

Sediment samples were collected using split spoon samplers pushed or driven into the upper one and one half feet of sediment. Sediment samples were extruded into a plastic collection bowl and homogenized with stainless steel sample scoops before being placed in 8 ounce plastic containers for analysis. Split spoon samplers, sample scoops and plastic bowls were decontaminated using a detergent (Liquinox) and tap water wash, tap water rinse, 10% nitric acid rinse and distilled water rinse sequence and then air dried. The split spoon ends were wrapped in plastic before being sealed in aluminum foil for field transport. The sample scoops and plastic bowls were wrapped in plastic for field transport.

Surface water samples were collected from approximately six inches below the water surface at each location. Each collection bottle was initially rinsed with surface water before sample collection;

collection bottles were used at only one location. The dedicated collection bottle was used to transport the water sample for metal analyses back to the site trailer for filtering.

Sample filtering was performed by pouring the sample directly into a Geotech barrel filter and forcing the sample under pressure through a 0.45 micron disposable filter directly to laboratory prepared sample bottles. The barrel filter was decontaminated prior to each use by a detergent (Liquinox) and tap water wash, tap water rinse, 10% nitric acid rinse and distilled water rinse sequence. A new 0.45 micron filter was used for each sample collected.

QA/QC samples consisted of field duplicates, field blanks and trip blanks. Trip blanks were prepared by ENCOTEC using organic-free deionized water, and were used at a rate of one per shipment cooler. Duplicate surface water and sediment samples were collected in a second set of bottles at a rate of one per ten samples collected for each analyses parameter. Field blanks for metal analyses were prepared by pouring distilled water into a dedicated laboratory prepared sample collection bottle which was rinsed prior to sample collection with 10% nitric acid and distilled water, then directly into a decontaminated Geotech barrel filter and forced under pressure through a 0.45 micron disposable filter directly to laboratory prepared sample bottles. Field blanks for organic analyses were prepared by pouring organic-free deionized water into a dedicated laboratory prepared sample collection bottle, then into a laboratory prepared sample bottle. Field blanks for volatile analyses were prepared by pouring distilled water into a dedicated laboratory prepared sample collection bottle, then into a laboratory prepared sample bottle.

All sample bottles were properly labeled and placed on ice while on site. Accurate records were kept of all sampling activities. At the end of each day's sample collection activities, samples were transported in coolers by Techna personnel to ENCOTEC in Ann Arbor, Michigan. Samples for inorganic analyses were subsequently shipped to Wilson Laboratories in Salina, Kansas by ENCOTEC for analyses. Proper chain-of-custody procedures were strictly followed.

2.1.3 Soil Investigations/Chemical Characteristics

Purpose and Scope

Soil sampling was performed in five separate suspect areas. The five areas were 1) a sample grid to evaluate potential metals contamination on unsurfaced areas generally south of the Hi-Mill

buildings, 2) a sample grid to evaluate potential organic contamination near the abandoned northeastern water supply well, 3) a sample grid to evaluate potential organic contamination around the abandoned southeastern water supply well, 4) off-grid sample points targeted at potential locations of surface run-off south and west or the property fence, and 5) off-grid sample points targeted for the location of the former large lagoon, the former small lagoon and the existing raised leach field. Soil samples were collected from locations shown on Figure 2-2 and Figure 2-3.

Eight background soil samples were collected from six different locations north, west and southeast of the Hi-Mill site. Background soil sample locations are shown on Figure 2-1.

Sample Area 1 is within the unsurfaced area generally south of the Hi-Mill buildings suspected for metals contamination. Samples from Area 1 have sample notations designated with alpha-numeric identifiers A through M and 1 through 8, e.g. E3.

Sample Area 2 is within a 20 by 40 foot grid adjacent to and northeast of the Hi-Mill office suspected of volatile organic contamination. Samples from Area 2 have sample notations of either VW, WX, XY, or YZ and 01 or 12, e.g. WX12.

Sample Area 3 is within a 20 by 40 foot grid adjacent to and southwest of the Hi-Mill building suspected of volatile organic contamination. Samples from Area 3 have sample notations of either RS or ST and 01, 12, 23, or 34, e.g. RS23.

Sample Area 4, consisted of small eroded drainage channels southwest of the site suspected as potential migratory pathways for metals contamination. Samples from Area 2 are designated with the sample notation OG.

Sample Area 5, consisted of borings G3/H4, G4 and H4/I4/I5 targeted for the suspected area of the former location of the small lagoon; borings H3/I4, I4 and I3 targeted for the former location of the large lagoon; and borings G4 and G4/H5 targeted for the currently operating raised seepage bed. Modifications to the originally planned locations were made after approval by the U.S EPA, the U.S EPA oversight contractor and the MDNR.

Background soil samples were collected in areas that were suspected to be free of contaminants. Background soil samples are designated with the sample notation BG.

Figure 2-2. TAL Inorganics and Short List Metal Soil Sample Point Map





Figure 2-3. TCL Volatile Organic and TCL Organic Soil Sample Point Map



The Remedial Investigation resulted in the collection and analysis of the following soil samples: 176 samples for short list metals, including 15 field duplicates; 26 samples for TAL inorganics, including 2 field duplicates; 54 samples for TCL volatiles, including 5 field duplicates; and 15 samples for TCL other organics, including 2 duplicates.

A master data table for soil samples is presented as Appendix C. The soils master data table presents the sample ID, ENCOTEC laboratory ID number, boring type, sample collection date, project east location coordinate, project north location coordinate, elevation, sample depth category, and sample type category for each soil sample.

Methodology

All sampling and testing procedures conformed to either approved Remedial Investigation protocols or subsequently approved (U.S. EPA RPM) field modification. Surface soil samples from area 1, area 4 and background locations were collected using a stainless steel hand auger. Area 1 surface soil samples, collected below water level, within the wetlands between the target pond and the Hi-Mill site, were collected using two-inch (2") diameter, eighteen-inch (18") split spoon samplers attached to an AW rod and forced by a portable drop hammer into the soil for a depth of eighteen inches (18"). Soil samples from soil borings (areas 1, 2, and 3) were drilled with hollow stem augers and were collected using two-inch (2") diameter, eighteen (18") or twenty-four (24") inch long split spoon samplers. Hollow-stem auger drilling procedures were followed as described in Section 2.5 of this report.

The soil profile was logged noting such features as color, grain size, sorting, roundness, structure, composition, and obvious presence of contamination such as discoloration and odor. Representative aliquots of selected split spoon samples were collected and were retained for visual records.

All boreholes, where monitor wells were not installed, were backfilled with bentonite grout upon completion. Decontamination procedures for drilling equipment were followed as described in the Section 2.5 of this report.

Soil samples collected for TCL non-volatile organic and TAL inorganic analyses were extruded into stainless steel and plastic bowls, respectively and homogenized with a stainless steel scoop before being placed in sample containers. Samples collected for TCL volatile organics were placed directly

into sample containers. A duplicate sample was obtained for every ten (10) samples collected for each analyte. The split spoon samplers, hand augers, bowls and scoops were decontaminated using a detergent (Liquinox) and tap water wash, steam cleaning or tap water rinse, 10% nitric acid rinse and distilled water rinse sequence. A further rinse sequence of methanol and final distilled water was used when collecting for TCL organic analyses. The split spoons, bowls and scoops were air dried. For samples collected for TAL inorganic analyses the split spoon ends, plastic bowls and scoops were wrapped in plastic, with a final wrap of aluminum foil on the split spoons, for field transport. For samples collected for TCL organic analyses the split spoons, stainless steel bowls and scoops were wrapped in aluminum foil for field transport.

All sample containers were properly labeled and placed on ice at the site. Accurate written records were kept of all sampling activities. At the end of each day's sample collection activities, samples were transported in coolers by Techna personnel to ENCOTEC in Ann Arbor, Michigan. Samples for TAL inorganic analyses were subsequently shipped to Wilson Laboratories in Salina, Kansas by ENCOTEC for analyses. Approved chain-of-custody procedures were strictly followed.

Modified Level D protection, as defined in the approved Health And Safety Plan, was used during drilling and sampling operations. A photoionization detector was used for ambient air monitoring of volatile organics during drilling operations. A combustible gas indicator was used for continuous ambient air monitoring of combustible gases during drilling operations. No ambient air conditions requiring modification of personal protection were encountered.

2.1.4 Soils Investigation/Physical Characteristics

Purpose and Scope

Physical characteristics of selected soils were tested to establish the types of site soils and the range of physical characteristics for each type. The following soil characteristic tests were performed as part of the Remedial Investigation: 16 samples for grain-size, including 1 field duplicate; 8 samples for Atterberg limits; 11 samples for moisture contents, including 1 field duplicate; and 15 samples for vertical hydraulic conductivity, including 1 field duplicate.

Methodology

All soil boring and monitor well installation procedures conformed to either approved Remedial Investigation protocols or subsequently approved (U.S. EPA RPM) field modification. Drilling of boreholes for well installation was performed by McDowell and Associates using four and one-quarter inch (4-1/4") I.D. hollow stem augers.

Soil samples were obtained approximately every five feet (5') or at changes in soil type using eighteen (18") or twenty four (24") inch long split spoon samplers in advance of the hollow stem augers according with ASTM Method D-1586. As split spoons were driven, blow counts were recorded every six inches (6"). Shelby tube and brass lined split spoons were used to collect soil samples for physical property analysis. At nested well locations, separate boreholes were drilled for shallow, intermediate and deep wells, however soil sampling and logging was only conducted as deeper depths were progressively drilled.

Each well was constructed of two-inch (2") diameter flush-coupled PVC casing with a three-foot (3') or five-foot (5') length, No. 10 slot, stainless steel or PVC screen and fitted with a like plug and vented PVC cap. All wells extended at least one foot (1') above the ground surface and were protected with a locking steel casing which was secured with keyed-alike padlocks. To prevent possible downward migration of shallow groundwater, intermediate and deep wells were set within a ten inch (10") diameter PVC outer casing which was grouted in place and allowed to set before deeper drilling occurred.

Decontamination procedures for well installation conformed to either approved Remedial Investigation protocols or subsequently approved (U.S. EPA RPM) field modification. All well casings, screens, caps, plugs and split spoon samplers were scrubbed with a detergent (Liquinox) and tap water wash followed by a steam cleaning/rinse. The drilling equipment (i.e. augers, rods, bits, etc.) were steam cleaned prior to the onset of drilling activities and between boring locations. Steam cleaning was conducted in a designated area in the Hi-Mill parking lot. Upon completion of drilling activities, all drilling equipment was steam cleaned.

Monitor well installation was accomplished as follows. The well screen and capped casing was lowered through the hollow stem augers to the selected depth followed by; 1) the emplacement of a sand pack to a height of approximately two feet (2') above the top of the screen while simultaneously retracting the augers, thus allowing the sand to settle into the annular space between

the well screen and borehole wall; 2) with the auger bottom located approximately at the top of the sand pack, installation of approximately two feet (2') bentonite pellet seal; and 3) the remaining annular space was grouted from the bottom up with a bentonite-portland cement slurry. A steel protective casing was installed around the well casing and extended approximately three feet (3') into the cement slurry below ground surface. Due to the shallowness of SW-5, SW-9A and SW-20, a steel plate with a six inch center hole was welded to the base of the steel casing such that shallower cementing of the protective casing was achieved and allowing the maximum length of screen to access the aquifer. SW-5, SW-9A and SW-20 had less than the two feet (2') of sand pack and bentonite pellets above the screen. SW-9A was installed in a hand augured boring. A notch was cut in the top of all well casings at the lowest point to serve as a measuring point. Each protective casing was labeled with the well number. Details for the construction or individual wells are presented in Appendix F.

Wells were developed at least twenty-four hours after well installation. The shallow wells were developed with a stainless steel bailer, except for SW-5, SW-7, SW-14, SW-15 and SW-22 which have PVC screens and were bailed with a PVC bailer. Prior to development, static groundwater levels were recorded and subtracted from previously obtained bottom of screen measurements to estimate the casing volume in each well. Bailers were decontaminated with a steam cleaning rinse, 10% nitric acid rinse and distilled water rinse sequence between well locations. The stainless steel bailers had an additional methanol and final distilled water rinse. The static water level indicator was decontaminated before and after use with a 10% nitric acid rinse, distilled water rinse, methanol rinse and final distilled water rinse sequence. Each bailer was fitted with a new piece of teflon-coated wire or nylon string prior to placement in the well. The shallow wells were initially surged with the bailer for approximately three to five minutes before groundwater was removed. Except for wells that were bailed dry, approximately five (5) well volumes were purged from each shallow well. Wells bailed dry were allowed to recharge, were and were rebailed to dryness.

The intermediate and deep wells were developed using filtered compressed air forced into the well at screen depth through one-inch (1") PVC pipe coupled with threaded connections. The PVC pipe was steam cleaned before being lowered into each well. Approximately five (5) well volumes were purged from these wells using this method, except for DW-2. Further development of DW-2, which initially produced very little water, was accomplished by purging with a stainless steel bailer and using the reguard bladder pump system.

Modified Level D protection as approved in the Health and Safety Plan was used during drilling and sampling operations. A photoionization detector was used for ambient air monitoring of volatile organics during drilling operations. A combustible gas indicator was used for continuous ambient air monitoring of combustible gases during drilling and monitor well installation. No ambient air conditions requiring modification of personal protection were encountered.

2.1.5 Groundwater Investigation/Chemical Characteristics


Purpose and Scope

The hydrogeological study was comprised of several components designed to attain the following objectives: determine groundwater flow direction and define and characterize the contaminant plume in surficial groundwater south and east of the site; determine the potential for migration of contaminants in surficial groundwater beyond the southern and eastern boundaries of the marsh; confirm groundwater flow direction and the potential for contamination of the two deeper aquifers located at approximately 50' and 85' below ground level; investigate the hypothesis that trichloroethylene contamination in the process wells is localized and not part of a larger contaminant plume; and determine the potential for contamination of the two deeper aquifers.

The Remedial Investigation resulted in the installation of twenty-one (21) shallow wells, five (5) intermediate wells, and three (3) deep wells (Figure 2-4). Borings SW-13 and SW-16 did not have shallow wells installed as planned due to the absence of shallow saturated zones. SW-9A and SW-22 were installed, although not planned in the Remedial Investigation Work Plan. SW-9A was installed to replace SW-9, which the MDNR thought was screened too deep. SW-9 has been used only for static water level measurements. SW-22 was installed to provide a supplemental monitoring point.

The Remedial Investigation resulted in the collection and analysis of the following groundwater samples: 31 samples for short list metals, including 3 field duplicates and 3 field blanks; 8 samples for TAL inorganics, including 1 field duplicate and 1 field blank; 29 samples for TCL volatiles, including 3 field duplicates, 3 field blanks and 3 matrix spikes; 5 samples for TCL other organics, including 1 field duplicate and 1 field blank; 30 samples for ammonia and nitrate/nitrite, including 3 field duplicates and 3 field blanks; and 32 samples for pH, and 33 samples for temperature and conductivity.

Figure 2-4. Monitor Well, Staff Gauge Location Map



A groundwater master data table is presented as Appendix D. The groundwater master data table presents sample ID, ENCOTEC laboratory ID number, descriptions of aquifer type, bottom of screen depth, sample collection date, east location coordinate, north location coordinate, top of screen elevation and sample type.

Methodology

All sampling and testing procedures conformed to either approved Remedial Investigation protocols or subsequently approved (U.S. EPA RPM) field modifications. Sampling of a well occurred no sooner than fourteen days following the development of that well.

Prior to sampling, static groundwater levels were recorded and subtracted from previously obtained bottom of screen measurements to calculate the volume of standing water in each well. The measuring tape and water level indicator was decontaminated before and after use using a detergent (Liquinox) and tap water wash, tap water rinse, 10% nitric acid rinse, distilled water rinse, methanol rinse and final distilled water rinse sequence.

Three to five well volumes were removed from each intermediate well (IW), each deep well (DW), and shallow wells SW-5, SW-17, SW-20 and EW-4, just prior to sampling. Due to slow recharge, all other shallow wells (SW and EW) were bailed dry, then allowed to recharge prior to sampling. The deep and intermediate wells were purged and sampled using a gas driven, air lift bladder pump Geoguard system. The bladder (teflon) pump (stainless steel) system ensured that lift air did not come in contact with the groundwater sample during pumping action. Two, three-foot bailers and one, eighteen-inch stainless steel bottom loading bailers with teflon check valves were dedicated to the Hi-Mill site and used to purge and sample the shallow wells.

The bladder pump and bailers were decontaminated between wells using a steam cleaning wash, detergent (Liquinox) and tap water wash, tap water rinse, 10% nitric acid rinse, distilled water rinse, methanol rinse and final distilled water rinse sequence. The air lift sampling hose for the Geoguard system was steam cleaned and then assembled to the decontaminated bladder pump and the entire system flushed with distilled water and organic-free deionized water sequence. Additional flushing of the system occurred during purging of the wells prior to sampling. Each bailer was fitted with a new piece of teflon-coated wire prior to placement in the well.

Samples for analysis of organic parameters were poured directly from the bailer or collected directly upon discharge from the Geoguard sampling hose into the sample bottles. VOA vials were completely filled to ensure that no headspace remained after capping. Samples for metal analysis were poured directly from the bailer or collected directly upon discharge from the Geoguard sampling hose into sample collection bottles dedicated to each well. The sample was then transported directly to the site trailer for filtering. Samples were filtered under pressure through a 0.45 micron disposable filter using a Geotech barrel filter.

The barrel filter was decontaminated prior to and after use by a detergent (Liquinox) and tap water wash, tap water rinse, 10% nitric acid rinse and distilled water rinse sequence. The dedicated laboratory prepared sample collection bottle was rinsed prior to sample collection with 10% nitric acid and distilled water. A new 0.45 micron filter was used for each sample collected.

QA/QC samples consisted of field duplicates, field blanks and trip blanks. Trip blanks were prepared by ENCOTEC using organic-free deionized water for each shipment cooler. Duplicate groundwater samples were collected in a second set of bottles at a rate of one per ten samples collected for each analyses parameter. Field blanks for metal analyses were prepared by pouring distilled water into a decontaminated bailer, then into a laboratory prepared sample collection bottle which was rinsed prior to sample collection with 10% nitric acid and distilled water, then directly into a decontaminated Geotech barrel filter and forced under pressure through a 0.45 micron disposable filter directly to laboratory prepared sample bottles. Field blanks for organic analyses were prepared by pouring organic-free deionized water into a decontaminated bailer, then into a laboratory prepared sample bottle. Field blanks for volatile analyses were prepared by pouring distilled water into a decontaminated bailer, then into a laboratory prepared sample bottle.

All sample bottles were properly labeled and placed on ice while on site. Accurate records were kept of all sampling activities. At the end of each day's sample collection activities, samples were transported in coolers by Techna personnel to ENCOTEC in Ann Arbor, Michigan. Samples for inorganic analyses were subsequently shipped to Wilson Laboratories in Salina, Kansas by ENCOTEC for analyses. Proper chain-of-custody procedures were strictly followed.

The temperature of each groundwater sample was measured immediately upon sample collection. The pH and specific conductivity of most groundwater samples was measured immediately upon sample collection; however, measurements on samples collected from wells SW-9A, SW-22.

EW-1, EW-2, EW-6, IW-2, IW-5, DW-1 and DW-3 were performed at Brighton Analytical within twenty minutes from time of collection. Instrument probes used to measure pH, specific conductivity and temperature were calibrated daily in accordance with the QAPP and used according to manufacturers directions.

2.1.6 Groundwater Investigation/Physical Characteristics

Purpose and Scope

Potentiometric surfaces were determined to establish the direction of groundwater flow and potential pathways for contaminant migration via groundwater. Measurements have to be repeated monthly to evaluate the potential for seasonal variation in potentiometric surfaces and direction of groundwater flow.

Static water levels were taken in all wells installed during the Remedial Investigation and in all existing observation wells on April 12, 1990, May 11, 1990 and June 8, 1990. Staff gauge measurements were obtained on April 12, 1990, May 11, 1990 and June 8, 1990. Additional monthly water level measurements are scheduled.

Slug tests were performed in shallow, intermediate and deep wells to estimate the horizontal hydraulic conductivity in the immediate vicinity of the selected wells. The Remedial Investigation resulted in the performance of 17 slug tests, including 4 duplicates. The tested wells were SW-4, SW-8, SW-9, SW-11, SW-15, SW-17, IW-1, IW-2, IW-3, IW-4, IW-5, DW-1, DW-2, and DW-3. Slug test results are summarized in Appendix G.

Methodology

Slug testing procedures conformed with approved Remedial Investigation protocols. Slug tests were performed using a Hermit Environmental Data Logger, Model SE1000B with field data recorder. Test methodology is described in the following paragraphs.

Three initial static water level measurements were obtained using an electronic static water level indicator in each observation well. A transducer, measuring water level changes with a precision of

0.01 feet, was lowered into the well a sufficient depth such that displacement of a known volume of water would not interfere with maintaining the transducer below saturation during the test period. The transducer cable was secured to the casing. The transducer water level was then allowed to equilibrate to initial static water level conditions or recover at least 90% in the condition of slow recharge (greater than 30 minutes).

A solid, cylindrical polypropylene slug was submerged in the well displacing either 0.5 or 0.75 gallons depending on the number of sections used. The well was then allowed to return to the initial static water level or recover at least 90% in the condition of slow recharge. Slow recharge occurred in wells, SW-8, SW-11, SW-15 and DW-3. Duplicate tests were performed on SW-9A, IW-1, IW-4, IW-5 and DW-3.

Slug test data was evaluated using the Bouwer and Rice Method. All calculations assumed the effective well diameter was six inches and that the effective screen diameter was two inches. Other assumptions used for the calculation of horizontal hydraulic conductivity and transmissivity are presented in Appendix G.

2.2 <u>Technical Memorandum</u>

A Phase I Data Completeness Technical Memorandum (Technical Memorandum) was submitted on June 1, 1990. This Technical Memorandum discusses the purpose, scope and completeness of all field activities. The field activities included background sampling, soil sampling, groundwater sampling, surface water sampling, and sediment sampling for chemical analyses; physical parameter testing of soils; potentiometric surface determination; and slug tests. The Technical Memorandum presents preliminary discussions of the physical characteristics and the nature and extent contamination in soils, groundwater, surface water and sediments at the Hi-Mill site. The Technical Memorandum also evaluates the adequacy of data and recommends modifications to the scheduled second round of groundwater sampling. The Technical Memorandum's table of contents with lists of figures, tables and appendices is presented as Appendix E. Some of the Tables, Figures and Appendices presented in the Technical Memorandum have been corrected, modified or expanded for inclusion in this Draft Remedial Investigation and Baseline Risk Assessment Report.

The Technical Memorandum concluded that assessment sampling met the data completeness requirements and were in fact 100% complete in all but the following areas: soil sampling appeared

to be only 95% complete but was being recalculated, Atterberg limit testing was 89% complete, horizontal hydraulic conductivity testing was 93% complete, and QA/QC samples were 100% complete except for the absence of three field duplicates for pH, specific conductivity, and temperature during groundwater sampling, the absence of one Atterberg limit field duplicate, and the absence of one permeability field duplicate.

Recalculation of soil sample completeness identified ten uncounted samples and results in a corrected completeness calculation of greater than 98%. Reexamination of slug test data revealed that SW-4 was tested but failed to recharge. Therefore, slug test completeness is recalculated as 100%.

The Technical Memorandum concluded that chemical and physical measurements were over 99% complete for inorganic analyses and 98.4% complete for organic analyses. No significant laboratory QA/QC deficiencies were identified. However, a data review indicated that eight surface water and four groundwater samples had elevated nickel values that were the result of a systematic analysis error. These samples have been reanalyzed by Wilson Laboratories.

The Technical Memorandum concluded that all required measurements of groundwater static water levels were performed. However, additional monthly measurements are scheduled. This Draft Remedial Investigation and Baseline Risk Assessment Report includes results from measurements of groundwater static water levels on June 8, 1990 that were not included in the Technical Memorandum.

3.0 PHYSICAL CHARACTERISTICS OF THE STUDY AREA

3.1 Surface Features

Surface features of the Hi-Mill site are depicted on Figure 1-2, and Plates I, II and III. These plates and figure show an area that consists of both natural and man-made features.

Natural features exhibit a topography typical of nearby areas within the glacial interlobate morainic system. Closed depressions dot a surface controlled by glacial moraine and/or outwash features. Drainage is poorly developed and generally deranged. Waterbury Lake, the Hi-Mill facility and the Target Wetland all occupy a gently sloping (generally less than 2% except for the slope to Waterbury Lake which reaches more than 10% locally) area ranging in elevation from approximately 999 feet to 1010 feet NGVD. Irregularly shaped upland areas locally extend to elevations of 1034.8 feet (directly east of Numatics), 1032.2 feet (northeast of Waterbury Lake and 1028.7 feet (north of M-59).

Man-made features are dominated by the M-59 roadway, drainages and nearby structures. M-59 is a four-lane, divided, asphalt-pavement highway with limited access. Culverts pass beneath the roadway from both the Target Wetland and the north arm of Waterbury Lake.

Hi-Mill consists primarily of enclosed, paved or fenced areas. The Hi-Mill buildings occupy approximately 50,000 square feet. The parking areas (primarily paved) cover approximately 60,000 square feet of the site. An eight-foot high, chain-link fence, topped with barbed wire surrounds the approximately two-acres of unimproved Hi-Mill property that lie south and east of the production building.

Numatics, Inc is located approximately 800 feet northeast of the Hi-Mill facility. Numatics occupies a production building approximately 12,000 square feet in size on a two to three acre site. Approximately 22,000 square feet of the site is used for vehicular parking and traffic. Several rural residences lie over 1000 feet east of the Hi-Mill site on the west side of Waterbury Road.

3.2 Surface Water Hydrology

The surface water hydrology of the Hi-Mill site is dominated by the presence of Waterbury Lake and the Target Wetland. These waterbodies are surficially unconnected, and both lie within closed basins without any external drainage. Waterbury Lake is approximately thirty-five to forty acres in size. The Target Wetland is approximately eight to ten acres in size.

The north arm of Waterbury Lake, which is isolated from the main Waterbury Lake body, drains north beneath M-59 to a small pond that drains north to Alderman Lake. Alderman Lake in turn drains to the south through Pettibone Creek. Pettibone Creek flows south into Pickerel Lake, which in turn drains south into Lower Pettibone Lake.

The Target Wetland under normal conditions is isolated with no outlet. During periods of high water elevations in the Target Wetland, it may be connected via a culvert to a small, shallow wetland north of M-59. This small shallow wetland has no external drainage.

Water levels in both Waterbury Lake and the Target Wetland fluctuate seasonally as indicated by staff gauge readings, vegetation and historic aerial photographs. Measurements of these fluctuations are presented in Table 3-1. Locations of the six staff gauges used for these measurements are shown on Figure 2-4.

Staff gauge measurements from April 12, May 11 and June 8, 1990 for staff gauges SG-1, SG-2 and SG-6 were averaged to determine flow potential between the Target Pond and a small wetland directly across M-59 to the north. Average surface water elevations for staff gauges in the Target Pond are 1005.55 feet (SG-2) and 1005.51 feet (SG-1). Average surface water elevation in the shallow wetland north of M-59 was 1005.34 feet (SG-6). These staff gauge data indicate a slight potential for surface water flow toward the north, but field observation show that the base of the culvert passing from the Target Pond beneath M-59 is above the recorded water levels in the Target Pond. This field observation does not indicate a direct connection between the Target Pond and the shallow wetland north of M-59., which is north of M-59.

Staff gauge measurements from April 12, May 11 and June 8, 1990 for staff gauges SG-3, SG-4, and SG-5 were averaged to determine flow potential between water bodies of Waterbury Lake, the isolated north arm of Waterbury Lake, and a wetland directly across M-59 to the north. Average surface water elevations for staff gauges in Waterbury Lake is 1000.08 feet (SG-4). The average

Table 3-1

Part A Shallow Aquifer Potentiometric Surface Data

Well No.	Coordinates East	North	Top of Casing Elevation	4/12/90 SWL/GWE	5/11/90 SWL/GWE	6/8/90 SWL/GWE
SW 1	4836.64	5161.85	1,013.17	8.72/1,004.45	9.11/1004.06	9.18/1003.99
SW 2	4195.70	5232.68	1,018.04	19.60/998.44	18.62/999.42	17.99/1000.05
SW 3	4835.29	5493.89	1,012.43	4.41/1,008.02	4.96/1007.47	4.71/1007.72
SW 4	4801.81	5856.60	1,010.18	3.64/1,006.54	4.21/1005.97	4.41/1005.77
SW 5	4961.10	5476.12	1,011.95	4.00/1,007.95	4.57/1007.38	7.82/1004.13
SW 6	4977.80	5336.34	1,011.63	3.37/1,008.26	4.00/1007.63	3.94/1007.69
SW 7	5036.95	5478.99	1,010.36	4.12/1,006.24	4.31/1006.05	4.62/1005.74
SW 8	5108.19	5393.99	1,010.85	3.70/1,007.15	4.85/1006.00	5.22/1005.63
SW 9	4974.48	5669.81	1,010.10	4.42/1,005.68	4.72/1005.38	4.84/1005.26
SW 9A			1,010.88			4.84/1006.04
SW 10	5112.85	5490.56	1,010.50.	4.48/1,006.02	5.02/1005.48	4.80/1005.70
SW 11	4913.90	4918.55	1,013.04	10.0/1,003.04	10.37/1,002.6	7 10.71/1002.33
SW 12	5029.18	5097.04	1,013.14	3.16/1,009.98	3.71/1009.43	4.07/1009.07
SW 14	5247.52	5304.50	1,009.76	5.18/1,004.58	5.31/1004.45	5.77/1003.99

Table 3-1 Con't

Part A Con't Shallow Aquifer Potentiometric Surface Data

Well No.	Coordinates East	North	Top of Casing Elevation	4/12/90 SWL/GWE	5/11/90 SWL/GWE	6/8/90 SWL/GWE
SW 15	5380.41	5262.08	1,010.93	3.62/1,007.31	4.31/1006.57	6.65/1004.28
SW 17	5877.47	5286.53	1,012.83	12.74/1,000.09	12.85/999.98	12.78/1000.0
SW 18	6150.44	5866.12	1,008.58	6.28/1,002.30	6.41/1002.17	6.43/1002.1
SW 19	5917.08	6146.97	1,015.61	11.94/1,003.67	11.89/1003.72	11.86/1003.7
SW 20	5024.46	6420.24	1,009.76	2.27/1,007.54	2.96/1006.80	2.26/1007.5
SW 21	4773.86	5467.87	1,012.93	5.39/1,007.54	NM/	DAMAGED
SW 22	5066.25	5550.10	1,010.25	4.27/1,005.98	4.62/1005.63	4.72/1005.5

Table 3-1 Con't

Part B: Intermediate and Deep Aquifers - Potentiometric Surface Data

			C	Groundwater Elevation Data				
Well No.	Coordinate: East	s North	Top of Casing Elevation	4/12/90 SWL/GWE	5/11/90 SWL/GWE	6/8/90 <u>SWL/GWE</u>		
IW 1	4201.32	5224.28	1,017.02	20.45/996.57	20.42/996.60	20.40/996.62		
IW 2	4930.85	5069.05	1,014.56	16.49/998.07	16.47/998.09	16.34/998.22		
IW 3	4835.32	5498.20	1,011.90	13.38/998.52	13.37/998.53	13.22/998.68		
IW 4	4796.28	5857.73	1,010.06	11.19/998.87	11.24/998.82	11.16/998.90		
IW 5	5242.66	5314.18	1,009.39	10.40/998.99	10.41/998.98	10.36/990.03		
DW 1	4929.12	5078.70	1,014.62	17.37/997.25	17.26/997.36	17.17/997.4		
DW 2	4835.83	5502.14	1,011.99	14.09/997.83	14.02/997.97	13.96/998.03		
DW 3	5237.63	5323.86	1,009.41	12.02/997.39	11.90/997.51	11.84/997.57		

Table 3-1 Con't

Part B: Intermediate and Deep Aquifers - Potentiometric Surface Data

			G	iroundwater Eleva	tion Data	
	Coordinates		Top of Casing	4/12/90	5/11/90	6/8/90
Well No.	East	North	Elevation	SWL/GWE	SWL/GWE	SWL/GWE
IW 1	4201.32	5224.28	1,017.02	20.45/996.57	20.42/996.60	20.40/996.62
IW 2	4930.85	5069.05	1,014.56	16.49/998.07	16.47/998.09	16.34/998.22
IW 3	4835.32	5498.20	1,011.90	13.38/998.52	13.37/998.53	13.22/998.68
IW 4	4796.28	5857.73	1,010.06	11.19/998.87	11.24/998.82	11.16/998.90
IW 5	5242.66	5314.18	1,009.39	10.40/998.99	10.41/998.98	10.36/990.03
DW 1	4929.12	5078.70	1,014.62	17.37/997.25	17.26/997.36	17.17/997.4
DW 2	4835.83	5502.14	1,011.99	14.09/997.83	14.02/997.97	13.96/998.03
DW 3	5237.63	5323.86	1,009.41	12.02/997.39	11.90/997.51	11.84/997.57

Table 3-1 Con't

Part C: MDNR Wells Potentiometric Surface Measurements

Well No.	Coord East	linates North	Top of Casing Elevation	4/12/90 SWL/GWE	4/19/90 SWL/GWE	5/11/90 SWL/GWE	6/8/90 SWL/GWE
EWI	4942.94	5703.00	1008.05	1.32/1006.73	1.78/1006.27	2.12/1005.93	1.28/1006.77
EW2	5052.12	5585.79	1007.33	1.40/1005.93	0.49/1006.84	1.74/1005.59	1.49/1005.84
EW3	5088.89	5523.17	1010.82	NM	4.93/1005.89	5.14/1005.68	
EW4	5151.44	5449.37	1009.94	3.8/1006.14	3.94/1006	4.24/1005.70	4.16/1005.78

Table 3-1 Con't

Part D Staff Gauge: Water Surface Elevation Data

Gauge Number/ Map Number	Coordinat East	tes North	Gauge Elevation @ 6 Foot Mark	Guage Reading/Elevati 4/12/90 GR/Elev	on 5/11/90 GR/Elev	6/8/90 GR/Elev
Target Pond						
SG1 Near TP4 86	4943.99	5865.77	1007.76	3.94/1005.70	3.70/1005.46	3.63/1004.36
SG2 SE 90	5692.28	5513.71	1005.97 (@6.5' Mark)	6.27/1005.74	6.0/1005.47	5.96/1005.43
SG6 North of M-59 154	4588.97	6250.34	1006.85	4.71/1005.56	4.40/1005.25	4.36/1005.21
Waterbury Lake						
SG WL1 235	6131.12	4840.50	999.31	6.17/999.48	6.15/999.46	6.26/999.57
SG WL2 232	4959.72	4679.41	999.97	6.36/1000.33	6.06/1000.03	5.92/999.89
North M-59						
SG 229	4501.74	4642.23	1006.67	3.30/1003.97	3.28/1003.95	3.32/1003.99

1

surface water elevation in the isolated north arm of Waterbury Lake is 999.50 feet (SG-3). The average surface water elevation in the wetland directly north of M-59 is 1003.97 feet (SG-5). These three staff gauges indicate what appears to be three discontinuous water bodies that step downward to the south. Field observations confirm that the staff gauges are in water bodies that are discontinuous.

Measured monthly fluctuations in staff gauge readings are as great as -0.35 feet between April and May at Staff Gauge 6 and as small as -0.02 feet between April and May at staff gauges, SG-3 and SG-5. Measured monthly fluctuations have all been downward except for an increase of 0.04 feet and 0.11 feet at staff gauges SG-3 and SG-5, respectively. The maximum total fluctuation over the two-month period of record is a decline in surface water level at staff gauge SG-6 of 0.35 feet. Surface water fluctuations result from an uneven temporal distribution of average annual precipitation (approximately 32 inches), temporal changes of evapotranspiration rate (estimated to be 32 inches a year from free water surfaces) and either a small gain or loss to groundwater.


The Target Wetland appears to be an exposed groundwater surface, and it is not known whether it receives a net gain or loss from groundwater. Waterbury Lake also appears to be an exposed groundwater surface, although this conclusion is less certain due to the absence of observation wells to the south and west. The shallow groundwater contour map presented in this document (Figure 3-3) was generated assuming that the Target Wetland and Waterbury Lake are exposed groundwater surfaces.

3.3 Geology

Figure 3-1 is an interpretive soil-type cross-section trending northwest (NW) to southeast (SE) across the site. This cross-section is constructed from a composite of sample descriptions from nested well borings at SW-2/IW-1 (location A), SW-3/IW-3/DW-2 (location B) and SW-14/IW-5/DW-3 (location C). Locations of these nested wells are shown in Figure 2-4. Soil boring logs are presented as Appendix F.

The NW location A is typical of higher moraine ridge soil structure with a thin surface veneer of sandy-clay topsoil, fine sands, silts and/or gravel mixtures. Shallow wells SW-17, SW-18, and SW-19 are located in these ridge-type deposits. Silty lacustrine clay lies beneath the ridge deposits. This silty lacustrine clay is blue/grey to tan with inhomogeneities ranging from varves to thin intervals

Figure 3-1. Conceptual Geologic Cross Section.



1

of silt, fine silty sand or sand. Beneath the lacustrine clay is a zone of glacial outwash (intermediate aquifer). This saturated zone is generally composed of medium to coarse sands that grade with depth to fine to medium sands. These deposits were encountered at locations B and C and may have been encountered near the bottom of location A. The intermediate aquifer is separated from another zone of glacial outwash (deep aquifer) by another lacustrine deposit. This lacustrine deposit is a blue/grey silty clay similar in character to the upper lacustrine clay except for greater stiffness and

somewhat thicker and coarser inhomogeneities. This lacustrine deposit is approximately 20 to 25 feet thick at locations B and C but thins considerably at DW-1 (two to three feet thick).


Beneath this lacustrine deposit is another saturated zone (deep aquifer). This second saturated zone is glacial outwash. This zone appears to be less than 10 feet in thickness and is a fine to medium grained grey sand. At location C a blue/grey silty clay with sand, gravel and cobbles underlies the deep aquifer. This till layer was not encountered at the other two deep borings.

Lateral discontinuities are commonly present in the types of glacial deposits described above. The limited number of data points facilitate multiple possible correlations of units. For this reason all interpolated unit boundaries are considered to be only conceptual representations. The shallow sediments at the site have more numerous data points for possible correlation. The clay interface contour map (Figure 3-2) shows that the contact surfaces are irregular and thin zones may be expected to be laterally discontinuous.

3.4 Soils

Site soils encountered during the Remedial Investigation were clay, silt, organic clay, peat, silt, sand, mixtures of the preceding soil types and fill materials ranging from sand and gravel to clayey sand. Soil boring logs are presented in Appendix F. Soil types for all soil samples are summarized on the soil sample master data table in Appendix C. This data table identifies soils based upon grain-size as one of the following twelve groups: peat (P), clayey topsoil (CT), sandy topsoil (SDT), organic silty clay (OSTC), silty clay (STC), sandy clay (SDC), silty clay with sand or silt lamina, lenses or beds (STC/LB), clayey silt (CST), clayey sand (CSD), silty sand (STSD), sand (SD) and sandy gravel (SDG).

Figure 3-2. Soil-Clay Interface Elevation Contour Map



Analysis of soil physical characteristics were performed on selected split spoon samples from confining clay layers and saturated zones. These analyses indicate that moisture contents range from 12% to 31%; liquid limits, plastic limits and plasticity indices range from 25.5 to 42.9, 16.0 to 25.5 and 9.5 to 22.1, respectively; and vertical permeabilities range from 1.4×10^{-2} centimeters/second to 7.46×10^{-8} centimeters/second. Results of physical soil characteristic analyses including the results of sieve analyses are presented in Appendix J.

The depth to the clay interface was determined in the field at each boring and was used to select sample depths. Clay depths varied from 1008' to 997' NGVD. Depth to clay contours are presented on Figure 3-2. This figure shows that the clay interface elevation varies from approximately 995 feet to 1008 feet NGVD. Depressions in the clay contour map appear to coincide with the area of the two former lagoons. A subsurface slay ridge is present between the Hi-Mill facility and Waterbury Lake. Other contours appear to slope toward the Target Wetland.

Site soils are generally described by the U.S.D.A. Soil Conservation Service as belonging to five map units (Soil Survey of Oakland County, Michigan). These five units are 1) Houghton and Adrian mucks encircling the Target Pond, 2) Kibbie fine sandy loam located on the broad knoll between the Target Wetland and Waterbury Lake, 3) Thetford loamy fine sand southwest of the Hi-Mill facility along both sides of M-59, 4) Aquents, sandy and loamy, undulating in the immediate vicinity of the Hi-Mill facility, and 5) Tedrow loamy sand on the ridge east of the Target Wetland and in the area immediately around the Numatics facility. Runoff for all of these soil groups is classified as slow except for the Houghton and Adrian Muck which has very slow runoff. Permeabilities of these materials ranges from moderately slow to moderately rapid except for the Tedrow loamy sand which has rapid permeability.

3.5 Hydrogeology

Hydrogeologic Units

Six distinct hydrogeologic units were encountered during the Remedial Investigation. These hydrogeologic units shown on Figure 3-1 are as follows: I, shallow soils and granular materials; II, periglacial and/or post-glacial lacustrine deposits; III, glacial outwash deposits; IV, periglacial or interglacial lacustrine deposits; V, glacial or periglacial outwash deposits; VI, till; and VII, the

upland area east of the Target Pond and northwest of the Hi-Mill facility across M-59 are glacial outwash or morainal deposits. Shallow soil and granular material are described as hydrologic unit I. Hydrogeologic I is predominantly silt, sand clay mixtures that locally contain well developed soil horizons, plant roots, areas of fill and thin zones of high organic content. This hydrogeologic unit generally is saturated near its base, but in most locations is too shallow to facilitate installation of monitor wells. Monitoring well SW-5 is the only monitor well thought to be screened entirely in hydrogeologic unit I. The soil-clay interface, used to select sample depths during the Remedial Investigation, is the boundary between hydrogeologic zones I and II. Monitor wells SW-3, SW-9A, SW-12, SW-20, SW-21, SW-22, EW-1, EW-2, EW-4, and EW-6 are screened across this soil-clay interface and straddle hydrogeologic zones I and II. Analysis of slug test data from SW-9A indicates a horizontal hydraulic conductivity of 2.25 x 10⁻⁸ cm/sec. for zone I/II wells.

Lacustrine clays are described as hydrogeologic unit II. Hydrogeologic unit II is a blue/gray to tan variegated silty clay with horizontal bedding varying from varves to thin silt or silty sand interbeds. Blue/grey color appear to be more prevalent with depth but periodic occurrences of tan beds and the occurrence of shallow blue/grey beds suggest that color is not a valuable correlation parameter. Silty clays varied in moisture content from moist to saturated while silt and silty sand seams all appeared to be saturated. Localized pathways for horizontal migration in hydrogeologic zone II may be present, but the zone is expected to be an effective barrier to vertical migration. Monitor wells SW-1, SW-4, SW-6, SW-7, SW-8, SW-10, SW-11, SW-14 and SW-15 are thought to be screened entirely within hydrogeologic zone II. Analysis of slug test data from SW-4, SW-8, SW-11 and SW-15 provide a range of horizontal hydraulic conductivities ranging from less than 1.53 x 10⁻⁵ cm/sec. to 8.77 x 10⁻⁵ cm/sec.

Hydrogeologic zone III is glacial outwash. Hydrogeologic zone III consists of sands that grade from medium to coarse at the top of the zone to fine to medium at the base of the zone. This hydrogeologic zone produces useable amounts of water and was tapped by Hi-Mill's abandoned western water supply well. Monitor wells IW-1, IW-2, IW-3, IW-4, IW-5 and SW-17 are thought to be screened entirely within hydrogeologic zone III. Analysis of slug test data from SW-17, IW-1, IW-2, IW-3, IW-4, and IW-5 indicate horizontal hydraulic conductivities ranging from 5.63 x 10⁻⁴ cm/sec. to 1.09 x 10⁻² cm/sec.

Hydrogeologic zone IV is a stiff to extremely stiff blue/grey silty clay with thin sand and silt intervals. This zone appears to be approximately 20 feet thick at DW-2, 12 feet thick at DW-3, but

only 1 foot thick at DW-1. This zone, when present, is expected to provide an effective barrier to vertical migration. No wells are screened in this hydrogeologic zone.

Hydrogeologic zone V is a fine to medium sand similar to hydrogeologic zone III. This hydrogeologic zone produces useable amounts of water and is currently tapped by the Hi-Mill water supply well. Hi-Mill's abandoned eastern water supply well was screened in this hydrogeologic zone.

Monitor wells DW-1, DW-2, and DW-3 are screened in this hydrogeologic zone. Analysis of slug test data from DW-1, DW-2 and DW-3 indicate horizontal hydraulic conductivities for zone V wells ranging from 1.04×10^{-3} cm/sec to $2.20 < 10^{-3}$ cm/sec.


Hydrogeologic zone VI is an extremely stiff clay till. This zone was encountered at DW-3 and may have been encountered at the base of DW-2. This hydrogeologic zone is expected to be an effective barrier to vertical migration when present.

Hydrogeologic zone VII is a surficial deposit encountered during the remedial investigation in upland areas to the east of the Target Wetland and northwest of M-59. Hydrogeologic zone VII is predominantly silts and sands with some zones of clay and occasional gravel and cobbles. This zone is expected to be an area of groundwater recharge. Monitor wells SW-2, SW-18 and SW-19 are screened in hydrogeologic zone VII.

Hydraulic Potential

Potentiometric surfaces at monitor well locations were measured on April 12, 1990, May 11, 1990 and June 8, 1990. Measurements of potentiometric surface elevations are presented in Table 3-1. The average variation in shallow well potentiometric surfaces was -0.18 and -0.32 feet April 12 and May 11 and May 11 and June 8, respectively. Wells SW-2, SW-5, SW-8, SW-15, SW-17, SW-19, SW-20 and SW-21 have potentiometric surfaces that seem to be fluctuating differently than the other shallow wells, which appear to show similar fluctuations. A potentiometric contour map (May 11, 1990 data) for shallow wells is presented as Figure 3-3. Some of the abrupt contour characteristics are thought to be a result of either the contouring program or the inclusion of dissimilar shallow wells in the data set. Examination of multiple sets of generated contours suggest that the bend around SW-17 results from its dissimilarity (hydrogeologic unit III) to other wells.

Figure 3-3. Shallow Well Potentiometric-Surface Contour Map (May 11, 1990 Data)



The mound just east of SW-12 is thought to result from the computer algorithm and is not expected to be present at the site. The shallow groundwater appears to be flowing generally south, as shown on Figure 3-3, although the potentiometric contours present an irregular surface. A northwestward component of flow may be present northwest of the Hi-Mill buildings. The relationship of the potentiometric surface in SW-2 to the other shallow well potentiometric surfaces is critical to this interpretation.

Potentiometric surface measurements varied with respect to time at all intermediate wells. The average variation in intermediate well potentiometric surfaces was +0.03 and +0.10 feet between April 12 and May 11 and May 11 and June 8, respectively. A potentiometric surface contour map. (June 8, 1990 data) for intermediate wells is presented as Figure 3-4. The intermediate wells appear to show similar fluctuations, although IW-4 may be fluctuating differently than the other intermediate wells. This could be a result of its proximity to Hi-Mill's operating water supply well.

The intermediate groundwater appears to be flowing generally to the northwest, as shown on Figure 3-4. The contour map developed from potentiometric surfaces in the five intermediate wells is regular and has an average gradient of about 0.0027 feet/foot. Estimated groundwater velocity in the intermediate aquifer, based upon the average hydraulic gradient and the range of slug test hydraulic conductivities, is 16 feet to 310 feet per year.

Potentiometric surface measurements varied with respect to time at all deep wells. The average variation in deep well potentiometric surfaces was +0.11' and +0.07 feet between April 12 and April and May 11; and May 11 and June 6, respectively. A potentiometric surface trend map (June 8, 1990 data) for deep wells is presented as Figure 3-5. All three deep wells appear to show similar fluctuations. Deep ground water appears to be flowing southwest, as shown on Figure 3-5. The trend surface developed from potentiometric surfaces in the three deep wells appears flat and regular. The regularity of this picture is the result of having only three data points and may or may not reflect the actual potentiometric surface shape. The average groundwater gradient in the deep aquifer is approximately 0.0012 feet/foot. Estimated groundwater velocity in the deep aquifer, based upon the average hydraulic gradient and the range of slug test hydraulic conductivities, is 13 feet to 28 feet per year.

Comparison of potentiometric levels at well nests shows a downward vertical hydraulic gradient in all cases. Well nest SW-2 and IW-1 shows average potentiometric levels of 998.83 and 996.60 feet, respectively. Well nest IW-2 and DW-1 shows potentiometric levels of 998.08 and 997.33 feet,

Figure 3-4. Intermediate Well Potentiometric-Surface Contour Map (June 8, 1990 Data)





Figure 3-5. Deep Well Potentiometric-Surface Trend Map (June 8, 1990 Data)



respectively. Well nest SW-3, IW-3 and DW-2 shows potentiometric levels of 1007.74, 998.56 and 997.92 feet respectively. Well nest SW-4 and IW-4 shows potentiometric levels of 1006.25 and 998.86 feet, respectively. Well nest SW-14, IW-5 and DW-3 shows potentiometric levels of 1004.53, 998.97 and 997.43, respectively.

Hydrogeologic Parameters

Physical soil tests and slug tests were performed to determine hydrogeologic characteristics. Atterberg limit testing, sieve analysis, moisture contents and vertical permeabilities were determined for typical fine and coarse grained materials. Results are presented in Appendix G. Vertical permeability testing of silty clays in hydrogeologic unit II included samples IW-4AD, SW-10C, SW-15A and IW-5A. Calculated vertical permeabilities ranged from 1.4 x 10⁻⁶ cm/sec to 7.46 x 10⁻⁸ cm/sec. Vertical permeability testing of medium to coarse sand in hydrogeologic unit III included samples IW-1C and IW-5C. Calculated vertical permeabilities ranged from 1.14 x 10⁻² cm/sec to 6.98 x 10⁻³ cm/sec. Vertical permeability of silts and sands from hydrogeologic units IV and V included DW-1P, DW-1Q, DW-2K, DW-3C and DW-3D. Calculated vertical permeabilities ranged from 1.44 x 10⁻² cm/sec to 8.12 x 10⁻⁶ cm/sec. The calculated values from these hydrogeologic units do not appear consistent with visual descriptions and may indicate the presence of thin lowpermeability horizontal layers. Sample DW-3F is from hydrogeologic unit VI and has a calculated vertical permeability of 1.67 x 10⁻⁷ cm/sec.

4.0 NATURE AND EXTENT OF CONTAMINATION

4.1 Soils

A soils master data table is presented as Appendix C. This master data list contains the sample ID, ENCOTEC laboratory sample number, boring type, sample collection date, project east location coordinate, project north location coordinate, elevation, sample depth category, and sample type.

4.1.1 Inorganics

Analyses for short list metals and TAL inorganics were performed on samples collected at the locations shown on Figure 2-3. Summary tables of analytical results for analyses of short list metals and TAL inorganics in soils are presented in Appendix H and I, respectively.

Short-list Metals

The identification of contaminants of concern was based on presence at concentrations above background criteria (BC). The background criteria was determined from chemical analysis of the representative background samples collected during the RI. A preliminary evaluation of the analysis data for the ten (10) background samples indicated that both samples collected at BG2 and one sample (BG4-1) collected at BG4 were not representative because the concentrations of several metals were clearly higher than the general trend observed in all other samples. BG2, being proximate to the manufacturing building and the M-59, is assumed to have been impacted by human activities. The sample from BG4-1, while not proximate to site activities, was observed in the laboratory to have significantly different soils characteristics when compared to the other samples. The analysis data from these three (3) apparently non-representative samples were omitted from all background calculations.

Analysis data from the seven (7) representative background samples were used to determine the BC. The BC was established as the mean, at the 95% confidence interval (mean value plus two (2) standard deviations) of all background measurements for a given analyte. When the analysis results

were reported as below detection limit (U flag), the value of the detection limit and zero (0) were alternated in the mean calculation. In other words, the detection limit value was used for the first "U" flagged result encountered, zero (0) was entered for the next "U" flagged value, the detection limit value was used for the next "U" flagged result encountered, etc. The results from foreground sample analyses were then compared to the BC to determine which contaminants were present at elevated levels. This data then revealed the contaminants of concern and the extent of contamination.

Short list metal concentrations in background samples, including mean background concentrations and standard deviations are presented in Table 4-1. Table 4-2 presents soils analyses with short list metal concentrations above BC.

Table 4-1 shows that for copper, the mean background concentration is 4.3 mg/kg, the maximum background concentration is 7.5 mg/kg and that the BC is 8.33 mg/kg. There are 107 foreground locations above 8.33 mg/kg. There are 9 locations above 900 mg/kg. These nine locations of highest concentration are L3, M3, M4, H7, I5, H3/I3, I5-2, L3-2 and H7-2. An isoconcentration map showing the spatial distribution of copper concentrations in shallow soil samples is presented as Figure 4-1. A second isoconcentration map showing the spatial distribution of copper concentrations in clay interface soil samples is presented as Figure 4-2.

Table 4-1 shows that for chromium; the mean background concentration is 14.09 mg/kg, the maximum background concentration is 45.2 mg/kg, and that the BC is 39.7 mg/kg. There are 31 stations above 39.7 mg/kg. The highest concentration is 4420 mg/kg (M3-0). An isoconcentration map showing the spatial distribution of chromium in shallow soils is presented in Figure 4-3.

Table 4-1 shows that for zinc; the mean background concentration is 30.30 mg/kg, the highest background concentration is 70.2 mg/kg, and that the BC is 63 mg/kg. There are 38 stations above 63 mg/kg. The four highest detections are K6-0 (844 mg/kg), B1-0 (834 mg/kg), J5-0 (573 mg/kg), and E2-0 (350 mg/kg). It should be noted that the results of duplicate analysis for B1-0D (B1-0) is only 259 mg/kg.

Table 4-1 shows that for aluminum; the mean background concentration is 8054 mg/kg, the highest background concentration is 26,400 mg/kg and that the BC is 23,174 mg/kg. Six locations have values above 23,174 mg/kg. The highest concentration is 27,100 mg/kg at both H-7 and I-7.

Figure 4-1. Isoconcentration Map of Copper Concentrations in Surface Soil Samples




TABLE 4-1
SUMMARY OF BACKGROUND CONCENTRATIONS AND STATISTICS
FOR SHORT LIST METALS IN SOILS

SAMPLE ID	ALUMINUM	CHROMIUM	COPPER	NICKEL	SILVER	ZINC		
HMS-BG1-0	4330.00	7.50	3.00	5.40	2.300	24.40		
HMS-BG1-OD	4850.00	6.60	5.00	2.800	2.300	26.60		
HMS-BG3-0	4760.00	8.00	5.80	4.90	2.40U	27.80		
HMS-BG4-0	6710.00	12.60	2.50U	6.00	2.30U	20.90		
HMS-BG5-0	3950.00	7.80	2.700	6.00	2.40U	22.90		
HMS-BG5-1	3900.00	8.00	2.30U	2.500	2.10U	22.40		
HMS-BG6-1	6330.00	9.50	6.40	3.80	2.10U	23.50		
		STATIS1	TICAL ANALYS	sis				
MEAN	4976	8.57	3.57	4.49	.96	24.07		
STANDARD DEVIATION	1120	1.97	2.27	1.46	1.20	3.35		
MEAN + 2 STD	7216	12.52	8.11	7.42	3.35	28.89		

TABLE 4-2
SUMMARY OF SOIL SAMPLES ABOVE BACKGROUND CRITERIA
(MEAN + 2s)

SAMPLE ID	ALUMINUM	CHROMIUM	COPPER	NICKEL	SILVER	ZINC
HMS-A1-0 HMS-A1-1 HMS-A2-0 HMS-A2-1 HMS-A3-0	8730.00 12300.00 8600.00	12.40 14.90 19.40 13.70	10.30 9.60 14.00	8.60 10.40 13.90 17.60		33.70 33.10 37.70 39.00 33.60
HMS-A3-1 HMS-A4-0 HMS-B1-0 HMS-B1-0D	19500.00 8620.00 10200.00 11900.00	32.40 18.60 27.10	24.10 112.00 212.00	28.70 8.70 15.50 18.60	3.70	52.30 36.50 259.00 834.00
HMS-B1-1 HMS-B2-0 HMS-B2-1 HMS-B3-0 HMS-B3-1 HMS-B4-0 HMS-B5-0	13800.00 14500.00 8200.00 24300.00 7620.00 7400.00	21.30 21.30 13.50 32.00	11.70 21.70 13.80 24.00	12.70 23.80 8.20 32.10 8.20		41.10 48.00 38.60 60.80 31.20 38.10
HMS-B5-0-D HMS-C1-0 HMS-C1-1 HMS-C2-0 HMS-C2-1 HMS-C3-0 HMS-C3-0D	18100.00 16900.00 16000.00 20400.00 14100.00 14600.00	25.40 25.30 21.90 27.40 19.20 23.70	24.40 16.20 16.60 16.30 10.30	31.70 26.60 18.40 26.20 14.70 22.50		35.70 53.40 49.10 42.10 48.10 47.40 44.20
HMS-C3-1 HMS-C4-0 HMS-C5-0 HMS-D2-0 HMS-D2-1 HMS-D3-0	19500.00 8960.00 12200.00 21100.00	26.70 14.30 23.10 29.90	18.20 11.20 289.00 19.10	28.70 8.50 8.20 17.30 26.90		50.50 44.60 30.70 332.00 41.90
HMS-D3-1 HMS-D4-0 HMS-D5-0 HMS-D6-0	12200.00 9720.00	18.60 53.40	14.40	19.40 14.00		40.60 44.00 31.20
HMS-E2-0 HMS-E2-1 HMS-E3-0 HMS-E3-1 HMS-E4-0 HMS-E5-0 HMS-E6-0	10300.00 13300.00 10500.00 18500.00 8480.00 11600.00	161.00 70.10 13.10 23.70	987.00 630.00 25.30 23.00 9.50 10.80	24.00 23.20 10.40 21.60 11.50 13.80		350.00 244.00 59.40 56.60 43.70 42.80 32.10
HMS-E7-0 HMS-F3-0 HMS-F3-0D HMS-F3-1 HMS-F4-0 HMS-F4-1 HMS-F5-0	10400.00 20800.00 14100.00 22500.00 18900.00 17500.00	18.70 68.90 44.70 41.10 14.20 31.30 26.30	1570.00 1150.00 121.00 524.00	16.40 33.30 26.90 33.70 10.70 27.70 19.90		38.70 185.00 163.00 74.90 103.00 56.20 55.80
HMS-F6-0 HMS-F7-0 HMS-F7-0-D	8510.00 7340.00			9.40 9.40		41.10 37.10 35.80

TABLE 4-2 (CONT)

SUMMARY OF SOIL SAMPLES ABOVE BACKGROUND CRITERIA (MEAN + 2s)

SAMPLE ID	ALUMINUM	CHROMIUM	COPPER	NICKEL	SILVER	ZINC
HMS-F8-0	12300.00	15.50	7.80	19.20		44.80
HMS-G3-0 HMS-G3-1	20300.00	30.10	18.10 11.40	22.20		33.20 42.10
HMS-G3/H4-0 HMS-G3/H4-1		13.40	10.80 28.10	11.70		33.20
HMS-G3/H4-2		118.00	222.00	12.90		73.10
HMS-G3/H4-3 HMS-G4-0	17100.00	28.20	22.40	27.60		59.10
HMS-G4-1				10.10		34.40
HMS-G4-2			12.70			
HMS-G4-2D		22 22		9.00		44 00
HMS-G4-3	11100.00	22.00	25 10	22.80		46.30
HMS-G5-0	22200 00	14.60	25.10	14.70		40.50 62.30
HMS-G5-2 HMS-G6-0	22200.00	34.30	25.20	33.00 12.10		42.30
HMS-G6-1	19500.00	36.60	37.00	34.60		61.20
HMS-G6-2	15800.00	20.00	37.00	25.90		48.60
HMS-G6-3	17500.00	26.80	20.10	28.00		53.50
HMS-G7-0	12100.00	139.00	1480.00	27.50	22.50	664.00
HMS-G8-0	18100.00	20.50	14.50	18.00	22.00	49.60
HMS-H3-0		17.90	54.50			34.70
HMS-H3/I3-0		50.00	201.00	9.00		34.20
HMS-H3/I3-1	9170.00	248.00	1850.00	21.50		89.40
HMS-H3/14-1						
HMS-H3/I4-2	10800.00	89.50	615.00	15.20		84.50
HMS-H3/I4-3	13700.00	21.60		26.50		56.70
HMS-H4-0						32.60
HMS-H4-1		48.00	68.20	16.00		53.80
HMS-H4/I5-0		15.60	19.40	9.40		47.40
HMS-H4/I5-1		13.40	29.60	8.60		87.00
HMS-H4/I5-3	9940.00	17.80	10.10	22.50		46.50
HMS-H5-O	9810.00	108.00	373.00	15.20		81.70
HMS-H5-1	14300.00	24.10	57 60	19.80 15.70		33.30 44.60
HMS-H6-0 HMS-H6-0D	8920.00 8950.00	32.10 63.70	57.60 105.00	18.50		43.00
HMS-H6-1	18300.00	97.00	309.00	30.20		60.70
HMS-H6-2	13200.00	24.30	309.00	19.60		39.40
HMS-H6-3	11300.00	13.30		25.10		40.00
HMS-H7-0	18200.00	196.00	813.00	30.70		107.00
HMS-H7-1	27100.00	615.00	2500.00	27.90		89.70
HMS-H7-2	15900.00	23.10	23.90	25.90		81.20
HMS-H7-3	19000.00	22.50		34.00		62.70
HMS-H8-0	21500.00	36.80	770.00	22.20		90.90
HMS-13-1		17.40	32.90	9.00		47.20
HMS-13-2	9330.00	16.70	11.90	12.50		41.60
HMS-13-3	10900.00	18.60		21.30		48.20
HMS-I4-1		<u> </u>				
HMS-14-2	11700.00	30.70	196.00	22.00		59.90
HMS-14-3	10300.00	18.30		20.30		45.70
HMS-14-3D	10000.00	18.70		24.70		48.40

TABLE 4-2 (CONT)

SUMMARY OF SOIL SAMPLES ABOVE BACKGROUND CRITERIA (MEAN + 2s)

SAMPLE ID	ALUMINUM	CHROMIUM	COPPER	NICKEL	SILVER	ZINC
HMS-15-0		15.90	37.10	8.50		40.50
HMS-15-1	14100.00	302.00	1820.00	30.40	4.60	75.40
HMS-15-2	17500.00	1620.00	4440.00	25.10	12.50	101.00
HMS-15-3	1.4500.00	18.60	42.40	10.80		104.00
HMS-16-0	14500.00	208.00	829.00	29.30		184.00
HMS-16-0D	18400.00	127.00	483.00	30.00		186.00
HMS-16-1	12400.00	22.60	29.40	18.70		37.50
HMS-16-2	7660.00	21 00		17.10		55.00
HMS-16-3	14900.00	21.00	4630.00	26.60 23.20		55.90
HMS-17-0	23700.00	294.00 23.50	125.00	23.20		113.00
HMS-17-1 HMS-18-0	24300.00	40.40	82.20	26.20		81.10
HMS-15-0	18200.00	163.00	735.00	20.00		573.00
HMS-J5-1	10200.00	103.00	733.00	9.30		3/3.00
HMS-J5-2				9.20		
HMS-J5-3	17300.00	28.40		31.20		58.90
HMS-J6-0	26900.00	109.00	968.00	17.90		628.00
HMS-J6-1	14000.00	24.20	26.60	19.70		55.10
HMS-J7-0	27100.00	67.30	336.00	26.90		119.00
HMS-K3-1	21200.00	43.40	120.00	41.50		66.90
HMS-K4-0		16.40	340.00	11.20		298.00
HMS-K4-OD		16.40	55.70	12.30		204.00
HMS-K4-1	13400.00	20.40		26.10		38.70
HMS-K5-0	17600.00	23.60	43.00		3.80	83.60
HMS-K6-0	24800.00	56.40	68.00	24.60	3.80	844.00
HMS-L3-0	12200.00	42.40	913.00	19.90		86. 60
HMS-L3-1	17500.00	165.00	981.00	30.20		58.20
HMS-L3-1D	15400.00	917.00	2110.00	18.10		52.40
HMS-L4-0	25200.00	49.00	182.00	29.70		81.10
HMS-L5-0	25900.00	36.10	34.10	17.70		70.70
HMS-M3-0	18200.00	4420.00	3950.00	15.10		79.20
HMS-M4-0	21900.00	105.00	5010.00	17.40		81.00
HMS-OG1-0	11100.00	18.80	10.00	14.90		34.90
HMS-OG2-0	9370.00	16.70	10.90 8.00	$11.40 \\ 11.00$		41.30 33.30
HMS-OG3-0 HMS-OG4-0	9770.00	18.00	13.70	12.50		55.50
HMS-RS01-0	9730.00	16.30	12.10	9.80		57.50
HMS-RS01-2	9830.00	27.00	10.50	8.40		73.60
HMS-RS01-3	12200.00	19.10	11.80	18.30		42.00
HMS-RS12-0	13300.00	18.10	15.50	24.30		55.80
HMS-RS12-3	11300.00	22.70	13.30	21.40		46.40
HMS-RS23-0	9890.00	18.00		13.20		45.20
HMS-RS23-1	10900.00	21.30		18.90		38.40
HMS-RS23-3	13800.00	24.30		24.40		52.20
HMS-RS23-3D	11900.00	19.40		24.40		48.20
HMS-RS34-0	14500.00	23.70		20.70		58.10
HMS-RS34-2	15000.00	23.70		27.70		56.20
HMS-RS34-3	11300.00	19.80		20.30		47.70
HMS-ST01-0	13900.00	27.10	13.50	10.80		65.90
HMS-ST01-3	12900.00	16.70	14.80	20.40		40.30

TABLE 4-2 (CONT)

SUMMARY OF SOIL SAMPLES ABOVE BACKGROUND CRITERIA (MEAN + 2s)

SAMPLE ID	ALUMINUM	CHROMIUM	COPPER	NICKEL	SILVER	ZINC
HMS-ST12-0	11400.00	62.40	15.90	15.70		77.70
HMS-ST12-3	12400.00	17.80	15.30	19.60		39.80
HMS-ST23-0	8820.00	14.70	13.50	17.70		58.10
HMS-ST23-2	9930.00	14.50	15.90	20.90		38.50
HMS-ST23-3	13600.00	17.30	17.70	22.70		45.50
HMS-ST34-0	9970.00	16.10	51.80	15.50		100.00
HMS-ST34-2	17300.00	21.80	42.70	30.70		61.70
HMS-ST34-3	10500.00	17.90	12.70	17.90		39.10
HMS-WV01-0		74.50	285.00	9.60		45.10
HMS-WV01-1	0410 00	16.00	10.00	8.90		28.70
HMS-WV01-2	9410.00	16.90	12.80	15.20 30.00		28.90
HMS-WV01-3	13800.00	24.40	9.00 4 3.70	11.90		55.80 77.10
HMS-XW01-0 HMS-XW01-1		12.50	35.30	11.30		47.40
HMS-XW01-1		17.60 12.30	35.30	14.20		47.40
HMS-XW01-2	13900.00	24.50		29.90		60.70
HMS-XW12-1	15500.00	39.70	119.00	18.70		63.50
HMS-XW12-1	7760.00	42.00	130.00	12.40		38.30
HMS-XW12-2	14500.00	24.60	13.90	28.20		53.10
HMS-YX01-0	14300.00	24.00	54.20	10.20		78.70
HMS-YX01-1			8.40	8.70		40.00
HMS-YX01-2			0.40	13.60		40.00
HMS-YX01-3	14500.00	21.00	17.70	29.60		49.70
HMS-YX12-2	18300.00	38.90	135.00	23.60		46.90
HMS-YX12-3D	12000.00	21.70	10.60	28.70		54.90
HMS-ZY01-0	22000100		12.70	9.80		31.00
HMS-ZYO1-1			10.90	11.30		40.30
HMS-ZY01-2		12.90	17.90	12.30		
HMS-ZY01-3	13600.00	19.20	20.20	29.00		51.00
HMS-ZY12-0			9.10			37.00
HMS-ZY12-1			-	9.60		38.30
HMS-ZY12-2	9210.00	19.60	162.00	19.90		39.20
HMS-ZY12-3	14500.00	25.50	· · · ·	30.60		55.60

Figure 4-2. Isoconcentration Map of Copper Concentrations in Clay Interface Soil Samples




Figure 4-3. Isoconcentration Map of Chromium Concentrations in Surface Soil Samples




Table 4-1 shows that for nickel; the mean background concentration is 11.26 mg/kg, the highest background concentration is 50.2 mg/kg and that the BC is 43.1 mg/kg. No locations (except for background location BG-4-1) are above 43.1 mg/kg.

Table 4-1 shows that for silver; the mean background concentration is 2.27 mg/kg, the highest background concentration is 2.4 mg/kg and that the BC is 2.51 mg/kg. The highest concentration is 3.80 mg/kg in K6-0. All analyses results have UN flags except L4-0 which only has a U flag.

TAL Inorganics

The identification of contaminants of concern was based on presence at concentrations above background criteria (BC). The background criteria was determined from the chemical analysis data from the representative background samples collected during the RI. A preliminary evaluation of the analysis data for the ten (10) background samples indicated that both samples collected at BG2 and one sample collected (BG4-1) at BG4 were not representative because the concentrations of several metals were clearly higher than the general trend observed in all other samples. BG2, being proximate to the manufacturing building, is assumed to have been impacted by site activities. The sample from BG4-1, while not proximate to site activities, was observed in the laboratory to have significantly different soils characteristics when compared to the other samples. The analysis data from these three (3) apparently non-representative samples were omitted from all background calculations.

Analysis data from the seven (7) representative samples were used to determine the BC. The BC was established as the mean, at the 95% confidence interval (mean value plus two (2) standard deviations) of all measurements for a given analyte. When the analysis results were reported as below detection limit (U flag), the value of the detection limit and zero (0) were alternated in the mean calculation. In other words, the detection limit value was used for the first "U" flagged result encountered, zero (0) was entered for the next "U" flagged value, the detection limit value was used for the next "U" flagged result encountered, etc. The results from foreground sample analyses were then compared to the BC to determine which contaminants were present at elevated levels. This data then revealed the contaminants of concern and the extent of contamination.

Table 4-3 shows the mean background concentrations and background criteria for each of the 24 target analytes at 9 sample locations. All measurements of Sb, Hg, Se, Ag, Na, Tl, and CN were less than or equal to the respective background criteria. As, Be, Cd and Mn have two or less excedances above their respective background criteria.

Lead has three excedances above the BC level. These are concentrations of 60.0 mg/kg (G7-0), 22.5 mg/kg (I4-2) and 21.1 mg/kg (C4), which exceed 16.82 mg/kg (BC).

Barium, calcium, iron magnesium, potassium and vanadium and previously discussed short list metals had more than three excedances above their respective BC.

Vanadium, barium, iron and aluminum concentrations appear to vary in a related manner. No clear relationship is obvious for the other potentially elevated analytes.

4.1.2 TCL Volatile Organics

Samples for TCL volatile organic analyses in soils were obtained at I4-2 and G4-2 and within the RST-01234 and VWXYZ-012 grids, as shown on Figure 2-3. All TCL volatile organic detections are shown in Appendix J. Detections of TCL volatile organics without B, J or BJ flags are presented in Table 4-4.

Acetone, methylene chloride, and toluene were detected in I4-2 at concentrations of 0.015, 0.006 and 0.007 mg/kg, respectively. Methylene chloride, toluene and trichloroethene were detected in G4-2 with B and J flags. No other volatile organic compounds were detected outside of the RST-01234 and VWXYZ-012 grids.

The RST-01234 grid had unflagged volatile organic compounds detected in samples from all 8 sample points. Volatile organic compounds detected were methylene chloride, toluene, acetone, xylene (total), trichloroethene, 1,2-dichloroethene (total), 1,1,1-trichloroethane, ethylbenzene, chlorobenzene, and 2-butanone. Methylene chloride, toluene, xylene, ethylbenzene and 2-butanone are only reported in analyses with B, J, or BJ flags. The number of unflagged detections per compound were: trichloroethene, 10; 1,2 dichloroethene (total) 4; 1,1,1 trichloroethane 2; chlorobenzene, 1; and acetone, 1. Volatile organic compounds reported present without B, J or BJ flags with highest concentrations in parentheses were: trichloroethene (0.350 mg/kg), 1,2

TABLE 4-3

SUMMARY OF SOIL BACKGROUND CONCENTRATIONS AND STATISTICS
FOR TAL INORGANICS

ANALYTE CONCENTRATIONS (mg/kg)

SAMPLE ID	ALUMINUM	ANTIMONY	ARSENIC	BARIUM	BERYLIUM	CADMIUM	CALCIUM	CHROMIUM
HMS-BG1-0	4330.00	13.10U	2.20	26.10	0.26U	0.71	342.00	7.50
HMS-BG1-OD	4850.00	13.10U	1.90	36.10	0.26U	0.72	417.00	6.60
HMS-BG2-0	16000.00	14.60U	4.90	116.00	0.70	1.90	18100.00	224.00
HMS-BG2-1	9980.00	11.70U	4.20	34.30	0.29	0.64	7460.00	15.00
HMS-BG3-0	4 760.00	13.40U	1.70	18.90	0.260	0.530	454.00	8.00
HMS-BG4-0	6710.00	12.80U	2.70	27.80	0.25U	0.50U	1010.00	12.60
HMS-BG4-1	26400.00	13.000	8.20	130.00	1.20	1.20	4360.00	45.20
HMS-BG5-0	3950.00	13.700	4.80	33.40	0.27U	0.66	786.00	7.80
HMS-BG5-1	3900.00	11.70U	3.30	9.60U	0.23U	0.46U	304.00U	8.00
HMS-BG6-1	6330.00	11.70U	3.90	18.60	0.230	1.10	857.00	9.50
			ST	ATISTICAL P	MALYSIS			
MEAN	4976	7.41	2.93	24.36	0.15	0.60	595.71	8.57
STANDARD DEVIATION	1120	6.96	1.14	9.27	0.14	0.33	282.14	1.97
MEAN + 2 STD	7216	21.34	5.21	42.9	0.43	1.23	1159.98	12.52

U = SAMPLE WAS ANALYZED, BUT NOT DETECTED

TABLE 4-3 (CONT)

SUMMARY OF BACKGROUND CONCENTRATIONS AND STATISTICS FOR TAL INORGANICS

ANALYTE CONCENTRATIONS (mg/kg)

SAMPLE ID	COBALT	COPPER	IRON	LEAD	MAGNESIUM	MANGANESE	MERCURY	NICKEL
HMS-BG1-0	3.60U	3.00	5260.00	12.90	617.00	222.00	0.100	5.40
HMS-BG1-OD	8.00	5.00	6030.00	13.90	671.00	617.00	0.110	2.80U
HMS-BG2-0	11.30	892.00	12900.00	251.00	5240.00	154.00	0.22	20.30
HMS-BG2-1	5.50	17.10	13400.00	9.00	2740.00	98.70	0.090	8.80
HMS-BG3-0	3.70U	5.80	6250.00	16.60	752.00	80.30	. 0.12 U	4.90
HMS-BG4-0	6.20	2.50U	9210.00	11.80	1730.00	132.00	0.100	6.00
HMS-BG4-1	14.80	7.50	43300.00	14.90	8200.00	619.00	0.120	50.20
HMS-BG5-0	3.70U	2.70U	8500.00	11.10	1020.00	337.00	0.110	6.00
HMS-BG5-1	3.20U	2.30U	7370.00	3.90	713.00	147.00	0.100	2.500
HMS-BG6-1	3.20U	6.40	10200.00	5.90	1390.00	210.00	0.110	3.80
			Sī	ATISTICAL	ANALYSIS			
MEAN	2.66	3.57	7545	10.87	984.71	249.33	.05	4.49
STANDARD DEVIATION	2.96	2.27	1823.8	4.48	924.77	181.65	.06	1.46
MEAN + 2 STD	8.56	8.11	1192.59	19.83	1834.25	612.62	.17	7.42

U = COMPOUND WAS ANALYZED, BUT NOT DETECTED.

(

TABLE 4-3 (CONT)

SUMMARY OF SOIL BACKGROUND CONCENTRATIONS AND STATISTICS FOR TAL INORGANICS

ANALYTE CONCENTRATIONS (mg/kg)

SAMPLE ID	POTASSIUM	SELENIUM	SILVER	SODIUM	THALLIUM	VANADIUM	ZINC	CYANIDE
HMS-BG1-0	203.00U	0.26U	2.30U	278.00U	1.00U	8.10	24.40	0.64U
HMS-BG1-0D	203.000	0.26U	2.30U	279.00U	1.000	7.50	26.60	0.650
HMS-BG2-0	989.00	0.34	2.60U	310.00U	1.100	26.80	100.00	√0.72∪
HMS-BG2-1	561.00	0.230	2.10U	249.00U	0.920	21.00	39.00	0.57U
HMS-BG3-0	207.000	0.260	2.40U	285.00U	1.10U	11.60	27.80	0.66U
HMS-BG4-0	733.00	0.40	2.30U	290.00	1.000	11.10	20.90	0.63U
HMS-BG4-1	3350.00	0.26U	2.30U	288.00	1.000	51.80	70.20	0.64U
HMS-BG5-0	368.00	0.270	2.40U	290.00	1.10U	6.90	22.90	0.67บ
HMS-BG5-1	289.00	0.230	2.10U	248.00U	0.910	12.40	22.40	0.57U
HMS-BG6-1	342.00	0.28	2.10U	249.00U	0.920	16.60	23.50	0.57U
			STA	TISITCAL A	NALYSIS			
MEAN	306.0	0.20	.96	199.0	0.59	10.6	24.07	.26
STANDARD DEVIATION	224.28	0.15	1.20	136.66	0.55	3.42	2.41	.33
MEAN + 2 STD	754.56	0.5	3.35	472.33	1.70	17.43	28.89	.92

U = COMPOUND WAS ANALYZED, BUT NOT DETECTED.

TABLE 4-4

SUMMARY OF TCL VOLATILE ORGANIC ANALYSIS RESULTS FOR SOIL SAMPLES (SPECIES DETECTED WITHOUT B, J, OR BJ FLAGS)

SAMPLE ID	COMPOUND	CONCENTRATION (mg/kg)
HMS-14-2	Acetone	0.015
HMS-I4-2 RE	Toluene	0.007
HMS-I4-2 RE	Methylene chloride	0.006
HMS-RS01-0	Trichloroethene	0.007
HMS-RS01-3	Trichloroethene	0.007
HMS-RS12-3	1,2-Dichloroethene (Total)	
HMS-RS23-0	Trichloroethene	0.028
HMS-RS23-1	Chlorobenzene	0.014
HMS-RS34-0	1,1,1-Trichloroethane	
HMS-RS34-0	Trichloroethene	0.043
HMS-RS34-2	1,1,1-Trichloroethane	0.011
HMS-RS34-2	Trichloroethene	0.007
HMS-ST01-0	Trichloroethene	0.007
HMS-ST01-3	Trichloroethene	0.350
HMS-STO1-3	1.2-Dichloroethene (Total)	
HMS-ST01-3 DL	Trichloroethene	0.210
HMS-ST12-3	1,2-Dichloroethene (Total)	0.013
HMS-ST12-3	Trichloroethene	0.012
HMS-ST23-0	Trichloroethene	0.022
HMS-ST23-3	1,2-Dichloroethene (Total)	0.041
HMS-ST34-0 RE	Acetone	0.086
HMS-WV01-2	Trichloroethene	0.240
HMS-WV01-2	1,2-Dichloroethene (Total)	0.130
HMS-WV01-2 DL	Trichloroethene	0.100
HMS-WV01-3	Trichloroethene	5.700
HMS-WV01-3	1,2-Dichloroethene (Total)	0.098
HMS-WV01-3 DL	Trichloroethene	57.000
HMS-WV01-3D	Trichloroethene	6.400
HMS-WV01-3D	1,2-Dichloroethene (Total)	0.140
HMS-WV01-3D DL	Trichloroethene	45.000
HMS-XW01-3	1,2-Dichloroethene (Total)	0.009
HMS-XW12-1	Trichloroethene	0.029
HMS-YW12-3	Acetone	0.054
HMS-YX01-3	Toluene	0.008
HMS-YX12-2	Trichloroethene	0.022
HMS-YX12-3 RE	Toluene	0.015
HMS-YX12-3 RE	Trichloroethene	0.080
HMS-YX12-3 RE	Methylene chloride	0.012
HMS-YX12-3 RE	Acetone	0.065
HMS-ZY01-3	1,2-Dichloroethene (Total)	0.010
HMS-ZY01-3	Toluene	0.012
HMS-ZY01-3 RE	Toluene	0.007
HMS-ZY12-0	Trichloroethene	0.032
HMS-ZY12-1	Trichloroethene	0.041
HMS-ZY12-1D	Trichloroethene	0.028
HMS-ZY12-1D RE	Trichloroethene	0.009
HMS-ZY12-2	Trichloroethene	0.008
HMS-ZY12-3	Trichloroethene	0.018

dichloroethene (0.041 mg/kg), 1,1,1-trichloroethane (0.140 mg/kg), chlorobenzene (0.014 mg/kg) and acetone (0.086 mg/kg).

Unflagged volatile organic compounds were detected at five of seven locations in the VWXYZ-012 grid. The following volatile organic compounds were detected: trichloroethene, 1,2- dichloroethene (total), acetone, methylene chloride, toluene, 2-butanone, 1,1,1-trichloroethane, 1,1,2,2-tetrachloroethane, 1,1,2 trichloroethane, and chlorobenzene. Chlorobenzene, 2-butanone, 1,1,1-trichloroethane, 1,1,2,2-tetrachloroethane, and 1,1,2-trichloroethane are only reported in analyses with B, J, or BJ flags. The number of unflagged detections for each compound was: trichloroethene, 15; 1,2-dichloroethene (total), 5; acetone, 2; methylene chloride 1; and toluene 3. The following volatile organic compounds (with highest concentration in parentheses) were detected without J, B, or JB flags: trichloroethene (57 mg/kg), 1,2-dichloroethene (total) (0.140 mg/kg), acetone (0.065 mg/kg), methylene chloride (0.012 mg/kg) and toluene (0.015 mg/kg).

4.1.3 TCL Organics

Reported detections for extractable (BNA), PCB and pesticide fractions are presented in Table 4-5 for both background and non-background locations. Compounds detected in both background and non-background locations were di-n-butylphthlalate; and bis(2-ethlylhexyl)phthalate. Samples detected only in background were dibenz(a,h)anthracene; benzo(b)fluoranthene; fluoranthene; benzo(a)pyrene; indeno(1,2,3-cd)pyrene; butyl benzyl phthalate; benzo(a)anthracene; benzo(g,h,i)perylene; chrysene; phenanthrene; and pyrene. No compounds were detected in non-background locations without J flags.

The only TCL organic compound (excluding volatile organic compounds discussed above) detected without B, J or BJ flags in any sample was bis(2-ethylhexyl)phthalate in one background sample. Reported background levels were 0.590 mg/kg.

4.2 Groundwater

A groundwater master data table is presented as Appendix D. The groundwater master data table includes sample ID, ENCOTEC laboratory ID number, partial descriptions of aquifer type, bottom

TABLE 4-5

SUMMARY OF TCL ORGANICS ANALYSIS RESULTS FOR SOIL SAMPLES SPECIES DETECTED

SAMPLE ID	COMPOUND	CONCENTRAION (mg/kg)		
HMS-YX12-2	bis(2-Ethylhexyl) phthalate	0.210J		
HMS-104-2	bis(2-Ethylhexyl) phthalate	0.290J		
HMS-104-2	di-n-Butyl phthalate	0.120J		

of screen depth, sample collection date, project east location coordinate, project north location coordinate, top of screen elevation, and sample type.

4.2.1 Inorganics

Analyses of groundwater for dissolved TAL inorganics was performed on samples from shallow wells SW-2, SW-5, SW-8 and SW-22 and intermediate wells IW-1, IW-3 and IW-5. Analyses for dissolved short list metals were performed on samples from all shallow wells, intermediate wells, deep wells and in the pre-existing shallow wells EW-1, EW-2, EW-4 and EW-6.

A summary table of analytical results for TAL inorganic analyses of groundwater is presented in Appendix K, and a summary of short list metal analysis results is presented in Appendix L. A summary table of ammonia and nitrate/nitrite analysis results is presented as Appendix M.

Short List Metals

Short list metals in groundwater were reported in the following ranges of concentrations: aluminum, from below the detection limit of 85 μ g/l to a maximum concentration of 648 μ g/l (SW-20); chromium, from below the detection limit of 7 μ g/l to a maximum concentration of 45.8 μ g/l (SW-15); copper, from below the detection limit of 10.0 μ g/l to a maximum concentration of 98.7 μ g/l SW-7; nickel, from below the detection limit of 11.0 μ g/l to a maximum concentration of 149.0* μ g/l (SW-15); silver, from below the detection limit of 9.0 μ g/l to a maximum concentration of 14.6N μ g/l (SW-20); and zinc, from below the detection limit of 5.0 μ g/l to a maximum concentration of 22.0 μ g/l (SW-7). All detections of short list metals in groundwater without U, B, and/or N flags are presented in Table 4-6.

TAL Inorganics

TAL inorganics in groundwater were reported in the following ranges of concentrations: aluminum from below the detection limit of 85.00 μ g/l to a maximum concentration of 208 μ g/l (SW-22); antimony, from below the detection limits of 51.0 μ g/l to 56.0 μ g/l; arsenic, all were below the detection limit of 3.0 μ g/l; barium, from below the detection limit of 23.0 μ g/l to a maximum

TABLE 4-6

SUMMARY OF SHORT LIST METALS ANALYSIS RESULTS FOR GROUNDWATER SAMPLES (SPECIES DETECTED WITHOUT U, B AND/OR N FLAGS)

ANALYTE CONCENTRATIONS (ug/1)

	ANALYTE CONCENTRATIONS (ug/1)								
SAMPLE ID	ALUMINUM	CHROMIUM	COPPER	NICKEL	SILVER	ZINC			
HMW-DW01 HMW-DW02 HMW-DW03 HMW-EW01 HMW-EW02 HMW-EW02-D HMW-EW04 HMW-EW04-FB HMW-EW06									
HMW-EWO6-FB									
HMW-IWO1		20.70							
HMW-IWO2									
HMW-IWO3		16.00							
HMW-IWO4 HMW-IWO5									
HMW-SW01									
HMW-SWO2		30.20							
HMW-SW02		30.20							
HMW-SW03									
HMW-SW04 HMW-SW05		21.10							
HMW-SW05		21.10							
HMW-SWO6		22.10							
HMW-SWO6-FB									
HMW-SW07			93.30			22.20			
HMW-SW07-D		12.00	98.70						
HMW-SW08 HMW-SW08		12.80 12.80							
HMW-SWO8-D		15.10							
HMW-SWO8-D		15.10							
HMW-SWO8-FB		21.90			10.90				
HMW-SW08-FB		21.90			10.90				
HMW-SWO9A									
HMW-SW09A-FB HMW-SW10			33.80						
HMW-SW11			33.00	129.00					
HMW-SW12									
HMW-SW14									
HMW-SW15		45.80		149.00					
HMW-SW17									
HMW-SW18 HMW-SW19				119.00					
HMW-SW20	648.00			131.00		22.10			
HMW-SW21	0.10.00								
HMW-SW22	208.00								
HMW-SW22	208.00								

concentration of 59.10B µg/l in SW-8D; beryllium, from below the detection limits of 1.00 µg/l to 2.00 μ g/l; cadmium, all were below detection limit of 2.00 μ g/l; calcium, from a minimum concentration of 59,000 µg/l (SW-2) to a maximum concentration of 305,000 µg/l (SW-8); chromium, from the detection limit of 9.0 μ g/l to a maximum concentration of 30.20* μ g/l (SW-2); cobalt, from below the detection limits of 9.0 μ g/l to 14.0 μ g/l; copper, from below the detection limits of $10.0\mu g/l$ to $11.0 \mu g/l$; iron, from below the detection limit of 29.00 $\mu g/l$ to a maximum concentration of 391.00 μ g/l (IW-3); lead, from below the detection limit of 2.00 μ g/l to a maximum concentration of 2.20B μ g/l; magnesium, from a minimum concentration of 18,000 μ g/l (IW-3) to a maximum concentration of 529,000 µg/l in SW-22; manganese, from a minimum concentration of 49.2 μ g/l (IW-5) to a maximum concentration of 811.00 μ g/l (SW-5); mercury, all were below the detection limit of 0.20 μ g/l; nickel, from below the detection limit of 11.00 μ g/l to a maximum concentration of 20.30B μ g/l (SW-22); potassium, from a minimum concentration of 905.00B μ g/l (SW-2) to a maximum concentration of 11,500 μg/l (SW-5); selenium, all were below the detection limit of 1.00 μ g/l; silver, from below the detection limit of 8.00 μ g/l to a maximum concentration of 10.90 μ g/I (SW-8-FB); sodium, from a minimum concentration of 3,450.00B μ g/I (SW-2) to a maximum concentration of 579,000 μ g/l (SW-22); thallium, all samples were below the detection limit of 4.00 μ g/l; vanadium, from below the detection limit of 8.00 μ g/l to a maximum concentration of 1090B μ g/l (IW-5); zinc, from below the detection limits of 5.00 μ g/l to 6.00 μ g/l; and cyanide, from below detection limit of 10.00 µg/l to a maximum concentration of 37.00 µg/l (SW-5).

Ammonia and Nitrate/Nitrite

Ammonia and nitrate/nitrite analyses were performed on groundwater from SW-1, SW-2, SW-3, SW-4, SW-5, SW-6, SW-8, SW-10, SW-11, SW-12, SW-14, SW-15, SW-17, SW-18, SW-19, SW-20, and SW-21. Ammonia concentrations ranged from below the method detection limit of 50.00 μ g/l to 2200.00 μ g/l in SW-22. All reported ammonia analyses had A and C flags. Nitrate plus nitrite concentrations ranged from below the method detection limit of 50.00 μ g/l to 16,000 μ g/l in SW-5. All reported nitrate plus nitrite analyses had A and C flags.

TABLE 4-7
SUMMARY OF ORGANIC ANALYSIS RESULTS FOR GROUNDWATER SAMPLES (SPECIES DETECTED)

TRIP BLANK REFERENCE DATE	SAMPLE ID	COMPOUND	CONCENTRATION (mg/l)	FLAG
03/15/90	HMW-SW11 HMW-SW11 HMW-SW20 HMW-SW20 HMW-SW20 HMW-TB-03/15/90 HMW-TB-03/15/90 HMW-TB-03/15/90 HMW-TB-03/19/90	Toluene Methylene chloride 2-Butanone Toluene Acetone Methylene chloride 2-Butanone Toluene Methylene chloride Acetone	0.003 0.005 0.010 0.003 0.017 0.005 0.004 0.003 0.011	JB B JB B JB JB B
03/16/90	HMW-SW04 HMW-SW04 HMW-SW05 HMW-SW05 HMW-SW05 HMW-SW05-D HMW-SW05-D HMW-SW05-D HMW-SW05-D HMW-SW05-D HMW-SW05-D HMW-SW06-FB HMW-SW06-FB HMW-SW06-FB HMW-SW08 HMW-TB-03/16/90 HMW-TB-03/16/90 HMW-TB-03/16/90	2-Butanone Toluene Methylene chloride Acetone 1,2-Dichloroethene (Toluene) Methylene chloride Methylene chloride Acetone 1,2-Dichloroethene (Toluene) Lebutanone Vinyl chloride Methylene chloride Acetone 2-Butanone Methylene chloride Acetone 2-Butanone Methylene chloride Acetone 2-Butanone Methylene chloride Methylene chloride Acetone 1-Butanone Methylene chloride Methylene chloride Acetone 1-Butanone Methylene chloride Acetone 1-Butanone Methylene chloride	0.004 0.009 0.033	BJB B BJBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBB
03/19/90	HMW-SW01 HMW-SW01 HMW-SW01 HMW-SW01 HMW-SW02 HMW-SW03 HMW-SW03 HMW-SW03 HMW-SW03 HMW-SW03 HMW-SW03 HMW-SW03 HMW-SW03 HMW-TB-03/19/90 HMW-TB-03/19/90	2-Butanone 1,2-Dichloroethene (TAcetone Methylene chloride Trichloroethene Methylene chloride 2-Butanone Vinyl chloride Acetone 1,2-Dichloroethene (TMethylene chloride Trichloroethene 2-Butanone Acetone Trichloroethene	0.160 0.100 1.100 0.010 0.018 0.068 0.046	JB B JB B JB B

TABLE 4-7 (CONT)

SUMMARY OF ORGANIC ANALYSIS RESULTS FOR GROUNDWATER SAMPLES (SPECIES DETECTED)

TRIP BLANK REFERENCE DATE	SAMPLE ID	COMPOUND	CONCENTRATION (mg/l)	FLAG
03/19/90	HMW-TB-03/19/90	Methylene chloride	0.012	В
	HMW-IW01 HMW-IW01 HMW-IW04 HMW-IW04 HMW-SW10 HMW-SW10 HMW-SW10 HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW12 HMW-SW12 HMW-SW12 HMW-SW12 HMW-SW12 HMW-SW12 HMW-SW12 HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D HMW-SW10-D	Toluene Methylene chloride Acetone Methylene chloride 2-Butanone Acetone Methylene chloride 2-Butanone 1,2-Dichloroethene (Total) Acetone Methylene chloride 1,2-Dichloroethene (Total) 2-Butanone Acetone Toluene Methylene chloride 2-Butanone Methylene chloride 2-Butanone Methylene chloride Toluene Methylene chloride Toluene Acetone	0.015 0.009	JB JB JB JB JB JB JB JB JB JB
03/21/90	HMW-DW02 HMW-DW02 HMW-DW02-FB HMW-DW02-FB HMW-IW03 HMW-IW03 HMW-TB-03/21/90 HMW-TB-03/21/90	Toluene Methylene chloride Acetone Methylene chloride Acetone Acetone Methylene chloride Toluene Methylene chloride Acetone	0.001 0.045 0.016 0.005 0.029 0.018 0.010 0.001 0.001	ЈВ В В В В В В В В В В В В В В В В В В
03/22/90	HMW-TB-03/22/90 HMW-TB-03/22/90	Methylene chloride Acetone	0.014 0.013	B B
03/23/90	HMW-DW01 HMW-DW01 HMW-DW01 HMW-DW03 AND MA HMW-IW02 HMW-IW05 HMW-TB-03/23/90 HMW-TB-03/23/90	Methylene chloride Methylene chloride Acetone Methylene chloride	0.014 0.007 0.022 0.007 0.008 0.017 0.011	B J B
03/25/90	HMW-SW22	Methylene chloride	0.020	

4.2.2 TCL Volatile Organics

TCL volatile organic compounds were analyzed in groundwater samples from shallow wells SW-1, SW-2, SW-3, SW-4, SW-5, SW-6, SW-8, SW-10, SW-11, SW-12, SW-20, SW-22; intermediate wells, IW-1, IW-2, IW-3, IW-4, IW-5; and deep wells DW-1, DW-2 and DW-3. Well locations are shown on Figure 2-4. A summary table of all analytical results above detection limits is presented in Appendix J. TCL volatile organic compounds detected above the detection limits are presented in Table 4-7. The samples in which volatile organics were detected were as follows: trichloroethene, SW-1 and SW-3; 1,2 dichloroethene (total), SW-3, SW-5, SW-5D, SW-10, SW-10D, SW-10MS; vinyl chloride, SW-3; methylene chloride, DW-3, IW-2, IW-5, SW-22, SW-22D, SW-22FB, and MW-TB. The highest concentration and location are: trichloroethene (1,100 μ g/1 in SW-1), 1,2 dichloroethene (total) (360 μ g/1 in SW-1), vinyl chloride (68 μ g/1 in SW-3), methylene chloride (29 μ g/1 in SW-22FB), and acetone (11 μ g/1 in MW-TB).

4.2.3 TCL Organics

TCL organic analyses were performed on groundwater from SW-2, SW-2D, SW-2FB, SW-5, SW-8 and IW-1. Di-n-butyl phthalate (8 μ g/l·in SW-2) was the only base-neutral or acid extractable compound detected in groundwater samples. Pesticides and PCB analyses were not performed on groundwater samples.

4.3 Surface Water and Sediments

A surface water master data table is presented as Appendix A. The surface water master data table presents station, sample ID, ENCOTEC sample ID number, sample collection date, project east location coordinate, project north location coordinate, elevation and sample type for each surface water sample point.

4.3.1 Inorganics

Analyses for short list metals were performed on samples from BP-1, BP-2, BP-3, TP-1, TP-4, TP-4FB, TP-10, TP-10D, WL-1 and WL-2. TAL inorganic analyses were performed on BP-4, TP-2,

TP-7, TP-7D, TP-11, TP-11D, and TP-11FB. Ammonia and nitrate plus nitrite analyses were performed on BP-1, BP-2, BP-3, BP-4, TP-7, TP-7D, TP-10, and WL-2. Hexavalent chromium analyses were performed on samples from BP-1, BP-2, BP-3, BP-4, TP-1, TP-2, TP-2FB, TP-4, TP-4DTP-7, TP-9, TP-10, TP-10D, TP-11, WL-1, and WL-2. A summary of short list metal concentrations in sediments is presented in Table 4-8.

Short List Metals

Short list metals in surface water had the following range of concentrations reported: aluminum below the detection limit of 85.00 μ g/l for all samples except TP-9 (5360 μ g/l); chromium, below the detection limit for all samples except TP-1 (13.00 μ g/l); copper, below the detection limit for all samples except BP-1 (19.50 BN) and TP-10 (21.40); nickel, from below detection limit of 11.00* μ g/l to a maximum concentration of 302.00* μ g/l in TP-9; silver, from below the detection limit of 9.00 μ g/l to a maximum concentration of 12.50N μ g/l in BP-2; and zinc, from below the detection limit of 6.00 μ g/l and a maximum concentration of 16.20B μ g/l in TP-10D.

TAL Inorganics

The following TAL inorganics were below detection limits in all surface water samples (limits in parentheses): aluminum (85.00 μ g/l); arsenic (3.00 μ g/l); barium (42.00 μ g/l); beryllium (1.00 μ g/l); cadmium (2.00 μ g/l); cobalt (14.00 μ g/l; mercury (0.20 μ g/l); nickel (11.00 μ g/l); selenium (1.00 μ g/l); thallium (4.00 μ g/l); vanadium (8.00 μ g/l); and cyanide 10.00 μ g/l). Surface water samples for all locations were below background surface water station BP-4 for antimony (background, 65.40 μ g/l) and zinc (background, 12.40 μ g/l).

TAL inorganic concentrations for all other compounds are presented below for the background sample (BP-4), lowest sample location and highest sample location: calcium, 26500.00 μ g/l (BP-4), 13,300.00 μ g/l (TP-11 FB),and 44,500.00 μ g/l (TP-7); chromium, 9.30* μ g/l (BP-4), 7.00* μ g/l (TP-2), and 38.50* μ g/l (TP-11); copper, less than the detection limit of 10.00 μ g/l for all samples except TP-11 (13.00B μ g/l); iron, less than the detection limit (BP-4), 625.00 μ g/l (TP-11); lead, 3.30 μ g/l (BP-4), less than the detection limit (TP-2), and 7.80 μ g/l (TP-11FB); magnesium, 5050.00 μ g/l (BP-4), less than the detection limit (TP-11FB), and 11,800 μ g/l (TP-7); manganese, 7.30B (BP-4), less than detection limit (TP-11FB), and 378.00 μ g/l (TP-11); potassium, 817.00B μ g/l (BP-4), less

FIGURE 4-8
SUMMARY OF SHORT LIST METALS CONCENTRATIONS - SEDIMENTS
ANALYTE CONCENTRATIONS (mg/kg)

SAMPLE ID	ALUMINUM	CHROMIUM	COPPER	NICKEL	SILVER	ZINC
HMS-BP01-0 HMS-BP02-0 HMS-BP03-0 HMS-BP04-0 HMS-TP01-0 HMS-TP01-0D HMS-TP03-0 HMS-TP03-0 HMS-TP04-1 HMS-TP04-1 HMS-TP06-0 HMS-TP06-1 HMS-TP07-1 HMS-TP07-1 HMS-TP07-1 HMS-TP08-1 HMS-TP08-1 HMS-TP08-1 HMS-TP08-1 HMS-TP08-1 HMS-TP08-1 HMS-TP11-0 HMS-TP11-0 HMS-TP11-0 HMS-TP11-1 HMS-TP12-0 HMS-WL01-0 HMS-WL01-0	1090.00 964.00 3530.00 3610.00 14100.00 13800.00 31800.00 11800.00 12700.00 12700.00 15300.00 16300.00 16300.00 15500.00 17300.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 12500.00 13600.00 13600.00 13600.00 13600.00	22.90B 29.80U 20.30U 37.10 21.90 18.60 43.20 17.30 145.00 24.90 34.80 36.20 25.40 50.90 28.50 24.80 256.00 30.50 32.40 31.20 36.40 974.00 32.00 33.60 51.80 7.30U	30.30UN 42.60UN 34.80B 28.20U 42.20 52.60 36.90 2.80U 429.00 18.40 277.00N 64.80 7.00 105.00 10.70 15.40 982.00 6.60 6.10B 189.00N 77.40N 1860.00 15.10 238.00 486.00 10.40U	33.30U 46.80U 31.90U 31.00U 13.90B 12.20 23.30 13.60 41.90 28.20 17.50B 20.10 27.80 27.00 27.20 25.40 33.10 30.60 32.40 7.30B 23.80 22.80 22.70 15.40 21.80U 28.10B	27.30UN 38.30UN 26.10UN 25.40U 3.30UN 2.70UN 3.50U 2.60UN 4.10UN 2.20UN 3.00UN 2.20UN 3.20U 2.30UN 2.30UN 2.30UN 2.20U 2.30UN 2.20U 2.30UN 2.20U 2.30UN 2.20U 2.30UN 2.20U 3.60UN 2.70UN 2.60UN 2.70UN 2.60UN	18.20U 25.50U 71.60 122.00 86.80 56.00 42.70 48.70 104.00 51.40 70.60 51.50 52.50 82.00 53.10 55.90 208.00 53.10 68.70 68.70 68.00 65.30 41.10 75.30 75.60 56.90
		STATIS'	TICAL ANALYS	ıs		
MEAN	2298.5	20.5	19.35	19.45	15.93	54.78
STANDARD DEVIATION	1272.6	13.24	19.55	20.24	16.57	46.53
MEAN + 2 STD	4843.7	47.28	58.45	59.93	49.07	147.84

than the detection limit of 788.00 μ g/l (TP-11FB), and 3880.00B μ g/l (TP-7); silver, less than detection limit of 9.00 μ g/l in all samples except TP-7 (9.10B μ g/l); and sodium, 2620.00B (BP-4), less than detection limit of 1,080.00 μ g/l (TP-11FB), and 26,000.00 μ g/l (TP-7).

Hexavalent chromium was less than the detection limit of 10.00 μ g/l at all surface water locations.

Ammonia and Nitrate/Nitrite

Ammonia analyses were performed on surface water samples from BP-1, BP-2, BP-3, BP-4, and TP-07FB. Nitrate/nitrite analyses were performed on surface water samples from BP-1, BP-2, BP-3, BP-4, TP-7, TP-7D, TP-7FB and WL-2.

Ammonia concentrations ranged from below the detection limit of 50.00 μ g/l to a maximum concentration of 160.00AC μ g/l (BP-1). Nitrate/nitrite concentrations ranged from below the detection limit of 50.00 μ g/l to a maximum concentration of 1200.00AC μ g/l in TP-7FB. The concentration in TP-7FB was considerably higher than the next highest concentration of nitrate\nitrite, 180.00AC μ g/l (BP-1), which was in the background pond.

4.3.2 Sediments

The sediment master data table is presented as Appendix B. The master data table includes sample station number, sample ID number, ENCOTEC laboratory ID number, sample collection date, project east and north coordinates, elevation, and sample type for each sample. Locations of sediment sample points are shown on Figure 2-1.

Inorganics

Short list metals were analyzed at all Background Pond, Target Pond and Waterbury Lake sample locations. A summary of results for those test points that exceeded background criteria is presented in Table 4-8. Hexavalent chromium was analyzed in samples from locations BP-1, BP-2, BP-3, BP-4, TP-1, TP-4, TP-4-1, TP-5, TP-6, TP-6-1, TP-9, TP-10, WL-1, WL-2, and WL-2D.

Values for aluminum range from 964 mg/kg to 3610 mg/kg in the Background Pond, from 11,800.00 mg/kg to 33,900.00 mg/kg (TP-2) in the Target Pond, and from 1360.00 mg/kg to 6770.00 mg/kg in Waterbury Lake. All nineteen test points in the Target Wetland and one sample point in Waterbury Lake (WL-02) exceeded the BC of 4842 mg/kg.

Values for chromium range from less than detection (20.30U mg/kg) to 37.10 mg/kg in the Background Pond, from 17.30 mg/kg to 256.00 mg/kg (TP-8) in the Target Pond, and from less than detection (7.30U mg/kg) to 51.80 mg/kg in Waterbury Lake. Three test points in the Target Wetland (TP04-0, TP07-0, and TP08-0) and one point in Waterbury Lake (WL01) exceeded the BC of 50.65 mg/kg.

Values for copper range from less than detection (28.20U mg/kg) to 37.10 mg/kg in the Background Pond, from 17.30 mg/kg to 256.00 mg/kg in the Target Pond, and from less than detection (10.40U mg/kg) to 486.00 mg/kg in Waterbury Lake. Eight test points in the Target Wetland and one test point in Waterbury Lake (WL01) exceeded the BC of 54.91 mg/kg.

Values for nickel range from less than detection (31.00U mg/kg) to less than detection (46.80U mg/kg) in the Background Pond, from 7.30B mg/kg to 41.90 mg/kg (TP-04) in the Target Pond, and from less than detection (21.80U mg/kg) to 28.10B mg/kg in Waterbury Lake. None of the test points exceeded the highest detection limit of the background samples (46.8 mg/kg).

Values for silver were reported below detection limits for all samples.

Values for zinc range from 18.20U mg/kg to 122.00 mg/kg in the Background Pond, from 42.70 mg/kg to 208.00 mg/kg (TP-8) in the Target Pond, and from 56.90 mg/kg to 75.90 mg/kg in Waterbury Lake. One sample point in the Target Pond (TP08-0) exceeded the BC of 162.23 mg/kg.

Analysis results for hexavalent chromium at all sample locations were below the detection limits of 0.10 mg/kg to 2.00 mg/kg.

4.4 Summary and Conclusions

4.4.1 Soils

Based upon evaluations of the Remedial Investigation site assessment data presented in Sections 3 and 4 above, contaminated soils within the investigation area can be divided into three areas for purposes of contamination assessment, risk evaluation and remedial feasibility planning. These areas are the area between the production facility and the Target Wetland, the general vicinity of the small eastern assessment area VWXYZ-012, and the general vicinity of the small western assessment area, RST-01234.

Area Between Production Facility and Target Wetland

Soils located between the production facility and the Target Wetland were found to contain elevated levels of certain metals. This area appears to be roughly bounded by portions of the sample grid, but has not been fully defined.

TAL analytes Ag, As, Be, Cd, Pd, and Mn were all measured at levels greater than their respective BC but in three or fewer samples. These results indicate that these metals are not characteristic of significant site contamination and need not be addressed further. TAL analytes, Al, Ba, Ca, Cr, Cu, Fe, Mg, Ni, K, V and Zn were all measured at levels greater than their respective BCs in multiple samples. The most significant site wide contamination is represented by the metals Al, Cr, Cu, Ni, and Zn. There are clearly locations containing significantly elevated concentrations of these metals. However, the areal extent of contamination indicated by the number of results above BC (Table 4-2) may be significantly overstated for these five metals. This statement is based upon a evaluation of the step-shaped distribution of concentrations in foreground samples. For each metal there is a large cluster of results which indicate slight elevation above the BC. There is no basis to assume that the selected background locations include all naturally occurring soil types. This may have resulted in a negative bias in the BC, making the number of excedences unreasonably high.

Chromium and copper appear to be reasonable indicators for the extent of metals contamination. The highest levels of contamination were generally found at or above the soil clay interface. The clay layer appears to be a barrier to downward migration. The locations of highest concentrations generally lie near and immediately southeast of the former lagoons and in the vicinity of grid

location L3, L4, M3, and M4. Samples from these areas were organic rich clay. In the soil interface samples, sample I-5 described as a peat, had the highest copper concentration. These data suggest a possible correlation between organic content and contaminant metal concentrations.

Grid Area VWXYZ-012

The TAL species Al. Ba. Ca, Cr, Cu, Fe, Mg, Ni, K, V and Zn were measured in concentrations above their respective BCs. Copper appears to be a reasonable indicator for metals contamination in this area. The highest levels of contamination were generally found at or above the soil clay interface. The clay layer appears to be a barrier to downward migration of metals.

The TCL volatile specie toluene was measured in two samples at concentrations of 8 μ g/kg and 12 μ g/kg. Since these values are only slightly elevated above CRDL, and toluene was not detected without flags in any other site soil sample, toluene is not considered a significant of concern. No other TCL organic species were detected without flags in this area.

Grid Area RST-01234

The TAL species Al, Cr, Cu, Ni and Zn were measured in concentrations above their respective BCs. However, greater than 95% of these values are in the cluster of measurements which are slightly elevated above BC. The highest levels of contamination were generally found at or above the soil clay interface. The clay layer appears to be a barrier to downward migration of metals.

The TCL volatile species trichloroethene, 1,1,1-trichloroethane and/or chlorobenzene were measured in nine samples from this area. Chlorobenzene was detected in only one sample (14 μ g/kg) collected during the Remedial Investigation; therefore it is reasonable to assume that this detection is an artifact or an isolated detection. Chlorobenzene is not considered a contaminant of concern within this grid or at the site. The other two volatile organic compounds were measured at concentrations between 7 μ g/kg and 350 μ g/kg.

4.4.2 Groundwater

Groundwater investigations were divided into three zones, shallow, intermediate and deep. Remedial Investigation data presented in Sections 3 and 4 of this report confirm that these are distinct zones as evidenced by the presence of clay layers, variability in flow direction and gradient, and differences in hydraulic potential. Therefore, it is appropriate to continue discussion of groundwater in terms of three distinct zones.

Shallow Saturated Zone

The TAL species detected in shallow groundwater were Al, Ag, Ca, Cr, Cu. Fe, Mg, Mn, K, Na, and Zn. Al, Ca, Fe, Mg, Mn K and Na are commonly occurring cations in groundwater. Since no groundwater background location has been established, there is no basis for identifying these species as contaminants at this time. However, based upon evaluations of general concentration trends, SW-5 has levels of Na, Mn, Ca, and K that may be significantly elevated; SW-8 has levels of Na, Mg, Mn, and Ca that may be significantly elevated; SW-20 has an aluminum level that may be significantly elevated; and SW-22 has levels of Al, Mg and Ca that may be significantly elevated.

Silver was only detected in SW-20, east of the Target Wetland. The groundwater flow direction in the shallow aquifer and the absence of silver in any other water sample indicates that the silver detected in SW-20 is not related to the Hi-Mill site. However, groundwater flow direction in the vicinity of SW-20 indicates that potential sources of this species would be toward the east, in the general vicinity of Numatics, Inc.

Chromium was the most frequently detected metal in the shallow aquifer. It was measured at elevated levels in three shallow wells between the production building and the Target Pond and in SW-15 southwest of the Target Pond. Copper was only detected in two wells, located between the production building and the Target Pond. Zinc was detected in two wells, one located between the production building and the Target Pond and one (SW-20) located east of the Target Wetland. The groundwater flow direction in the shallow aquifer indicates that the zinc detected in SW-20 is not related to the Hi-Mill site. However, groundwater flow direction in the vicinity of SW-20 indicates that potential sources of this species would be toward the east, in the general vicinity of Numatics, Inc. These results indicate that contamination of the shallow zone of saturation is generally confined to the area between the production facility and the Target Pond.

Several TCL volatile organics were detected in shallow monitor wells; however, no extractable TCL organic species were measured. Based upon the types of chemicals used at the Hi-Mill site, chemical analysis flags, identification of common laboratory artifacts, and the infrequent detection, the following species were eliminated from consideration as potentially significant contaminants: methylene chloride, acetone, toluene, and 2-butanone. Trichloroethene, 1,2-dichloroethene (total), and vinyl chloride are considered potentially significant contaminants based upon concentrations and frequency of detections. These contaminants were detected in five wells, and their distribution appears consistent with the direction of groundwater flow and known areas of chemical use or handling. Sampling and analysis of additional shallow wells for TCL volatile organics has been recommended in the Technical Memorandum for the planned confirmatory groundwater sampling event to further identify the extent of this contamination.

Intermediate Aquifer

The TAL species detected in groundwater samples from monitor wells in the intermediate aquifer were Ba, Ca, Cr, Fe, Mg, Mn, K, Na and V. Ba, Ca, Fe, Mg, Mn, K and Na are commonly occurring cations in groundwater. Since no groundwater background location has been established, there is no basis for identifying these species as contaminants at this time. Chromium was identified in IW-1 and IW-3, both of which appear to be hydraulicly downgradient of the Hi-Mill former lagoons. Vanadium was only detected in IW-5 and is not thought to be a contaminant of concern based upon its absence in the shallow aquifer and the fact that IW-5 appears to hydraulically upgradient of the Hi-Mill facility.

Four TCL volatile organic species (toluene, methylene chloride, acetone, and 2-butanone) were detected in samples from the intermediate aquifer. Based upon the types of chemicals used at the Hi-Mill site, chemical analysis flags, identification of common laboratory artifacts, and the infrequent detection, all of these species were eliminated from consideration as potentially significant contaminants.

Deep Aquifer

No TAL inorganics contaminants of concern were detected in samples from the deep aquifer. Several TCL volatile organic species (toluene, methylene chloride, acetone, and 2-butanone) were

detected in samples from the deep aquifer. Based upon the types of chemicals used at the Hi-M i I I site, chemical analysis flags, identification of common laboratory artifacts, and the infrequent detection, all of these species were eliminated from consideration as potentially significant contaminants.

Surface Water and Sediments

The TAL short list metal species detected in surface water were Al and Cr. Hexavalent chromium was not detected in any surface water sample; therefore, the chromium detected in surface water was trivalent. Aluminum was only detected at TP-9. Chromium was only detected at TP-1. These sample points are north of M-59 and in the southernmost end of the Target Wetland, respectively. These data indicate that metals contamination of surface waters near the Hi-Mill site is not of concern.

The TAL short list metals species detected in sediments were Al, Cr, Cu, and Zn. Hexavalent chromium was not detected in any sediment samples. Aluminum was found to be elevated in all sediment samples collected from the Target Wetland and slightly elevated in one sample from Waterbury Lake (WL-02).

Elevated levels of chromium in the Target Pond were found in samples collected from the uppermost sediment layer along the shore nearest the Hi-Mill facility (TP-4, TP-7, and TP-8). Elevated levels of chromium were also found in one sample collected at TP-2 in an isolated wet area near Numatics, Inc. Samples from underlying sediments were found to not contain chromium at elevated levels, thus indicating that there is rapid attenuation of concentration with respect to sediment depth. Slightly elevated levels of chromium was detected in Waterbury Lake (WL-1). Since hexavalent chromium was not detected in sediment samples, all elevated chromium levels in sediments are trivalent chromium.

Elevated levels of copper in the Target Wetland were found in the shallow sediments at eight sample points (TP-4, TP-5, TP-6, TP-7, TP-8, TP-9, TP-10 and TP-12). These points are evenly distributed across the Target Wetland. Samples from underlying sediments were found to not contain copper at elevated levels, thus indicating that there is rapid attenuation of concentration

with respect to sediment depth. Elevated copper was also measured in one sample (WL-01) from Waterbury Lake.

Zinc was found to be slightly elevated in only one shallow sediment sample (TP-8). This single data point is insufficient to make zinc a contaminant of concern in the Target Wetland.

The three detections of elevated metals in sediments of Waterbury Lake were aluminum at WL-02, chromium at and copper at WL-01. Aluminum and chromium are only slightly elevated. WL-2 is in the isolated northern arm of Waterbury Lake. Therefore, there is insufficient evidence to indicate that any contaminants of concern are present in the main body Waterbury Lake.

5.0 CONTAMINANT FATE AND TRANSPORT

5.1 Potential Routes of Migration

Potential routes of migration include routes for both translocation within a given media type or transfer between media types. Potential migration routes within soils are expected to require either actual translocation of soil particles or transfer from either air or water. Soil particle translocation can occur as a result of the action of wind, surface water, and human or animal activities. Only potential human activities are considered significant. Surfaces are generally vegetated and no indication of wind erosion or transport was observed during the Remedial Investigation. It is possible that volatile species could be transported in the vapor phase through subsurface soils. Vapor transport is expected to be driven primarily by diffusion or density. Surface water drainages are poorly developed at the site and all site soils are considered to have poor runoff. Therefore, the potential for soils transport by surface water is considered minimal. No indication of large burrowing animals were observed during the Remedial Investigation, however, several large ant hills were noted during the Remedial Investigation. Contaminant migration, as a result of soil particle translocation, is expected to be minimal unless related to hypothetical human activities.

Groundwater is a potential route for contaminant migration. All species detected in groundwater are expected to be transported in the general direction of groundwater flow at a rate equal or less than the rate of groundwater movement. Retardation of dissolved species may be significant for both metals and volatile organic compounds. Soluble species in other media may reach groundwater via infiltration and subsequently be mobilized with groundwater. Fluctuations of shallow groundwater levels may result in the dissolution of soluble species present in soils within the zone of fluctuation. soil. Groundwater is in direct communication with surface water in the Target Wetland and probably with surface water in Waterbury Lake, and may contribute dissolved species to either surface water or sediments. However, groundwater transport typically results in concentrations that are lower than the concentrations present in the groundwater.

Surface water bodies within the study area have no external drainage except for the small wetland across from Waterbury Lake and north of M-59. Surface runoff within the study area is generally limited. Small drainages are present south and west of the Hi-Mill fence. These were sampled during the Remedial Investigation as they have the potential to be routes of transport for dissolved species. Surface water within the wetlands may leach soluble species from sediments or soils which may then be translocated through either advection or dispersion.

5.2 Contaminant Persistence

Five metals (aluminum, chromium, copper, nickel and zinc) and four volatile organic compounds (trichloroethene, 1,2-dichloroethene, vinyl chloride and 1,1,1-trichloroethane) have been identified as potential contaminants of concern. Contaminant persistence for these metals and volatile organics are discussed below.

The metals of concern are expected to persist unless dissolved and transported by water. The extent or rate of this dissolution and transport in not known at the Hi-Mill site. Metals may be immobilized in soils as a result of fixation within soil minerals or adsorption onto soil surfaces. Fixation reactions may involve chemisosorption, solid state diffusion or precipitation of minerals. Adsorption by cation adsorption, often associated with organic materials, is known to occur for all five metals of concern. The Soil Chemistry of Hazardous Materials by James Dragun reports the observed range of adsorption coefficients (Kd) for three of these five metals. The adsorption coefficient ranges (mg/l) are as follows: trivalent chromium (470 to 150,000); copper (1.4 to 333); and zinc (0.1 to 8,000). Element mobility in soils may vary over a wide range and is controlled by soil physical and chemical properties.

The four volatile organic compounds of concern are not expected to persist in the environment due to volatilization and degradation. Microbes are known to be able to strip chlorines from three of these chlorinated hydrocarbons. Numerous literature sources site typical degradation sequences from 1) 1,1,1-trichloroethane to 1,2-dichloroethene (total), 1,1-dichloroethene or 1,1-dichloroethane and then to vinyl chloride and 2) trichloroethene to 1,2-dichloroethene (total) and then to vinyl chloride. Vinyl chloride is not thought to be easily degraded by microbes but is susceptible to hydrolysis has a high volatility and rapidly degrades in the atmosphere. Each of these volatile organic compounds are adsorbed to soil particles especially organic carbon. The following physical and chemical properties that are expected to affect relative persistence are reported for the four volatile organics of concern:

Water solubility (mg/l): trichloroethene 1100; 1,2-dichloroethene 600 to 800; vinyl chloride

2,670; and 1,1,1-trichloroethane 720

Vapor pressure (torr): trichloroethene 58; 1,2-dichloroethene 200 to 360; vinyl chloride 2580;

and 1,1,1-trichloroethane 100.

Octanol/water

1,1,1-trichloroethene 120; 1,2-dichloroethene 59; vinyl chloride 57;

partion coefficient (mg/l):

and trichloroethane 152.

5.3 Contaminant Migration

Historic activities at the Hi-Mill site may have resulted in transport of contaminants via several pathways. Overflows of the removed lagoons may have transported metals directly onto soils and into the Target Wetland. Spray evaporation of lagoon water may have resulted in the airborne migration of metals. Infiltration of water from the removed lagoons may have resulted in groundwater transport of metals. The only significant route of transport thought to currently be active is groundwater migration. Groundwater migration is suspected to be transporting dissolved metals and volatile organics in the shallow groundwater.

DRAFT ENDANGERMENT ASSESSMENT

HI-MILL MANUFACTURING COMPANY HIGHLAND, MICHIGAN

6.0 BASELINE RISK ASSESSMENT

6.1 Introduction

6.1.1 Purpose and Scope

This report presents the results of a baseline risk assessment that was performed in conjunction with a Remedial Investigation conducted at the Hi-Mill CERCLA site between November 6, 1989 and May 11, 1990. The objective of the study is to define and to evaluate the ecological and human health risks associated with the inorganic and organic contaminants found within the site soils, groundwater, surface water and sediments. Information obtained during the human health and ecological evaluations for the baseline risk assessment will be used during the Remedial Investigation/Feasibility Study for the purpose of ensuring that the selected remedy will be protective of human health and the environment.

Information developed for the baseline risk assessment includes: identification of the hazardous substances present at the site; assessment of exposure and exposure pathways; the environmental fate and transport of the hazardous substances present; assessment of the toxicity of the hazardous substances present; characterization of the human health risks present and characterization of the impacts and/or risks to the environment.

6.1.2 Contents of the Baseline Risk Assessment

The baseline risk assessment consists of an evaluation of human health risks, involving assessment of exposure, chemical toxicity and characterization of risk under current and alternate future site

conditions, evaluation of ecological impacts and a summary and conclusions section in which the results of the risk assessment are discussed in relation to recommended remedial action objectives. Risk assessment procedures used in the study followed evaluation methodologies discussed in "Risk Assessment Guidance for Superfund. Volume 1. Human Health Evaluation Manual, Part A", United States Environmental Protection Agency, Washington, DC, December, 1989.

Section 6.2 presents the following results of the exposure assessment: nature and extent of contamination; identification of the contaminants of concern for the site; the exposure pathways which exist at the site; analysis of the exposed populations; reasonable maximum expected levels of contaminants of concern and the estimated chemical intakes for each of the four media (soils, groundwater, surface water and sediments). Reasonable maximum exposure concentration for site-related inorganic chemicals were based upon the geometric mean of all sample concentrations for each analyte. For organic parameters, the maximum measured concentration was used in estimating chemical intake.

Section 6.3 presents a toxicity assessment for the contaminants of concern. Toxicity data is gathered from approved sources (i.e., the Integrated Risk Information System, Health Effects Assessment Summary Tables and the Agency for Toxic Substances and Disease Registry) and is used in evaluation of the carcinogenic and non-carcinogenic effects of site-related chemicals.

Section 6.4 presents a discussion of the risk characterization for the site in which information from the toxicity and exposure assessments is organized and used to quantify pathway risks for each substance, and to determine the total cancer risk and non-cancer hazard index for each pathway and across pathways.

Section 6.5 presents the results of the evaluation of environmental/ecological risks resulting from the presence of contaminants identified in the Remedial Investigation.

Section 6.6 provides a summary of the findings of the baseline risk assessment and the human health risks associated with the nature and extent of contamination found at the site. Data limitations and recommendations for future work and for remedial action objectives are presented.

6.2 Exposure Assessment

6.2.1 Site Soils: Nature and Extent of Contamination

Table 6-1 presents a summary of the soils sample results by sample depth and includes the following: number of soil samples collected by parameter group; range of quantitation limits for each analyte of concern; range of detected concentrations and frequency of detection.

A soils master data table is presented as Appendix C. The soils master data table includes sample ID, ENCOTEC laboratory ID number, descriptions of soils type, sample collection date, boring east location coordinate, boring north location coordinate, and sample type.

The identification of site-related inorganic contaminants of concern was based on presence at concentrations above background criteria (BC). The background criteria was determined from the chemical analysis data from the representative background samples collected during the RI. A preliminary evaluation of the analysis data for the ten (10) background samples indicated that both samples collected at BG2 and one sample (BG4-1) collected at BG4 were not representative because the concentrations of several metals were clearly higher than the general trend observed in all other samples. BG2, being proximate to the manufacturing building, is assumed to have been impacted by site activities. The sample from BG4-1, while not proximate to site activities, was observed in the laboratory to have significantly different soils characteristics when compared to the other samples. The analysis data from these three (3) apparently non-representative samples were omitted from all background calculations.

Analysis data from the seven (7) representative samples were used to determine the BC. The BC was established as the mean, at the 95% confidence interval (mean value plus two (2) standard deviations) of all measurements for a given analyte. When the analysis results were reported as below detection limit (U flag), the value of the detection limit and zero (0) were alternated in the mean calculation. In other words, the detection limit value was used for the first "U" flagged result encountered, zerowas entered for the next "U" flagged value, the detection limit value was used for the next "U" flagged result encountered, etc. The results from foreground sample analyses were then compared to the BC to determine which contaminants were present at elevated levels. This data then revealed the contaminants of concern and the extent of contamination.

TABL. ...I SOILS (mg/kg)

	Inorganic Chemicals of Concern (mg/kg)								Organic Chemicals of Concern (mg/kg)			
⊃bemical .	Aluminum	Caromium	Copper	Nickel	Sliver	Zinc	Lead	Vinyl Chloride	Trichioroethylene	1,2-Dichloroethylene	I,I,I Trichioroethane	
iurface												
No. of Samples	91	91	91	91	91	91	8 (Site)	25	ಚ	25	25	
No. of Pield	4	4	4	4	4	4	0	0	0	0	0	
Duplicates												
Frequency of	91	91	80	91	91	91	8	0	10	1	1	
Detection												
Range of Sample			2.40-3.60		2.20-22.0		2.00	0.012	0.006	0.006	0.002	
Quantitation Limits												
Range of Detected	3490-25900	4.50-4420	4.10-5010	5.90-33.30		22-844	17.5-60.0	ND	0.007-0.043	0.140	0.140	
Concentrations												
Depth 2												
No. of Samples	17	17	17	17	17	17	5	21	21	21	21	
No. of Field	0	0	0	0	0	0	1	2	2	2	2	
Duplicates												
Prequency of	16	17	16	17	1	17	6	0	3	0	0	
Detection												
Range of Sample			2.2		2.00-2.3		2.0	0.012	0.006	0.006	0.002	
Quantitation Limits Range of Detected	2 (10 27 100	43.415	603600	0 4 14 4	4.4	100.007	4.433.5					
Concentrations	2,610-27,100	6.2-615	5.9-2,500	8.6-34.6	4.6	19.9-89.7	4.4-22.5		0.002-0.041			
											,	
Depth 3												
Soil/Clay Interface												
No. of Samples No. of Field	39 0	39 0	39 0	39 0	39 0	39	0	38	38	38	38	
Duplicates	v	v	•	v	v	0	0	0	0	0	0	
Prequency of	39	39	6	39	1	39	0	0	7	2	1	
Detaction		•	•	•	-	3,	v	•	•	•	•	
Range of Sample	_	_	2.3-2.6		2.1-2.2	_	_	0.012	0.006	0.006	0.002	
Quantiation Limits												
Range of Detected	6,440-22,500	5.7-1,620	4.7-4,400	4.9-33	33.70	17.6-244		_	0.002-0.24	0.002-0.130	0.011	
Concentrations												
Below S/C												
Interface												
No. of Samples	27	27	27	27	27	27	0	63	63	63	63	
No. of Field	2	2	2	2	2	2	0	0	0	0	0	
Duplicates												
Prequency of	29	29	6	29	0	29	o	0	13	8	O	
Detection												
Range of Sample	_	_	23-2.5	~	2.1-2.3		~	0.012			0.001-0.002	
Quantitation Limits Range of Detected	6,520-14,500	12 2 24 9	64.004	10 8 20 4		27.440.4						
Concentrations	0,220-14,300	13.3-26.8	5.4-42.4	10.8-30.6	_	27.6-59.1			0.001-5.7	0.009-0.098		
CONCINCTION												

Short List Metals

Short list metal concentrations in background samples, including mean background concentrations and standard deviations are presented in Table 4-1 of the Draft Remedial Investigation Report.

Table 4-2 of the Draft Remedial Investigation Report presents soils analyses with short list metal concentrations above mean background concentrations plus two standard deviations.

For copper, the mean background concentration is 4.3 mg/kg, the maximum background concentration is 7.5 mg/kg and that the BC is 8.33 mg/kg. There are 107 foreground locations above 8.33 mg/kg. There are 9 locations above 900 mg/kg. These nine locations of highest concentration are L3, M3, M4, H7, I5, H3/I3, I5-2, L3-2 and H7-2. An isoconcentration map showing the spatial distribution of copper in shallow soil samples is presented in Figure 4-1.

For chromium; the mean background concentration is 14.09 mg/kg, the maximum background concentration is 45.2 mg/kg, and that the BC is 39.7 mg/kg. There are 31 stations above 39.7 mg/kg. The highest concentration is 4420 mg/kg (M3-0). An isoconcentration map showing the spatial distribution of chromium in shallow soils is presented in Figure 4-2.

For zinc; the mean background concentration is 30.30 mg/kg, the highest background concentration is 70.2 mg/kg, and that the BC is 63 mg/kg. There are 38 stations above 63 mg/kg. The 4 highest detections are K6-0 (844 mg/kg), B1-0 (834 mg/kg), J5-0 (573 mg/kg), and E2-0 (350 mg/kg). It should be noted that the results of duplicate analysis for B1-0D (B1-0) is only 259 mg/kg.

For aluminum; the mean background concentration is 8054 mg/kg, the highest background concentration is 26,400 mg/kg and that the BC is 23,174 mg/kg. Six locations have values above 23,174 mg/kg. The highest concentration is 27,100 mg/kg at both H-7 and I-7.

For nickel; the mean background concentration is 11.26 mg/kg, the highest background concentration is 50.2 mg/kg and that the BC is 43.1 mg/kg. No locations (except for background location BG-4-1) are above 43.1 mg/kg.

For silver; the mean background concentration is 2.27 mg/kg, the highest background concentration is 2.4 mg/kg and that the BC is 2.51 mg/kg. The highest concentration is 3.80 mg/kg in K6-0. All analyses results have UN flags except L4-0 which only has a U flag.

TAL Inorganics

The identification of contaminants of concern was based on presence at concentrations above background criteria (BC). The background criteria was determined from the chemical analysis data from the representative background samples collected during the RI. A preliminary evaluation of the analysis data for the ten (10) background samples indicated that both samples collected at BG2 and one sample collected (BG4-1) at BG4 were not representative because the concentrations of several metals were clearly higher than the general trend observed in all other samples. BG2, being proximate to the manufacturing building, is assumed to have been impacted by site activities. The sample from BG4-1, while not proximate to site activities, was observed in the laboratory to have significantly different soils characteristics when compared to the other samples. The analysis a from these three (3) apparently non-representative samples were omitted from all backgrous it calculations.

Analysis data from the seven (7) representative samples were used to determine the BC. The BC was established as the mean, at the 95% confidence interval (mean value plus two (2) standard deviations) of all measurements for a given analyte. When the analysis results were reported as below detection limit (U flag), the value of the detection limit and zero (0) were alternated in the mean calculation. In other words, the detection limit value was used for the first "U" flagged result encountered, zero (0) was entered for the next "U" flagged value, the detection limit value was used for the next "U" flagged result encountered, etc. The results from foreground sample analyses were then compared to the BC to determine which contaminants were present at elevated levels. This data then revealed the contaminants of concern and the extent of contamination.

Table 4-3 of the RI report shows the mean background concentrations and background criteria for each of the 24 target analytes at 9 sample locations. All measurements of Sb, Hg, Se, Ag, Na, Tl, and CN were less than or equal to the respective background criteria. As, Be, Cd and Mn have two or less excedances above their respective background criteria.

Lead has three excedances above the BC level. These are concentrations of 60.0 mg/kg (G7-0), 22.5 mg/kg (I4-2) and 21.1 mg/kg (C4), which exceed 16.82 mg/kg (BC).

Barium, calcium, iron magnesium, potassium and vanadium and previously discussed short list metals had more than three excedances above their respective BC. Vanadium, barium, iron and

aluminum concentrations appear to vary in a related manner. No clear relationship is obvious for the other potentially elevated analytes.

TCL Volatile Organics

Samples for TCL volatile organic analyses in soils were obtained at I4-2 and G4-2 and within the RST-01234 and VWXYZ-012 grids, as shown on Figure 2-3. Detections of TCL volatile organics without B, J or BJ flags are presented in Table 4-4.

Acetone, methylene chloride, and toluene were detected in I4-2 at concentrations of 0.015, 0.006 and 0.007 mg/kg, respectively. Methylene chloride, toluene and trichloroethene were detected in G4-2 with B and J flags. No other volatile organic compounds were detected outside of the RST-01234 and VWXYZ-012 grids.

The RST-01234 grid had unflagged volatile organic compounds detected in samples from all 8 sample points. Volatile organic compounds detected were methylene chloride, toluene, acetone, xylene (total), trichloroethene, 1,2-dichloroethene (total), 1,1,1-trichloroethane, ethylbenzene, chlorobenzene, and 2-butanone. Methylene chloride, toluene, xylene, ethylbenzene and 2-butanone are only reported in analyses with B, J, or BJ flags. The number of unflagged detections per compound were: trichloroethene, 10; 1,2 dichloroethene (total) 4; 1,1,1 trichloroethane 2; chlorobenzene, 1; and acetone, 1. Volatile organic compounds reported present without B, J or BJ flags with highest concentrations in parentheses were: trichloroethene (0.350 mg/kg), 1,2 dichloroethene (0.041 mg/kg), 1,1,1-trichloroethane (0.140 mg/kg), chlorobenzene (0.014 mg/kg) and acetone (0.086 mg/kg).

Unflagged volatile organic compounds were detected at five of seven locations in the VWXYZ-012 grid. The following volatile organic compounds were detected: trichloroethene, 1,2- dichloroethene (total), acetone, methylene chloride, toluene, 2-butanone, 1,1,1-trichloroethane, 1,1,2,2-tetrachloroethane, 1,1,2 trichloroethane, and chlorobenzene. Chlorobenzene, 2-butanone, 1,1,1-trichloroethane, 1,1,2,2-tetrachloroethane, and 1,1,2-trichloroethane are only reported in analyses with B, J, or BJ flags. The number of unflagged detections for each compound was: trichloroethene, 15; 1,2-dichloroethene (total), 5; acetone, 2; methylene chloride 1; and toluene 3. The following volatile organic compounds (with highest concentration in parentheses) were detected without J, B,

or JB flags: trichloroethene (57 mg/kg), 1,2-dichloroethene (total) (0.140 mg/kg), acetone (0.065 mg/kg), methylene chloride (0.012 mg/kg) and toluene (0.015 mg/kg).

TCL Organics

Reported detections for extractable (BNA), PCB and pesticide fractions are presented in Table 4-5 for both background and non-background locations. Compounds detected in both background and non-background locations were di-n-butylphthlalate; and bis(2-ethlylhexyl)phthalate. Samples detected only in background were dibenz(a,h)anthracene; benzo(b)fluoranthene; fluoranthene; benzo(a)pyrene; indeno(1,2,3-cd)pyrene; butyl benzyl phthalate; benzo(a)anthracene; benzo(g,h,i)perylene; chrysene; phenanthrene; and pyrene. No compounds were detected in non-background locations without J flags. The only TCL organic compound (excluding voladle organic compounds discussed above) detected without B, J or BJ flags in any sample was bis(2-ethylhexyl)phthalate in one background sample. Reported background levels were 0.590 mg/kg.

6.2.2 Groundwater: Nature and Extent of Contamination

A groundwater master data table is presented as Appendix D. The groundwater master data table includes sample ID, ENCOTEC laboratory ID number, partial descriptions of aquifer type, bottom of screen depth, sample collection date, project east location coordinate, project north location coordinate, top of screen elevation, and sample type.

Table 6-2 presents a summary of the sample results for the three aquifers investigated that includes number of water samples collected by parameter group, range of quantitation limits for each analyte of concern, and range of detected concentrations and frequency of detection.

Inorganics

Analyses of groundwater for dissolved TAL inorganics was performed on samples from shallow wells SW-2, SW-5, SW-8 and SW-22 and intermediate wells IW-1, IW-3 and IW-5. Analyses for dissolved short list metals were performed on samples from all shallow wells, intermediate wells, deep wells and in the pre-existing shallow wells EW-1, EW-2, EW-4 and EW-6.

TABLE 6.2 GROUNDWATER (mg·l)

			organic Chemicals c	of Concern (mg/l)				Vola	tile Organic Chemica	ls of Concern (mg/l)	
Chemical	Aluminum	Chromium	Copper	Nickel	Silver	Zinc	l.ead	Vinyl Chloride	Trichloroethylene	1,2-Dichloroethylene	1,1,1 Trichloroethane
Shallow Aquifer											
No. of Samples	26	26	26	26	26	26	1	12	12	12	12
No. of Field	2	2	2	2	2	2	1	3	3	3	3
Duplicates											
Frequency of	2	5	3	0	7	5	0	1	2	7	0
Detection											
Range of Sample	85.00-114.00	7.00-9.00	10.0-11.0	11.0	9.00	5.00-6.00	2.00	0.010-0.100	0.005-0.050	0.005-0.050	0.005-0.050
Quantitation Limits											
Range of Detected	208-648	12.80-45.80	33.80-98-70		14.60	7.20-22.20		0.068	0.014-1.10	0.030-0.360	
Concentrations											
Intermediate Aquifer											
No. of Samples	5	5	5	5	5	5	3	5	5	5	5
No. of Field	0	0	0	0	0	0	0	0	0	. 0	0
Duplicates											
Frequency of	0	2	0	0		0	7	0	0	0	0
Detection											
Range of Sample	85.00-114.00	7.00-9.00	10.00-11.00	11.00-19.00	8.00-9.00	5.00-6.00	2.00	0.010	0.005	0.005-0.050	0.005-0.050
Quantitation Limits											
Range of Detected		16.00-20.70				••	2.50				
Concentrations											
Deep Aquifer											
No. of Samples	3	3	3	3	3	3	0	3	3	3	3
No. of Field	1	1	1	1	1	1	0	0	0	0	0
Duplicates											
Frequency of	0	0	0	0	0	1		0	0	0	0
Detection											
Range of Sample	85.00-114.00	7.00-9.00	10.00-11.00	11.00-17.00	8.00-9.00	5.00-6.00		0.010	0.005	0.005-0.050	0 005 0 050
Quantiation Limits											
Range of Detected						7.70	•	•••			
Concentrations											

A summary table of analytical results for TAL inorganic analyses of groundwater is presented in Appendix K, and a summary of short list metal analysis results is presented in Appendix L. A summary table of ammonia and nitrate/nitrite analysis results is presented as Appendix M.

Short List Metals

Short list metals in groundwater were reported in the following ranges of concentrations: aluminum, from below the detection limit of 85 μ g/l to a maximum concentration of 648 μ g/l (SW-20); chromium, from below the detection limit of 7 μ g/l to a maximum concentration of 45.8 μ g/l (SW-15); copper, from below the detection limit of 10.0 μ g/l to a maximum concentration of 98.7 μ g/l SW-7; nickel, from below the detection limit of 11.0 μ g/l to a maximum concentration of 149.0* μ g/l (SW-15); silver, from below the detection limit of 9.0 μ g/l to a maximum concentration of 14.6N μ g/l (SW-20); and zinc, from below the detection limit of 5.0 μ g/l to a maximum concentration of 22.0 μ g/l (SW-7). All detections of short list metals in groundwater without U, B, and/or N flags are presented in Table 4-6.

TAL Inorganics

TAL inorganics in groundwater were reported in the following ranges of concentrations: aluminum from below the detection limit of 85.00 μ g/l to a maximum concentration of 208 μ g/l (SW-22); antimony, from below the detection limits of 51.0 μ g/l to 56.0 μ g/l; arsenic, all were below the detection limit of 3.0 μ g/l; barium, from below the detection limit of 23.0 μ g/l to a maximum concentration of 59.10B μ g/l in SW-8D; beryllium, from below the detection limits of 1.00 μ g/l to 2.00 μ g/l; calcium, from a minimum concentration of 59,000 μ g/l (SW-2) to a maximum concentration of 305,000 μ g/l (SW-8); chromium, from the detection limit of 9.0 μ g/l to a maximum concentration of 30.20* μ g/l (SW-2); cobalt, from below the detection limits of 9.0 μ g/l to 14.0 μ g/l; copper, from below the detection limits of 10.0 μ g/l to 11.0 μ g/l; iron, from below the detection limit of 29.00 μ g/l to a maximum concentration of 391.00 μ g/l (IW-3); lead, from below the detection limit of 2.00 μ g/l to a maximum concentration of 2.20B μ g/l; magnesium, from a minimum concentration of 18,000 μ g/l (IW-3) to a maximum concentration of 529,000 μ g/l in SW-22; manganese, from a minimum concentration of 49.2 μ g/l (IW-5) to a maximum concentration of 811.00 μ g/l (SW-5); mercury, all were below the detection limit of 0.20 μ g/l; nickel, from below the detection limit of 11.00 μ g/l to a maximum

concentration of 20.30B μ g/l (SW-22); potassium, from a minimum concentration of 905.00B μ g/l (SW-2) to a maximum concentration of 11,500 μ g/l (SW-5); selenium, all were below the detection limit of 1.00 μ g/l; silver, from below the detection limit of 8.00 μ g/l to a maximum concentration of 10.90 μ g/l (SW-8-FB); sodium, from a minimum concentration of 3,450.00B μ g/l (SW-2) to a maximum concentration of 579,000 μ g/l (SW-22); thallium, all samples were below the detection limit of 4.00 μ g/l; vanadium, from below the detection limit of 8.00 μ g/l to a maximum concentration of 1090B μ g/l (IW-5); zinc, from below the detection limits of 5.00 μ g/l to 6.00 μ g/l; and cyanide, from below detection limit of 10.00 μ g/l to a maximum concentration of 37.00 μ g/l (SW-5).

Ammonia and Nitrate/Nitrite

Ammonia and nitrate/nitrite analyses were performed on groundwater from SW-1, SW-2, SW-3, SW-4, SW-5, SW-6, SW-8, SW-10, SW-11, SW-12, SW-14, SW-15, SW-17, SW-18, SW-19, SW-20, and SW-21. Ammonia concentrations ranged from below the method detection limit of 50.00 μ g/1 to 2200.00 μ g/1 in SW-22. All reported ammonia analyses had A and C flags. Nitrate plus nitrite concentrations ranged from below the method detection limit of 50.00 μ g/1 to 16,000 μ g/1 in SW-5. All reported nitrate plus nitrite analyses had A and C flags.

TCL Volatile Organics

TCL volatile organic compounds were analyzed in groundwater samples from shallow wells SW-1, SW-2, SW-3, SW-4, SW-5, SW-6, SW-8, SW-10, SW-11, SW-12, SW-20, SW-22; intermediate wells, IW-1, IW-2, IW-3, IW-4, IW-5; and deep wells DW-1, DW-2 and DW-3. A summary of all analytical results above detection limits is presented in Appendix J. TCL volatile organic compounds detected above the detection limits are presented in Table 4-7 of the RI report. The samples in which volatile organics were detected were as follows: trichloroethene, SW-1 and SW-3; 1,2 dichloroethene (total), SW-3, SW-5, SW-5D, SW-10, SW-10D, SW-10MS; vinyl chloride, SW-3; methylene chloride, DW-3, IW-2, IW-5, SW-22, SW-22D, SW-22FB, and MW-TB. The highest concentration and location are: trichloroethene (1,100 μ g/1 in SW-1), 1,2 dichloroethene (total) (360 μ g/1 in SW-1), vinyl chloride (68 μ g/1 in SW-3), methylene chloride (29 μ g/1 in SW-22FB), and acetone (11 μ g/1 in MW-TB).

TCL Organics

TCL organic analyses were performed on groundwater from SW-2, SW-2D, SW-2FB, SW-5, SW-8 and IW-1. Di-n-butyl phthalate (8 μ g/l in SW-2) was the only base-neutral or acid extractable compound detected in groundwater samples. Pesticides and PCB analyses were not performed on groundwater samples.

6.2.3 Surface Water: Nature and Extent of Contamination

A surface water master data table is presented as Appendix A. The surface water master data table presents station, sample ID, ENCOTEC sample ID number, sample collection date, project east location coordinate, project north location coordinate, elevation and sample type for each surface water sample point.

Table 6-3 presents a summary of the sample results for the three surface water bodies investigated during the RI (i.e., the Background Pond (BP), Waterbury Lake (WL) and the Target Pond (TP)) that includes the following: number of water samples collected for each parameter group; number of water samples collected by parameter group; range of quantitation limits for each analyte of concern; range of detected concentrations and frequency of detection.

Inorganics

Analyses for short list metals were performed on samples from BP-1, BP-2, BP-3, TP-1, TP-4, TP-4FB, TP-10, TP-10D, WL-1 and WL-2. TAL inorganic analyses were performed on BP-4, TP-2, TP-7, TP-7D, TP-11, TP-11D, and TP-11FB. Ammonia and nitrate plus nitrite analyses were performed on BP-1, BP-2, BP-3, BP-4, TP-7, TP-7D, TP-10, and WL-2. Hexavalent chromium analyses were performed on samples from BP-1, BP-2, BP-3, BP-4, TP-1, TP-2, TP-2FB, TP-4, TP-4DTP-7, TP-9, TP-10, TP-10D, TP-11, WL-1, and WL-2.

TABLE 6.3
SURFACE WATER

				Inorgani	c Chemicals	of Concern	(mg/l)	
Chemical		Aluminum	Chromium	Copper	Nickel	Silver	Zinc	Lead
Surface								
No. of Samples:	BP	4	4	4	4	4	4	1
	TP	7	7	7	7	7	7	3
	WL	2	2	2	2	2	2	0
No. of Field		2	2	2	2	2	2	1
Duplicates								
Frequency of		1	5	3	0	1	8	2
Detection								
Range of Sample		85.00	7.00	10.00	11.0	9.0	6.0	2.0-10.0
Quantitation Limits								
Range of Detected		5360	9.3-38.5	13.00-21.4		12.5	12.40-15.7	3.1-10.0
Concentrations								

BP = Background Pond

TP = Target Pond

WL = Waterbury Lake

Short List Metals

Short list metals in surface water had the following range of concentrations and sample quantitation limits reported: aluminum below the detection limit of 85.00 μ g/l for all samples except TP-9 (5360 μ g/l); chromium, below the detection limit for all samples except TP-1 (13.00 μ g/l); copper, below the detection limit for all samples except BP-1 (19.50 BN) and TP-10 (21.40); nickel, below detection limit of 19.00 μ g/l for all samples; silver, from below the detection limit of 9.00 μ g/l to a maximum concentration of 12.50N μ g/l in BP-2; and zinc, from below the detection limit of 6.00 μ g/l and a maximum concentration of 16.20B μ g/l in TP-10D.

TAL Inorganics

The following TAL inorganics were below detection limits in all surface water samples (limits in parentheses): aluminum (85.00 μ g/l); arsenic (3.00 μ g/l); barium (42.00 μ g/l); beryllium (1.00 μ g/l); cadmium (2.00 μ g/l); cobalt (14.00 μ g/l); mercury (0.20 μ g/l); nickel (11.00 μ g/l); selenium (1.00 μ g/l); thallium (4.00 μ g/l); vanadium (8.00 μ g/l); and cyanide 10.00 μ g/l). Surface water samples for all locations were below background surface water station BP-4 for antimony (background, 65.40 μ g/l) and zinc (background, 12.40 μ g/l).

TAL inorganic concentrations for all other compounds are presented below for the background sample (BP-4), lowest sample location and highest sample location: calcium, 26500.00 μ g/l (BP-4), 13,300.00 μ g/l (TP-11 FB),and 44,500.00 μ g/l (TP-7); chromium, 9.30* μ g/l (BP-4), 7.00* μ g/l (TP-2), and 38.50* μ g/l (TP-11); copper, less than the detection limit of 10.00 μ g/l for all samples except TP-11 (13.00B μ g/l); iron, less than the detection limit (BP-4), 625.00 μ g/l (TP-11); lead, 3.30 μ g/l (BP-4), less than the detection limit (TP-2), and 7.80 μ g/l (TP-11FB); magnesium, 5050.00 μ g/l (BP-4), less than the detection limit (TP-11FB), and 11,800 μ g/l (TP-7); manganese, 7.30B (BP-4), less than detection limit (TP-11FB), and 378.00 μ g/l (TP-11); potassium, 817.00B μ g/l (BP-4), less than detection limit of 788.00 μ g/l (TP-11FB), and 3880.00B μ g/l (TP-7); silver, less than detection limit of 9.00 μ g/l in all samples except TP-7 (9.10B μ g/l); and sodium, 2620.00B (BP-4), less than detection limit of 1,080.00 μ g/l (TP-11FB), and 26,000.00 μ g/l (TP-7).

Hexavalent chromium was less than the detection limit of 10.00 μ g/l at all surface water locations.

Ammonia and Nitrate/Nitrite

Ammonia analyses were performed on surface water samples from BP-1, BP-2, BP-3, BP-4, and TP-07FB. Nitrate/nitrite analyses were performed on surface water samples from BP-1, BP-2, BP-3, BP-4, TP-7, TP-7D, TP-7FB and WL-2.

Ammonia concentrations ranged from below the detection limit of 50.00 μ g/l to a maximum concentration of 160.00AC μ g/l (BP-1). Nitrate/nitrite concentrations ranged from below the detection limit of 50.00 μ g/l to a maximum concentration of 1200.00AC μ g/l in TP-7FB. The concentration in TP-7FB was considerably higher than the next highest concentration of nitrate\nitrite, 180.00AC μ g/l (BP-1), which was in the background pond.

6.2.4 Sediments: Nature and Extent of Contamination

Table 6-4 presents a summary of the sediment sample results for the three surface water bodies investigated during the RI (i.e., the Background Pond (BP), Waterbury Lake (WL) and the Target Pond (TP)) that includes: number of water samples collected for each parameter group; number of water samples collected by parameter group; range of quantitation limits for each analyte of concern; range of detected concentrations and frequency of detection.

The sediment master data table is presented as Appendix B. The master data table includes sample station number, sample ID number, ENCOTEC laboratory ID number, sample collection date, project east and north coordinates, elevation, and sample type for each sample. Locations of sediment sample points are shown on Figure 2-1 of the RI report.

Inorganics

Short list metals were analyzed at all Background Pond, Target Pond and Waterbury Lake sample locations. A summary of results for those test points that exceded background criteria is presented in Table 4-8. Hexavalent chromium was analysed in samples from locations BP-1, BP-2, BP-3, BP-4, TP-1, TP-4, TP-4-1, TP-5, TP-6, TP-6-1, TP-9, TP-10, WL-1, WL-2, and WL-2D.

TABLE 6.4 SEDIMENTS (mg/kg)

		Inorganic Chemicals of Concern (mg/l)									
Chemical		Aluminum	Chromium	Copper	Nickel	Silver	Zinc	Lead			
Surface											
No. of Samples:	ВР	4	4	4	4	4	4	1			
	TP	17	17	17	17	17	17	3			
	WL	2	2	2	2	2	2	0			
No. of Field Duplicates		3	3	3	3	3	3	1			
Frequency of Detection		26	26	26	26	0	26	5			
Range of Sample Quantitation Limits		7.3-29.80	2.80-42.60	21.80-46.80	2.20-38.30	18.20-25.50					
Range of Detected Concentrations		964-33900	17.30-974	7.00-1860	7.30-41.90	-	41.10-208.00	3.3-20.7			

BP = Background Pond TP = Target Pond

WL = Waterbury Lake

Values for aluminum range from 964 mg/kg to 3610 mg/kg in the Background Pond, from 11,800.00 mg/kg to 33,900.00 mg/kg (TP-2) in the Target Pond, and from 1360.00 mg/kg to 6770.00 mg/kg in Waterbury Lake. All nineteen test points in the Target Wetland and one sample point in Waterbury Lake (WL-02) exceded the BC of 4842 mg/kg.

Values for chromium range from less than detection (20.30U mg/kg) to 37.10 mg/kg in the Background Pond, from 17.30 mg/kg to 256.00 mg/kg (TP-8) in the Target Pond, and from less than detection (7.30U mg/kg) to 51.80 mg/kg in Waterbury Lake. Three test points in the Target Wetland (TP04-0, TP07-0, and TP08-0) and one point in Waterbury Lake (WL01) exceded the BC of 50.65 mg/kg.

Values for copper range from less than detection (28.20U mg/kg) to 37.10 mg/kg in the Background Pond, from 17.30 mg/kg to 256.00 mg/kg in the Target Pond, and from less than detection (10.40U mg/kg) to 486.00 mg/kg in Waterbury Lake. Eight test points in the Target Wetland and one test point in Waterbury Lake (WL01) exceded the BC of 54.91 mg/kg.

Values for nickel range from less than detection (31.00U mg/kg) to less than detection (46.80U mg/kg) in the Background Pond, from 7.30B mg/kg to 41.90 mg/kg (TP-04) in the Target Pond, and from less than detection (21.80U mg/kg) to 28.10B mg/kg in Waterbury Lake. None of the test points exceeded the highest detection limit of the background samples (46.8 mg/kg).

Values for silver were reported below detection limits for all samples.

Values for zinc range from 18.20U mg/kg to 122.00 mg/kg in the Background Pond, from 42.70 mg/kg to 208.00 mg/kg (TP-8) in the Target Pond, and from 56.90 mg/kg to 75.90 mg/kg in Waterbury Lake. One sample point in the Target Pond (TP08-0) exceeded the BC of 162.23 mg/kg.

Analysis results for hexavalent chromium at all sample locations were below the detection limits of 0.10 mg/kg to 2.00 mg/kg.

Ammonia and Nitrate/Nitrite

Ammonia analyses were performed on surface water samples from BP-1, BP-2, BP-3, BP-4, and TP-07FB. Nitrate/nitrite analyses were performed on surface water samples from BP-1, BP-2, BP-3, BP-4, TP-7, TP-7D, TP-7FB and WL-2.

Ammonia concentrations ranged from below the detection limit of 50.00 μ g/l to a maximum concentration of 160.00AC μ g/l (BP-1). Nitrate/nitrite concentrations ranged from below the detection limit of 50.00 μ g/l to a maximum concentration of 1200.00AC μ g/l in TP-7FB. The concentration in TP-7FB was considerably higher than the next highest concentration of nitrate\nitrite, 180.00AC μ g/l (BP-1).

6.2.5 Evaluation and Selection of Chemicals of Concern

Summaries of conclusions based on the Remedial Investigation results are presented in the following paragraphs. Rationale for selection of chemicals of concent to be carried through the risk assessment are presented at the end of this subsection.

Conclusions - Soils

Based upon evaluations of the Remedial Investigation site assessment data presented in Sections 3 and 4 in the RI report, contaminated soils within the investigation area can be divided into three areas for purposes of contamination assessment, risk evaluation and remedial feasibility planning. These areas are the area between the production facility and the Target Wetland, the general vicinity of the small eastern assessment area VWXYZ-012, and the general vicinity of the small western assessment area, RST-01234.

Soils located between the production facility and the Target Wetland were found to contain elevated levels of certain metals. This area appears to be roughly bounded by portions of the sample grid, but has not been fully defined.

Area Between Production Facility and Target Wetland

TAL analytes Ag, As, Be, Cd, Pd, and Mn were all measured at levels greater than their respective BC but in three or fewer samples. These results indicate that these metals are not characteristic of significant site contamination and need not be addressed further. TAL analytes, Al, Ba, Ca, Cr, Cu, Fe, Mg, Ni, K, V and Zn were all measured at levels greater than their repctive BCs in multiple

samples. The most significant site wide contamination is represented by the metals Al, Cr, Cu, Ni, and Zn. There are clearly locations containing significantly elevated concentrations of these metals. However, the areal extent of contamination indicated by the number of results above BC (Table 4-2) may be significantly overstated for these five metals. This statement is based upon a evaluation of the step-shaped distribution of concentrations in foreground samples. For each metal there is a large cluster of results which indicate slight elevation above the BC. There is no basis to assume that the selected background locations include all naturally occuring soil types. This may have resulted in a negative bias in the BC, making the number of excedences unreasonably high.

Chromium and copper appear to be reasonable indicators for the extent of metals contamination. The highest levels of contamination were generally found at or above the soil clay interface. The clay layer appears to be a barrier to downward migration. The locations of highest concentrations generally lie near and immediately southeast of the former lagoons and in the vicinity of grid location L3, L4, M3, and M4.

Grid Area VWXYZ-012

The TAL species Al. Ba. Ca, Cr, Cu, Fe, Mg, Ni, K, V and Zn were measured in concentrations above their respective BCs. Copper appears to be a reasonable indicator for metals contamination in this area. The highest levels of conmtamination were generally found at or above the soil clay interface. The clay layer appears to be a barrier to downward migration of metals.

The TCL volatile specie toluene was measured in two samples at concentrations of 8 μ g/kg and 12 μ g/kg. Since these values are only slightly elevated above CRDL, and toluene was not detected without flags in any other site soil sample, toluene is not considered a significant of concern. No other TCL organic species were detected without flags in this area.

Grid Area RST-01234

The TAL species AI, Cr, Cu, Ni and Zn were measured in concentrations above their respective BCs. However, greater than 95% of these values are in the cluster of measurements which are slightly elevated above BC. The highest levels of communication were generally found at or above the soil clay interface. The clay layer appears to be a barrier to downward migration of metals.

The TCL volatile species trichloroethene, 1,1,1-trichloroethane and/or chlorobenzene were measured in nine samples from this area. Chlorobenzene was detected in only one sample (14 μ g/kg) collected during the Remedial Investigation; therefore it is reasonable to assume that this detection is an artifact or an isolated detection. Chlorobenzene is not considered a contaminant of concern within this grid or at the site. The other two volatile organic compounds were measured at concentrations between 7 μ g/kg and 350 μ g/kg.

Conclusions - Groundwater

Groundwater investigations were divided into three zones, shallow, intermediate and deep. Remedial Investigation data presented in Sections 3 and 4 of this report confirm that these are distinct zones as evidenced by the presence of clay layers, variability in flow direction and gradient, and differences in hydraulic potential. Therefore, it is appropriate to continue discussion groundwater in terms of three distinct zones.

Shallow Saturated Zone

The TAL species detected in shallow groundwater were Al, Ag, Ca, Cr, Cu. Fe, Mg, Mn, K, Na, and Zn. Al, Ca, Fe, Mg, Mn K and Na are commonly occurring cations in groundwater. Since no groundwater background location has been established, there is no basis for identifying these species as contaminants at this time. However, based upon evaluations of general concentration trends, SW-5 has levels of Na, Mn, Ca, and K that may be significantly elevated; SW-8 has levels of Na, Mg, Mn, and Ca that may be significantly elevated; SW-20 has an aluminum level that may be significantly elevated; and SW-22 has levels of Al, Mg and Ca that may be significantly elevated.

Silver was only detected in SW-20, east of the Target Wetland. The groundwater flow direction in the shallow aquifer and the absence of silver in any other water sample indicates that the silver detected in SW-20 is not related to the Hi-Mill site. However, groundwater flow direction in the vicinity of SW-20 indicates that potential sources of this species would be toward the east, in the general vicinity of Numatics, Inc.

Chromium was the most frequently detected metal in the shallow aquifer. It was measured at elevated levels in three shallow wells between the production building and the Target Pond and in SW-15 southwest of the Target Pond. Copper was only detected in two wells, located between the production building and the Target Pond. Zinc was detected in two wells, one located between the production building and the Target Pond and one (SW-20) located east of the Target Wetland. The groundwater flow direction in the shallow aquifer indicates that the zinc detected in SW-20 is not related to the Hi-Mill site. However, groundwater flow direction in the vicinity of SW-20 indicates that potential sources of this species would be toward the east, in the general vicinity of Numatics, Inc. These results indicate that contamination of the shallow zone of saturation is generally confined to the area between the production facility and the Target Pond.

Several TCL volatile organics were detected in shallow monitor wells; however, no extractable TCL organic species were measured. Based upon the types of chemicals used at the Hi-Mill site, chemical analysis flags, identification of common laboratory artifacts, and the infrequent detection, the following species were eliminated from consideration as potentially significant contaminants: methylene chloride, acetone, toluene, and 2-butanone. Trichloroethene, 1,2-dichloroethene (total), and vinyl chloride are considered potentially significant contaminants based upon concentrations and frequency of detections. These contaminants were detected in five wells, and their distribution appears consistent with the direction of groundwater flow and known areas of chemical use or handling. Sampling of additional shallow wells has been recommended for the planned confirmatory groundwater sampling event to futher identify the extent of this contamination.

Intermediate Aquifer

The TAL species detected in groundwater samples from monitor wells in the intermediate aguifer were Ba, Ca, Cr, Fe, Mg, Mn, K, Na and V. Ba, Ca, Fe, Mg, Mn, K and Na are commonly occurring cations in groundwater. Since no groundwater background location has been established, there is no basis for identifying these species as contaminants at this time. Chromium was identified in IW-1 and IW-3, both of which appear to be hydraulicly downgradient of the Hi-Mill former

lagoons. Vanadium was only detected in IW-5 and is not thought to be a contaminant of concern based upon its absence in the shallow aquifer and the fact that IW-5 appears to hydraulically upgradient of the Hi-Mill facility.

Several TCL volatile organic species (toluene, methylene chloride, acetone, and 2-butanone) were detected in samples from the intermediate aquifer. Based upon the types of chemicals used at the Hi-Mill site, chemical analysis flags, identification of common laboratory artifacts, and the infrequent detection, all of these species were eliminated from consideration as potentially significant contaminants.

Deep Aquifer

No TAL inorganics contaminants of concern were detected in samples from the deep aquifer. Several TCL volatile organic species (toluene, methylene chloride, acetone, and 2-butanone) were detected in samples from the deep aquifer. Based upon the types of chemicals used at the Hi-Mill site, chemical analysis flags, identification of common laboratory artifacts, and the infrequent detection, all of these species were eliminated from consideration as potentially significant contaminants.

Conclusions - Surface Water and Sediments

The TAL short list metal species detected in surface water were Al and Cr. Hexavalent chromium was not detected in any surface water sample; therefore, the chromium detected in surface water was trivalent. Aluminum was only detected at TP-9. Chromium was only detected at TP-1. These sample points are north of M-59 and in the southernmost end of the Target Wetland, respectively. These data indicate that metals contamination of surface waters near the Hi-Mill site is not of concern.

The TAL short list metals species detected in sediments were Al, Cr, Cu, and Zn. Hexavent chromium was not detected in any sediment samples. Aluminum was found to be elevated in all sediment samples collected from the Target Wetland and slightly elevated in one sample from Waterbury Lake (WL-02).

Elevated levels of chromium in the Target Pond were found in samples collected from the uppermost sediment layer along the shore nearest the Hi-Mill facility (TP-4, TP-7, and TP-8). Elevated levels of chromium were also found in one sample collected at TP-2 in an isolated wet area near Numatics, Inc. Samples from underlying sediments were found to not contain chromium at elevated levels, thus indicating that there is rapid attenuation of concentration with respect to sediment depth. Slightly elevated levels of chromium was detected in Waterbury Lake (WL-1). Since hexavalent chromium was not detected in sediment samples, the all elevated chromium levels in sediments are trivalent chromium.

Elevated levels of copper in the Target Wetland were found in the shallow sediments at eight sample points (TP-4, TP-5, TP-6, TP-7, TP-8, TP-9, TP-10 and TP-12). These points are evenly distributed across the Target Wetland. Samples from underlying sediments were found to not contain copper at elevated levels, thus indicating that there is rapid attenuation of concentration with respect to sediment depth. Elevated copper was also measured in one sample (WL-01) from Waterbury Lake.

Zinc was found to be slightly elevated in only one shallow sediment sample (TP-8). This single data point is insufficient to make zinc a contaminant of concern in the Target Wetland.

The three detections of elevated metals in sediments of Waterbury Lake were aluminum at WL-02, chromium at and copper at WL-01. Aluminum and chromium are only slightly elevated. WL-2 is in the isolated northen arm of Waterbury Lake. Therefore, there is insufficient evidence to indicate that any contaminants of concern are present in the main body Waterbury Lake.

Selection of Chemicals of Concern

The inorganic chemicals that were identified as site-related chemicals (chemicals of concern), based upon exceedances of the background criteria, and that will be carried through the quantitative risk assessment process include the following four short list metals, copper, chromium, nickel, zinc and one TAL inorganic compound, lead.

All unflagged volatile organic compounds detected in site samples are being considered during the risk assessment except for those chemicals that are common lab contaminants (toluene, methylene chloride, acetone and 2-butanone) since sample concentrations for these chemicals were measured

at less than ten times the maximum amount detected in any blank. Chlorobenzene, which was detected in only one soil sample at a level slightly above its quantitation limit (0.006 mg/Kg), was not included in the risk quantitation process. The presence of this chemical was considered to be a laboratory artifact or isolated anomaly.

The list of volatile organic compounds that will be carried through the risk assessment process includes trichloroethylene, 1,1,1-trichloroethane, vinyl chloride and 1,2-dichloroethylene.

The only TCL organic compound (excluding volatile organic compounds discussed above) detected without B, J or BJ flags in any sample was bis(2-ethylhexyl)phthalate in one background sample. Reported background levels were 0.590 mg/kg. The presence of this chemical is not considered as site-related.

6.2.6 Exposure Pathways

Elevated levels of chemicals of concern were found in the surface and subsurface soils, surface water and sediments in the adjoining Target Pond and Waterbury Lake, and groundwaters in the shallow and intermediate aquifers. No contaminants were found in groundwater in the deep aquifer.

Table 6-5 presents a matrix of potential exposure pathways and potentially affected populations for the Hi-Mill site, identifying those pathways selected for evaluation and providing rationale for selection or exclusion. The following exposure pathways were judged complete for current/alternate future site use:

Dermal Contact with surface soil;

- Incidental ingestion of surface soil;
- Occasional ingestion of surface water by swimmers; and
- Ingestion of groundwater.

Significant risk of exposure was not found to exist for any of the pathways judged complete under current use because of 1) present use of the site is industrial with restricted access to those portions of the facility in which contamination of the surface was identified, 2) the surrounding site vicinity is State-owned recreational land of low recreational interest value, 3) area wells do not rely upon the shallow aquifer as a potable water supply except for possible exposures resulting from ingestion of

TABLE 6-5

MATRIX OF POTENTIAL EXPOSURE PATHWAYS

Current/Future Land Use	Release/ Transport Medium	Exposure Point/ Exposure Route	Residential	Commercial/ Industrial	Recreational	Pathway Selected	Rationale
FU	Groundwater	Shallow Aquifer					
		Incidental Ingestion	U,LP	Ü	U	YES	Contaminants present in shallow and intermediate
		Dermal Contact	U,LP	U	U	NO	aquifers (chromium in intermediate aquifer,
inorganic and VOA	As in shallow)						
CU/FU		Intermediate Aquifer					
		Incidental Ingestion	LP	LP	U	YES	Exposure concentrations not sufficiently elevated
		Dermal Contact	LP	U	U	МО	concern
CU/FU	Surface Water	Target Pond					
		Incidental Ingestion Dermal Contact	U	U	U,LP	YES	
CU/FU	Sediment	Target Pond					
		Incidental Ingestion	U	U	U	NO	Sediments are water covered
		Dermal Contact	ប	U	U	NO	Sediments are water covered
	Air	Hi-Mill Site Inhalation of Vapor Phase and Particulate Che Indoor Outdoors	micals			NO	No Air Monitoring Data
CU/FU	Soil/Dust	Hi-Mill Site					
		Incidental Ingestion	U	U	Ü	YES	
		Dermal Contact	U	U	U		
	Food/Fish, Game	Recreational Area	U	U	U	NO	

LP = Low Probability of Occurrence

U = Exposure Event Unlikely CU/FU = Current/Future Site Use

groundwater from the intermediate aquifer. The maximum measured chromium concentration for samples from the intermediate aquifer (0.021 mg/l) which slightly exceeds the Maximum Contaminant Level of 0.02 mg/l for this chemical. The site is located in a rural and sparsely populated area, with the nearest residences situated one quarter-mile distant. Recreational use of the area is limited hiking and hunting activity. No instances of any events likely to result in exposures of any magnitude or frequency were reported by the Highland Park Manager.

Factors that diminish current exposure through any of the above pathways, include recognition of the following:

- The Hi-Mill site is an industrial facility with restricted access to nearly all portions of the site in which inorganic contamination of the surface soils was discovered. The site is in a rural area, and the probability of exposure, especially for a residential population (i.e. children) is very low. Additional protection would be afforded since the ground surface in the impacted areas is well vegetated;
- 2) Asphalt paving covers those soils found during the RI to be contaminated with volatile organic substances, so that potential for direct contact is minimal except for such activities as building foundation repair or subsurface excavation;
- 3) The Target Pond lying due east and south of the facility is too shallow to support a resident fish population, since winter overkill occurs. This eliminates consumption of fish as a pathway. The target pond does not communicate via surficial channels with the nearby Waterbury Lake;
- 4) The adjoining Target Pond is without a beach or a boat launching area, being ill-suited and undesirable for such recreational uses as boating or swimming activity. Human exposure to substances of concern via ingestion of surface water is, therefore, a highly unlikely, or rarely occurring event.
- 5) As reported by the Highland Park Recreational Area Manager, recreational use in the site vicinity is limited to deer hunting and occasional hiking. The State of Michigan prohibits firing of any shotgun within 450 feet of any residence or building, a prohibition that is likely to discourage close approach during hunting season.

6) Although inorganic and organic chemicals were detected in the shallow aquifer, residential wells in the site vicinity rely upon the intermediate or deep aquifers for a potable water supply.

However, since alternate future land use may be residential, exposure estimates for calculation of chemical intakes in this risk assessment were highly conservative and based upon assumed exposure to a residential population (e.g., daily contact and lifetime exposure).

6.2.7 Exposed Population Analysis: Current Use

The Hi-Mill Site is a small to medium size industrial facility which occupies approximately 4.5 acres. The site adjoins the Highland Recreational Area. Recreational use in the site vicinity is limited to hiking and hunting for deer and wild game. No residential population is located immediately near the site vicinity (fewer than 15 - 20 households are located within a one-half mile radius of the site).

The Hi-Mill Manufacturing Company operates a single eight hour shift, 5 days per week using an adult work force that is includes male and female workers. Plant operations are totally enclosed within the production building and adjoining warehouse. No work activity is conducted south of the building in the vicinity of the former lagoons (i.e., near areas of the site in which the most significant contamination of the surface was identified during the RI).

Human populations potentially currently exposed to the contaminants found at the site would include the adult industrial worker/employee engaged in grounds-keeping or construction activity and the occasional recreational user (hiker/hunter). Potential for exposure under current use would have a low probability due to the unlikelihood of and/or infrequency of contact.

6.2.8 Exposed Population Analysis: Alternate Future Use

Alternate future use of the site may include possible residential development. Baseline risk assessment of the site considers residential exposures for all pathways judged complete.

6.2.9 Intake Estimates: Exposure Concentrations

Table 6-6 presents for each medium/pathway judged complete and chemical of concern detected in the medium/pathway, a list of the exposure point concentrations used in the risk quantitation process. Media for which specific site-related chemicals were found only at levels below background criteria levels are so identified.

Exposure point concentrations used in the intake estimates were 1) a calculated concentration value that estimates the reasonable maximum exposure by using the geometric mean of all sample concentrations and 2) the maximum measured concentration for the media sampled. For media where there was a low equency of detection, the maximum measured concentration was the only exposure point concentration used in the risk calculation process.

6.2.10 Intake Estimates: Factors Used in Predicting Exposures

In the absence of quantative, site-specific data regarding human activity patterns, evaluations for the baseline risk assessment include use of qualitative predictions of contact rate, exposure duration and frequency of exposure. Conservative assumptions regarding contact rates and exposure durations (90 or 95th percentile variable values) were made during the risk characterization process to overestimate the actual risk and to provide an additional margin of protection.

Intake estimates developed for the baseline risk characterization were based upon possible alternate future residential use, with assumed daily exposures and 70 year duration. For the ingestion of surface water while swimming pathway, however, frequency of exposure was estimated at less than 7 days per year (the national average for engaging in swimming activity) and exposure time was estimated at one-half hour per occurrence.

Tables 6-7 through 6-11 present a summary of chemical intakes quantitations resulting from residential exposure through ingestion of chemicals in soils by the adult and child, ingestion of chemicals in drinking water, occasional ingestion of chemicals in surface water while swimming, and dermal contact with chemicals in soils. Equations and the variables used in the calculations of chemical intake estimates were obtained from the "Risk Assessment Guidance for Superfund" document and have been presented in the tables.

TABLE 6.6

Exposure Concentrations

	Chromium MS <rme></rme>	Copper MS <rme></rme>	Nickel MS <rme></rme>	Zinc MS <rme></rme>	Lead MS <rme></rme>	Trichloro- ethylene MS <rme></rme>	Vinyl Chloride MS <rme< th=""><th>1,1,1-Tri- chlorethane MS<rme></rme></th><th>1,2-Dichloro- ethene MS<rme></rme></th></rme<>	1,1,1-Tri- chlorethane MS <rme></rme>	1,2-Dichloro- ethene MS <rme></rme>
Soils (mg/kg)	4,420 <24>	5010 <44.1>	34.6 <12.9>	844 <47.4>	60 <16.8>	0.043 <0.019>	ND	0.140	ND
Shallow Aquifer	0.045 <0.224>	0. 099 <0.067>	ND	0.022 <11.9>	ND	1.1	0.068	ND	0.036
Groundwater (mg/l)									
Intermediate Aquifer	0.021 <0.0182>	ND	ND	ND	ND	ND	ND	ND	ND
Surface Water (mg/l)	0.038 <0.017>	0.021 <0.016>	ND	0.016 <0.012>	ND	NS	NS	NS	NS

Exposure Concentration Values

MS - Maximum Measured Concentration reported in boldface <RME> Indicates Reasonably Expected Maximum Concentration

ND - Not Detected NS - Not Sampled per R1 Workplan

TABLE 6.7

Residential Exposure: Ingestion of Chemicals in Soil by Adult

Chemical	Chemical Concentration (mg/Kg)	Ingestion Rate (mg/Day) Annual Avg.	Conversion Factor 10 ⁴ Kg/mg	Fraction Ingested From Contaminated Source	Exposure Frequency (Days)	Exposure Duration (Years)	1/Body Weight	1/Averaging Time	Chronic Daily Intake mg/Kg-Day
Vinyl Chloride	ND @ Surface	100	10*	1	365	70 years	1/70 kg	1/25,550	
TCE	0.043 <0.019>	100	10⁴	1	365	70 years	1/70 kg	1/25,550	6 x 10' <2.7 x 10'>
1,2-DCE	ND @ Surfaœ	100	104	1	365	70 years	1/70 kg	1/25,550	
1,1,1 TCA	0.140	100	104	1	365	70 years	1/70 kg	1/25,550	2 x 10*
Cr	4,420 <24>	100	104	1	365	70 years	1/70 kg	1/25,550	6.3 x 10 ¹ <3.4 x 10 ⁴ >
Cu	5,010 <44.1>	100	104	1	365	70 years	1/70 kg	1/25,550	7.16 x 10 ¹ <6.3 x 10 ⁴ >
Ni	34.60 <12.9>	100	104	1	365	70 years	1/70 kg	1/25,550	4.9 x 10 ² <1.85 x 10 ⁴ >
Zn	844 <47.4>	100	104	1	365	70 years	1/70 kg	1/25,550	1.2 x 10 ² <6.78 x 10 ⁴ >
Pb	60 <16.8>	100	104	1	36 5	70 years	1/70 kg	1/25,550	8.57 x 10° <2.4 x 10°>

ChemicalConcentration

Maximum Measured Concentration reported in boldface

< > Indicates Reasonably Expected Maximum Concentration

TABLE 6.8

Residential Exposure: Ingestion of Chemicals in Soil by Older Child
(Maximum Measured Concentration)

Chemical	Chemical Concentration (mg/Kg)	Ingestion Rate (mg/Day) Annual Avg.	Conversion Factor 10 ⁴ Kg/mg	Fraction Ingested From Contami- nated Source	Exposure Frequency (Days)	Exposure Duration (Years)	1/Body Weight	1/Averaging Time	Chronic Daily Intake mg/Kg-Day
Vinyl Chloride	0.068	24	104	1	365	4 years	1/20.8 Kg	1/25,550	4.48 x 10 °
TCE: Surface Subsurface	$\frac{0.043}{5.7}$	24	10⁴	1	365	4 years	1/20.8 Kg	1/25,550	$\frac{2.83 \times 10^{9}}{3.76 \times 0^{4}}$
1,2-DCE	0.140	24	104	1	365	4 years	1/20.8 Kg	1/25,550	9.23 x 10°
1,1,1 TCA	0.140	24	104	1	365	4 years	1/20.8 Kg	1/25,550	9.23 x 10°
Cr	4,420 <24.0>	24	104	1	365	4 years	1/20.8	1/25,550	2.43 x 10° <1.32 x 10°>
Cu	5,010 <44.1>	24	104	1	365	4 усага	1/20.8	1/25,550	3.3 x 10 ⁴ <2.4 x 10 ⁴ >
Ni	34.60 <12.9>	24	10*	1	365	4 years	1/20.8	1/25,550	2.28 x 10 ⁴ <7.1 x 10 ⁴ >
Zn	844 <47.4>	24	104	1	365	4 усагз	1/20.8	1/25,550	5.56 x 10° <2.6 x 10°>
Рь	60 <16.8>	24	104	1	365	4 years	1/20.8	1/25,550	3.96 x 10° <9.24 x 10°>

ChemicalConcentration Maximum Measured Concentration reported in boldface

< > Indicates Reasonably Expected Maximum Concentration

Table 6-9

TABLE 6.10

RESIDENTIAL EXPOSURE

OCCASIONAL INGESTION OF CHEMICALS IN SURFACE WATER WHILE SWIMMING

CHEMICAL	CHEMICAL CONCENTRATION mg/L	CONTACT RATE	EXPOSURE TIME	EXPOSURE FREQUENCY	EXPOSURE DURATION	1/BODY WEIGHT	1/AVERAGING TIME	INTAKE mg/kg-day
Aluminum	5.3	50ml/Hr	2.5 Hr.	7 days/year	70 years	1/70kg	1/365.70	0.036
Cr III	0.038 <0.017>	50ml/Hr	2.5 Hr.	7 days/year	70 years	1/70 kg	1/365.70 <5.8x10 ⁴ >	1.6x10 ⁻⁵
cu	0.021 <0.016>	50ml/Hr.	2.5 Hr.	7 days/year	70 years	1/70 kg	1/365.70	7.2×10. ⁴ <5.48×10. ⁴ >
ZN	0.016 <0.012>	50ml/Hr.	2.5 Hr.	7 days/year	70 years	1/70 kg	1/365.70	5.5x10.4 <4.1x10.4>

TABLE 6.11

Residential Exposure: Dermal Contact with Chemicals in Soil

Absorbed Dose (mg/kg-day) = $CS \times CF \times SA \times AF \times ABS \times EF \times ED$ BW x AT

			Skin	Skin to Soil					1/	
	Chemical	Conversion	Surface	Adhesive	Absorption	Exposure	Exposure	1/Body	Averaging	Absorbed
Chemical	Concentration	Factor	Area	Factor	Factor	Frequency	Duration	Weight	Time	Dose (mg/kg-day)
Chromium	4,420	10⁴	1.94	2.77	1	80	70 yrs.	1/70 kg	1/70 yrs. x	1.1 x 10 ⁻¹
C.IIOMIUM	<24.0>			- ,	•		, c , . c .	-7. ·B	365 days/year	
Copper	5,010	104	1.94	2.77	1	80	70 yrs.	1/70 kg	1/70 yrs. x	1.3 x 10 ³
	<44.1>								365 days/year	<1.1 x 10 ⁻¹ >
Zinc	844	10-^	1.94	2.77	1	80	70 yrs.	1/70 kg	1/70 yrs. x	2.1 × 10 ⁻⁴
	<47.4>								365 days/year	<1.2 x 10 ⁴
Nickel	34.60	10-4	1.94	2.77	1	80	70 yrs.	i/70 kg	1/70 yrs. x	8.9 x 10 ⁴
	<12.9>								365 days/year	<3.3 x 10 ⁴ >
Lead	60	10-4	1.94	2.77	1	80	70 yrs.	1/70 kg	1/70 yrs. x	1.5 x 10 ⁻⁵
	<16.8>								365 days/year	<4.3 x 10 ⁴ >

{

Discussion of the variables and assumptions used in calculations; assumed, worst-case or actual site-measured exposure concentrations; and the estimated chemical intake values for each pathway judged complete for the site are presented in the following sections.

Dermal Contact with Surface Soils

Estimated intakes presented below were based upon 95th percentile values for contact rates and exposure frequency variables. A soil absorption factor of 1 was used. Area of exposed skin was assumed was to be 50th percentile of total body surface (1.94 m²); a soil to skin adherence factor of 2.77 and exposure frequency of 121 days (equivalent to eight hours of daily exposure on an annual basis) for a 70 year duration.

Chronic Daily Intake (mg/kg-day)

	Ad	ult
Chemical	RME	MS
Chromium	6.1E-03	1.1E-03
Copper	1.1E-05	1.3E-03
Nickel	3.3E-06	8.9E-06
Zinc	1.2E-05	2.1E-04
Lead	4.3E-06	1.57E-05

Ingestion of Chemicals in Surface Soil

Exposure frequency of 365 days per year for a lifetime duration were used in the risk calculations. Average ingestion rates of 100 mg/day for adults and 200 mg/day for children were used in the estimate calculations.

Estimated chronic daily intake values for incidental ingestion of site soils at the surface by adults and the older child that were calculated based on the geometric mean of sample concentrations as the reasonably expected maximum exposure (RME) concentration and maximum sample (MS) concentration measured in site soils are presented below:

Chronic Daily Intake (mg/kg-day)

	Adu	ilt	Chil	d
Chemical	RME	MŞ	RME	MS
Trichloroethylene	2.7E-07	6.0E-07		2.38E-07
1,1,1-Trichloroethane	,	2E-06		
Chromium	3.4E-04	6.3E-02	1.3E-04	2.45E-03
Copper	6.3E-04	7.2E-02	2.4E-04	2.8E-02
Nickel	1.85E-04	4.9E-02	7.1E-05	1.92E-04
Zinc	6.8E-04	1.2E-02	2.6E-04	4.6E-03
Lead	2.4E-04	8.57E-04	9.25E-05	3.3E-04

Ingestion of Chemicals in Surface Water While Swimming

An ingestion rate of 50 ml, and a figure of 7 days (national average) of swimming activity was used in the calculation of risk factors presented below. An exposure time variable of 2.5 hours and a 70 year lifetime duration period.

Estimated chronic daily intake values for incidental ingestion of surface water by an adult individual were calculated based on the geometric mean of sample concentrations as the reasonably expected maximum exposure (RME) and maximum sample (MS) concentrations measured in surface waters residing in the target pond are presented below:

Estimated Chronic Daily Intake (mg/kg-day)

Adult

Chemical	RME	MS
Chromium (III)	5.8E-08	1.6E-05
Copper	5.5E-08	7.2E-08
Zinc	4.1E-08	5.5E-08

Ingestion of Chemicals in Drinking Water

An ingestion rate of 2 1/day (90th confidence level) was used in the calculation with an exposure frequency of 365 days per year over a 70 year lifetime period.

Estimated chronic daily intake values for incidental ingestion of groundwater for the adult individual were calculated based on 1) the geometric mean of sample concentrations as the reasonably expected maximum exposure (RME) concentration and 2) maximum sample (MS) concentrations measured. These values are presented below for contaminants found in the shallow and intermediate aquifers:

Estimated Chronic Daily Intake (mg/kg-day)

	Shallow A	quifer	Intermediate Aquifer		
Chemical	RME	MS	RME MS		
Vinyl Chloride		3.1E-02	Not Detected		
Trichloroethylene		1.9E-03	Not Detected		
Chromium (III)	6.4E-04	1.3E-03	5.2E-04 6.0E-04		
Copper	2.8E-03	1.9E-03	Not Detected		
Nickel	•				
Zinc	3.1E-04	6.3E-04	Not Detected		

6.3 Toxicity Assessment

All reference dose and slope factor values used in the risk characterization process were obtained from one of the following approved sources: the USEPA Integrated Risk Information System Database, the Health Effects Assessment Summary Tables (Fourth Quarter, FY 1989) and toxicological profiles from the Agency for Toxic Substances and Disease Registry.

Additionally, Techna Corporation contacted the USEPA's Environmental Criteria and Assessment Office (ECAO) for technical guidance concerning oral route to dermal route extrapolation and toxicity values for dermal contact and to verify the whether the most appropriate reference dose and slope factors were located from the above reference sources.

6.3.1 Toxicity Effects: Non-Carcinogenic Effects

Information concerning the critical effects for non-carcinogenic inorganic and volatile organic site-related chemicals, reference dose and reference dose basis, uncertainty factors, and modifying factors are presented in Tables 6-12 and 6-13. A general overview of the health effects associated with the non-carcinogenic site-related chemicals are described in the following sections.

A general overview of the health effects associated with the non-carcinogenic site-related chemicals are described in the following sections. Pertinant information was obtained from Cassarett and Doull's <u>Toxicology</u>. The <u>Basic Science of Poisons</u>, Second Edition, Macmillan Publishing Company, New York, New York, 1980 for all chemicals of concern with the exception of 1,2-dichloroethene wherein the ATSDR Toxiclogical Profile for 1,2-dichloroethene was relied upon for toxicity information.

Chromium

Chromium exists in several valence states. Only the trivalent and hexavalent are biologically significant. The conversion of hexavalent to trivalent does not take place in the body. Trivalent chromium is an essential element in animals and chromium supplementation improves or normalizes glucose tolerance in diabetics, older people, and malnourished children.

TABLE 6.12

TOXICITY VALUES POTENTIAL NON-CARCINOGENIC HEALTH EFFECTS INORGANICS

CHEMICAL	ORAL CHRONIC R _f D (mg/kg-day)	CONFIDENCE LEVEL	CRITICAL EFFECT	R _f D/BASIS SOURCE	UNCERTAINTY & MODIFYING FACTORS
Oral Route Aluminum	Data Inadequate for Quant Health Effects Assessment				
Chromium III	1E+D	Low	NOEL	IRIS	H,A,S,L UF=100 MF=10
IV	5E-3	Low	Cancer	IRIS	H,A, UF=500 MF=1
Copper	3.70×10 ²			ATSDR	
	1.3mg/l(MCL)			HEAST	
Nickel	2×10 ²	Medium		IRIS/Diet	UF=100 MF=3
Silver	3.00×10 ⁻³			IRIS	
	0.05mg/1 MCL			HEAST	
Zinc	2.1×10 ⁻¹			HEAST	UF=10
Lead	1.4×10 ⁻³			ATSDR	
	ND			IRIS	

TABLE 6.13 TOXICITY VALUES FOR NON-CARCINOGENIC EFFECTS VOLATILE ORGANICS

		 			
CHEMICAL	CHRONIC R _f D	CONFI- DENCE LEVEL	CRITICAL EFFECT	R _t D BASIS/ SOURCE	UNCERTAINTY & MOBILITY FACTORS
Oral Route					
1,1,1 TCA	2x10 ⁻²			HEAST	
	0.09mg/kg-day			ATSDR	
t-1,2 Dichloro- ethylene	Long Term DW HEA 1.43 mg/L Child 5.0 mg/L Adult			ATSDR	
t-1,2 Dichloro- ethylene	2.0x10 ⁻²			HEAST	

The total chromium body burden of man has been estimated at less than 6 mg. The major environmental exposure to chromium occurs as a consequence of its presence in food. The daily intake has been estimated at 60 ug(30 to 100 ug), 10 ug of which is due to 10 ug. However, absorption is limited to approximately 1 percent.

Water-soluble chromates disappear from the lungs into the circulatory system after intratracheal application, while the trivalent chromic chloride remains in the lungs. Oral administration of trivalent chromium results in little chromium absorption. The degree of absorption is slightly higher following administration of hexavalent compounds. Once absorbed, the trivalent chromium ion is bound to the plasma proteins.

Occupational expsoure to chromium compounds (hexavalent chromium) causes dermatitis, penetrating ulcers on the hands and forearms, perforation of the nasal spetum, and inflammation of the larynx and liver. Epidemiologic studies indicate that chromate is a carcinogen with bronochogenic carcinoma as the principal lesion. The latent period appears to be 10 to 15 years. Studies have been performed to show that incorporation of hexavalent chromium into the drinking water of mice over their lifetimes produced a slightly higher incidence of malignant tumors than in the controls. Trivalent chromium given to rats under similar conditions showed no such effect.

Copper

Copper is widely distributed in nature and is an essential element. Oxidative enzymes, such as catalase, peroxidase, cytochrome oxides, and others, also require copper. The intestinal mucosa acts to some extent as a barrier to the absorption of ingested copper. Information exists abouth the absorption of copper following inhalation exposure is not complete, and the data on the absorption of copper through the skin are limited. Most cuprous salts are insoluble in water but they tend to oxidize in the cupric form. Most cuprous salts are insoluble in water but they tend to oxidize to the cupric form. The bile is the normal excretory pathway and plays a primary role in copper homestasis. The liver and bone marrow are the storage organs for excess copper. Man is less sensitive to copper than other mammals, presumably because of a better-developed homeostatic mechanism.

Acute poisoning resulting from accidental ingestion of excessive amounts of oral copper salts, most frequently copper sulfate, may produce death. Long-term exposure of humans to copper by inhalation, oral, and dermal routes occurs in occupational settings.

Nickel

Nickel is a constituent of urban air, possibly as a result of fossil fuel combustion. Nickel is not a normal constituent of water. Relatively large amounts occur naturally in vegetables, legumes and grains.

The average body burden of nickel has been estimated at <10 mg. Nickel is present present in the lung, liver kidney and intestine of most stillborn infants. The concentration in the lung increases with age; ncikel has been found in the bile. Excretion is largely via the feces. A mechanism for limiting intestinal absorption has been suggested. Many nickel salts have astringent and irratant properties which limit their absorption.

Dermatitis is the most frequent effect of exposure to nickel. Nickel carbonyl is the most toxic of nickel compounds. It has been estimated to lethal to man at atmospheric exposures of 30 ppm for 20 minutes. Chronic exposure to nickel carbonyl has been implicated epidemiologically in cancer affecting lung and nose.

Zinc

Zinc is ubiquitious and is considered an essential trace element. Its necessary roles involve enzymes and enzymatic functions, protein synthese, and carbohydrate metabolism. It is necessary for normal growth and development in mammals and birds.

Zinc is omnipresent in the environment being found in water, in air, and in all living organisms. Normally, the muscle, liver, kidney, and pancreas contain large amounts. The eyes also have large concentrations. The zinc in blood is largely contained in the red blood cells.

Zinc is elimnated principally by the gastrointestinal tract. The pancreatic fluids contain significant amounts, while additional quantities are found in the bile. The urine contains significantly less than the feces.

Accidental oral poisioning has been reported in humans as aresult of consuming acidic food or beverages from galvanized containers. The symptoms of such intoxications consist of fever, vomiting, stomach cramps, and diarrhea. Industrial exposures occur as a result of inhalation of freshly formed fumes of zinc oxide. Only the freshly formed material is potent, presumably because of flocculation n the air, thereby preventing deep penetration into the lungs. Dermal toxicity following exposures to ZnCl₂ has resulted from consistently handling these salts.

Attempts to produce zinc toxicity by incorporating as much as 25 percent in the diet of rats have not been successful. At levels above this the homeostatic mechanism breaks done: growth retardation, and defective mineralization of the bone occur.

<u>Lead</u>

There are two forms of lead - inorganic lead in which the various salts and oxides are considered to act as identically once absorbed into the systemic circulation and alkyl lead which rapidaly dealkylated by the liver to the trialkyl metabolites that are resposible for toxicity. The trialkyl metabolites are then only slowly metabolized to inorganic lead.

Major routes of exposure include gastrointestinal tract and the respiratory system.

The absorption of lead from the gastrointestinal tract is greatly influenced by concurrent dietary levels of numerous substances, notably calcium, iron, fats, and proteins. Absorption also is considerably greater in infants than in adults and during the fasting state than with meals.

Approximately 90 percent of the total body burden of lead with long-term exposures is in the bones. No other striking affinities exist, althogh liver and kidney have somewhat higher than average concentrations. Excretion of lead occurs by way of the bile and urine and by exfoliation of epithelial tissue, including hair.

Biological effects include central nervous effects such as lead encephalopathy; renal effects involving damage to the proximal tublules, interstitial fibrosis, sclerosis of vessels, and glomeral atrophy of the

kidney. Lead encephalopathy is a severe, often fatal condition, with features such as dullness, restlessness, headaches, loss of memory, occurring as a result of chronic or subchronic exposure to high doses of inorganic lead. Subtle behavioral effects, particularly in children, at levels of exposure below those causing encephalopathy, may cause deficits as reflected in psychometric performance tests and certain neurologic tests.

1,1,1-Trichloroethane

1,1,1-Trichloroethane (Methyl Chloroform) has received received widespread acceptance as an industrial solvent. It has a depressant action on the central nervous system. 1,1,1-trichloroethane is partially metabolized to trichloroethanol and to a less extent to trichloroacetic acid.

Experimental human exposures to 500 ppm of methyl chloroform for 6.5 to 7 hours per day for five days gave no evidence of abnormal organ function as measured by a variety of clinical laboratory tests. In experimental animals, near lethal doses of 1,1,1-trichloroethane are required to produce a measurable hepatoxic response to a single dose.

1,2-Dichloroethene

cis- and trans-1,2-Dichloroethene are man-made compounds. Sources of 1,2-dichloroethene environmental exposure include: process and fugitive emissions from its production and use as a chemical intermediate, formation via anaerobic biodegradation of some chlorinated solvents and leaching from landfills.

Clinical symptons that have been reported in humas expsoed to 1,2-dichloroethene in air include nausea, drowsiness, fatiques, intracranial pressure and ocular irritation. Concentration of cis- and trans-1,2-dichloroethene in air that is lethal to humans is not known. Trans-1,2-dichloroethene is an ocular irritant in humans. No other specific systemic effects have been reported in humans.

6.3.2 Toxicity Effects: Carcinogenic Effects

Information concerning the type of cancer, slope factors, weight of evidence, slope factor basis and source for carcinogenic site-related chemicals is presented in Table 6-14. A general overview of the health effects associated with the carcinogenic site-related chemicals are described in the following sections.

Trichloroethylene

Overexposure to trichloroethylene produces central nervous system depression resulting in mental confusion, incoordination, and insomnia. Other effects include increased liver and kidney weights, severe changes in the cerebellum and changes in Punrinje cell layers of dogs. Metabolic byproducts of trichloroethylene include trichloroacetic acid, trichloroethanol, and small amounts of chloroform and monochloroacetic acid. Trichloroethylene has a rather long biologic half-life.

Animal toxicity studies involving oral exposure to mice have shown that at low and high dose levels, in both sexes, there was a highly significant increase in hepatocellular carcinomas; inhalation of trichloroethylen vapor produces pulmonary carcinomas. Based on this evidence, trichloroethylene is classified as a Probable Human Carcinogen (Group B2).

Vinyl Chloride

Vinyl chloride is considered to have a low order of acute toxicity. Central nervous system depression will occur when animals and man are exposed to moderately high levels of the gas.

Vinyl chloride is classified by the Carcinogen Assessment Group of the USEPA as a Group A Human Carcinogen. It has been shown to be carcinogen in rats, mice and hamsters. Following oral and inhalation exposures, vinyl chloride has produced a high incidence of liver, kidney, lung and brain tumors in the aforementioned animals.

No information is available on the teratogenicity of vinyl chloride following oral exposures. Inhalation exposures have not led to significant embryonal or fetal toxicity or gross teratogenic abnormalities.

6.4 Risk Characterization

Health risks potentially posed by site-related contaminants were quantitatively evaluated as appropriate for the following pathways: dermal contact with surface soil, incidental ingestion of surface soil, occasional ingestion of surface water by swimmers and ingestion of groundwater. For each pathway analyzed, risk calculations were performed to quantify risk posed for both carcinogenic and non-carcinogenic effects. Chronic daily intakes were calculated using exposure concentrations for each chemical used in the risk calculations were include: 1) the geometric mean of all sample concentrations for each media sampled (or the reasonable maximum expected concentration) and 2) the maximum measured concentration in the medium sampled (for the volatile organic chemicals and those inorganics with low frequency of detection in a specific medium).

6.4.1 Site Cancer Risk Estimates

For carcinogens, risks are estimated as the incremental possibility of an individual developing cancer over a lifetime as a result of exposure to the potential carcinogen. Carcinogenic risk estimates are generally an upper-bound estimate, since many assumptions that tend to be overprotective are used in the risk evaluation process (e.g., chemicals found to be carcinogenic in animals are assumed to be carcinogenic in humans, carcinogens are considered as having non-threshold effects and to pose some level of risk at all exposure levels). Site-related chemicals identified as carcinogens include trichloroethylene and vinyl chloride. Trichloroethylene was detected in site soils (in the RST and UVWYXZ grid areas which lie beneath asphalt paving and are located adjoining to and northeast and southwest of the building) and in the groundwater in the shallow saturated zone. Vinyl chloride was detected only in the groundwater of the shallow saturated zone.

Table 6-15 presents a summary of the cancer risk estimates that were calculated for chemical-specific risks, total pathway risk and total site exposure risk (an additive risk for all carcinogens encountered at the site) for each of the site-related chemicals that are known carcinogens. Current use of the site would preclude exposure to the shallow aquifer and the contaminated soils. Pathways considered for the cancer risk evaluations were based upon alternate future potential use of the site and are described as follows:

TABLE 6.14
TOXICITY VALUES FOR POTENTIAL CARCINOGENIC SITE RELATED CHEMICALS

CHEMICAL	SLOPE FACTOR	WEIGHT OF EVIDENCE	TYPE OF CANCER	SF SOURCE	SF BASIS
Vinyl Chloride	2.3EO	A	Lung	IRIS	Diet
ТСЕ	1.1E-2	B2	Liver	IRIS	Diet
1,1,1 TCA		D		HEAST	
Lead	ND	B2		HEAST	
Silver		D		HEAST	

TABLE 6.15

CANCER RISK ESTIMATES

Chemical	CDI	CDI Adjusted For Absorption	Slope Factor	Weight of Evidence	Type of Cancer	SF Source	SF Basis	(CDI x SF) Chemical Specific Risk	Total Pathway Risk	Total Exposure Risk
Ingestion of GW	·									
Vinyl Chloride	0.031	No	2.3E 0	Α	Lung	Iris		7.13 x 10 ⁻²		
Trichloroethylene	1.9 x 10 ⁻³	No	1.1E -2	B2	Liver	Iris		2.09 x 10 ⁻⁵	7.13 x 10 ²	
Ingestion of Soils										
Vinyl Chloride N	ID @ Surfa	ace								
Trichloroethylene	6x10 ⁷		1.1E -2					6.6 x 10 ⁻⁹		

7.13 x 10⁻²

(

Shallow Aquifer

Ingestion of Drinking Water Alternate future potential use of the site may be residential.

This pathway is considered as a possible worst case scenario since public health regulations would not permit use of the

shallow saturated zone as a potable water source.

Ingestion of Site Soils Alternate future potential use of the site may be residential

with resulting exposure of children and adults.

Vinyl chloride and trichloroethylene were estimated to pose chemical-specific risks equal to 7.1E-02 and 2.1E-05, respectively. Total pathway risk from exposures due to ingestion of groundwater and site soils under alternate future residential use scenarios were estimated to equal 7.1E-02 and 6.6E-09, respectively. Total site exposure was estimated to equal 7.1E-02.

6.4.2 Non-Carcinogens: Potential Health Effects Risk Estimates

Table 6-16 presents a summary of the chronic hazard indices that quantified chemical-specific risk, total pathway risk and total site exposure (additive and across all pathways) for non-carcinogenic site-related chemicals. Pathways considered for the chronic hazard risk evaluations performed were based upon alternate future potential residential use of the site and include the following: ingestion of groundwater and site soils, ingestion of surface water while swimming, and dermal contact with site soils. As shown in Table 6-16, hazard indices (the cumulative sum of the hazard quotients or ratio of estimated intake concentration to reference dose) were found to be below unity for all pathways except for ingestion of site soils. Hazard quotients for exposure to copper and nickel in site soils were estimated to equal 1.9 and 2.45 respectively.

6.4.3 Risk Quantitation

The National Contingency Plan (NCP) recognizes the existence of insignificant levels of risk, or acceptable levels of exposure which are adequately protective of human health and the environment. For known or suspect carcinogens, acceptable exposure levels are generally concentrations levels that represent an excess upper bound risk range of 1E-04 to 1E-06 (40 CFR Part 300 Section 300.430 (e) (2)). For determining the extent of protectiveness, the NCP considers that the target total carcinogenic risks to the individual resulting from exposures at a Superfund site may range from anywhere from 1E-04 to 1E-06, with risk levels of 10E-06 as the point of departure. Selection of

TABLE 6-16 CHRONIC HAZARD RISK ESTIMATES

 $Chronic \ Non-Carcinogenic \ Hazard \ Quotient = Estimate \ Intake \ (mg/kg-day)/R_f D \ (mg/kg-day)$

EXPOSURE PATHWAY CHEMICAL	INGESTION OF CONTAMINATED WELL WATER (ADULT)	INGESTION OF CHEMICALS IN SURFACE WATER WHILE SWIMMING (ADULT)	INCIDEI INGEST CHEMIC IN SOL (ADULT)	ION OF CALS	DERMAL CONTACT WITH SURFACE SOIL
Chromium	Shallow 1.29x10 ⁻³ <6.4X10-4>	1.6x10 ⁻⁵ <5.8X10-8>	6.3x10 ⁻²	2.56x10 ⁻¹	1.1x10 ₋₃
	Intermediate 6x10-4 <5.2x10 ⁻⁴ >		<3.4×10-4>	<1.32x10-4>	<6.1x10-6>
Copper	7.6x10 ⁻² <5.13x10 ⁻² >	7.19x10 ⁻⁸ <1.48x10 ⁻⁸ >	1.9 <1.7x10 ⁻² >	2.56X10 ⁻¹ <6.4x10-3>	3.5X10 ⁻² <2.97x10-8>
Nickel	ND	ND	2.45 <9.2x10 ⁻³ >	9.6×10 ⁻³ <3.5×10 ⁻³ >	9.45×10-4 <1.6×10 ⁻⁴ >
Zinc	2.99x10 ⁻³ <1.48x ⁻³ >	5.5x10 ⁻⁸ <1.95x10 ⁻⁷ >	5.7x10 ⁻² <3.23x10 ⁻³	2.19x10 ⁻² > <1.23x10 ⁻³ >	1.0×10 ⁻³ <5.7×10 _{-5>}
Lead	ND	ND	6.12x10 ⁻³ <1.7x10 ⁻³ >	2.3x10 ⁻³ <6.6x10 ⁻⁴ >	1.07x10 ⁻¹ <3.07x10 ⁻⁵ >
1,2 DCE	5.5×10 ⁻¹	ns	ND at Surface	ND at Surface	
1,1,1TC A	ND	NS	2.2x10 ⁻⁵	8.8×10 ⁻⁶	ND at Surface
Pathway Index	5.8x10 ⁻¹ <5.68x10 ⁻¹ >	1.6x10 ⁻⁵ <1.73x10 ⁻⁶ >	4.48 <3.15x10 ⁻²	7.9x10 ⁻¹ > <1.2x10 ⁻² >	1.4x10 ⁻¹ <2.5x10 ⁻⁴ >

ND = Not Detected NS = Not Samples Total Exposure Index:

5.2 (Maximum Exposure Point Concentrations)
5.9x10⁻¹ (Maximum Reasonably Expected Concentrations

remedies will be towards those that are at the protective end of this range. Remedial alternatives being considered should be able to reduce total carcinogenic risks to individuals to levels within this range, except where exceptional circumstances warrant more stringent cleanups.

For non-carcinogens, risks are estimated based upon the possibility of a dose-related toxicological effect occurring with exposure. Exposure levels are compared over a specified period with the time-related reference dose (dose determined not to cause an adverse effect) to develop a hazard quotient (e.g., risk index). If the total hazard index is greater than one, evaluation of the hazard for target organ effect is necessary. If the hazard still exceeds one, potential health hazards may be unacceptable.

For comparative purposes, Table 6-17 presents the maximum exposure concentrations measured in site groundwaters for the site-related chemicals, applicable Maximum Contaminant Levels, and drinking water concentrations corresponding to the reference dose for non-carcinogenic site-related chemicals. Table 6-18 presents the cancer risk per ug/l, cancer risk associated with the maximum exposure point concentration, and Maximum Contaminant Levels for those carcinogenic site-related chemicals.

The estimated risk associated with the presence of vinyl chloride in the shallow aquifer contributes significantly to the overall magnitude for estimated total cancer exposure risk. The pathway risk for the site through ingestion of drinking water of 7.13E-02. The chemical specific risk for trichloroethylene by this pathway was estimated to equal to 2.09E-05. Total pathway cancer risk due to incidental ingestion of site soils is based only upon exposure to trichloroethylene, since vinyl chloride was not detected in site soils, and was calculated to equal 6.6E-09.

Total exposure index for the site from non-carcinogens is equal to 6.1E-01 based upon intake estimates derived using reasonably expected maximum contaminant levels. The presence of 1,2-dichloroethene in the groundwater determines the overall magnitude of this value. The estimated chronic hazard quotient for 1,2-dichloroethylene is 5.15E-01.

Using maximum measured concentrations for the site-related chemicals in each media (worst case scenario) and assuming alternate future potential residential use of the site, the total chronic hazard index score for the site is estimated to equal 5.85.

TABLE 6.17

DRINKING WATER STANDARDS AND R₁D DRINKING WATER EQUIVALENT LEVELS NON-CARCINOGENIC CHEMICALS OF CONCERN

CHEMICAL	CRQL CRDL	DRINKING WATER R _t D EQUIVALENT CONCENTRATION	AXIMUM EXPOSURE CONCENTRATION	RATIO MAXIMUM ESPOSURE CONCENTRATION TO R _I D _{DW}	MAXIMUM CONTAMINANT LEVEL (mg/l)
Chromium	7 ug/l	III 35 mg/l VI 1.75×10 ⁻²	Shallow 0.045 Intermediate 0.021	1.28×10 ⁻³ 1.1×10 ⁻²).10 mg/L
Соррег	10 ug/l	1.29×10 ⁰	0.099	7.67×10 ⁻²	1.3 mg/l
Nickel	11 ug/l	7.0×10 ⁻¹	ND		
Lead		4.9×10 ⁻²		5.1×10 ⁻²	5.0
Zinc	6 ug/1	7.35×10 ⁰	0.022	2.99×10 ⁻³	

TABLE 6-18

CANCER RISKS ASSOCIATED WITH INGESTION OF CONTAMINATED GROUNDWATER

CHEMICAL	CRQL CRDL	CANCER RISK PER ug/l	CANCER RISK AT CRQL or CRDL	MAXIMUM MEASURED CONCEN-	CANCER RISK AT MAXIMUM EXPOSURE PT.	MAXIMUM CONCEN- TRATION
Trichloroethylene	5 ug/l	3.14×10 ⁻⁷	1.57×10 ⁻⁶	1,100 ug/l	Shallow Aquifer 3.45×10 ⁻³	0.005 mg/l
1,1,1 Trichloroethane	5 ug/l					0.200 MCL 0.02 MCLG
Vinyl Chloride	10 ug/l	6.57×10 ⁻⁴	6.57×10 ⁻³	68 ug/l	Shallow Aquifer 4.4×10 ⁻²	0.002
Dichloroethylene (Total)	5 ug/l					cis 0.07 trans 0.07

6.5 Environmental Risk Assessment

6.5.1 Objective of the Assessment

The objective of this environmental assessment is to determine if contaminants originating from the Hi-Mill Manufacturing Company pose a threat of actual and/or potential risk to both biotic and abiotic components on the study site and/or to peripheral areas surrounding the area of concern.

6.5.2 Scope of the Assessment

One objective of this environmental assessment is to evaluate the actual and/or potential pathways of the migration of contaminants from the contaminant source and to determine the actual and/or potential receptors both on-site and in the immediate vicinity of the study area. Subsequently, these pathways of exposure will be analyzed to determine damage to the environment that could result from

exposure to these contaminants.

The assessment procedure for the study site consisted of relevant methodologies for the sampling and subsequent testing of groundwater, local soils, surface waters and associated sediments for the contaminants of interest as described in Sections 1 - 4 and Section 6.2 of this report.

6.5.3 Site/Study Area Description

A geographical and historical overview of the Hi-Mill Manufacturing site study area is presented in Section 1.2 of this document. The Target Wetland, Waterbury Lake, and terrestrial areas surrounding these features and the Hi-mill facility are the primary concern and will comprise the focus of this environmental assessment.

Species of interest in the assessment area would include aquatic free-swimming organisms, aquatic benthic organisms, and terrestrial species (vertebrates and invertebrates) found in the transition zone between marsh-like conditions and upland areas. Some species of birds that typically nest in these environments, such as the red-winged blackbird, as well as migratory species of water fowl, such as

ducks and geese, may also be exposed to the contaminants of concern. Vegetation which could be impacted by the species of concern are also of interest; these species may suffer direct harm or serve as a pathway for indigenous herbivorous animal species.

A survey was conducted of the study site in April of 1984 by the Water Quality Surveillance Section of the Michigan Department of Natural Resources (Appendix O). The aquatic ecosystem under investigation was sampled to assess the diversity of both floral and faunal species, and a list of observations was then compiled to summarize the findings.

The diversity and numbers of faunal species identified in the 1984 survey was very low. Ponar grab samples of the local sediments produced only midges, a ubiquitous aquatic insect; no other benthic aquatic insects, insect larvae or macroinvertebrates were identified in the sediment samples. This limited population of bottom-dwelling organisms may be related to seasonal fluctuations of the water levels of the marsh, seasonal freezing of the shallow water, or possibly by a combination of several other environmental conditions.

One species of daphnids, an aquatic free-swimming invertebrate, was identified in abundance at one sampling site, and a fish, believed to be a mud-minnow, was sighted as well.

The diversity and numbers of floral species identified was much more impressive, and included a variety of algaes, macrophytes and numerous periphyton. Algaes identified included Spirogyra, Euglena, Scenedesmus, Oocystis, Oscillatoria, Mougeotia and Synedra. Macrophytes identified included Typha, Scirpus, Lemna minor, Elodea and Potamogeton. Much periphyton was noted at several sampling sites coating much of the substrate.

The average measured depth (rough measurement performed during the RI) of the wetland area under investigation was between six and eight feet deep. This relatively shallow depth certainly precludes any recreational use such as boating, swimming, etc. Also, from a seasonal perspective, a complete freeze-through would be expected during the winter months, followed by elevated water temperatures during the summer months with a concomitant depletion of the dissolved oxygen concentration in the surface waters. Such drastic seasonal variations in the chemical and physical parameters of the wetland area are probably responsible for the relatively low diversity of indigenous biota.

6.5.4 Contaminants of Concern

The contaminants of concern for the various media under investigation include elevated concentrations of several TAL metals species. These contaminants were identified as a concern in this environmental risk assessment primarily by statistical inference. An average value (mean), standard deviation and mean plus two standard deviations from the mean were calculated for the background media samples. Therefore, subsequent samples collected and analyzed were then assessed as problematic if they contained contaminants at levels above the statistical criteria established by the background contaminant levels.

The primary contaminants of concern for the surface waters of the wetland area are aluminum, copper and trivalent chromium; no hexavalent chromium was detected in any of the samples. The primary contaminants of concern for the sediments are four metals of interest including aluminum, trivalent chromium, zinc, and copper. The contaminants of concern for the soils on the Hi-Mill site are numerous inorganics including aluminum, barium, calcium, chromium, copper, iron, magnesium, nickel, potassium, vanadium and zinc.

Volatile chlorinate solvents were measured in soil samples from the small assessment are (grid RST-01234) located south of the Hi-Mill production building. However, since solvent contamination of soils is limited to this area, and this area is paved, TCL volatiles are not contaminants of concern for this environmental risk assessment.

6.5.5 Exposure Pathways

This section of the environmental risk assessment will identify the potential biological fate of the hazardous materials of interest, namely, the aforementioned TAL metals. The elements of the indigenous biological community that are the actual and/or potential target populations for these contaminants include both aquatic and terrestrial floral and faunal components.

Both aquatic plants and animals are particularly sensitive to assimilating higher levels of hazardous environmental pollutants because they are stantly immersed in the contaminated water medium under investigation. It is commonly assumed that the body tissue contaminant concentration of aquatic species seeks equilibrium with the levels of contaminant concentration of the ambient body

of water. The rate of uptake and the amount of contaminant assimilation is highly dependent on both the nature of the contaminant and on the species of the organism as well. Of particular interest when assessing the bioavailability of heavy metals in aquatic ecosystems is the relationship of other physical and chemical parameters, such as organic content, pH and water hardness.

Little data is available to quantify the effect of the contaminant concentration of metals in the body tissue of aquatic or terrestrial animal species relative to the ambient environmental concentrations of the contaminants. Most research to date has focused on the bioaccumulation of organic, lipid-soluble substances in the body fat (lipids) of terrestrial organisms, as well as in the hepatic and pancreatic organ tissues of various biota. Since these contaminants are of no concern in the surface water, sediments, or soils in this investigation, a discussion of food-chain enhancement is irrelevant. Also, it has been demonstrated that heavy metals such a those present at this study site, do not represent a threat to higher trophic levels of terrestrial organisms since they do not typically biomagnify at higher trophic levels in the food chain.

Contaminant uptake by terrestrial plants has been extensively studied, but almost exclusively from a perspective of the human consumption of edible cash crops such as vegetables and grains. Therefore, little, if any, data to adequately assess contaminant uptake by naturally occurring, native vegetation; therefore, comment will be limited to the fact that only physical sampling and analyses of plant tissues over time would adequately address this concern.

Terrestrial and burrowing animals may also come into contact with the inorganic contaminants; the primary route of exposure would be the direct dermal contact with the contaminated soils. The uptake of metals by organisms via this mode of exposure would be expected to be minimal, if any.

6.5.6 Risk Characterization

This section of the environmental assessment will characterize the actual and/or potential risk to biological receptors at the study site. The risk to indigenous biota in this ecosystem of study is in the marsh water and associated sediments, as well as surrounding soils. Due to the obvious dearth of both the diversity and the numbers of individuals per species represented, the risks associated with the heavy metal contaminants are probably minimal.

Historically, heavy metals, as trace elements in biotic ecosystems are important in plant and animal nutrition where they play an essential role as micronutrients in tissue metabolism and organism growth. Requirements differ substantially for plants and animals; severe imbalances can cause death, whereas marginal imbalances contribute to poor health, retarded growth and/or reproductive disorders. The marsh, associated sediments, and surrounding soils in this study site are experiencing anthropogenic enrichment of several trace metals originating from the Hi-Mill Manufacturing operation. The question is whether this inorganic enrichment is detrimental and/or lethal to the native biotic community of this ecosystem.

To characterize the risk to the environment by the contaminants of concern, it is prudent to examine relevant established criteria. Sources of information researched for this environmental risk assessment include "Toxicological Profiles" as published by the Agency For Toxic Substances and Disease Registry (ATSDR) of the U.S. Public Health Service, and also a computer-accessed database of the "Toxnet" system called "Integrated Risk Information System" (I.R.I.S.)

Unfortunately, these sources primarily address the risk associated with environmental contaminants in the context of human health concerns. Therefore, relevant information to adequately address the various environmental media for this risk assessment are minimal. No established standards could be located to judge both soils and sediments; only a limited amount of information could be found to assess surface waters. Table 6-17 presents a guide to the ambient surface water quality criteria as established by the U.S. Environmental Protection Agency, juxtaposed with the maximum detected value of a given contaminant identified in the surface water samples. All values are reported in micrograms per liter (ug/l). In no case does the reported maximum sample value for any dissolved contaminant under investigation exceed these established guidelines; the contaminants of concern are not a threat to the wetland ecosystem.

TABLE 6-17

COMPARISON OF HIGHEST DETECTED LEVELS OF SURFACE WATER CONTAMINANTS

TO USEPA AMBIENT WATER QUALITY CRITERIA

Contaminant	Maximum Detected Level (µg/l)	Ambient Water Quality Criteria (µg/l)
Al	<crdl< td=""><td>Not Available</td></crdl<>	Not Available
Cr ⁺³	38.5	59,000
Cr ⁺⁶	<mdl< td=""><td>50</td></mdl<>	50
Cu	21.4	1000
Ag	11.4	Not Available
Zn	16.2	5000

APPENDIX A

SURFACE WATER SAMPLE MASTER DATA TABLE

ge No. ,/30/90

SURFACE WATER MASTER FILE

			SURFA	CE WATER THE			
TATIONNO	SAMPLEID	ENCOTECNO	SAMCOLDATE	FEETEAST	FEETNORTH	ELEVATION	SAMPLETYPE
201 202 203 204 201 202 204 204 204 207 207 207 207 207 207 207 207 207 207	HMW-BP01 HMW-BP02 HMW-BP03 HMW-BP04 HMW-IP01 HMS-TP02 HMW-TP04-D HMW-TP04-D HMW-TP07-D HMW-TP07-FB HMW-TP07-FB HMW-TP10-D HMW-TP10-D HMW-TP11-D HMW-TP11-FB HMW-TP11-FB HMW-WL01 HMW-WL02	E48376 E48377 E48378 E48379 E48405 E48405 E48407 E48407 E48408 E48414 E48409 E48410 E48410 E48415 E48401 E4840 E48401 E4840 E48401 E484	03/01/90 03/01/90 03/01/90 03/01/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90 03/02/90	49446.76 49446.76 5144.51 5144.51 5144.51 .5724.70 5383.06 5383.06 5172.76 5172.76 5172.75 6154.04 4850.46	5699.19 5699.19 5699.19 5464.78 5991.93 5991.93 5482.82 5482.82 5482.82 4870.93 4666.79	993.70 993.70 993.70 .999.61 1005.06 1005.80 1005.65 1005.65 1005.65 1005.71 1005.71 1005.71 1005.75 1005.63 1005.63 1005.67 1005.67	SLM, NPN, CR5 SLM, NPN, CR5 TAL INO, NPN, CR5 SLM, CR6 CR6 SLM, CR6 CR6 SLM, CR6 TAL INO, NPN, CR6 TAL INO, NPN NPN SLM, CR5 SLM, CR6 SLM, CR6 TAL INO, NPN SLM, CR6 TAL INO, CR6 SLM, CR6, NPN
15-10	HHW TPIOFS		<i>310a)40</i>	かったぞう	५५ २१.२३	1005.6	3 416

APPENDIX B

SEDIMENT SAMPLE MASTER DATA TABLE

Page No. 05/30/90

SEDIMENTS MASTER FILE

STATIONNO	SAMPLEID	ENCOTECNO	SAMCOLDATE	FEETEAST	FEETNORTH	ELEVATION	SAMPLETYPE
8901	HMS-8P01-0	E48010	02/24/90	4888.91	2735.58	993.70	SLM, CRS
BP02	HMS-8202-0	E48011	02/21/90	4823.19	2517.57	993.70	SLM, CR6
BP03	HMS-8P03-0	E48012	02/21/90	5050.60	2558.89	993.70	SLM, CR5
BP04	HMS-8204-0	E48013	02/21/90	4921.42	2287.57	999.51	TAL Ino, CR5
BP2	HMS-8P2-0	E48011	02/22/90	0.00	0.00	0.00	
TPOI	HMS-TP01-0	E48017	02/21/90	4589.98	6237.97	1005.06	SLM, CR6
TPO1	HMW-TP01-00	E48018	02/21/90	4589.98	6237.97	1005.06	SLM
TPO2	HMW-TP02-0	E48092	02/22/90	.5199.43	5341.68	1005.80	TAL Ino, CR5
TP03	HMS-TP03-0	E48091	02/22/90	5209.03	6394.91	1006.69	SLM, CRS
TPO4	HMS-TP04-0	E48019	02/21/90	49445.76	6394.91	1005.55	SLM, CR6
TPO4	HMS-TP04-1	E48020	02/21/90	49446.75	6394.91	1005.65	SLM, CR6
TP05	HMS-TP05-0	E47962	02/20/90	5495.99	5864.93	1005.65	SLM, CR6
TP06	HMS-TP05-0	E48021	02/21/90	5049.77	5790.81	1005.68	SLM, CR5
TPO6	HMS-TP06-1	E48022	02/21/90	5049.77	5790.81	1004.18	SLM, CR6
TPO7	HMS-TP07-0	E48093	02/22/90	5144.51	5699.19	1005.71	TAL Ino, CR5
TPO7	HMS-TP07-1	E48094	02/22/90	5144.51	5699.19	1005.71	SLM, CR6
TP07	HMS-TP07-10	E48095	02/22/90	5144.51	5599.19	1005.71	SLM, CR5
TPOB	HMS-TP08-0	E48096	02/22/90	5207.15	5520.58	1005.75	SLM, CR6
TPO8	HMS-TP08-1	E48097	02/22/90	5207.15	5520.58	1005.75	TAL Ino, CR6
TPOB	HMS-TP08-1D	E48101	02/22/90	5207.15	5520.58	1005.75	TAL Ino
TPO9	HMS-TP09-0	E47953	02/20/90	5724.70	5464.78	1005.75	SLM, CR5
TP10	HMS-TP10-0	E47954	02/20/90	5383.05	5991.93	1005.63	SLM, CR5
TP11	HMS-TP11-0	E48098	02/22/90	5172.75	5482.82	1005.67	SLM, CR5
TP11	HMS-TP11-1	E48099	02/22/90	5172.76	5482.82	1005.67	SLM, CR5
TP11	HMS-TP11-1D	E48100	02/22/90	5172:76	5482.82	1005.67	CR6
TP12	HMS-TP12-0	E48944	03/14/90	0.00	0.00	0.00	SLM, CR6
WLO1	HMW-WLD1-0	E48014	02/21/90	6154.05	4870.93	999.31	SLM, CR5
WL02	HMW-WL02-0	E48015	02/21/90	4850.45	4666.79	1000.19	SLM, CR5
WL02	HWM-MF05-00	E48016	02/21/90	4850.46	4566.79	1000.19	SLM, CR6

APPENDIX C

SOIL SAMPLE MASTER DATA TABLE

6

, 					/ 3011	N 190157				
				SAMPLE				DEPTH		
2	a	29100m20	POPTNO	COLLECTION	222	FEET	SAYPLE		SOIL	
 -	SAYPLE	ENCOTEC :NMBER	3CRING TYPE	DATE	PEET EAST	NORTH	ELEVATION DEPTH		7772	SAMPLE TYPE
	:D		MTYFELL				1009.4	0.0	SDC	SIX
3	HYS-A1-0	2+6+62		01/24/90	4819.81	5011.05	1006.1 3	3.3	CSS	51. 51.
	_ HYS-A:-:	E48463	MYPEII	01/04/90	4819.81 4879.25	5011.05		0.5	S2C	SIM
	HYS-A2-0	E46464	NTYPEII	01/24/90		5006.78	1011.0 1 1005.0 3	ε.S	CST	SLY
	12/25-A2-1	246465	MYPEII	01/24/90	4879.25	5006.78		0.0	CI.	SLM
	H73-A3-0	E46466	NTYPEII	01/24/90	4940.20	5006.44	1010.6 1 1008.1 3	2.5	<u> </u>	SIM
	HYS-A3-1	E46467	TIPETT	01/24/90	4940.20	5006.44			<u> </u>	SIX:
	H3-44-0	E46502	SCF	01/24/90	5000.00	5000.01	996.6	0.0	SDI	SIX
		E45468	WIYPEII	01/24/90	4812.45	5067.17	1009.4	<u> </u>	22.	SIX:
	HYS-31-00	E46469	MARRIE	01/24/90	4312.45	5067.17	1009.4 1	0.0	CSD	SLY.
-	HYS-31-1	246470	NTZPII	01/24/90	4812.45	5067.17	1006.5	2.8	SDC	SIM.
	EVS-32-C	E46471	MIYPEII	01/24/90	4883.C3	5063.28	1010.6 1	0.0		51
	HVS-32-1	E46472	MIYPEII	01/24/90	4883.03	5063.26	1007.4 3	3.2		
•	HYS-33-0	E46473	MIYPELI	01/24/90	4939.49	5061.15	1011.9 1	0.0	SDT	SIM
	EYS-53-1	E46474	WALETI.	01/24/90	4939.49	5061.15	1005.2 3	3.?_	STC,'L'3	52:
-:	HYS-34-0	E46503	SOF	01/24/90	5001.35	5059.87	1010.4	2.3	CI.	SIM
2.5	HYS-35-0	246504	SOF	01/24/90	5061.31	5060.98	1010.8 1	0.0	CT	SIM
<u>:</u> -	# 25-35-00	E46505	SOF	01/24/90	5061.31	5060.98	1010.8 1	<u> </u>	C.	SIM
2.2	HMS-C1-C	E46475	HIMPELL	C1/24/90	4823.72	5123.51	1009.5	0.0	SCC	SLM
2.3	HYS-C1-1	E46476	NTYFEII	01/24/90	4823.72	5123.51	1008.5 3	1.0	SIC	SIX:
<u>::-</u>	13:S-C2-C	E46589	XIYPELL	01/26/90	4884.89	5122.52	1010.6 1	0.0	STC	SLM
77	HYS-C2-1	E46590	NIYPEII	01/26/90	4884.89	5122.52	1008.1 3	2.5	STC	SIM
= :	HYS-C3-0	24659 1	ntypeli	01/26/90	4945.C3	5121.31	1011.2	0.0	STC	SIM
:-	13/5-C3-00	E46592	NTYPELL	01/26/90	4945.03	5121.31	1011.2 1	0.0	STC	SLM
	HYS-C3-1	E+6593	MINEELL	01/25/90	4945.03	5121.31	1008.2 3	3.0	STC/L3	27.
29	HYS-C4-0	E46506	SOF	01/24/90	5003.28	5120.13	1010.0 1	C.0	CI	TAL Ino
?:	HYS-C5-0	E46507	SOF	01/24/90	5062.99	5119.19	1009.9 1	0.0	<u>cr</u>	SLX
2!	HYS-D2-0	E46594	NIYPEII	01/26/90	4867.75	5192.22	1010.1 1	0.0	STC	SLM
22	HYS-D2-1	E46595	NIYPEII	01/26/90	4867.75	5192.22	1006.8 3	3.3	STC/L3	SLM
23	HYS-D3-0	E47380	NTYPEII	02/07/90	4956.89	5181.44	1009.6 1	0.0	<u>cr</u>	SIM .
34	1345-D3-1	E47381	NTYPEII	C2/07/90	4956.89	5181.44	1007.3 3	2.3	STC	SIM
35.	HMS-D4-0	E46508	SCF	01/24/90	5004.22	5179.96	1009.8	0.0	CI	SIM
26	13MS-D5-0	E46509	SOF	01/24/90	5063.86	5178.06	1009.5 1	0.0	SDT	SLM
37	HMS-D6-0	E46510	SOF	01/24/90	5124.57	5176.67	1009.8 1	0.0	SDT	SIM
38	HMS-E2-0	E46597	NTYPEII	01/26/90	4886.55	5240.53	1010.0 1	0.0	STC	SIM
39	HMS-E2-1	E46596	NIYPEII	01/25/90	4886.55	5240.53	1007.5 3	2.5	STC	SLM
40	HYS-E3-0	E46598	NTYPEII	01/26/90	4945.51	5241.37	1010.2 1	0.0	STC	SLM
41	FMS-E3-1	E46599	NIYPEII	01/26/90	4945.51	5241.37	1007.2 3	2.5	STC	SIM
12:	iams-e4-0	E46511	SOF	01/24/90	5006.24	5239.77	1009.2 1	0.0	SDT	SIM
43	HMS-E5-0	E46512	SOF	01/24/90	5066.08	5238.42	1009.2 1	0.0	CT	TAL Ino
- 44 	HMS-E6-0	E46513	SOF	01/24/90	5125.89	··· 5237.13	1009.2 1	0.0	SDT	SIM
45	HMS-E7-0	E46514	SOF	01/24/90	5186.68	5235.86	1010.0 1	0.0	CT	SLM
16.	HMS-F3-0	E46601	NTYPELL	01/26/90	4948.40	5300.71	1009.2 1	0.0	STC	SIX
æ 47. 	HMS-F3-CD	E46600	NIYPELL	01/26/90	4948.40	5300.71	1009.2 1	0.0	STC	SLM
10,	HMS-F3-1	E46602	NTYPEII	01/26/90	4948.40	5300.71	1006.2 3	3.0	STC	SIM
49	1345-F4-0	E46892	NTYPELL	02/01/90	5007.69	5304.85	1009.0	0.0	SISD	SLM
) := ;	HMS-F4-1	E46893	NIYPEII	02/01/90	5007.69	5304.85	1005.5 3	3.5	STC	SLM
, 5 1	HMS-F5-0	E46515	SOF	01/24/90	5066.08	5238.42	1009.8 1	0.0	SDT	SLM
52,	1245-F6-0	E46516	SOF	01/24/90	5127.34	5297.21	1009.0 1	0.0	CI	SIM
53	HYS-F7-0	E46517	SOF	01/24/90	5188.22	5295.25	1008.0 1	0.0	CI	SLM
34	HMS-F7-0D	E46518	SOF	01/24/90	5188.22	5295.25 542.5293.97	1008.0 1	0.0	_ <u>cr</u>	SLM
133	HMS-F8-0	E46521	SOF	01/24/90	5247.66 4952.46	5362.35	1007.3 1 1009.0 1	0.0 0.0	CI.	SLM SLM
56	HMS-G3-0	E46603	NIYPEII	01/26/90 01/26/90		5362.35	1004.0 3	5. 0	OSTC	SIM
		E46604	NTYPELL	01/28/90	4989.71	5386.86	1009.9 1	0.0	<u> </u>	
-	HMS-G3/H4-0	E46428	TypeII	01/ 53/ 20	7007.14		1003.3	0.0	Car.	SLM

SOIL TYPE: P=PEAT CT=CLAYEY TOPSOIL SDT=SANDY TOPSOIL CSTC=CRGANIC SILTY CLAY STC=SILTY CLAY SDC=SANDY CLAY STC/LB=SILTY CLAY WITH SAND OR SILT LAMINA, LENZES OR BEDS CST=CLAYEY SILT CSD=CLAYEY SAND STSD=SILTY SAND SD=SANDY SDC=SANDY GRAVEL

\$

					20117	TAS. ET.				
				C1107.7				DEPTH		
2			2007110	SAMPLE	FEET	FEET	SAMPLE	BELCW	SOIL	
	SAMPLE	ENCOTEC	BORING TYPE	COLLECTION	EAST	NORCH	ELEVATION DESTR	SURFACE	<u></u>	SAGIE TIPE
	ID	NU SER			4989.71	5386.86	1006.9 2	3.0	sü	SIA
5	HYS-G3/H4-1	E46429	TypeII	01/23/90		5385.86	998.9 3	11.0	SD	Tal Ino
5	H/S-G3/H4-2	E46430	TypeII	01/23/90	4989.71 4989.71	5386.86	995.9			517.
•	HYS-G3/H4-3	E46431	TypeII	01/23/90	5015.19	5386.09	1010.1 1	0.0	SDI	SIM
:	HYS-G4-0	E47174	TypeII	02/05/90	5015.19	5385.09	1007.6 2	2.5	STSD	SIM
· -	::::S-G4-1	E47175	TypeII	02/05/90	5015.19	5386.09	998.5 3	11.3		Tal ino, Tel Cr
	HVS-G4-2	E47176	TypeII	02/05/90			998.6 3	11.3	STSD	Tal Ino
	HYS-G4-20	247177 247177	TypeII	02/05/90	5015.19 501 5. 19	5386.09	995.1 4	25.0	STC/L3	SIM
	HYS-64-3	E47178	TypeII	02/05/90		5386.09 5358.98	1008.6	C.0	<u> </u>	SIV.
÷	::VS-G5-0	E46432	MYPETT	01/23/90	5069.13 5069.13	5353.98	1003.1 3	5.5	STC	SIM
•	H/S-G5-2	E46433	NTYPELL	01/23/90 01/22/90	5129.31	5357.11	1007.9	0.0	CSD	SIA
	HMS-G6-0	E46349	TypeII		5129.31	5357.11	1007.9	2.5	CSD	SIX.
	:YS-G6-1	246351 246352	TypeII	01/22/90	5129.31	5357.11	1004.9 3	3.0	CSD	SLM
-	HMS-G6-2	E46350	TypeII	01/22/90 01/22/90	5129.31	5357.11	1001.9 4	6.0	STC	SIM
·	EYS-66-3 EYS-67-0	E46519	SOF	01/24/90	5188.72	5359.49	1006.0	0.0		TAL Ino
	#3-67-0 #35-68-0		SCF	01/24/90 01/24/90	5249.32	5353.70	1006.1	0.0	CI	SIM
	HMS-H3-0	E46520 E47382	NTYPEII	02/07/90	4950.51	5421.36	1008.0 1	0.0	SD	SIM
=	HYS-R3-CD	E47383	NIVEZII	02/07/90	4950.51	5421.36	1008.0 1	0.0		SIM
	HYS-H3-1	E47384	MYPELL	02/07/90	4950.51	5421.36	1003.7 3	4.3	SD	SIM
22		E48435	NTYPEII	03/04/90	4913.59	5448.75	1007.9	0.0	SD	SLY.
= = = = = = = = = = = = = = = = = = =	HYS-H3/I3-0 HYS-H3/I3-1	E46435 E46436	NIYPEII	03/04/90	4913.59	5448.75	1001.1 3	6.8	S2	51M
	RMS-R3/13-1 RMS-R3/14-1	E47272	TypeII	02/06/90	4975.43	5449.83	1001.7 2	6.0	5D 5D	SIM
25	HMS-H3/14-2	E47273	TypeII	02/06/90	4975.43	5449.83	996.9 3	10.8	STC	Tal Ino
===	HMS-H3/14-3	E47274	TypeII	02/05/90	4975.43	5449.83	991.7 +	16.0	STC/L3	SIM
	HMS-H4-0	E48437	NIYPELL	03/04/90	5007.76	5419.45	1010.0 1	0.0	SOT	SIM
29	HMS-R4-1	E48438	MIYPEII	03/04/90	5007.76	5419.45	1003.5 3	6.5	STSD	SIM:
20	EVS-H4/15-0	E47164		02/05/90	5042.62	5453.99	1007.3 1	0.0	<u>Cî</u>	\$1. ⁴
2:	HYS-H4/I5-1	E47165	TypeII TypeII	02/05/90	5042.62	5453.99	1007.3 1	2.5	CI	SIM
22	HYS-H4/I5-2	E47166	TypeII	02/05/90	5042.62	5453.99	1002.0 3	5.3	STC	Tal Ino
23	HMS-H4/I5-3	E47167	TypeII	02/05/90	5042.62	5453.99	998.3 4	9.0	STC/13	SIM
22	H2S-H5-0	E46894	MINAEII	02/03/90	5070.67	5420.46	1007.9	0.0	SDT	SIM
36	125-15-1	E46895	NIYPEII	02/01/90	5070.67	5420.46	1004.2 3	3.7	STC/LB	SIX:
37	HMS-H6-0	E46344	TypeII	01/22/90	5129.59	5416.24	1007.2 1	0.0	SD	SIX.
29	HMS-H6-OD	E46345	TypeII	01/22/90	5129.59	5416.24	1007.2	0.0	SD	SIM
30	HMS-H6-1	E46346	TypeII	01/22/90	5129.59	5416.24	1004.7 2	2.5	STC	SIM
	HNS-H6-2	E46347	TypeII	01/22/90	5129.59	5416.24	1003.0 3	4.2	CSD	SIM
41.	HYS-H6-3	E46348	TypeII	01/22/90	5129.59	5416.24	1000.2 4	7.0	STC	SIM
- 2	HMS-H7-0	E46245	TypeII	01/19/90	5188.57	5412.21	1006.1 1	c.5	CI.	SIM
43	HMS-H7-1	E46246	TypeII	01/19/90	5188.57	5412.21	1003.6 2	2.5	?	SIM
44	HMS-H7-2	E46247	TypeII	01/19/90	5188.57	5412.21	1000.6 3	5.5	P	SIM
45	HMS-H7-3	E46248	TypeII	01/19/90	5188.57	5412.21	997.6 4	8.5	STC	SLM
	HMS-H8-C	E47597	SOF	02/09/90	5243.69	5418.14	1005.9	0.5	570	SZ:
4.7	HMS-13-1	E47168	TypeII	02/05/90	4949.69	5482.48	1001.5 2	7.0	CSD	SIX:
4:	HMS-13-2	E47169	TypeII	02/05/90	4949.69	5482.43	995.3 3	12.7	CSD	SIM
	HYS-13-3	E47170	TypeII	02/05/90	4949.69	5482.48	992.5 4	16.0	STC, 13	SLY
	HMS-14-1	E47171	TypeII	02/05/90	4988.33	5480.21	1003.8 2	5.0	SD	SIM
:•	E/S-I4-2	E47172	TypeII	02/05/90	4988.33	5480.21	999.6 3	9.2	SDC	Tal Imp, Tol Or
: 2	:D:S-14-3	E47173	TypeII	02/05/90	4988.33	5480.21	995.8 4	13.0	STC/LB	SIM
: 1	HYS-I4-3D	E47179	TypeII	02/05/90	4988.33	5480.21	995.3 4	13.0	STC/LE	SIM
	:YS-15-0	E46424	TypeII	01/23/90	5072.85	5478.53	1007.4 1	0.0	csz	su:
$\overline{}$:MS-15-1	E46425	TypeII	01/23/90	5072.85	5478.63	1005.0 2	2.4	STC	SIM
٠,	HMS-15-2	E45426	TypeII	01/23/90	5072.85	5478.63	1001.9 3	5.5	P	SLM
5	HMS-15-3	E46427	TypeII	01/23/90	5072.85	5478.63	998.9 4	8.5	STC/LB	SIM
	HNS-16-0	E46339	TypeII	01/22/90	5:24.71	5472.53	1006.8 1	0.0	STC	SIM

SOIL TYPE: P=PEAT CT=CLAYEY TOPSOIL SUT=SANDY TOP=QIL OSTC=ORGANIC SILTY CLAY STC=SILTY CLAY SDC=SANDY CLAY
STC/LB=SILTY CLAY WITH SAND OR SILT LAMINA, LENZES BEDS CST=CLAYEY SILT CSD=CLAYEY SAND STC=SILTY SAND SDC=SANDY
SDC=SANDY GRAVEL

Text				SAMPLE				DEPTH		
195-16-00 166340 Typell 0.7/22/90 1214,71 5472.33 1004.3 2 .0 .0 570 SLM 105-16-1				COLLECTION		FEET			SOIL	
1955-19-1										
1955-16-2										
Month Mont	HYS-16-1	E46341								
195-17-0	HVS-16-2									
195-17-1	HYS-16-3		TypeII							
MSS-18-0							1005.9 1			SLM
ESS-15-0 246335 Cype11 C1/22/90 5080.48 5527.23 1001.1 2 2.1 CSD SEZ CSD CSD	HYS-17-1									
PSS-15-1	HYS-18-0	247687	SCF	02,/12,/90			1005.9 1			
PSS-15-2 246337 TypeII 01/22/90 5360.46 5427.23 593.6 1	E-25-J5-0	E46335	TypeII	01/22/90	5080.48					52.4
Hearts	HYS-J5-1	E46336	TypeII	C1/22/90	5080.46		1004.1 2			
ESS-16-0	HYS-J5-2	E46337	TypeII	01/22/90	5080.46	5527.23	1003.1 3	3.5		
Mary	H245-J5-3	E46338	TypeII	01/22/90	5080.46	5527.23	999.6 ÷			
MSS-76-10 SUF92	::::S-J6-0	E47690	MTYPEII	02,13/90	5133.52	5535.53	1005.9 1	C.C		
March Marc	HYS-J6-1	E47891	NTYPEII	02/13/90	5133.52	5535.53	1004.4 3	1.5		
1925-13-0 2,48902 NYTZEII 02/01/90 4995.34 5603.77 1009.5 3 0.0 CT SLM 1925-13-1 2,48996 NYTZEII 02/01/90 5013.97 5998.45 1008.0 1 0.0 CS SLM 1925-13-0 2,48996 NYTZEII 02/01/90 5013.97 5998.45 1008.0 1 0.0 CS SLM 1925-13-1 2,48996 NYTZEII 02/01/90 5013.97 5998.45 1005.0 3 3.0 STC SLM 1925-13-0 2,48996 NYTZEII 02/01/90 5013.97 5998.45 1005.0 3 3.0 STC SLM 1925-13-0 2,48999 NYTZEII 02/01/90 5192.08 5997.81 1005.1 0.0 CT SLM 1925-13-1 2,48990 NYTZEII 02/01/90 4998.30 5662.52 1007.3 1 0.0 CT SLM 1925-13-1 2,48990 NYTZEII 02/01/90 4998.30 5662.52 1007.3 1 0.0 CT SLM 1925-13-1 2,48990 NYTZEII 02/01/90 4998.30 5662.52 1004.8 3 2.5 CSTC SLM 1925-13-1 2,48990 NYTZEII 02/01/90 4998.30 5662.52 1004.8 3 2.5 CSTC SLM 1925-13-1 2,48990 NYTZEII 02/01/90 4998.30 5662.52 1004.8 3 2.5 CSTC SLM 1925-13-1 2,48990 NYTZEII 02/01/90 5013.59 5661.55 1006.0 1 0.0 CSTC SLM 1925-13-2 2,47893 SCF 02/12/90 5013.59 5661.55 1006.0 1 0.0 CSTC SLM 1925-13-3 2,48990 2,48990 4998.39 5722.19 1005.9 1 0.0 CSTC SLM 1925-13-4 2,47895 SCF 02/09/90 5015.68 5721.08 1005.9 1 0.0 CSTC SLM 1925-13-4 2,47895 SCF 02/09/90 5015.68 5721.08 1005.9 1 0.0 CSTC SLM 1925-13-4 2,44990 2	HYS-J6-10	E47692		02/13/90	5133.52	5535.53	1004.4 3	1.5	STC	
HCS-H2-0							1005.9 1			
POS-IS-1 PASSO								0.0	CT	
PSS-74-0 P48896								4.5	STC	
NSS-K4-00 146897 NYYEII C2/01/90 5013.97 5988.45 1008.0 1 0.0 CSD SIM PSS-K5-0 126889 NYYEII C2/01/90 5075.06 5588.40 1006.1 1 0.0 CT SIM PSS-K5-0 127885 SSF 02/01/90 5075.06 5588.40 1006.1 1 0.0 CT SIM PSS-L3-0 126889 NYYEII 02/01/90 4988.30 5682.12 1007.3 1 0.0 CT SIM PSS-L3-1 126890 NYYEII 02/01/90 4988.30 5682.12 1007.3 1 0.0 CT SIM PSS-L3-1 126890 NYYEII 02/01/90 4988.30 5682.12 1004.8 3 2.5 CSTO SIM PSS-L3-1 126890 NYYEII 02/01/90 4988.30 5682.12 1004.8 3 2.5 CSTO SIM PSS-L3-1 126890 NYYEII 02/01/90 4988.30 5682.12 1004.8 3 2.5 CSTO SIM PSS-L3-1 126890 NYYEII 02/01/90 4988.30 5682.12 1004.8 3 2.5 CSTO SIM PSS-L3-0 127893 SSF 02/12/90 5015.28 5681.35 1006.0 0 0 CSTO SIM PSS-L3-0 127895 SSF 02/12/90 5013.49 5681.59 1005.0 0 0 CSTO SIM PSS-L3-0 127895 SSF 02/12/90 5013.68 S721.108 1005.9 1 0.0 CSTO SIM PSS-M6-0 127385 SSF 02/09/90 5018.8 39 5722.19 1005.9 1 0.0 CSTO SIM PSS-C00-0 127386 SSF 02/09/90 5018.68 S721.08 1005.9 1 0.0 CSTO SIM PSS-C00-0 127386 SSF 02/09/90 5182.99 5183.11 1006.2 1 0.0 CT TAL PSS-C00-0 127386 SSF 02/09/90 4955.49 4982.59 1005.5 1 0.0 CT TAL PSS-C00-0 127388 SSF 02/09/90 4955.49 4982.59 1005.5 1 0.0 CT TAL PSS-C00-1 127386 SSF 02/09/90 4955.49 4982.59 1005.5 1 0.0 CT TAL PSS-C00-1 127386 SSF 02/09/90 4779.50 5186.13 1006.6 3 1.1 STO/LB PSS-RS01-0 126655 SKP11 01/29/90 4779.84 5186.13 1006.6 3 1.1 STO/LB PSS-RS01-0 126656 SKP11 01/29/90 4779.55 5186.13 1006.6 3 1.1 STO/LB PSS-RS01-0 126656 SKP11 01/29/90 4779.55 5186.13 1006.6 3 1.1 STO/LB PSS-RS01-0 126656 SKP11 0									CSD	SLM
PS-SK-1- 26698 HTYEII C2/O1/90 5013.97 5598.45 1005.0 3 3.0 STU SLM							1008.0 1	0.0	CSD	311.
PSS-NS-O									STU	
MYS-16-0								0.0	CI	S1.Y.
PMS-L3-0										SIM
PASS-L3-1										
PMS-L4-0										
HYS-L3-0 E47693 SCF O2/12/90 SOL5.25 S681.35 LOGG.										
PSS-L5-0										
Res-Ma										
##S-M4-O										
PMS-OGI-O										
PMS-OG2-0				· · · · · · · · · · · · · · · · · · ·						
PMS-0G3-0										
PMS-OG4-0										
PMS-RSO1-0 E46654 SMGrid O1/29/90 4758.43 5166.13 1009.4 1 0.3 SDG TCL VOA, SLM PMS-RSO1-2 546655 SMGrid O1/29/90 4758.43 5166.13 1008.6 3 1.1 STC/LB TCL VOA SLM PMS-RSO1-3 E46656 SMGrid O1/29/90 4758.43 5166.13 1008.6 3 1.1 STC/LB TCL VOA PMS-RSO1-3 E46656 SMGrid O1/29/90 4758.43 5166.13 1005.4 4 4.0 STC TCL VOA SLM PMS-RSO1-3 E46657 SMGrid O1/29/90 4769.54 5164.26 1009.2 1 0.5 SDG TCL VOA SLM PMS-RSO3-3 E46658 SMGrid O1/29/90 4769.54 5164.26 1009.2 1 0.5 SDG TCL VOA SLM PMS-RSO3-1 E46659 SMGrid O1/29/90 4769.54 5163.95 1009.5 1 0.3 SDG TCL VOA SLM PMS-RSO3-1 E46650 SMGrid O1/29/90 4779.54 5163.95 1009.5 1 0.3 SDG TCL VOA SLM PMS-RSO3-3 E46660 SMGrid O1/29/90 4779.54 5163.95 1007.3 3 2.5 SDC TCL VOA SLM PMS-RSO3-3 E46660 SMGrid O1/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA SLM PMS-RSO3-3 E46660 SMGrid O1/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA SLM PMS-RSO3-4 E46660 SMGrid O1/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA SLM PMS-RSO3-2 E46660 SMGrid O1/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA SLM PMS-RSO3-2 E46660 SMGrid O1/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA SLM PMS-RSO3-2 E46668 SMGrid O1/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA SLM PMS-STO1-0 E46687 SMGrid O1/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VOA SLM PMS-ST12-3 E46668 SMGrid O1/30/90 4769.80 5174.56 1009.3 1 0.5 SDG TCL VOA SLM PMS-ST12-3 E46668 SMGrid O1/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA SLM PMS-ST12-3 E46668 SMGrid O1/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA SLM PMS-ST12-3 E46668 SMGrid O1/30/90 4769.80 5174.25 1009.3 1 0.5 SDG T										
HMS-RS01-2 E45655 SMGrid 01/29/90 4758.43 5165.13 1008.6 3 1.1 STC/LB TCL VOA, SLM HMS-RS01-3D E45656 SMGrid 01/29/90 4758.43 5165.13 1008.6 3 1.1 STC/LB TCL VOA HMS-RS01-3 E45656 SMGrid 01/29/90 4758.43 5165.13 1008.6 3 1.1 STC/LB TCL VOA HMS-RS12-0 E45657 SMGrid 01/29/90 4758.43 5165.13 1005.4 4 4.0 STC TCL VOA, SLM HMS-RS12-3 E45658 SMGrid 01/29/90 4769.54 5164.26 1009.2 1 0.5 SDG TCL VOA, SLM HMS-RS23-0 E45659 SMGrid 01/29/90 4779.54 5163.95 1005.7 4 4.0 STC TCL VOA, SLM HMS-RS23-1 E45650 SMGrid 01/29/90 4779.54 5163.95 1007.3 3 2.5 SDC TCL VOA, SLM HMS-RS23-3 E45651 SMGrid 01/29/90 4779.54 5163.95 1007.3 3 2.5 SDC TCL VOA, SLM HMS-RS23-3D E45652 SMGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA, SLM HMS-RS23-3D E45653 SMGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA, SLM HMS-RS23-3D E45656 SMGrid 01/29/90 4779.55 5163.60 1007.1 3 2.5 SDC TCL VOA, SLM HMS-RS34-2 E45656 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 SDC TCL VOA, SLM HMS-RS34-3 E45655 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 SDC TCL VOA, SLM HMS-RS34-3 E45665 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HMS-RS34-3 E45665 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HMS-ST01-0 E45687 SMGrid 01/30/90 4759.80 5174.55 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST01-3 E45668 SMGrid 01/30/90 4759.80 5174.55 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST12-3 E45680 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST12-3 E45680 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA HMS-ST12-3 E45680 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA HMS-ST23-0 E45667 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA HMS-ST23-0 E45668 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA HMS-ST23-0 E45670 SMGrid 01/30/90 4779.79 5173.95 1008.3 1 0.5 SDG TCL VOA, SLM HMS-ST23-0 E45670 SMGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VOA, SLM										
HNS-RS01-2D										
HMS-RS01-3 E4656 SAGrid 01/29/90 4758.43 5166.13 1005.4 4 4.0 STC TCL VOA, SLM HMS-RS12-0 E46657 SAGrid 01/29/90 4769.54 5164.26 1009.2 1 0.5 SDG TCL VOA, SLM HMS-RS23-3 E46658 SAGrid 01/29/90 4779.54 5163.95 1005.5 1 0.3 SDG TCL VOA, SLM HMS-RS23-1 E46660 SAGrid 01/29/90 4779.54 5163.95 1007.3 3 2.5 SDC TCL VOA, SLM HMS-RS23-3 E46661 SAGrid 01/29/90 4779.54 5163.95 1007.3 3 2.5 SDC TCL VOA, SLM HMS-RS23-3 E46661 SAGrid 01/29/90 4779.54 5163.95 1007.3 4 5.5 STC TCL VOA, SLM HMS-RS23-3 E46662 SAGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA, SLM HMS-RS34-0 E46663 SAGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HMS-RS34-2 E46664 SAGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HMS-RS34-3 E46665 SAGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HMS-RS34-3 E46665 SAGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HMS-RS34-3 E46665 SAGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC TCL VOA, SLM HMS-RS10-3 E46687 SAGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 STC TCL VOA, SLM HMS-ST01-0 E46687 SAGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 STC TCL VOA, SLM HMS-ST12-0 E46689 SAGrid 01/30/90 4759.80 5174.55 1009.3 1 0.5 STC TCL VOA, SLM HMS-ST12-3 E46680 SAGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 STC TCL VOA, SLM HMS-ST12-3 E46680 SAGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-3 E46680 SAGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-3 E46680 SAGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-3 E46680 SAGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-30 E46680 SAGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-30 E46680 SAGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-30 E46692 SAGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-30 E46692 SAGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VOA, SLM										
HYS-RS12-0 E46657 SWGrid 01/29/90 4769.54 5164.26 1009.2 1 0.5 SDG TCL VCA, SLM HYS-RS12-3 E46658 SWGrid 01/29/90 4769.54 5164.26 1005.7 4 4.0 STC TCL VCA, SLM HYS-RS23-0 E46659 SWGrid 01/29/90 4779.54 5163.95 1009.5 1 0.3 SDG TCL VCA, SLM HYS-RS23-1 E46660 SWGrid 01/29/90 4779.54 5163.95 1007.3 3 2.5 SDC TCL VCA, SLM HYS-RS23-3 E46661 SWGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VCA, SLM HYS-RS23-3D E46662 SWGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VCA, SLM HYS-RS34-0 E46663 SWGrid 01/29/90 4790.05 5163.60 1009.1 1 0.5 SDG TCL VCA, SLM HYS-RS34-2 E46664 SWGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VCA, SLM HYS-RS34-3 E46665 SWGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC TCL VCA, SLM HYS-ST01-0 E46687 SWGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VCA, SLM HYS-ST01-3 E46688 SWGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VCA, SLM HYS-ST01-3 E46689 SWGrid 01/30/90 4769.80 5174.56 1009.3 1 0.5 SDG TCL VCA, SLM HYS-ST12-3 E46690 SWGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HYS-ST12-3 E46690 SWGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HYS-ST12-3D E46688 SWGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA SLM HYS-ST23-0D E46692 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VCA, SLM HYS-ST23-0D E46692 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VCA, SLM HYS-ST23-0D E46707 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM									•	
HYS-RS12-3 E46658 SMGrid 01/29/90 4769.54 5163.95 1005.7 4 4.0 STC TCL VOA, SLM HYS-RS23-0 E46659 SMGrid 01/29/90 4779.54 5163.95 1009.5 1 0.3 SDG TCL VOA, SLM HYS-RS23-1 E46660 SMGrid 01/29/90 4779.54 5163.95 1007.3 .3 2.5 SDC TCL VOA, SLM HYS-RS23-3 E46661 SMGrid 01/29/90 4779.54 5163.95 1007.3 .3 2.5 SDC TCL VOA, SLM HYS-RS23-3D E46662 SMGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA, SLM HYS-RS34-0 E46663 SMGrid 01/29/90 4790.05 5163.60 1004.3 4 5.5 STC SLM HYS-RS34-2 E46664 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 SDG TCL VOA, SLM HYS-RS34-3 E46665 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HYS-RS34-3 E46667 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HYS-ST01-0 E46687 SMGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST01-3 E46688 SMGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST12-0 E46689 SMGrid 01/30/90 4769.80 5174.55 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST12-3 E46688 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST12-3 E46688 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST23-0 E46689 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST23-0 E46689 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST23-0 E46689 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST23-0 E46689 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST23-0 E46689 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST23-0 E46692 SMGrid 01/30/90 4769.80 5173.95 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST23-0 E46697 SMGrid 01/30/90 4769.79 5173.95 1009.3 1 0.5 SDG TCL VOA, SLM										
HMS-RS23-0 E46659 SNGrid 01/29/90 4779.54 5163.95 1009.5 1 0.3 SDG TCL VOA, SLM HMS-RS23-1 E46660 SNGrid 01/29/90 4779.54 5163.95 1007.3 3 2.5 SDC TCL VOA, SLM HMS-RS23-3 E46661 SNGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA, SLM HMS-RS23-3D E46662 SNGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC SLM HMS-RS34-0 E46663 SNGrid 01/29/90 4790.05 5163.60 1009.1 1 0.5 SDG TCL VOA, SLM HMS-RS34-2 E46664 SNGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HMS-RS34-3 E46665 SNGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VOA, SLM HMS-ST01-0 E46687 SNGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC/LB TCL VOA, SLM HMS-ST01-3 E46688 SNGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST12-3 E46688 SNGrid 01/30/90 4769.80 5174.55 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST12-3 E46688 SNGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST12-3D E46688 SNGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST12-3D E46688 SNGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST12-3D E46688 SNGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST23-0 E46692 SNGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST23-0 E46692 SNGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST23-0 E46692 SNGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										TOD TON, OD.
HMS-RS23-1 E46660 SMGrid 01/29/90 4779.54 5163.95 1007.3 .3 2.5 SDC TCL VOA, SLM HMS-RS23-3 E46661 SMGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA, SLM HMS-RS23-3D E46662 SMGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC SLM HMS-RS34-0 E46663 SMGrid 01/29/90 4790.05 5163.60 1009.1 1 0.5 SDG TOL VOA, SLM HMS-RS34-2 E46664 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TOL VOA, SLM HMS-RS34-3 E46665 SMGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC/LB TCL VOA, SLM HMS-ST01-0 E46687 SMGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TOL VOA, SLM HMS-ST01-3 E46688 SMGrid 01/30/90 4759.80 5174.56 1006.3 4 3.5 STC TCL VOA, SLM HMS-ST12-0 E46689 SMGrid 01/30/90 4769.80 5174.55 1009.3 1 0.5 SDG TOL VOA, SLM HMS-ST12-3 E46688 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TOL VOA, SLM HMS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TOL VOA, SLM HMS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TOL VOA, SLM HMS-ST12-3D E46689 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-3D E46689 SMGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TOL VOA, SLM HMS-ST23-0D E466707 SMGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
##S-RS23-3 E46661 SMGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC TCL VOA, SLM HMS-RS23-3D E46662 SMGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC SLM HMS-RS34-0 E46663 SMGrid 01/29/90 4790.05 5163.60 1009.1 1 0.5 SDG TCL VCA, SLM HMS-RS34-2 E46664 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VCA, SLM HMS-RS34-3 E46665 SMGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC/LB TCL VCA, SLM HMS-ST01-0 E46687 SMGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST12-0 E46688 SMGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST12-3 E46690 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST12-3 E46688 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA, SLM HMS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA, SLM HMS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA, SLM HMS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA HMS-ST23-0D E46692 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA HMS-ST23-0D E46692 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST23-0D E46697 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST23-0D E46697 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST23-0D E466707 SMGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
HMS-RS34-0 E46662 SNGrid 01/29/90 4779.54 5163.95 1004.3 4 5.5 STC SLM HMS-RS34-0 E46663 SNGrid 01/29/90 4790.05 5163.60 1009.1 1 0.5 SDG TOL VCA, SLM HMS-RS34-2 E46664 SNGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TOL VCA, SLM HMS-RS34-3 E46665 SNGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC/LB TOL VCA, SLM HMS-ST01-0 E46687 SNGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST01-3 E46688 SNGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST12-0 E46689 SNGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST12-3 E46690 SNGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST12-3D E46688 SNGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TOL VCA, SLM HMS-ST12-3D E46688 SNGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TOL VCA HMS-ST12-3D E46688 SNGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TOL VCA HMS-ST23-0 E46692 SNGrid 01/30/90 4769.79 5173.95 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST23-0D E46707 SNGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
HMS-RS34-0 E46663 SMGrid 01/29/90 4790.05 5163.60 1009.1 1 0.5 SDG TOL VCA, SLM HMS-RS34-2 E46664 SMGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TOL VCA, SLM HMS-RS34-3 E46665 SMGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC/LB TOL VCA, SLM HMS-ST01-0 E46687 SMGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST12-0 E46688 SMGrid 01/30/90 4759.80 5174.25 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST12-3 E46690 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TOL VCA, SLM HMS-ST23-0 <td></td>										
HMS-RS34-2 E46664 SNGrid 01/29/90 4790.05 5163.60 1007.1 3 2.5 STC TCL VCA, SLM HMS-RS34-3 E46665 SNGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC/LB TCL VOA, SLM HMS-ST01-0 E46687 SNGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST01-3 E46688 SNGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST12-0 E46689 SNGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST12-3 E46690 SNGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST12-3D E46688 SNGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA, SLM HMS-ST23-0 E46692 SNGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA HMS-ST23-0D E46692 SNGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST23-0D E46707 SNGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
HYS-RS34-3 E46665 SWGrid 01/29/90 4790.05 5163.60 1004.1 4 5.5 STC/LB TCL VOA, SLM HYS-ST01-0 E46687 SWGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST01-3 E46688 SWGrid 01/30/90 4759.80 5174.56 1006.3 4 3.5 STC TCL VOA, SLM HYS-ST12-0 E46689 SWGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST12-3 E46680 SWGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HYS-ST12-3D E46688 SWGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA SLM HYS-ST12-3D E46680 SWGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA HYS-ST23-0D E46692 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VOA, SLM HYS-ST23-0D E46707 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										TOU YUR, GIV.
HMS-ST01-0 E46687 SMGrid 01/30/90 4759.80 5174.56 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST01-3 E46688 SMGrid 01/30/90 4759.80 5174.56 1006.3 4 3.5 STC TOL VCA, SLM HMS-ST12-0 E46689 SMGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST12-3D E46680 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TOL VCA HMS-ST23-0 E46692 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TOL VCA HMS-ST23-0D E46692 SMGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TOL VCA, SLM HMS-ST23-0D E46707 SMGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
HYS-ST01-3 E46688 SWGrid 01/30/90 4759.80 5174.56 1C06.3 4 3.5 STC TCL VCA, SLM HYS-ST12-0 E46689 SWGrid 01/30/90 4769.80 5174.25 1C09.3 1 0.5 SDG TCL VCA, SLM HYS-ST12-3 E46690 SWGrid 01/30/90 4769.80 5174.25 1C05.8 4 4.0 STC/LB TCL VCA, SLM HYS-ST12-3D E46688 SWGrid 01/30/90 4769.80 5174.25 1C05.8 4 4.0 STC/LB TCL VCA HYS-ST23-0 E46692 SWGrid 01/30/90 4779.79 5173.95 1C09.3 1 0.5 SDG TCL VCA, SLM HYS-ST23-OD E46707 SWGrid 01/30/90 4779.79 5173.95 1C09.3 1 0.5 SDG SLM										
HMS-ST12-0 E46689 SWGrid 01/30/90 4769.80 5174.25 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST12-3 E46690 SWGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA, SLM HMS-ST12-3D E46688 SWGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA HMS-ST23-0 E46692 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST23-0D E46707 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
HMS-ST12-3 E46690 SWGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA, SLM HMS-ST12-3D E46688 SWGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VOA HMS-ST23-0 E46692 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST23-0D E46707 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
HMS-ST12-3D E46688 SMGrid 01/30/90 4769.80 5174.25 1005.8 4 4.0 STC/LB TCL VCA HMS-ST23-0 E46692 SMGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VCA, SLM HMS-ST23-0D E46707 SMGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
HMS-ST23-0 E46692 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG TCL VOA, SLM HMS-ST23-0D E46707 SWGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
hms-st23-od E46707 SwGrid 01/30/90 4779.79 5173.95 1009.3 1 0.5 SDG SLM										
HMS-ST23-2 E46693 SWGrid 01/30/90 4779.79 5173.95 1007.1 3 2.7 CSD TCL VCA, SLM									SDG CSD	SIM TOL VOA, SIM

SOIL TYPE: P=PEAT CT=CLAYEY TOPSOIL SDT=SANDY TOPSOIL OSTC=ORGANIC SILTY CLAY STC=SILTY CLAY SDC=SANDY CLAY STC/LB=SILTY CLAY WITH SAND OR SILT LAMINA, LENZES OR BEDS CST=CLAYEY SILT CSD=CLAYEY SAND STSD=SILTY SAND SD=SAND SDG=SANDY GRAVEL

i

														-																											
		•	TCL VOA, SLY			_	TCT VOA, SIN		TCT NOW'S STA		ł .	TOT VOA, STX		TCT VOR, SIM	בכו עסי, אנוי	i		_	TCL VOA, SIM	TCT NOW' STA		_	Š.	TCI VOA, SIN		i G			Š	, c	TCL VCA, SLM	TCT VCA, SUM			TCL VOA, SLM		TCL VOA, SLY	TOT VCA, SEN			
	SOIL		STC/I.5	SDG	216	570/13	ട്ടാ	225	SS	570,73	SICKE	S	CSD	130	S.C	STC/CES	SIZ'CIS	STC/TE	SiSD	SiSD	Siss	22	225	SS	SS	272	STC/13	STC/IB	SO	CS)	ညင	Sic/ila	SIC/IB	CSD	8	8	SIC	STC, T3			
111.0110	BELOW	SCHEME	6.0		10	4.1	0.5	2.5	(n [*1	6.7	0.1	0.3	(4 ()	3.5	9.S	69 C)	6.3	9. 5.	0.3	2.0	5.0	e) e)	3.8	0.1	2.0	6.5	9.5	9.5	0.5	7.0	6.0	9.0	0.0	0.5	2.3	2.0	6.5	0.0			
	SAMPLE	1	4	• •	5	4	٠,	2	(°)	٠,٣	*	٠,	61	(')	٠,	C 1	 က 	۰,	. 1	2	(·1	ເກ	.,	•1	7	6	٠,	7	.,	(1	က	5	٠,	- 1	2	7	3	٠,			
	is .	TOTAL OF	1003.8	1.6001	1007.8	1004.9	1008.5	1007.0	1003.3	1000.3	1000.3	1008.3	1001	3.2021	9.656	1006.0	1,003.0	3.666	1008.6	1006.9	5006.9	1003.6	10001	1011.4	1010.4	1005.9	1002.9	1002.9	1038.5	1007.0	1003.0	1200.0	1000.0	1008.3	1006.8	1006.8	1002.3	9.866			
	1311	NOX.	5173.95	5173.64	5173.64	5173.64	5474.02	5474.02	5474.02	5474.02	5274.02	5483.03	5483.01	5453.01	5483.01	5479.82	5479.82	5479.82	5493.09	5493.09	5493.09	5493.09	5493.09	5493.89	5493.89	5493.89	5493.83	5493.89	5502.33	5502.93	5502.93	5502.93	5502.93	5505.48	5505.48	5505.48	5505.48	5505.48			
	LEGA	IS ST	4779.79	4789.79	£189.73	4769.73	4328.44	1523.44	+328.++	÷328. ÷÷	4828.44	4827.83	+327.81	.327.6.	4827.81	4839.17	4839.17	4839.17	4828.32	4828.32	4828.32	4828.32	4828.32	4835.29	4835,29	+835.29	4835.29	4835.29	4827.56	4827.56	4827.56	4827.56	4827.56	\$839.12	4839.12	4839.12	4839.12	4839.12			
SAMPLE	COLLECTION	DATE	05/05/10	06/08/10	05/02/10	05/30/30	05/15/10	05/18/10	08/18/10	01/31/90	01/31/30	05/33/30	05/15/10	01/31/90	01/31/90	05/31/30	01/31/90	01/31/90	01/30/90	01/30/90	05/32/30	01/30/90	01/36//50	01/31/90	01/31/90	C:/3:/90	01/31/90	01/31/90	01/30/90	01/30/90	05/06/10	01/30/90	01/30/30	01/31/90	01/31/90	01/31/90	01/31/90	01/31/90			į
	BORING	2011	SWCzżd	SPECTO	SAGETC	SAGET	1133714	27.501	NEGrid.	Negrid)2C=1d	Negrid	ESr.1c	NEGRIC	Negrid	N.33-14		NEGrid	NEGrid	NEGETA	NEGrid	Neerid	100 P. C.	NESS-16	NEGrid	Nation:	MEGTIC	NEGrid	NEGETE	NEGrid	NEGrid	NEGRIC	NEGrid	NEGrid	NEGE 1G	Neorid	NEGrid	NEGrid			
	EXCOTEC	V. 5.7.	*69UTE	246695	3.5596	245697	11 CO	2,5302	3.5803	246804	246805	267.97	E46798	561973	3468CC	E46819	246815	E46816	246702	E46705	E46706	246703	246704	546806	E46807	308372	246809	2.6810	£46698	E 46699	246700	246701	E46708	E+6811	E46812	E46818	E46813	£46814			
	SAMPLE		6-66-5-5A-5	-522-ST34-0		8-78-SA-	0-10/M-M()	- COM-Sign	2-10/M-5-1-2	E-10/M-5/:	CE-TOW-SA-	0-10%x-5/c-	- 13/2-X-	2-5/2-5/5	E-13M2-3	3-12-X-12-	-WS-W12-2	-35-XW12-3	525-2301-0	- 0XA-SA-	C :022-Sx-	E-XX-XX1-2	F4S-4X0:-3	13/2-YX12-0	F25-YX12-1	2-577.2-5	E-1312-3	CE-2007-SCE	0-10XZ-Sv-	1-1012-54	F-75-ZY01-2	E-ZYC1-3	CE-10XZ-5XE	EXS-ZY12-0	EMS-ZV12-1	ANS-2Y12-1D	HS-2/12-2	HMS-ZV12-3			
. .		1			1			i			i			!	٠.			: :			: :	:		; ;,	. 4.		::	١,	 	2	1 .		g		1	3.5	'n	å	:,	::	

SOIL TYPE: P-FEAT CT-CLAYEY TOPSOIL SDT-SANDY TOPSOIL OSTO-OFCANIC SILLY CLAY STO-SILLY CLAY STO-SILLY CLAY STO-SILLY SAND STSD-SILLY SAND STSD-SILLY SAND STSD-SILLY SAND STSD-SAND STAD-SAND STSD-SAND STSD-

the sales sales sales

.,/

Page No.

Page | Mo 05/13/

j 1

1.

SACRESCUED SULLS DATABASE

)

									-						
1	Total Org	בני סגל	25 12 L	5.0		5x0 102	TOT OLG	101 OH							
SOILTYPE SANDLEITYPE	TAL-INO	THE TO'	ou :	187. Tro.		TOTA MAR	TAL INO,	(O11 14)	400000000000000000000000000000000000000						
	-		0 C	١		ı									
SANZ		rd.	. 1 (t (t)			, I							
EI EVATION	10:6:	1016.1	1008.6	500	1006.2	£.905.	1006.3	1006.3	1001					,	
FEETNORCH	5258,36	5258.36	5451.94		4787.40	5897,00	5897.00	5897.00	5397.00						
FEETSAST	*2:0::7	\$210.47	4727.84	6.386.2	5356.13	5:75	6175.22	5957.44	5357.44						
SANCOLDATE	65,69,750	05/08/30	02/03/90	06/60/50	05/08/30	05/60/20	05/09/30	05/60/20	03/02/90						
ENCOTECNO		347514	u) (u 1 (u 1 (u 1 (u)	27.75.7	547518	5:7592	E47593	E47594	B43441						
SANPLEID		CD-196-SVE	3-362-5 3-362-0	S.S. 262	202-303-3	25.25.25.25.25.25.25.25.25.25.25.25.25.2	H-364-1	535-565-0	-1975-8G5-1						

SOIL TYPE: P-PEAT CT-CLAVEY TOPSOIL SDT-SANDY TOPSOIL OSTC-ORGANIC SILIY CLAY STC-SILIY CLAY SDC-SANDY CLAY STC/LB-SILIY CLAY WITH SAND GR SILT LAYINA, LENZES OR BEDS CST-CLAYEY SILT CSD-CLAYEY SAND STSD-SILIY SAND SD-SAND STRESANDY (RAVE).

APPENDIX D

GROUNDWATER SAMPLE MASTER DATA TABLE

GROUNDWATER MASTER FILE

				G.00.	DWILL . JULIA				
	SAYPLEID	ENCOTECNO	AQUIFER	BOSDEPTH	SAVCOLDATE	FEETEAST	FYETWORTH	TOCELEVATI	SAYPLETYPE
2	HOW-DWC1	£49374	Fire Sand	83'0"	03/23/90	4929.12	5078.70	1014.62	SIM TOL VOAS
	55W-DWC2	E49306	Fine to Medium Sand	86'6"	03/21/9C	4929.12	5502.14		SIM, TOL VOAS
:	ED31-DW02-D	E49307		0.0	03/21/90	÷929.12	55C2.14	1011.99	
-	_E0H5W02+5	E49310			03/21/90	<u> </u>	55 <u>02.1</u> 4		TOT VOAS
	1204-2M23	E49701	Silty Sardy Clay W/Seams &	70'0"	03/23/30	5237.63	5323.86	1009.41	SLM, TOL VOAS
	_E-W-E-W01	F49698	Layers Clayey Sand	81:"	03/23/90	4942.94	5703,00	1008.05	SLY IP:
	HMM-EXCI-F3	E49699			03,′23,′90	4942.94	57C3.C0	1008.05	
	HW-EW02	249700 249700		7'10"	03,123,190	5052.12	5585.79		SLM, NEW
2	ENW-ENG2-0	E49702			03/23/90	5052.12	5585.79	1007.33	
-;	EW-EW02-D	E49703			03/23/90	5151.44	5449.37		SLM, NEX
:	HYW-EWC4	£49703		8'0"	03/23/90	5151.44	5449.37	1009.94	SLM, NPN
• 1	HWH-EN04-D	E49704			03/23/90	5:5:.44	5449,37	1009.94	
-	HMW-EMO4-FB	E49710			03/23/30	5151.44	5449.37	1009.94	
-	HW-EW06	E49373		8'C"	03/22/90	5151.44	5449.37		SLM, XPN
. 2	574-5406-F3	E49696		• •	03/23/90	5151.44	5449.37	1009.94	
75	EMH-IWO1	E49233	Fine Sand	47'0"	03/20/90	4201.32	5224.28		TAL INC, TCL Org
25	HASH-IWO2	E49697	Medium to Coarse Sand	46'6"	03/23/90	4930.85	5069.05		SIM, TCL VOAS
3.	HWH-IWO3	F49309	Coarse Sand	47'6"	03/21/90	4835.32	5498,20		TAL Inc. TCL VOAS
	HW-IWC4	E49227	Medium Sand	54'0"	03/20/90	4796.28	5857.73		SIM, TCL VOAS
22	HMN-IWO5	E497C5	Medium to Coarse Sand	35'0"	03/23/90	5242.66	5314.18		TAL Ino, TCL VCAS
2 %	=VW-SWC:	749167	Silty Clay w/Sand Seams	17'0"	03/19/20	4201.32	5224.28		SIM. TCL VCAS, NPN
=3	YYW-5W02	E49168	Fine Silty Sand	28'4"	03/19/90	4195.70	5232.68	1018.04	TAL Ino, TCL Org, NEW
24	H-14-SW02-D	E49169	•		03/19/90	4195.70	5232.68	1018.04	TCL Org
<u></u>	:-VW-SW02-F3	F49226			03/20/90	4195.70	5232.68	1018.04	TCL Org
2.5	HMM-SW03	E49165	Organic Clay w/Sand Lenses	7'0"	03/19/90	4835.29	549.89	1012.43	SLM, TCL VOAS, NEW
29	HMW-5W04	E49131	Silty Clay	12'5"	03/18/90	4801.81	5856.6C		SLM, TCL VOAS, NPN
30	-5%-5%C5	F49:32	Coarse Sand and Silty Sandy	6'::"	03/16/90	4961.10	5476.12	10:1.95	TAL Ino. TCL Org. NEW
3:			Clay						
32 23	HMM-SM05-D	E49133			03/16/90	4961.10	5476.12		TCL VOAS
34	HYW-5WC6	FA9134	Silty Clay	10'10"	03/15/90	4977.80	5335.34		SIM. TCL VOAS. NPN
. 5	1344-54C6-F5	E49135	011 01		03/15/90	4977.80	5336.34		SIM, TCL VOAS
26	HMM-SW07	E49141	Silty Clay w/Silt Seams	15'0"	03/17/90	5036.95	5478.99		SLM, NPN
37	FMH-SN07-D	F49142	Silms Class of Sand Sann	10'3"	03/17/90 03/16/90	5036.95 5108.19	5478,99 5393.99	1010.36	TAL INO, TCL Org, NPN
39	HMW-SWC8 F2W-SW08-D	E49136 E49137	Silty Clay w/Sand Seams	10.3	• •	5108.19	5393.99		TAL INO, NEW
39	FM-SNO8-FR	P19138			03/16/90 03/16/90	5108.19	5393.99		TAL INO, NEW
::	HYW-SW09A	E50719	Silty Clay W/Thin Sand Bed	7'0"	C4/12/9C	0.00	0.00		SIM, NEN
. .	HM-SWO9A-FB	E50720	Sirty Stay William Salar Dea	. •	04/12/90	0.00	0.00	1010.88	•
.=	EVWESHIO	F49228	Silty Clay	4!6"	03/20/90	5::2.85	5490.56		SIM. TOL VOAS, NEW
:3	HW-5W10-D	E49229			03/20/90	5112.85	5490.56		TCL VCAS
:-a :-	HMW-SW11	E49049	Silty Clay w/Medium Sandy Silt	19'0"	03/15/90	4913.90	4918.55	,1013.04	SIM, TCL VOAS, NPN
;	HW-SW12	E49232	Silty Clay	10'0"	03/20/90	5029.18	5097.04	1013.14	SIM, TOL VOAS, NFT:
-	HYM-SW14	E49231	Silty Clay	16'0"	C3/2 C /9C	5247.52	5304.50	1009.76	SIM, NEW
	-NA-SW15	E49047	Silby Clay	17"	03/15/90	5380.41	5262_03	1010.93	SIM, NPN
. "	HMM-5W17	E49236	Silty Sand	38'6"	03/20/90	5877.47	5286.53		SLM, NPN
	HMM-SW17-D	249238	_		03/20/90	5877.47	5236.53	1012.83	NPN
	HW-SW18	F49237	Silty Sand	1411"	03/20/90	6150.44	5665.12	1008.58_	SIM. NEN
	F2W-SW19	E48943	Silty Sand	29'0"	03/14/90	5917.08	6145.97	1015.61	SLM, XH3
.3	HYW-SW20	E49048	Silty Clay	6'0"	03/15/90	5024.45	6420.24		SLM, TCL VCAS, NPN
·	EMH-SN21	E49166	Silty Organic Clay	7'0"	03/19/90	4773.86	5467_87		SIM, YPN
,	HMW-SW22	E49706	Sand and Clay Fill	5'0"	03/25/90	5066.25	5550.10		SLM, TCL VOAS, NPN
	HMH-SW22-D	E49706			03/23/90	5066.25	5550.10		TCL VOAS, TCH
	HW-TB-3/15	F49050			03/15/90	0.00	0.co		TCL VCA
	HM-TB-3/16	E49139			03/16/90	0.00	0.00		TCL VOA
	HM-TB-3/19	E49171			03/19/90	0.00	0.00	0.00	TCL VOA

			GEOUT:	DWATER MASTER	FILE			
SAMPLEID	ENCOTECNO	AQUIFER	SOSDEPTH	SAMCOLDATE	FEETEAST	FEETNORTH	TOCELEVATI	SAYPLETYPE
HW-TB-3/20	F±9235			03/20/90	0.00	0.00	0.00	TCL VOA
HMW-T3-3/21	E49311			03/21/90	0.00	U.CC	0.00	TCL VOA
13W-TS-3/22	E49375			C3/22,'90	0.00	0.00	0.00	TCL VOA
HW-TB-3/23				03/23 '90	0.00		0.00	TOL VOA
	-13010							
								•
		**						
								
							·	
								
						······································		
	·							
•								,
						<u>-</u>		
					 -			
								
								

APPENDIX E

TECHNICAL MEMORANDUM TABLE OF CONTENTS

HI-MILL MANUFACTURING COMPANY REMEDIAL INVESTIGATION PHASE I DATA COMPLETENESS

TECHNICAL MEMORANDUM

Prepared by:

Techna Corporation 44808 Helm Street Plymouth, Michigan 48170

TABLE OF CONTENTS

1.0	INTRODUCTION	ı
	1.1 Purpose and Scope	ı
	1.3 Related Documents and Involved Parties	
2.0	BACKGROUND INFORMATION	3
	2.1 Site Location	3
	2.2 Site Description	
	2.3 Site History	. 7
3.0	FIELD ACTIVITIES	9
	3.1 Background Sampling for Chemical Analyses	9
	3.1.1 Purpose	9
	3.1.2 Scope	10
	3.1.3 Completeness	12
	3.2 Soil Sampling for Chemical Analyses	13
	3.2.1 Purpose	13
	3.2.2 Scope	13
	3.2.3 Completeness	15
	3.3 Groundwater Sampling for Chemical Analyses	16
	3.3.1 Purpose	16
	3.3.2 Scope	16
	3.3.3 Completeness	17
	3.4 Surface Water Sampling for Chemical Analyses	19
	3.4.1 Purpose	19
	3.4.2 Scope	
	3.4.3 Completeness	19
	3.5 Sediment Sampling for Chemical Analyses	20
	3.5.1 Purpose	20
	3.5.2 Scope	
	3.5.3 Completeness	21

	3.6 Phys	sical Parameter Testing of Soils	21
	3.6.1	Purpose	21
	3.6.2	Scope	21
		Completeness	
	3.7 Pote	entiometric Surface Determination	22
	371	Purpose	22
		Scope	
	3.1.3	Completeness	23
	3.8 Slug	Tests	23
	3.8.1	Purpose	23
	3.8.2	Scope	23
		Completeness	
4.0	PHYSICAL	CHARACTERISTICS OF THE HI-MILL SITE	25
	4.1 Soils	5	25
		undwater	
		ace Water	
		ments	
	v. v 000.		•••
5.0	NATURE	AND EXTENT OF CONTAMINATION	35
	5.1 Soils	s	35
	5.1.1	Inorganics	35
	5.1.2	TCL Volatile Organics	43
	5.1.3	TCL Organics	45
	5.2 Gro	undwater	46
	5.2.1	Inorganics	48
	5.2.2	TCL Volatile Organics	51
	5.2.3	TCL Organics	53
	5.3 Surl	face Water	53
	531	Inorganics	52
		TCL Volatile Organics	
	5.3.3	TCL Organics	20
	5.4 Sedi	iments	56
	5.4.1	Inorganics	56
	5.4.2	TCL Volatile Organics	57
		TCL Organics	

6.0	DATA	ADEQUACY EVALUATION	58
	6.1	Data Completeness and Accuracy	58
	6.2	Identified Data Gaps	60
	6.3	Recommendations for Round Two Groundwater Sampling	61
	(5.3.1 Original Proposed Scope	61
	(5.3.2 Recommended Modifications to Scope	62

APPENDICES

VOLUME I

- A Summary of Short List Metal Analysis Results Soils
- B Summary of TAL Inorganic Analysis Results Soils
- C Summary of TCL Volatile Organic Analysis Results (Species Detected) Soils
- D Summary of TAL Inorganic Analysis Results (Species Detected) Groundwater
- E Summary of Short List Metal Analysis Results Groundwater
- F Summary of TCL Volatile Organics Results (Species Detected) Groundwater
- G Summary of Ammonia and Nitrate/Nitrite Analysis Results Groundwater
- II Slug Test Data Time Versus Drawdown
- 1 Soil Boring Logs and Well Installation Diagrams
- J Physical Soil Test Analysis Results
- K Master Data Table for Soil Samples

VOLUME II

- L. Laboratory Reports for Short List Metal Analyses of Soils
- M Laboratory Reports for TAL Inorganic Analyses of Soils
- N Laboratory Reports for TCL Volatile Organic Analyses in Soils
- O Laboratory Reports for TCL Organic Analyses in Soils
- P Master Data Table for Groundwater Samples
- Q Laboratory Reports for TAL Inorganic Analyses of Groundwater
- R Laboratory Reports for Short List Metal Analyses of Groundwater
- S Laboratory Reports for Ammonia and Nitrate/Nitrite Analyses of Groundwater
- T Laboratory Reports for TCL Volatile Organic Analyses of Groundwater

- U Laboratory Reports for TCL Organic Analyses of Groundwater
- V Master Data Table for Surface Water Samples
- W Laboratory Reports for Inorganics Analyses (TAL Inorganics, Short List Metals, Ammonia Nitrate/Nitrite and Hexavalent Chromium) of Surface Water
- X Master Data Table for Sediment Sample
- Y Laboratory Reports for TCL Inorganic Analyses of Sediments
- Z Summary of Temperature, Specific Conductivity and pH Measurements Groundwater
- AA Laboratory QA/QC Data Evaluation Summary

LIST OF FIGURES

- Figure 2-1 Site Location Map
- Figure 2-2 Site Features Map
- Figure 3-1 Background Soil, Sediment and Surface Water Sample Point Map
- Figure 3-2 Monitor Well and Staff Gauge Location Map
- Figure 4-1 Depth to Clay Contours
- Figure 4-2 Shallow Well Potentiometric-Surface Contour Map (April 12, 1990 Data)
- Figure 4-3 Intermediate Well Potentiometric-Surface Contour Map (April 12, 1990 Data)
- Figure 4-4 Deep Well Potentiometric-Surface Trend Map (April 12, 1990 Data)
- Figure 4-5 Shallow Well Potentiometric-Surface Contour Map Without Well SW-2 (April 12, 1990 Data)
- Figure 5-1 TAL Inorganics and Short List Metals Sample Point Map
- Figure 5-2 TCL Volatile Organics and TCL Organics Sample Point Map

LIST OF TABLES

- Table 4-1 Potentiometric Surface Measurements at Monitor Wells and Staff Gauges
- Table 5-1 Summary of Background Concentrations and Statistical Data for Short List Metals in Soils
- Table 5-2 Summary of Soil Samples with Short List Metal Concentrations Above Background Criteria (Mean + 2σ)
- Table 5-3 Summary of Background Concentrations and Statistical Data for TAL Inorganics in Soils
- Table 5-4 Summary of TCL Volatile Organic Analysis Results for Soils Samples (Species Detected Without B, J or BJ Flags)
- Table 5-5 Summary of TCL Organics Analysis Results for Soils Samples
- Table 5-6 Summary of Short List Metals Analysis Results for Groundwater Samples (Species Detected Without U,B and/or N Flags)
- Table 5-7 Summary of TCL Volatile Analysis Results for Groundwater Samples (Species Detected)

APPENDIX F

BORING LOGS AND WELL CONSTRUCTION

SW-1	
DM-T	

LOG OF SOIL BORING NO. _____SW-1



()

McDOWELL & ASSOCIATES

Geotechnical Engineers

89-630 JOB NO._

PROJECT Hi Mill Facility

M-59 & Waterbury LOCATION

DATE ___11-20-89 Highland Township, Michigan SURFACE EI EV. __ Natural Ory Den Wt. P.C.F. Wt. P.C.F. Penetration Moisture Unc. Com .ple & Type Depth SOIL DESCRIPTION Legend Strength PSF Blows For 6" 0'4" Wet gray clayey SAND fill 3 4 Stiff moist brown silty CLAY, with gray & tan silt lenses, plastic 6 7 6 9 13 8 10 10'6" Stiff moist blue silty CLAY, with plastic 5 8 11'9" Moist variegated fine 12 9 12'0" silty SAND, well graded Stiff moist blue silty CLAY, with gray silt lenses, seams of wet gray 15 silty sand between 16'6" - 16'9" 16 3 6 17 5 17'0" 18 19 20 21 22 23 24 REMARKS: GROUND WATER OBSERVATIONS TYPE OF SAMPLE - DISTURBED 0 G.W. ENCOUNTERED AT INS. - UNDIST. LINER 11 6 G.W. ENCOUNTERED AT FT. INS. S.T. - SHELBY TUBE G.W. AFTER COMPLETION FT. INS. S.S. - SPLIT SPOON G.W. AFTER HRS. HRS. Auger - ROCK CORE - PENETROMETER Standard Penetration Test - Driving 2" 00 Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

Bori	ng Nosw-	1		
Job No. 89-630 Well	No sw-	1	Type	2"
Piez	ometer No	-		
Type and Size of Auger	41"	From <u>17</u>	'0"	To Surface
Type and Size of Casing		From	************	То
Wash Boring With	Bit	From		То
Size of Screen010		Type	SS	
Bottom of Screen Set At	16'6"			
Riser Pipe 2" PVC from 11'6"	to surface			
Filter No. 3 tan sand	From 16'6	5"	To8	
Bentonite 1 pellets	From 8'0)" ———	To	10"
Grout Cement/bentonite	From 7'	0"	To s	ırface
Well Protector 4" steel				
Developed With		· · · · · · · · · · · · · · · · · · ·	 	
Remarks Top of casing elev	ation 1,013.17	•		
				
			· · · · · · · · · · · · · · · · · · ·	

C77.7	•
211	-,

LOG	0F	SOIL	BORING	NO.
-----	----	------	--------	-----

M

McDOWELL & ASSOCIATES

Geotechnical Engineers

JOB NO. _____89-630

PROJECT Hi Mill Facility

LOCATION M-59 & Waterbury

			ACE ELEV.	DATE11-13-						
ype	Depth	Legend	-	SOIL DESCRIPTION	Penetration Blows For 6"	Moisture %	Natural Wt. P.C.F.	Ory Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str %
		のなが		Sandy brown TOPSOIL						
4	1	37.20.5	1'0"			ļ	ļ	ļ		ــــ
+				Moist oxidized brown fine		 	 -	ļ		├ ─
+	2			SAND, with a trace of sil	.t	 	 		ļ	┼
┿	3		3'0"			 	 			}
+	J		3.0	Compact moist brown fine	 	 	 			├
+	4			SAND, with a trace of	-	 	†			├─
+	<u> </u>			silt			 			
\top	5									
					3					
	6		6'0"		4					
				Chiff maint house alone	4					
	7			Stiff moist brown clayey SILT	4	<u> </u>				
_				3111	<u> </u>	<u> </u>				<u> </u>
+	8				 	<u> </u>	 			
+					<u> </u>	 	 			
+	9				 		 			
+	10				 		 			- -
+	10		10'3"		2		 			
-	11				3					<u> </u>
7				Medium compact moist tan	2	 				
	12			fine silty SAND	3					
T										
\perp	13									
\perp	14									
\perp					<u> </u>	ļ				
_	15		15'6"		<u> </u>	<u> </u>		ļļ		
	4.6		12.6.	Compat int top Sine	6	 				
-8	16			Compact wet tan fine silty SAND, with seams	8	 				
-	17			of clayey silt	9	 				
-				or crafel arre	- <u>-</u> -		 -			
+	18		18'0"			<u> </u>				
Ť	-									
T	19									
]]		Compact wet tan sandy	5					
	20	![SILT, with seams of	_6					
_				clayey silt	_5					
_	21	<u> </u>			10	 				
+	100	}								
+	22	{ 			 	 				
+	23	{			 	 	 			
十	1-3	(23'6"		1					
+	24	******	43 6"	Compact test ten fine						
十	<u> </u>			Compact wet tan fine silty SAND						
I	25]		arrel out						
	OF SAM	1	REMARKS:			GRO	DUND WATE	A OBSERVA		
	- DISTUR - UNDIST					ENCOUNTER		15		INS.
T.	- SHELBY	TUBE				ENCOUNTER AFTER COM		23	श. श. 0	INS. INS.
	- 3PTH 3	oruum		Panetration Test - Driving 2" 0D Sampler 1' With		AFTER		HAS.		INS.

Geotechnical Engineers

89-630 JOB NO.____

PROJECT_	Hi	Mill	Facility

G.W. VOLUMES Medium Hollow Auger

LOG OF SOIL BORING NO.

LOCATION M-59 & Waterbury DATE ___11-13-89 Highland Township, Michigan SURFACE ELEV.__ Ory Den Wt. P.C.F. Penetration Moisture Unc. Comp. SOIL DESCRIPTION Depth Lagend Blows For 6" Wt. P.C.F. Strength PSF Compact wet tan fine 26 silty SAND 27 28 E 6 29'0" 29 6 Stiff moist blue silty 6 7 CLAY, with clayey silt 30 5 F 4 31 5 32 32'0" 4 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 **GROUND WATER OBSERVATIONS** REMARKS: TYPE OF SAMPLE - DISTURBED 6 FT. G.W. ENCOUNTERED AT INS. U.L. - UNDIST. LINER G.W. ENCOUNTERED AT FŤ. INS. S.T. - SHELBY TUBE S.S. - SPLIT SPOON R.C. - ROCK CORE () - PENETROMETER 0 23 INS. G.W. AFTER COMPLETION FT. HRS. Standard Penetration Test - Driving 2" 00 Sampler 1' With G.W. AFTER FT. INS.

140# Hammer Falling 30"; Count Made At 6" Intervals

Boring No. SW-2 Well No. SW-2 Job No. 89-630 Type 2" Piezometer No. To 30'0" Type and Size of Auger 42" From 0 Type and Size of Casing None From _____ To _____ Wash Boring With None Bit From To Type Stainless Size of Screen _____.010 Bottom of Screen Set At _____28'4" Riser Pipe _ 2" PVC (10' sections) To 12'10" From 28'4" Filter #3 Tan Sand To 10'4" 12'10" From 10'4" From Grout To Well Protector _____ 4" Round Steel with hinged cover Developed With _____ Remarks Top of Casing Elevation 1,018.04

S.S. - SPLIT SPOON

R.C.

- ROCK CORE

- PENETROMETER

McDOWELL & ASSOCIATES

Geotechnical Engineers

89-630

PROJECT	Ηi	Mill	Facility

LOG OF SOIL BORING NO. _____

G.W. AFTER COMPLETION

G.W. AFTER

G.W. VOLUMES

FT.

HRS.

INS.

INS.

LOCATION M-59 & Waterbury JOB NO.__ 11-17-89 Highland Township, Michigan DATE_ SURFACE ELEV. Natural Dry Den Unc. Comp. Wt. P.C.F. Wt. P.C.F. Strength PSF. Moisture Penetration .iple & Type SOIL DESCRIPTION Depth Legend Blows For 6" % 012" -ASPHALT 0'6" -- Moist medium discolored SAND & GRAVEL fill 000 2 000 -Wet fine silty oxidized brown SAND & GRAVEL fill 3 3'0" - Wet silty sandy clayey 4 4'0" organic PEAT, with 4'6" vegetation 5 L Moist silty organic 5'6" discolored CLAY, with vegetation 7'0" -Moist silty organic CLAY, with oxidation streaks, a trace of vegetation -Moist silty oxidized 9 slightly organic variegated CLAY, with wet sand lenses 10 11 12 13 14 15 17 18 19 20 21 23 25 REMARKS: GROUND WATER OBSERVATIONS TYPE OF SAMPLE - DISTURBED INS. G.W. ENCOUNTERED AT - UNDIST. LINER U.L. G.W. ENCOUNTERED AT FT INS S.T. - SHELBY TUBE

Standard Penetration Test - Driving 2" 00 Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

Boring No. ___sw-3 Job No. 89-630 Well No. _____ SW-3 Type 2" Piezometer No. To surface Type and Size of Auger 41" I.D. From 7'0" Type and Size of Casing _____ From ____ To _____ Wash Boring With ______ Bit From ____ To _____ Size of Screen _____.010" Type ss Riser Pipe 2" PVC from 2'0" to surface Filter No. 3 tan sand From 7'0" To 1'9" Bentonite | Pellets From To Grout Cement/bentonite From 6" To surface Well Protector 4" steel Developed With _____ Remarks __ Top of casing elevation 1,012.43

SW	-4
----	----

	LOG	0F	SOIL	BORING	NO.
--	-----	----	------	--------	-----

McDOWELL & ASSOCIATES Geotechnical Engineers

PROJECT Hi Mill Facility

	Geolechnical	Engineers
AL,	100 110	89-630

LOCATION M-59 & Waterbury

SURFACE ELFV. DATE 11-15-89

Highland Township, Michigan

Sample	Depth	Legend	SOIL DESCRIPTION	Penetrati		Moisture	Natural	Dry Den	Unc. Comp.	Str.
& Type	F	112000000000000000000000000000000000000	0'1" ← ASPHALT	Blows For	0	%	Wt. P.C.F.	Wt. P.C.F.	Strength PSF.	-%
	1		0'7" Moist exidized medium to							
			coarse SAND, with fine							
	2		gravel, well graded							
			216"							
	3	,	Moist gray fine clayey	<u> </u>						
	1		3'6"	<u> </u>						
	4		Clayey sandy fiberous	-						\vdash
 	5		black PEAT							\vdash
A	13		Chies he was this main	. –	4					
A	6		Stiff to very stiff moist	- 1	5					
			blue silty CLAY, with silt seams & vegetation		9		-			
	7		, sile seams a vegetation		12					
<u> </u>	8		•	<u> </u>						
B					7					
	9	1111	9'0" Very stiff moist brown		12			-		$\vdash \vdash \vdash$
	10		clayey SILT, with blue		17					
	10		10'0" clay seams, non-plastic	<u> </u>	17	-				
	11			-						
	1	////								
	12									
	13			_						
	<u> </u>			_						
	14			-						
	15			-						
C	113		P.P. 1 TSF	-	3					
	16		F.F. I ISI	-	<u>3</u> 3					
\		<i>Y////</i>			3					
	17		Diam maint blue eilte		3					
			Firm moist blue silty							
	18	<i>\///</i>	CLAY, plastic	_						
 	10			<u> </u>						
 	19	V///		-	-					
 	20	Y///		-						
В	20	<i>\///</i>	P.O. 0.5 TSF	<u> </u>	2			-		
"	21	V///			2					
		<i>\///</i>			4					
	22	<i>Y////</i>			4					
	23	<i>V///</i>	23'0"							
	124	<i>\///</i>	1	<u> </u>						
└	24	////	Soft moist blue silty	\vdash			 			
\dashv	25	V///	CLAY, plastic				 			$\vdash \vdash \vdash$
	-	Y///	1	-						
TYP	E OF SAN	IPLE	REMARKS:			GRO	TAW DNU	ER OBSERV	ATIONS	
D.	- DISTUR	IBED				ENCOUNTER	ED AT	2	ғт. _О	INS.
S.T.	- UNDIS1 - SHELB	y tube		(S.W.	ENCOUNTER	ED AT	~	FT.	INS.
	SPLIT Rock (Standard Penetration Test - Driving 2" 00 Sampler 1' With			AFTER COM AFTER	rttirUN	HRS.	त. त.	INS. INS.
1 1.0	PENET	ROMETER	140 # Hammer Falling 30"; Count Made At 6" Intervals			VOLUMES		··· • ·		



Geotechnical Engineers

nn NO 89-630

angert Hi Mill Facility

LOCATION M-59 & Waterbury

11-14-89 DATE 11-15-89

Highland Township, Michigan

	SURF	PACE ELEV. DATE 11-15-89	_	maga	ILAIIG .	COWITSTIT	p, Mich	rga.
e Depth	Legend		Penetration lows For 6'	Moisture	Natural Wt. P.C.F.	Ory Den Wt. P.C.F.	Unc. Comp. Strength PSF	Str.
2	////	0.5: 1.1.1.3.	2					
26	////	Soft moist blue silty	2					
	////	CLAY, plastic	2		<u> </u>			<u> </u>
27		27'0"	14		ļ			ــــــ
			ļ	 	<u> </u>		<u> </u>	
28			ļ					<u> </u>
	1		L					<u> </u>
29			<u> </u>		ļ <u>.</u>			
	Ì			 	ļ			<u> </u>
30					<u> </u>			↓
	ļ			ļ	<u> </u>		<u> </u>	
31					<u> </u>			├ -
				+	 	ļ		 -
32				 	ļ			├
				1				
33				+	 			
		41" Hollow auger, Boring	<u> </u>	 	 	 		
34		advanced to 7'0" on 11-14-89		+	 	 		
1 35		terminated due to rain and	<u> </u>	+	-	-		
35	j	lightning, boring extended		+	 	 		
36		to completion 11-15-89. Hole		+	-	-		
30		grouted with Cement Bentonite	<u> </u>	 	 		 	
37		Slurry by Tremie full depth.			 			
		Stuffy by fremie tuff depen.		 	 			-
38				+	 			
1 30				+				\vdash
39				+	 			
+ 133	•					-		<u> </u>
40			}	 	 			
				1				
41								
				1	1			
42	1							
11:-			1					
43								
44								<u>-</u>
45								
46								
		r						
47			<u> </u>			<u> </u>		
			<u> </u>	ļ	ļ			ļ
48			-	1		 		
			-	 	 	 		
49	,		 	 		} -		
			<u> </u>	 	 	 		
50		·		 				
				<u> </u>	<u> </u>	<u> </u>		
TYPE OF SAM		REMARKS:				ER OBSERV		
D DISTURI U.L UNDIST				. ENCOUNTE		2	я. 0	INS.
S.T SHELBY	TUBE			/. Enco untei /. After con			हा. हा.	INS. INS.
	POUN	Canada and Canada Tree Chining 2" Off Canada 1' With			52 11018	unc		INS.
S.S SPLIT S R.C ROCK C	ORE	Standard Penetration Test - Driving 2" 0D Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals		/. AFTER /. VOLUMES		HRS.	FT.	1113.

ing	ne sn	11	BORING	NΩ	SW-4A
LUG	DL 20	11	BURING	πυ.	



Geotechnical Engineers

PROJECT	Нi	Mill	Facility	

		JOB (NO	89-630	ເດ	CATION	M-59	& Wat	erbury	,	
		SURF	ACE ELEV	DATE	<u>11-16-</u> 89						
Sample & Type	Depth	Legend		SOIL DESCRIPTION		etration For 6"	Moisture %		Ory Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
	1 2		0'1" 0'7"	ASPHALT Moist oxidized medi coarse SAND, with f gravel, well graded	ine						
	3		2'6" 3'6"	Moist gray fine cla							
	5			Clayey sandy fibero							
	6			Stiff to very stiff plastic blue silty with silt seams and	CLAY,						
A	8		7'0"	vegetation Extremely stiff moi		7 9					
В	9		10'0"	variegated silty CI with fine sand seam lenses, plastic		18 20 5					
	10		10,0	Very stiff to extre		11 17 23					
	12			plastic		5 7 12					
Ω	14		13*6"	Stiff to very stiff	moist	21 6 8 11					
E	15			blue silty CLAY, wi silt lenses, plasti	ith	13					
	17		17'0"			4					
	18										
	20	4									
	22	1		•							
	23	•									
	25										
D. U.L.	e of Sar - Distu - Undis - Shele	rbed T. Liner	REMARKS:			G.W.	ENCOUNTER ENCOUNTER	ED AT	O O	FT. 0 FT.	INS.
S.S.	- SPLIT - ROCK	SPOON		-Penetration Test - Driving 2" 00 Sampler		G.W.	AFTER COM AFTER	PLE HON	HRS.	ਜ. ਜ.	INS. INS.

		boring No.	· —	W-4A			
Job No.	89-630	Well No.	S	W-4A	Ту	pe <u>2"</u>	
		Piezometer	No.				
Type and	Size of Aug	er <u>41" I.</u>	D.	From _	17'0"	To _	surface
Type and	Size of Cas	ing		From _		To _	
Wash Bor	ing With		Bit	From _		To _	· · · · · · · · · · · · · · · · · · ·
Size of	Screen	.010		Type _	ss	 	
Bottom o	f Screen Set	At 12'6"			,	·	
Riser Pi	pe 2" PVC 7'6	" to surface			•		
Filter _	No. 3 tan san	d F	rom	L2'6"	To .	6'10"	
Bentonit	e ½" pellets	F:	rom _	6'10"	To	6'0"	
Grout _	Cement/bentonit	e F	rom	6'0"	To .	Surface	<u>.</u>
Well Pro	tector 4"	steel					
Develope	ed With			·	····		
Remarks	Top of casing	elevation 1,	010.18'				
					<u></u> -		
			·····				

Geotechnical & Hydrogeological Services Materials Testing & Inspection

CIA	_	ς
211		_

LOG (OF	SOIL	BORI	NG	NO
-------	----	------	------	----	----

Geotechnical Engineers

_	MO		8	9-	6	3	0	

PROJECT	Hi	Mil1	Facility
FRUSEGI.			

M-59 & Waterbury LOCATION_

DATE 11-21-89 Highland Township Michigan CHREACE ELEV

SURFAC		ACE ELEV	DATE 11-21-	DATE 11-21-89		Highland Township, Michi					
ample Type	Depth	Legend		SOIL DESCRIPTION	Penet Blows	ration For 6"	Moisture %	Natural Wt. P.C.F.	Drv Den Wt. P C.F.	Unc. Comp. Strength PSF	Str.
		REPORTER TO	0'3"	Wet sandy TOPSOIL fill	\Box						
	1										
				Wet dark brown fine SAND	. [
_	2			fill, with a trace of	L			ļ			
				coarse sand, organic,	L			<u> </u>			
_	3		3'0"	well graded	<u> </u>						
	_				-			<u> </u>			
-+	4			Compact wet brown medium	-						
	5			to coarse SAND, well	<u> </u>						
				graded	 	4					 -
	6		6'0"		ŀ	5					-
	<u> </u>	7777		Moist blue silty sandy	 	3					
	7		7'0"	CLAY, with sand & silt	r	4					
			/-0	seams, plastic							
	8			_	Γ						
	9]									
		1			L	_					
	10				L						
					-						-
	11	4			 	-					
-+	10	4			┝	-					
	12	4			-						
	13	4			ŀ						
-+	13	1			-				-		
-	14	1]		ŀ						
	1 -	1									
一十	15	1	1								
		1	-								
	16]									
]									
	17	_									ļ
	 	4			-						
	18	-			- 1						
	40	4	1		H						
	19	-			H		_				
	20	-{			<u> </u>		_	 			
	20	1			H			 			
	21	1			h			 -	-		
\dashv	 	1			ŀ			 		-	
	22	7			ľ						
]									
	23										
\Box		_									
	24	4						<u> </u>			
-	 	4			Į.						
	25	4			Ļ			 			
	L							1			
	OF SAM		REMARKS:		J				ER OBSERV	_	
0. U.L.	- DISTU - Undis				- 1		ENCOUNTER ENCOUNTER		0	я. 0 я. 6	INS.

- UNDIST. LINER
- SHELBY TUBE
- SPLIT SPOON
- ROCK CORE

Standard Penetration Test - Driving 2" 0D Sampler 1' With

G.W. ENCOUNTERED AT 1 FT. INS. G.W. AFTER COMPLETION INS. FT. G.W. AFTER

C ME VOLUMES

Hallow Auger FT. INS.

	Boring No.	SW-5	_	
Job No. 89-630	Well No.	SW- 5	Туре	2"
	Piezometer No.		_	
Type and Size of Auger	4 ¹ " I.D.	From	<u>0</u> To	7'0"
Type and Size of Casin	ng	From	То	
Wash Boring With	Bit	From	To	
Size of Screen0	10	Туре	SS	
Bottom of Screen Set	At6'11"			
Riser Pipe 2" PVC from	<u>1'</u> 11"			
Filter #3 Tan Sand	From	6'11"	To1'6"	
Bentonite Pellets	From	1'6"	To 0'6"	
Grout Cement/Bentonite	From	0'6"	To Surfa	ce —
Well ProtectorN	one			
Developed With				
Remarks	g Elevation 1,011.9	5		
		<u>.</u>		



Geotechnical Engineers

PROJECT Hi-Mill Facility

JOB NO. 201-8058-13 LOCATION M-59 and Waterbury SURFACE ELEV.______ DATE 11/22/89 Highland Township, Michigan

		30111	ALE ELEV.	UATE 11/ 22/ 03					77 11101119	
Sample Type	Depth	Legend			etration s For 6"	Maisture %	Natural Wt. P.C.F.	Dry Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
			0"-6"	Sand, pred. fine to medium						
	11			some silt, ocassional fine	_					
				gravel, sub-angular to sub-			 	<u> </u>		
	2			round, moist to saturated	4		 -	-		
	-						 		<u> </u>	
				brown	5		 	_		├
	3	Α	6"-1'6"	Clay with considerable	4					$ldsymbol{ldsymbol{ldsymbol{eta}}}$
				organic content and some						
	4			silt, medium to high plasti-						
			ļ	city, moist to saturated,						
	5			mottle dark brown, orange						
					9					\vdash
	6	В	1.60 2.00	brown and blue grey				 	 	┢──
		D	1'6"-3'3"	Clay with some silt and some	18	 	 	 		
	├ ──			organic content, medium to	_22_		 -	ļ		
	7			high plasticity, moist,	<u></u>		ļ <u></u>			L
				mottle orange brown and						<u> </u>
	8			blue grey	i	}	•		İ	1
			3'3"-6'	Clay with some silt,						
	9			occasional fine sand, medium			<u> </u>		i	\vdash
	╅┷╌┤				 -		ļ			
	+			to high plasticity, stiff,	├			 	 	
	10			slightly moist, orange	ļ	<u> </u>	ļ			⊢
_	4			brown and blue grey,		<u> </u>	ļ	ļ <u>.</u>		
	11		ļ	occasional light grey			ļ. <u>. </u>	<u> </u>		!
				mottling	<u> </u>		<u> </u>			<u> </u>
\perp	12						<u> </u>			<u> </u>
			NOTE:	Drill rig broke trying to						
	13			withdraw A-rod from 6'6".						
				Borehole grouted and						
	14			abandoned.	<u> </u>	——	 			
	 ' -			abandoned.		-	 	 		\vdash
	100				<u> </u>		 	 		
	15		5'0"	EOB			 			├
					<u> </u>		<u> </u>	ļ		<u> </u>
	16						<u> </u>	<u> </u>		
\Box	17		}							
_		ı								\Box
\neg	18				<u> </u>				·	
	1.0				-		 	<u> </u>		
	10				 		 			\vdash
	19					 		 		
	+						 	 	 	
	20		1			 	 	ļ	 	—
}			1						<u> </u>	
	21		1					<u> </u>		
7			1					<u> </u>		
	22		1					1	L_	
	 									Г
	23	İ	1			 	 	 	 	
\dashv	23	ł			\vdash	 	+	 	 	+
 i	124	}				 	 	 	 	├-
	24	1		•	— —		 	 		├
		 	}		<u> </u>	ļ	 			↓ _
	25	1						<u> </u>	<u> </u>	
TYP	E OF SAM	PLE	REMARKS:		1	GR	OUND WAT	ER OBSERV	ATIONS	
0.	- DISTUR			Joel Hunt, Techna	1 ~ ~		RED AT NO		FT.	INC
U.L.	- UNDIST	LINER	39 ~1			ENCOUNTE		VIC.	FI. FT.	INS
	- SHELBY : SPLIT :					AFTER CON			н.	INS.
R.C.	- ROCK (ORE		Penetration Test - Driving 2" 00 Sampler 1' With	G.W.	AFTER		HRS.	FT.	INS.
1 1) - PENETI	ROMETER	140#	Hammer Falling 30"; Count Made At 6" Intervals	GW	VOLUMES				

140# Hammer Falling 30"; Count Made At 6" Intervals



Geotechnical Engineers

PROJECT Hi-Mill Facility

JOB NO. 201-8058-13

LOCATION M-59 and Waterbury

	_	 Surfa	ACE ELEV.	DATE 12/14/8	9		High	land T	ownship	o Michic	an
Sample & Type	Depth	Legend		SOIL DESCRIPTION	Pene	etration For 6"	Moisture %	Natural Wt. P.C.F.	Dry Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
			0"-1'0"	Sand and gravel, well							
 -	1 -	Ì		graded to fine gravel, round to sub-round, mois	<u>+</u>						
 	2			to saturated, brown	Ŭ				-		
				·							
	3		1'0"-2'6"	Silty clay with some							
\vdash	_	•		medium to coarse sand,							
\vdash	4			some roots or wood, dark brown, light brown and	•						
	5			grey green layers							
	6		2'6"-13'0"								
	 			high plasticity, stiff,							-
\vdash	7			moist grey and tan laminations, some dark		\vdash					
	8_]		brown spots and reddish							
]		stains between laminatio	ns	7					
	9	A				11		<u> </u>			
-	10					$\frac{11}{17}$					
-	7	1				-					
	11	1	11'0"	EOB							
١	42	1 _				4					
	12	В				6		 			
-	13_	1				7					
]									
	14]									
<u> </u>	1 15	4									
	11.3	1									
	16									-,	
]									
<u> </u>	17	4 /					· · · · · ·				\longrightarrow
 	18	1				-					
]									
	19]									
	20	4				<u> </u>					
-	1 20	1				-		-			
	21	1									
]									
	22	4				ļ		 			
-	23	-				-		 			
		1	}								
	24]									
·	1 25	-{						-			
, —	25	4				 					
TY	PE OF SAI	MPLE	REMARKS:			 	GR	OUND WAT	ER OBSERV	ATIONS	
0.		R8ED		ob Erps, Techna			ENCOUNTER	RED AT		гт . 6	INS.
S.1	T SHELE	IY TUBE					ENCOUNTER AFTER COM			त. त.	INS.
S.S R.(S SPLIT C ROCK } - PENET	SPOON CORE TROMETER		netration Test - Driving 2" DD Sampler 1' With nmer Falling 30": Count Made At 6" Intervals		G.W.	AFTER VOLUMES		HRS.	FT.	INS.

	Boring No. SW	-6B	_		
Job No. <u>201-8058-13</u>	Well No. SW	-6B	Туре	2"	
	Piezometer No.				
Type and Size of Auge:	41/2"	From 1	1'0"	To _	Surface
Type and Size of Casi	ng	From		To _	
Wash Boring With	Bit	From		To _	•
Size of Screen 0.010		Type	SS		
Bottom of Screen Set	Ατ <u>10'10"</u>			•	
Riser Pipe 2" PVC from !	5'10" to surface		·		
Filter No. 3 tan sand	From _	10'10"	To _4	17"	
Bentonite Pellets	From _	4'7"	To _2	<u>'5"</u>	
Grout Cement/beutonite	From _	2'5"	To S	urface	-
Well Protector 4" dia	méter, 5' long rou	und steel with	n hinged 1	ocking	cover
Developed With					-
Remarks Top of casing	elevation 1011.63	3			

nc	UE	cuii	BORING	NO	SW-7	
LVU	u.	3016	00111140	110		



S.T. - SHELBY TUBE
S.S. - SPLIT SPOON
R.C. - ROCK CORE

McDOWELL & ASSOCIATES

Geotechnical Engineers

89-630

PROJECT	Hi	Mill	Facility	

_ LOCATION M-59 & Waterbury SURFACE ELEV.____ DATE 11-21-89 Highland Township, Michigan Natural Dry Den Unc. Comp. Wt. P.C.F. Wt. P.C.F Strength PSF. Sample & Type Penetration Moisture Str SOIL DESCRIPTION Legend Blows For 6" % Wet brown SAND & GRAVEL fill, with stones 1'6" 4 Α Stiff moist blue silty 9 3 CLAY fill, with sand and 5 4 layers of wood 3 4'6" Firm moist variegated В 2 6 silty CLAY fill, with roots and sand layers 3 5 С 6 8 8 8'6" 11 9 13 10 Very stiff moist blue silty CLAY, with silt 12 seams, plastic 13 14 7 27 (2000)15 6 15'0" 9 16 17 18 19 20 21 22 23 24 25 **GROUND WATER OBSERVATIONS** TYPE OF SAMPLE REMARKS: - DISTURBED FT. G.W. ENCOUNTERED AT INS. * Calibrated Penetrometer - UNDIST. LINER

Standard Penetration Test - Driving 2" OD Sampler 1' With

140 # Hammer Falling 30": Count Made At 6" Intervals

G.W. ENCOUNTERED AT

G.W. AFTER

G.W. AFTER COMPLETION

INS.

INS.

INS.

FT.

FT.

FT.

HRS.

SW VOLUMES Hollow Auger

Во	oring No	sw-7								
Job No. 89-630 We	ell No.	SW-7	Тур	2"						
P:	iezometer No.									
Type and Size of Auger	4½" I.D.	From	0	To						
Type and Size of Casing		From _		То						
Wash Boring With	Bit	From		То						
Size of Screen0	10	Type	PVC							
Bottom of Screen Set At	15'0"									
Riser Pipe 2" PVC from 10	·0"									
Filter #3 Tan Sand	_ From _	15'0"	To _	9'0"						
Bentonite Pellets	From _	9'0"	To _	7'11"						
Grout Cement/Bentonite	From _	7'11"	To _	Surface						
Well Protector4" Dia steel with locking hinged top										
Developed With										
Remarks Top of Casing	Elevation 1,010	.36								
			·							



	Geotechnical Engineers	PROJECT HI-MILL PACILITY
MA	J08 NO. 201-8058-13	LOCATION M-59 and Waterbury
	SURFACE FLEV	DATE 12/14/89 Highland Township, Michigan

SURFACE ELEV.				DATE 12/14/89			Highland Township, Michi			
Sample & Type	Depth	Legend			tration For 6"	Moisture %	Natural Wt. P.C.F	Dry Ven WiPCF	Unc. Comp. Strength PSF	Str.
			0"-1'3"	Sand and gravel, poorly						
	1			graded, round to sub-						
\	-			angular, moist, reddish						
	2			brown						
-	3									[
l i	<u> </u>		1'3"-1'9"	Silty clay with some sand,						
	4			trace gravel, moist, light brown						
	5	_	1'9"-2'0"	Clayey silt and sand with	5					
	-	A		some fine gravel, moist,	7					
	6			dark brown	12					├
	7	f	2'0"-5'0"	Clayey sand, pred. fine,	12					
	 	1		some fine gravel, moist						
	8]		greenish black						
		В								-
	9	ST			<u> </u>		<u> </u>			
	10	4	5'0"-10'0"	Silty clay, occasional fine	<u> </u>		ļ			├
-	10	С		sand seams, trace vegeta-	<u>5</u>					
	11	1		tion, medium plastic, stiff moist, gray and light brown	1 1					
	1	†		laminae with occasional	9					
,	12]	Į.	reddish brown lenses						
]								
	13	-	10'0"-12'0"	Silty clay, with some red-						
-	14	-		dish roots, medium plastic						\vdash
	14	1		moist to saturated, gray with tan laminae, some						\vdash
	15	1		reddish streaks						
]		readish screaks						
	16	1	10'0"	EOB			<u> </u>			
		4								- !
	17	-					 			1
	18	1					 -			
	<u> </u>	1								
	19	1								
]								
<u> </u>	20	4	j		<u> </u>	 	-			
	21	4	1			<u> </u>	 -			
	21	-	,			 	 			
	22	1			 		 	 		†
]								
	23					<u> </u>	ļ			
	H	4			<u></u>	ļ		ļ		
	24	4	1 .		-	 	 	 		
-	25	-{						 		+
	1	1					 			
TY	E OF SAI	MPLE	REMARKS:			GR	OUND WAT	ER OBSERY	ATIONS	
0.	- DISTU	RBED	Logged by F	do Erps, Techna		ENCOUNTE		8	3 ਜ.) INS.
S.1	- UNDIS	BY TUBE				ENCOUNTED			វា. វា.	INS.
S.S R.O	s split s rock			enetration Test - Driving 2" OD Sampler 1' With	G.W.	AFTER	H EE 1014	HRS.	हा. हा.	INS.
		TROMETER	140# H	ommer Falling 30"; Count Made At 6" Intervals	G.W.	VOLUMES				

Boring N	lo. <u>SW-8</u>									
Job No. 201-8058-13 Well No.	SW-8	Type2"								
Piezomet	er No.									
Type and Size of Auger 44"	From 10'0"	To Surface								
Type and Size of Casing	From	To								
Wash Boring With	Bit From	то								
Size of Screen 0.010	Type <u>SS</u>									
Bottom of Screen Set At 10'3"										
Riser Pipe 2" PVC from 5'3" to su	rface									
Filter No. 3 tan sand	From5'3"	To								
Bentonite Pellets	From _5'0"	To 3'6"								
Grout Cement/beutonite	From 3'6"	To <u>Surface</u>								
Well Protector 4" diameter 5' long round steel with hinged locking cover										
Developed With Top of casing el	evation 1,010.85									
Remarks										

LOG	OF S	OIL	BORING	NO.	Sw-9
-----	------	-----	--------	-----	------



Geotechnical Engineers

JOB NO.______89-630

ROJECT_	Нi	Mill	Manufacturing	
_				

LOCATION M-59 & Waterbury

Highland Township, Michigan DATE 1-18-90 SURFACE ELEV.__ Natural Ory Den Wt. P.C.F. Wt. P.C.F. Penetration Moisture Unc. Comp. SOIL DESCRIPTION Legend Blows For 6" Strength PSF 0.0 Moist SAND & GRAVEL fill with chunks of clay and). *© ć* some vegetation 2 2'0" Stiff moist olive brown 3 CLAY with vegetation, plastic 4 4'0" Extremely stiff moist 16 UL 5 variegated CLAY, plastic 20 6 20 6'0" Extremely stiff moist brown 15 8 UL. CLAY, plastic 18 9 22 9'6" 10 Stiff moist blue silty CLAY 11 Ш. plastic 8 12 11 12'6" 13 3 n 14 3 III. 15 Firm to stiff wet blue 16 silty CLAY, with wet silt 3 lenses ŮΙ 17 4 4 18 6 19 20 3 UL 4 21 21'0" 22 23 24 25 REMARKS: GROUND WATER OBSERVATIONS TYPE OF SAMPLE - DISTURBED G.W. ENCOUNTERED AT FT. INS. 12 - UNDIST. LINER G.W. ENCOUNTERED AT FT. INS. S.T. - SHELBY TUBE G.W. AFTER COMPLETION FT. INS. - SPLIT SPOON R.C. - ROCK CORE Standard Penetration Test - Driving 2" 00 Sampler 1' With G.W. AFTER HRS. FT. INS. CW VOLLINES DEV 140 # Hammer Fallion 70" Count Made At 8" Intervals

В	oring No	SW-9								
Job No. 89-630 W	ell No	SW-9	Typ	e	·					
P	iezometer No	·								
Type and Size of Auger	4½" Ι.D.	- From	21'0"	To _	Surface					
Type and Size of Casing		From		To _						
Wash Boring With	Bit	From		To _						
Size of Screen010		Туре	PVC							
Bottom of Screen Set At	20.0" - 12.0)" ———								
Riser Pipe 15'0" to Surf	ace									
Filter No. 3 tan sand	_ From	20'0"	To _	10'0"						
Bentonite ½" pellets	From	10'0"	To _	7*5"						
Grout Cement/Bentonite	From	7'5"	To _	Surface						
Well Protector 4" square steel										
Developed With										
RemarksTop of Casing	g Elevation 1,	010.10								
		 _								
·····										

Boring No. SW-9 Job No. 201-8058-13 Well No. SW-9 Type 2" Piezometer No. Type and Size of Auger $\frac{4\frac{1}{4}}{4}$ From 20'0" To Surface Type and Size of Casing _____ From ___ Wash Boring With ______ Bit From Size of Screen 0.010 Type PVC Bottom of Screen Set At 20'0" Riser Pipe 2" PVC from 15'0" Filter No. 3 tan sand From 20'0" To 10'0" Bentonite Pellets From 10'0" To <u>7'5"</u> Grout Cement/Bentonite From 7'5" To <u>Surface</u> Well Protector 4" diameter x 7' long steel with locking hinged top Developed With Remarks Top of casing elevation 1,010.10

Geotechnical & Hydrogeological Services
Materials Testing & Inspection



- ROCK CORE

() PENETROMETER

McDOWELL & ASSOCIATES

Geotechnical Engineers

JOB NO. 201-8058-13

PROJECT_	Hi-Mi	11 F	acil	ity

_____ LOCATION M-59 and Waterbury

HRS.

FT.

INS.

G.W. AFTER

G.W. VOLUMES

DATE 3/26/90 Highland Township, Michigan SURFACE ELEV.__ Natural Wt. P C.F Ory Den Wt. P.C.F. Unc. Comp. Strength PSF Penetration Depth Legend SOIL DESCRIPTION Blows For 6' 0"-4" Clayey silt with consider-1 able sand, trace gravel, low plasticity, moist brown 2 topsoi1 3 4"-6" Silty clay, medium plasticity, moist, variegated 4 grey and brown 5 6"-1'9" Sand with some silt and trace gravel, pred. medium 6 to coarse, saturated brown 1'9"-2'1" Clayey peat, moist to saturated, brown 8 2'1"-3'0" Silty clay, with trace sand 9 and vegetation, low-medium plasticity, moist, grey 10 brown to variegated grey and brown 11 7'0" **EOB** 12 NOTE: Hand-auger boring 13 14 15 16 17 18 19 20 21 22 23 24 25 REMARKS: GROUND WATER OBSERVATIONS TYPE OF SAMPLE - DISTURBED 0. Logged by Grant DeWitt, Techna O FT. G.W. ENCOUNTERED AT 6 INS. - UNDIST, LINER U.L G.W. ENCOUNTERED AT FT. INS. - SHELBY TUBE G.W. AFTER COMPLETION FT. INS. - SPLIT SPOON

Standard Penetration Test - Driving 2" 00 Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

Boring 1	No. SW-9A	
Job No. 201-8058-13 Well No.	. SW-9A	Type2"
Piezomen	ter No.	
Type and Size of Auger 3" hand	auger From 7'0	To Surface
Type and Size of Casing	From	То
Wash Boring With	Bit From	То
Size of Screen 0.010	Type PVC	
Bottom of Screen Set At	0"	·
Riser Pipe 1'6" to surface	,	
Filter No. 3 tan sand	From <u>7'0"</u>	To 1'6"
Bentonite Pellets	From <u>1'6"</u>	To
Grout Cement	From <u>1'4"</u>	To Surface
Well Protector 4" x 4½" long sq	ware steel with locking	hinged top
Developed With	<u> </u>	
Remarks Top of casing elevation		
		·

Geotechnical & Hydrogeological Services Materials Testing & Inspection

LOG	OF SOL	BORING	NΩ	SW-10
LV4	UF JUII	. DUNING	140	0.1. 2.0



Geotechnical Engineers

מו	NΩ		8	9-	-6	3	C
10	IWIL						

PROJECT	Hi	Mill	Manufac	turing	
PROJECT	<u> 111</u>	MITT	Manurac	turing	

LOCATION M-59 & Waterbury

DATE 1-18-90 Highland Township, Michigan SURFACE ELEV.__ Sample & Type Natural Wt. P.C.F. Dry Den Wt. P.C.F. Unc. Comp. Strength PSF. Penetration Moisture SOIL DESCRIPTION Depth Legend Blows For 6" % Moist CLAY fill with organics 1'6" A UL Wet black clayey TOPSOIL 2'0" 6 Stiff moist blue silty CLAY 7 with trace of vegetation 10 and fine sand seams 4 B. 4'0" Ш. 6 Compact wet medium grained 4'6" 6 SAND 7 5 c 6 Extremely stiff wet brown ūΓ 6 14 silty CLAY 19 7'0" 19 8 9 10 12 13 14 15 16 17 18 19 20 21 22 23 24 25 GROUND WATER OBSERVATIONS REMARKS: TYPE OF SAMPLE D. - DISTURBED
U.L. - UNDIST. LINER
S.T. - SHELBY TUBE
S.S. - SPLIT SPOON
R.C. - ROCK CORE
() - PENETROMETER G.W. ENCOUNTERED AT INS. G.W. ENCOUNTERED AT INS. 1 FT. INS. **G.W. AFTER COMPLETION** INS. Standard Penetration Test - Driving 2" 00 Sampler 1' With G.W. AFTER HRS. FT. G.W. VOLUMES Medium 140# Hammer Falling 30"; Count Made At 6" Intervals

Во	ring No	SW-10			
Job No. 89-630 We	11 No	SW-10	Ту	pe2"	
Pi	ezometer No	•			
Type and Size of Auger	4년'' I.D.	From	7'0"	To	Surface
Type and Size of Casing		From		To	
Wash Boring With	Bit	From		To	
Size of Screen010		Type	SS		· · · · · · · · · · · · · · · · · · ·
Bottom of Screen Set At	4'6" - 1'6"	······································			
Riser Pipe 1'6" to Surface	:				
Filter No. 3 tan sand	From	7'0"	То	1'5"	_
Bentonite ½" pellets	From	1'5"	To	10"	-
Grout Cement/Bentonite	From	10''	To	Surface	_
Well Protector 4" round	i steel				_
Developed With				 	-
Remarks Top of Casing E	levation 1,010).50			



| - PENETROMETER

McDOWELL & ASSOCIATES

Geotechnical Engineers

89-630

PROJECT_	Ηi	Mill	Facil	ity

LOCATION M-59 & Waterbury

HRS.

G.W. AFTER

G.W. VOLUMES

INS.

SURFACE ELEV.____ DATE ___11-14-89 _ Highland Township. Natural Wt. P.C.F. Penetration Moisture Dry Den Wt. P C.F. Unc. Comp. Strength PSF. Sample & Type Depth Legend SOIL DESCRIPTION Blows For 6" 013" Moist brown sandy clayey TOPSOIL Moist brown silty CLAY 3'0" 4 5 Stiff moist variegated 6 clayey SILT 6 8 8 9 10 11'6" 12 Firm to stiff moist blue silty CLAY 13 15 C 2 16'0" Medium compact moist 3 gray sandy SILT 17 3 17'0" 18 Medium compact moist blue silty CLAY, with sandy 19 silt layers 20 21 22 22'0" 23 24 25 REMARKS: GROUND WATER OBSERVATIONS TYPE OF SAMPLE D. - DISTURBED U.L. - UNDIST. LINER G.W. ENCOUNTERED AT FT. INS. G.W. ENCOUNTERED AT FĨ INS. S.T. - SHELBY TUBE INS. **G.W. AFTER COMPLETION** FT. S.S. - SPLIT SPOON R.C. - ROCK CORE

Standard Penetration Test - Driving 2" 00 Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

	. ч	Во	ring	No	SW-11			
Job No.	89-630	We	ell No	·	SW-11	Туре	2"	
Type an	d Size of	Auger _	41" H	.A.	From _	Surface	To _	20'0"
Type an	d Size of	Casing			From _		To _	
Wash Bo	oring With		 	Bit	From _		To _	·
Size of	Screen _		.010		Type _	ss		
Bottom	of Screen	Set At		19'0"			•	
Riser P	Pipe	0"	_					
Filter	#3 Tar	Sand	_	From _	20'0"	To 13	0"	-
Bentoni	ite Pellet	:s 		From _	13'0"	To 10	'6"	•
Grout _	Cement/Bent	tonite	-	From _	10'6"	To Su	face	-
Well Pr	rotector _	4"	Dia ste	eel with	hinged cove	er		-
Develor	ped With _							-
Remarks	S Top of	Casing E	levatio	on 1,013.	04			
				-		 	· · · · · · · · · · · · · · · · · · ·	
 								



Geotechnical Engineers

PROJECT Hi-Mill Facility

JOB NO. 201-8058-13

LOCATION M-59 and Waterbury

DATE 12/12/89 Highland Township, Michigan SURFACE ELEV.__ Natural Wt. P.C.F Ory Den Wt P.C.F. Penetration SOIL DESCRIPTION Legend Strength PSF Blows For 6" 0"-6" Silty sand pred. fine, some 1 clay, low-medium plasticity occasional coarse sand, 7 sub-angular to sub-round, moist, dark brown 3 6"-10'0" Silty clay, medium-high 4 plasticity, slightly moist to moist, tan with grey and 5 occasional greyish white laminae, varved 6 12 NOTE: 1" moist to 10 Α saturated silt seam at approximately 8 3'6" 9 NOTE: Split-spoon saturated В outside slightly moist 10 inside on Sample B. 10'0" EOB 11 12 13 14 15 16 17 18 19 20 21 22 23 24 GROUND WATER OBSERVATIONS REMARKS: TYPE OF SAMPLE - DISTURBED 7 ft. G.W. ENCOUNTERED AT O INS. Logged by Joel Hunt, Techna - UNDIST. LINER U.L. G.W. ENCOUNTERED AT FT. INS. - SHELBY TUBE FT. G.W. AFTER COMPLETION INS. - SPLIT SPOON Standard Penetration Test - Driving 2" OD Sampler 1' With HRS. G.W. AFTER FT. INS. - ROCK CORE 140# Hammer Falling 30"; Count Made At 6" Intervals G.W. VOLUMES - PENETROMETER

Boring N	No. SW-12	·			
Job No. 201-8058-13 Well No.	SW-12	-	Type	2"	·
Piezomet					
Type and Size of Auger 44"		From 10'0	···	To _	Surface
Type and Size of Casing		From		To _	
Wash Boring With	Bit	From		To _	
Size of Screen 0.010		Type PVC	·		
Bottom of Screen Set At 10'	o"	· -			
Riser Pipe 2" PVC from 4'6" to st	urface	·			
Filter No. 3 tan sand	From _10'	0"	To <u>4:4:</u>		-
Bentonite Pellets	From <u>4.4</u>	!!	To 2:2:		
Grout Cement/Bentonite	From 2'2	11	To Surf	ace	-
Well Protector 4" diameter round	d steel wit)	n locking him	ged top		
Developed With	· · · · · · · · · · · · · · · · · · ·				-
Remarks Top of casing elevation	1,013.14				
					· · ·
· ·					
•					

Geotechnical & Hydrogeological Services Materials Testing & Inspection

C	1 2	
- 3 W =	1.)	

LOG	OF	SOIL	BORING	NO.



Geotechnical Engineers

JOB NO. 89-630

PROJECT Hi Mill Facility

LOCATION M-59 & Waterbury

Highland Township, DATE 11-10-89 Michigan SURFACE ELEV.__ Natural Wt. P.C.F. Dry Den Wt. P.C.F. Penetration Moisture Unc. Comp. Str. Deoth SOIL DESCRIPTION Legend Strength PSF. Blows For 6" 4 0'7" Dark brown moist clayey TOPSOIL Moist variegated silty CLAY, with a trace of sand 3'0" 4 Very stiff moist variegated clayey SILT, with a trace 10 SS 5 of sand 12 5'6" 15 6 Very stiff wet variegated SILT & CLAY (slight seepage 06' in silt seams) 8'0" 9 Stiff moist variegated silty CLAY, with occasional SS 10 silt seams 10 11 11'6" 12 Firm moist blue silty 13 CLAY, with silt seams (seams are wet) 14 SS 15 16 17'0" 17 **Boring Grouted upon completion. 18 19 20 21 22 23 24 25 GROUND WATER OBSERVATIONS REMARKS: TYPE OF SAMPLE - DISTURBED G.W. ENCOUNTERED AT FT. INS. U.L. - UNDIST. LINER
S.T. - SHELBY TUBE
S.S. - SPLIT SPOON
R.C. - ROCK CORE
() - PENETROMETER G.W. ENCOUNTERED AT FT. INS. G.W. AFTER COMPLETION Dry FT. INS. Standard Penetration Test - Driving 2" DD Sampler 1' With INS G.W. AFTER G.W. VOLUMES Trace very light 140# Hammer Falling 30"; Count Made At 6" Intervals

CM-	1	.1		
SW-	T	4		

LOG OF SOIL BORING NO.

M

McDOWELL & ASSOCIATES

Geotechnical Engineers

JOB NO.______89-630

PROJECT Hi Mill Manufacturing

LOCATION M-59 & Waterbury

SURFACE ELEV. DATE 12-20-89 Highland Township, Michigan

			SUNF	ACE ELEV.	DATE 12						ip, Mich	iryan
Sample & Type		Depth	Legend		SOIL DESCRIPTION		etration s For 6"	Moisture %	Natural Wt. P.C.F.	Ory Den Wt. P C.F	Unc. Comp. Strength PSF.	Str. %
	\Box		CET 19	0'6"	Moist silty clayey b	cown						
	Ц	1			TOPSOIL							
	Н		<i>X////</i>		Maist brown silter St	N V	<u> </u>		<u> </u>		<u></u>	
	Н	2	<i>{////</i> }		Moist brown silty CLA with a trace of veget		<u> </u>		 		 	├ -
	Н	3	Y/// X		plastic	Lation	 				<u> </u>	├
	H	3	/////	3'0"	Plastic			_	<u> </u>		<u> </u>	
	Н	4	<i>{////</i> }							 		
	H		V///)		Very stiff moist		-		<u> </u>		 	
		5	Y///		variegated silty CLA	ζ,					<u> </u>	
A			<i>Y////</i>		plastic		8					
SS		6	<i>\$///\</i>				9					
			\$///X				15			<u> </u>		ļ
		7	<i>\///</i>				17					ļ
	Н		<i>{////</i>	8'0"								
	Н	8	//// /	6 ° U "			ļ		<u> </u>	_		
	Н	9	V///		Stiff moist blue silt					 		
	H	3	<i>\///</i>		CLAY, with oxidation,	•				-		
	H	10	////		silt lenses, plastic				-			
В		<u> </u>	V///				4					
SS		11	<i>Y///</i>				5					
			<i>Y///</i> /				88					
	Ц	12	1///	12'0"								
	Н		V///		Firm moist blue silty	,						ļ
	Ц	13	<i>\///</i>		CLAY, with a 3" wet of		<u> </u>					
c ss		14	<i>\///</i>		silty seams below 14		3					
33		14	*///		_		4					
$\vdash -$		15	V///	15'0"			3					
D			1///	13 0			2					
SS		16	Y////		Soft moist blue silty	•	2					
					CLAY		2					
		17					3					
	Ц		<i>\///</i>	- 100								
<u> </u>	Ц	18	\/// A	18'0"								<u> </u>
├—	H	10	: ////		Firm to stiff moist b	lue.	ļ					
		19	\///		very silty CLAY, plas		<u> </u>					
E SS		20	Y///		omit bras		4					
133			Y/// /				4					
		21	V///				4					
			<i>}////</i>									
		22	<i>Y////</i>									
	\Box		1////									
<u> </u>	\sqcup	23	1////				ļ					
F		-	<i>\///\</i>				2			 _	,	
SS		24	4////	2416"			4					
ļ	F	25	1////	24'6"			_3_					
	Н	25	1////									
TV	ليل	OF SAI	ADIS	REMARKS:			 	CPC	UMD WATE	ER OBSERV	ATIONS	
0.		- DISTU	RBED	THE PROPERTY OF STREET			C W	ENCOUNTER		Justina	FT.	INS.
Ü.L		- UNDIS	T. LINER IY TUBE				G.W.	ENCOUNTER	ED AT		FT.	INS.
S.S) .	- SPLIT	SPOON	Countried I	Penetration Test - Driving 2" OD Sampler 1" W	ieh		after comi After	PLETION	HAS.	គ. គ.	INS.
(R.C) }	- rock - penet	CORE ROMETER		ammer Falling 30"; Count Made At 6" Interval		_	VOLUMES		raid.		

Job No. 89-630	Boring No Well No Piezometer No.	SW-14		/pe <u>2"</u>					
Type and Size of Auger	4 ¹ / ₃ " I.D.	From	24'6"	_ To _	Surface				
Type and Size of Casin	g	From		To _	·····				
Wash Boring With	Bit	From		To _					
Size of Screen	.010	Туре	PVC						
Bottom of Screen Set A	16'0"			•					
Riser Pipe 2" PVC from	11'0" to surface								
Filter No. 3 tan sand	From _	24'6"	То	10'0"	_				
Bentonite 1/4" Pellets	From	10'0"	To	8'0"	-				
Grout Cement/Bentonite	From	8'0"	То	Surface	-				
Well Protector 4" Square steel									
Developed With					_				
Remarks Top of Casing Elevation 1,009.76									
			· · · · · · · · · · · · · · · · · · ·						



Geotechnical Engineers

PROJECT Hi-Mill Facility

JOB NO. 201-8058-13

LOCATION M-59 and Waterbury

\checkmark	
•	

		SURF	ACE ELEV.	DATE 12/11,						p, Michi	gan
ampie & Type	Depth	Legend		SOIL DESCRIPTION	8low	etration s For 6"	Moisture %	Natural Wt. P.C.F.	Dry Den Wt. P.C.F.	Unc. Comp. Strength PSF	Str.
			0"-9"	Silty sand, pred. fine	,						
	1			some clay, some roots, sub-angular to sub-rour	NA.	 -			<u> </u>		
	2			moist, brown, topsoil	ıu,						
				moreo, scomi, copacit							
	3		9"-2'6"	Clayey sand, pred. fine							
				considerable silt, some							
	4			sub-angular to sub-rou	nd			<u> </u>			
	5			medium sand, medium		7	-	 			
	ا			plasticity, moist, tan		10			-		
	6	A	2'6"-14'0"	Clay, some silt, medium	a	15					
				plasticity, slightly me		14					
	7			to moist, tan with grey		<u> </u>	ļ	<u></u>			
\longrightarrow				laminae, occasional		 		-			<u> </u>
\dashv	8			greyish white laminae		 	<u> </u>	 			
	9		MOTE -	Cample P. no version							-
	<u> </u>		NOTE:	Sample B, no recovery. Split Spoon wet.		5					
	10			Spire Spoon wee.		7					
		В				9					
	11					11 5					<u> </u>
	12					6					
	12		12'0"	EOB		1 7					 -
	13	С				8					
	14					<u> </u>					
						}	_				
-+	15										
	16										
	1										
	17				:						
 -	18										
-+	19					<u> </u>					
	13									<u> </u>	
	20										
	21					 					
	22					<u> </u>					
-	22					 					
	23					<u> </u>					
	24										
 _	 	ļ]			 					
	25	ł				 					
TVO	OF SAM	015	REMARKS:	<u></u>		 	CP4	IIIMO WAT	R OBSERV	PHOITA	
D.	- DISTUR	BED		el Hunt, Techna		g.w	ENCOUNTER				INS.
S.T.	- UNDIST - SHELBY	TUBE				G.W.	ENCOUNTER	ED AT	J	FT.	INS.
S.S.	- SPLIT S	SPOON	Standard Pend	etration Test - Driving 2" OD Sampler 1' With			AFTER COM AFTER	PLE I ION	HRS.	हा. हा.	INS. INS.
	- PENETE			mer Falling 30"; Count Made At 6" Intervals			VOLUMES				

Job No. 201-8058-13 Well No. SW-15 Type 2"
Piezometer No.
Type and Size of Auger 44" From 12'0" To Surface
Type and Size of Casing From To
Wash Boring With Bit From To
Size of Screen 0.010 Type PVC
Bottom of Screen Set At 11'7"
Riser Pipe 2" PVC from 6'7" to surface
Filter No. 3 tan sand From 11'7" To 5'0"
Bentonite Pellets From 5'0" To 3'0
Grout Cement/Bentonite From 3'0" To Surface
Well Protector 4" round steel with locking hinged top
Developed With
Remarks Top of casing elevation 1,010.93



Geotechnical Engineers

JOB NO. 201-8058-13

PROJECT Hi-Mill Facility

LOCATION M-59 and Waterbury

SURFACE ELEV. DATE 12/11/89

Highland Township, Michigan

	SU	RFACE ELEV.	DATE 12/11/89					o, Michic	
ample Der	pth Legend			enetration was For 6"	Moisture %	Natural Wt. P.C.F.	Orv Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
		0"-2"	Silty sand, pred. very	1	 				
-11		-	fine, with some clay and					1	\top
 			occasional coarse sand,	-	 	 			+
1 2			fine gravel and roots,		+		 	 	+
}}					+	 	 	 	+
			moist to saturated, dark			 			┼
3			brown, topsoil					ļ	
				<u> </u>	<u> </u>				<u> </u>
4		2"-1'5"	Silty sand, pred. very	l					<u> </u>
			fine, with some clay,						
5	_	1	saturated tannish brown	10					
	7			15			· · · · ·	1	_
6	A	1'5"-14'0"	Silty clay, medium plas-	17	 	<u> </u>	Τ		
	 "	1 3 -14 0		15		-	 	 	┼
			ticity, slight moist to		 	+	┼──	 	+
7			moist, tan with some grey	 	 	 	 	 	+
		*	laminations, occasional	L	 	 			↓
8			black specks and orange	L	<u> </u>	<u></u>		L	
			staining						\perp
9						T	T T		T
-+ - -	 	NOTE:	Frost depth approximately	—	 	†	 	 	
10	- 1	MOTE:	2".	6	 	 	 	 	
	' {		2"•		+	 	 	 	
		,		8		├ ──			├ ─
11				9		 	 		—
	<u> </u>	1		9		<u> </u>	 		↓
12	<u> </u>			L	<u>.l</u>		L	İ	
13		ł						1	Ī
					1				
14				3	 	<u> </u>	<u> </u>		
	<u>•</u>			6	 	 			
		Į		1 7		 	-		├ ──
1!		į			 	<u> </u>			—
	C	İ		6			Ļ		<u> </u>
110	6			L					<u> </u>
17	, 								
				-	 	 	<u> </u>		
11					 	 			
	<u></u>			-	 	 	 		
-++		1			 	 	 		
1!	9	Ì		<u> </u>	ļ <u>.</u>		ļ		<u> </u>
				L	<u> </u>				<u> </u>
21	0			2			<u> </u>		
		1		2				1	
2	1 D			4	1			1	
+-	- -			4	1	 	1		
1 2	, 			-	 	 	 	 	\vdash
	-				 	 	 	 	
				<u> </u>	 	 	<u> </u>		₩
2				3	 			 	<u> </u>
	E	1		2		<u> </u>	L		<u> </u>
2	4			2	_	<u></u>	L		<u> </u>
		1		3					
2	5	25'0"	EOB .	<u> </u>	1	1	<u> </u>		
-1+4	-		ited upon completion.	-	+	 	 	 	
			inca abou combitentous	-	<u> </u>	<u> </u>	L		Щ.
	SAMPLE	REMARKS:		1	GR	OUND WAT			
TYPE OF				I		DED AT	•	D FT. 2	2 ins.
O OI	STURBED	Logged by J	Toel Hunt, Techna	6.W	. Encountei	NEU AI	,	J FI. 2	- 1110.
0 DI U.L UI	ISTURBED NDIST. LINER	Logged by J	Toel Hunt, Techna	G.W	. ENCOUNTER	RED AT	`	FT.	INS.
0 01 U.L UI S.T SI S.S SI	STURBED		netration Test - Driving 2" QD Sampler 1' With	G.W G.W		RED AT	HRS.		

LOG	OF SO	L BORING	NO	SW-17



Geotechnical Engineers

		-	
0	NO		89-63

PROJECT H	li M	ill F	'ac	il.	it	Y
-----------	------	-------	-----	-----	----	---

LOCATION M-59 & Waterbury

		SUR	FACE ELEV.	DATE11-9-89)			and To	wnshio	, Michie	gan
inple & Type	Depth	Legend		SOIL DESCRIPTION BI		tration For 6"	Moisture %	Natural Wt. P.C.F.	Dry Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
				Moist dark brown sandy	\Box						
\vdash	1		1'0"	silty TOPSOIL	ŀ		l T		 		
 	2		† *	Moist brown silty fine	}			 			
	 		2'6"	SAND, with traces of clay	ı						
	3			and gravel							
				Moist brown clayey SAND							
A	4					4					
SS	5	,,,,,	4'6"		-	_6_		 			
	<u> </u>		1	Extremely stiff moist	ł	<u>8</u> 14					
	6]	variegated silty CLAY,	l	1.4				2.11	
		<i>\///</i>	ł	with a trace of sand and							
	7		1	occasional silt & fine sand	1						
	-		}	seams	ŀ			-			
	8	<i>\///</i>	1		}			-			
В	9	V///	}		ŀ	5					
SS		<i>\///</i>	∤		İ	8					
	10		1		[10					
	144	////	}		ŀ	13					
	11	<i>\///</i>	ł		ŀ						
├	12		1		ŀ						
ユ		////			[
	13		13'0"								
С	4.6	<i>\///</i>]	Stiff to very stiff moist	ŀ						
SS	14	<i>\///</i>	1	blue silty CLAY, with silt	ŀ	4					
	15	\///	1	and fine sand seams	ŀ	7					
				(NOTE: Wet gray silt seams		7					
	16	<i>\///</i>	1	between 20'6" & 21'0")	ŀ						
' →	17	<i>\///</i>	1		ŀ						
	+1/-	<i>\///</i>	1		ł						
	18		1		Į						
		<i>V////</i>	7				<u></u>				
D	19	<i>\////</i>	1			3					
SS	20	V///	7		ŀ	3		 			
		\///	1		ŀ	4				•	
	21		1		İ						
		<i>\///</i>	`		[
	22	/////	22'0"		}						
	23	111111		Stiff moist gray clayey	ŀ						
]		SILT, with a trace of fine sand & occasional silt	l						
E	24]		seams		4					
SS	45	411111			-	5			ļ		
' -	25	<u> </u>			- }	6		-			
TVO	E OF SAN	APLE	REMARKS:		+	7	G A	DUMD WAT	ER OBSERV	ATIONS	
D.	- Distui	RBED				G.W.	ENCOUNTER		20	FT. 6	INS.
S.T.	- Undis - Shelb	y tube				G.W.	ENCOUNTER	RED AT	32	FT. O	INS.
	- SPLIT - ROCK			Penetration Test - Oriving 2" 00 Sampler 1' With			AFTER COM AFTER	ITLE I IUN	HRS.	ក. គ.	INS.
	- PENET			Hammer Falling 30"; Count Made At 6" Intervals	_ [VOLUMES				

LOG OF SOI	L BOR	ING	NO.
------------	-------	-----	-----



Geotechnical Engineers

JOB NO. 89-630

PROJECT Hi Mill Facility

LOCATION M-59 & Waterbury

		SUR	RFACE ELEV.	DATE					, Michi	
e Type	Depth	Legend		SOIL DESCRIPTION	Penetration Blows For 6"	Moisture %	Natural Wt. P.C.F.	Dry Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str. %
	26					<u> </u>				
	26	11111				 	-			
	27		27'0"	•						
	28			Stiff moist blue silty	-	 	 	<u> </u>		├
-	20			CLAY	-		-			
	29									
F	30				_45	 	<u> </u>			
SS	30				7		 			
	31				13					
	32		31'6"			<u> </u>	 			
	32			Compact wet gray silty		 	 			
	33			SAND, with a trace						
	24					 				
G	34				3					
SS	35				5					
	36				8	<u> </u>				
	30				10					
	37									
	38					 				
	Jo					<u> </u>				
	39									
H SS	40				6				!	
33	40				7	<u>.</u>				
	41		!		9					
	42		42'0"		-	-	<u> </u>			
	42	************	42 0							
	43									
	44				 	 				
	1					 				
	45									
 -	46			•					 -	
	40					<u> </u>				
	47	1								
	AO	1								
+	48	†								
	49]								
L	En	4				ļ				
,十	50	1			 					
	OF SAM		REMARKS:	,		GR	OUND WAT	R OBSERV	ATIONS	
U.L.	- DISTUR - UNDIST	r. Liner				ENCOUNTE			हा. हा.	INS. INS.
\$.T. S.S.	- SHELB' - SPLIT	y Tube Spoon			G.W	AFTER COM			FT.	INS.
R.C.	- ROCK	CORE	Standard 140#	Penetration Test - Driving 2" OD Sampler 1' With Hammer Falling 30"; Count Made At 8" Intervals		AFTER VOLUMES		HRS.	FT.	INS.

	Boring No	SW-17								
Job No. 89-630	Well No.	SW-17	Тур	e						
	Piezometer No.									
Type and Size of Auge	r 4½" I.D.	From 4	2'0"	To surface						
Type and Size of Casi	ng	From _		To						
Wash Boring With	Bit	From _		To						
Size of Screen	010	Type _	ss							
Bottom of Screen Set	At35'0"									
Riser Pipe 2" PVC from	n 30'0" to surface	1	÷							
Filter No. 3 tan sand	From _	35'0"	To _	29'0"						
Bentonite 1 pellets	From_	29'0"	To _	28'0"						
GroutCement/bentonit	e From	28'0"	To _	surface						
Well Protector4"	steel									
Developed With		·								
Remarks Top of casing elevation 1,012.83										
			·							

Geotechnical & Hydrogeological Services Materials Testing & Inspection

SW-1	. ક
------	-----

1	0 G	0F	SOIL	. 80	RIN	G	NU.



Geotechnical Engineers

		89-63	C
JUB	NO		_

PROJECT Hi Mill Facility

LOCATION M-59 & Waterbury

DATE 11-10-89 Highland Township, Michigan SURFACE ELEV._ Natural Wt. P.C.F. Dry Den Wt. P C.F. Unc. Comp. Strength PSF. Penetration Moisture Sample & Type SOIL DESCRIPTION Depth Blows For 6" Moist dark brown sandy 1'0" silty TOPSOIL Moist brown silty SAND, 2 with a trace of clay 2'6" 3 Stiff moist brown sandy 4 CLAY, with sand seams SS 5 5 (Note: Wet seam 3" thick 6 @6'6") 6 Tip : Clayey SAND 6'10" Cobble @ 8'0" 8 Cobble @8'0" 9 3 2 Medium compact wet brown 3 10 silty SAND, with traces of gravel & pebbles, clay 11 seams & cobble 12 Water Level @ 10'6" with augers @ 15' 13 14 5 5 SS 15 16 17 17'0" 18 19 20 21 22 23 24 25 GROUND WATER OBSERVATIONS REMARKS: TYPE OF SAMPLE - DISTURBED D. G.W. ENCOUNTERED AT FT. INS. HSD - UNDIST. LINER ti i G.W. ENCOUNTERED AT FT. INS. S.T. - SHELBY TUBE S.S. - SPLIT SPOON G.W. AFTER COMPLETION FT. INS. G.W. AFTER FT. Standard Penetration Test - Driving 2" OD Sampler 1' With HRS. - ROCK CORE 140# Hammer Falling 30"; Count Made At 6" Intervals G.W. VOLUMES PENETROMETER

В	oring No	SW-18			
Job No. 89-630 W	ell No	SW-18	Ty	/pe2"	······
P	iezometer No	•			
Type and Size of Auger	4½" I.D.	From	17'0"	To .	surface
Type and Size of Casing		From		To .	
Wash Boring With	Bit	From		To .	
Size of Screen010		Type	SS		
Bottom of Screen Set At	14'1"			•	
Riser Pipe 2" PVC from 9	9'1" to surface		•		
Filter No. 3 tan sand	_ From	14'1"	То	5'0"	-
Bentonite 1" pellets	From	5'0"	To	4'0"	-
Grout Cement/bentonite	From	4'0"	То	surface	-
Well Protector4"	steel				-
Developed With	·····		·,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	· · · · · · · · · · · · · · · · · · ·	-
Remarks Top of casing e	levation 1,008	.58'			
					
					

Geotechnical & Hydrogeological Services Materials Testing & Inspection

LOG OF SOIL BORING NO. 5W-19	LOG OF	SOIL BORING	NO. SW	1-19
------------------------------	--------	-------------	--------	------



Geotechnical Engineers

		89
J08	NO	 99

	89-6	31
--	------	----

PROJECT Hi Mill Facility

LOCATION M-59 & Waterbury

		SUR	FACE ELEV.	DATE _11-8-89					, Michi	
mple Type	Depth	Legend			etration s For 6"	Moisture %	Natural Wt. P.C.F.	Dry Den Wt. P C.F.	Unc. Comp. Strength PSF.	Str. %
	1		0'11"	Moist dark brown fine sandy	<u> </u>			<u> </u>		
\dashv	-		. 0 11	clayey silty TOPSOIL	ļ					\vdash
	2			* * * * * * * * * * * * * * * * * * *	_		<u> </u>			
				Moist brown silty SAND, with a trace of clay and						
_	3		3'0"	occasional pebbles, cobbles			ļ			↓
	-			resultational personal, constitution			ļ			├
\overline{A}	4				3	 	 			
SS	5			Extremely stiff moist	11	 	<u> </u>			\vdash
				variegated SILT & CLAY, with occasional silt and	15					
	6			fine sand seams	18		<u> </u>		<u> </u>	
	-		· I	Tille Sand Scams			 	ļ		₩
	7	MUN				-	 	-		├
+	8	HUUH				<u> </u>				\vdash
		WW				<u> </u>	 			
	9									
3			l		7					
SS	10				11	ļ				├
	11	HUUH			12 15					-
╌┦		unu			13		 			
	12	MAN	12'0"	•						
-	13	4		Stiff moist blue	 	 				
\dashv	14	 		Stiff moist gray clayey	 	 				
3	1.4	1		SILT, with occasional	Δ	 	-			
SS	15	<u> </u>		silt seams	5					
]			_5_					<u> </u>
	16	411111		P.P. = 1.0 TSF						<u> </u>
+	17	-{{{ }}}			<u> </u>	 				-
	+''	-			 					
	18									
\rightarrow]			<u> </u>					
	19	411111			<u> </u>		 			
ss	20	-{			8					
33		付∭			11					
	21		21'0"		11					
\Box					<u>·</u>					
	22	_				ļ				
\dashv	23	-		Compact to very compact	 	-		-		
-+	23	-		wet brown silty fine SAND,		 				
E	24			with a trace of gravel	2					
SS.]		and occasional oxidized silt seams	4					
_	25	4			7		 			
			DC144 GUG		5		011110		4710PC	
TYP 1	e of Sai - Distu		REMARKS:		, w	ENCOUNTER	OUND WATI BED AT	ER OBSERV 12		INS.
U.L.		ST. LINER			G.W.	ENCOUNTER	RED AT	11	я. 0 я. 0	INS.
S.S.	- SPLIT	SPOON	Standard	Penetration Test - Driving 2" 00 Sampler 1' With		AFTER COM AFTER	IPLETION	13 HRS.	छ. <u>१</u> हा.	INS.
H.C.	- ROCK	CURE TROMETER	140#	Hammer Falling 30"; Count Made At 6" Intervals		VOLUMES		illio.		



Geotechnical Engineers

JOB NO. _____89-630

PROJECT	Hi	Mill	Facil	1.117

LOCATION M-59 & Waterburg

	SURFACE ELEV. DATE 11-8-89 Highland Township, Michigan									
Sample & Type	Depth	Legend	SOIL DESCRIPTION	Pene	tration For 6"	Moisture	Natural Wr. P.C.F.	Ory Cen Wr P.C.F	Unc. Comp Strength PSF	Str.
	<u> </u>									
	26						ļ			ļ
	27			- {		· 	 			
\vdash	121									
	28			ı						
										
	1 29		Compact to very compact		2			ļ <u>.</u>		
FS_ SS_	30		wet brown silty fine SAND,		5					
			with a trace of gravel and occasional oxidized	j	5					
	31		and occasional oxidized silt seams		_13_					
	32		51.10 50 dillo				 			ļ
	1 32						 			
	33									
1							ļ		 	
-G-	34				4		-			
SS	35				5					
				Ţ	9					
	36				_13_		 			
' -	1 37		2710#							
1	1		37'0"							
	38]		ĺ			ļ		_ 	<u> </u>
	1 20									
-	39									
	40	1								
	+									
'	41	-								
7	142	1								
]								
	43	- i								
-	44	1								
]								
	1 45	{		1					!	
	46	_	t				 		<u> </u>	
]								
	47									
—	48	4		i			-			
	1 40	1								
	49]								
	11	4								
,	150	-			L		 			
TYP	E OF SAN	APLE	REMARKS:			GR	TAW DNU	ER OBSERV	ATIONS	<u> </u>
D.	- DISTU	RBED				ENCOUNTER			<u>ព</u>	INS.
S.T	- SHELB - SPLIT	Y TUBE	· .		G.W.	ENCOUNTER AFTER COM			त. त.	INS. INS.
R.C	- ROCK	CORE ROMETER	Standard Penetration Fest - Oriving 2" 00 Sampler I' With 140# Hammer Falling 30", Count Made At 6" Intervals			AFTER VOLUMES		HRS.	ſŢ.	INS.

Boring No. SW-19 Job No. 89-630 Well No. ____sw-19 Type 2" Piezometer No. Type and Size of Auger 41" I.D. From 37'0" To surface Type and Size of Casing _____ From ____ To _____ Wash Boring With _____ Bit From _____ To Size of Screen .010" Type __ss Bottom of Screen Set At 32'0" Riser Pipe 2" PVC from 27'0" to surface To ^{26'0}" From 32'0" Filter No. 3 tan sand Bentonite <u>t" pellets</u> From 26'0" 25'0" To To surface From _25'0" Grout Cement/bentonite Well Protector 4" steel Developed With ____ Remarks Top of casing elevation 1,015.61'

los	OF S	ะกม	BORING	NO	SW-20
	•••	,,,,	00111110	100.	



Geotechnical Engineers

ne No	89-63	30
ILV MAI		

PROJECT_	Hi	Mill	Facility
LUOSECI —			

LOCATION M-59 & Waterbury

		SURF	ACE ELEV	DATE 11-13-89	• <u> </u>	Hig	hland '	<u> Pownshi</u>	p, Mich	igan
Sample & Type	Depth	Legend	-		enetration ows For 6"	Moisture %	Natural Wt. P.C.F.	Ory Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str. %
	1	DECKA SI	0'5"	Dark brown sandy TOPSOIL						
-	•			Wet silty brown SAND	<u> </u>			 	l	
	2			wet stity blown SAND						
	3	,,,,,	2'6"		-	 	 			-
	.					<u> </u>	 			-
	4			Extremely stiff moist						
-	5			variegated silty CLAY	-					
A					5	 				
	6				14					
-	7				18 23		 			
	8				<u> </u>		ļ <u> </u>			ļ
	9									
 	10		10'6"		<u> </u>					
В	11		10.6	Stiff moist blue silty	8					
				CLAY, with some silt	7					
. –	12	////	12'0"	seams	10		 			
	13					 	l			
	14									
	15									
 	16				-					
,	10									
	17									
	18									
	19					<u> </u>				
	20				<u> </u>					
	21		/		-	 			· · · · ·	
	22									
	1									
	23				-					
	24									
· _	25					 				
1 -	43									
	PE OF SAM		REMARKS:			GR	TAW GRUD	ER OBSERV		
D. V.L	- DISTUR - UNDIST	LINER				ENCOUNTER ENCOUNTER		0	त. 7 त.	INS. INS.
l s.s	r SHELBY	SPOON	Standard B	enetration Test - Driving 2" OD Sampler 1' With	G.W.	AFTER COM	PLETION	MBC	FT.	INS.
	ROCK C) - PENETF	OMETER		emmer Falling 30"; Count Made At 6" Intervals	G.W.	VOLUMES	Hollov	HRS. / Auger	· •.	

McDOWELL & ASSOCIATES Geotechnical Engineers 21355 Hatcher Avenue

21355 Hatcher Avenue Ferndale, Michigan 48220 Phone: (313) 399-2066

Вс	oring No.	SW-20		
Job No. 89-630 We	ell No.	SW-20	Type _	2"
Pi	Lezometer No			
Type and Size of Auger _	41" I.D.	From <u>12'0'</u>	1	To surface
Type and Size of Casing		From		То
Wash Boring With	Bit	From		То
Size of Screen	.010	Type	ss	
Bottom of Screen Set At	6'0"	_		
Riser Pipe 1'0" below t	co 2'0" above grad	e 2" PVC		
Filter #3 Tan Sand	From	6'6"	To	Surface
Bentonite	From		То	
Grout	From		To	
Well Protector2" Cas	st Aluminum lock o	over provided	l by M &	A
Developed With	- 			
Remarks Top of Casing E	levation 1,009.76			
				

~	T. T		\sim	1
5	w	-	Z	L

n	C	ΩE	SU.	11	RU	RI	NC	NO.
LU	u	UF	30	IL.	טם	nı	Пu	MU.



Geotechnical Engineers

89-630 JOB NO._

PROJECT_	Hi	Mill	Facility	
----------	----	------	----------	--

_____ LOCATION M-59 & Waterbury

_ DATE <u>11-17-89</u> SURFACE ELEV. Highland Township, Michigan Penetration Moisture Natural Ory Den Unc. Comp. Strength PSF. Str. SOIL DESCRIPTION Depth Legend Blows For 6" Wt. P.C.F. Wt. P.C.F. % 0'2" **ASPHALT** Wet fine silty oxidized brown SAND & GRAVEL fill, with slight clay content 3'0" Moist silty organic discolored CLAY, with vegetation 5 5'0" Α 5 Stiff to very stiff moist 6 8 silty organic CLAY, with 9 oxidation streaks, a trace 7'0" 13 of vegetation, roots and wet sand lenses 9 10 11 12 13 14 15 16 17 18 19 20 21 23 24 25 GROUND WATER OBSERVATIONS REMARKS: TYPE OF SAMPLE - DISTURBED 0 0. FI. 2 G.W. ENCOUNTERED AT INS. U.L. - UNDIST. LINER 6 0 G.W. ENCOUNTERED AT INS. FT. S.T. - SHELBY TUBE 2 0 **G.W. AFTER COMPLETION** FT. INS. S.S. - SPLIT SPOON Standard Penetration Test - Driving 2" 00 Sampler 1' With HAS. - ROCK CORE - PENETROMETER G.W. AFTER INS. FT. A.C.

140# Hammer Falling 30"; Count Made At 5" Intervals

G.W. VOLUMES

Heavy Hollow Auger

Boring	No. SW-	21			
Job No. 89-630 Well No.	. <u> </u>	-21	Туре	2"	
Piezome	eter No.				
Type and Size of Auger 41"	I.D.	From _	7'0"	To _	surface
Type and Size of Casing		From _		То _	
Wash Boring With	Bit	From _		To _	
Size of Screen		Type _	PVC		
Bottom of Screen Set At	0"				
Riser Pipe 2" PVC from 2'0" to s	surface				
Filter No. 3 tan sand	From 7'	0"	To1	10"	
Bentonite <u>l" pellets</u>	From 1'	10"	То	6"	
Grout Cement/bentonite	From	6"	To Sur	rface	
Well Protector 4" steel					
Developed With		·			
Remarks					
					

LOG OF SOIL BORING NO.	LOG	OF	SOIL	BORING	NO.
------------------------	-----	----	------	--------	-----



McDOWELL & ASSOCIATES

Geotechnical Engineers

89-630 IOR NO

PROJECT Hi Mill Manufacturing	PROJECT	Ηi	Mill	Manufacturing
-------------------------------	---------	----	------	---------------

INCATION M-59 & Waterbury

		JOB	NO	89-630	L	OCATION	<u> M-59</u>	& wat	erbury		
		SURF	ACE ELEV	l	DATE 1-18-90		High	land T	ownshi	p, Michi	gan
Sample & Type	Depth	Legend	-	SOIL DESCRIPTION	Pen	etration s For 6"	Moisture %	Natural Wt. P.C.F.	Dry Den Wt. P C.F.	Unc. Comp. Strength PSF.	Str.
	1										
A				Miscellaneous	SAND & CLAY	3					
UL	2			fill		4					
	3		3'0"			6					
В	4					5					
UL.	4			Very stiff moi	st variegated	10 13					
	5		,			28					
	6	7///	5'6"								
	7										
-├	8								-		
	9										
-	10	!									
-	11					<u> </u>	-				
'=	12										
-	13										
	14					-					
	15										
-	18										
-	17										
	I										
	18	.									
	19	1		•							
-	20										
		1	j j								
-	21										
	22] :									
-	23	}									
]									
-	24	1									
. 그	25										
TYP	E OF SAN	I IPLE	REMARKS:	·	 		GRO	ITAW DRU	R OBSERV	ATIONS	
D. U.L.	- DISTUR - UNDIST	ibed F. Liner					ENCOUNTER ENCOUNTER			हा. हा.	INS.
S.S.	- SHELBY	SPOON .	- Ctandard	Penetration Test - Driving 2" 00	Sensiter 1' With	G.W.	AFTER COMI AFTER		HRS.	त. त.	INS.
R.C.	- ROCK (LUME ROMFTFR	140#	Hammer Falling 30": Count Made	At 6" Intervals	G.W.	VOLUMES	None	img.	14.	

Boring No. SW-22 Job No. 89-630 Well No. _____SW-22 ____ Type __2" Piezometer No. ____ Type and Size of Auger 44" I.D. From 5'6" To Surface Type and Size of Casing ____ From ____ To ___ Wash Boring With ____ Bit From To _____ Type SS Size of Screen _____1010 Bottom of Screen Set At 5'0" to Surface Riser Pipe 2'0" to Surface From 5'6" 2'0" Filter No. 3 tan sand Bentonite 4" pellets From 2'0" From 1'6" Grout Cement/Bentonite Surface Well Protector ___ 4" round steel Developed With _____ Remarks Top of Casing Elevation 1,010.25



- UNDIST. LINER

S.T. - SHELBY TUBE

S.S. - SPLIT SPOON R.C. - ROCK CORE

() - PENETROMETER

McDOWELL & ASSOCIATES

Geotechnical Engineers

PROJECT	Hi-Mill	Manufacturing	

LOCATION M-59 & Waterbury 89-630 JOB NO.___ DATE __1-9-90 Highland Township, Michigan SURFACE ELEV._ Natural Wi. P.C.F. Penetration Dry Cen Unc. Comp. SOIL DESCRIPTION Legend Strength PSF. в туре Wt. P.C.F. 26 27 28 29 AUGERED TO 35' NO SAMPLE 31 32 33 34 35'0" 35 3 3 Firm moist blue silty CLAY, plastic 4 37 5 39 40 41 9 41'0" Very stiff moist blue 16 silty CLAY 41'9" 42 20 Very compact wet medium 43 to coarse brown SAND 44 44'0" 45 6 Compact wet medium to 46 7 coarse brown SAND, with 9 seams of gray clayey sand 47 11 48 6 49 49'0" 9 Very compact wet brown 1.2 fine SAND 50 50'0" 13 GROUND WATER OBSERVATIONS REMARKS: TYPE OF SAMPLE - DISTURBED G.W. ENCOUNTERED AT FT. O INS.

Standard Penetration Test - Driving 2" 00 Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

G.W. ENCOUNTERED AT

G.W. AFTER

G.W. VOLUMES

G.W. AFTER COMPLETION

FT.

FT.

HAS.

INS.

INS

INS.

Boring No.	IW-1		
Job No. 89-630 Well No	IW-1	Туре	ss
Piezometer	No		
Type and Size of Auger 45" I.D.	From50'0"	To	Surface
Type and Size of Casing			
Wash Boring With	Bit From	To	
Size of Screen010	Type SS		
Bottom of Screen Set At 47'0" to	42'0"	•	
Riser Pipe 42'0" to Surface			
Filter No. 3 tan Fr	om 50'0"	To 39'10"	
Bentonite ½" pellets Fr	om 39'10"	To 36'6"	
Grout Cement/Bentonite Fr	om 36'6"	To Surface	:
Well Protector 4" square steel	····		
Developed With		····	******
Remarks Top of Casing Elevation	1,017.02		

LOG OF SOIL BORING NO._____



() - PENETROMETER

McDOWELL & ASSOCIATES

Geotechnical Engineers

89-630 JOB NO.____

PROJECT Hi Mill Facility

LOCATION M-59 & Waterbury

DATE __12-12-89 SURFACE ELEV.____ Highland Township, Michigan Dry Den Wt. P.C.F. Unc. Comp. Penetration Moisture Natural Jample & Type Deoth Legend SOIL DESCRIPTION Wt. P.C.F. Blows For 6" Strength PSF. % % Moist brown fine silty SAND with clay content, 2 fill 2'6" UL 3 Wet brown sandy SILT with 4 clay 5 В 516" UL 7 8 Moist tan CLAY with gray streaks and silt lenses 9 10 5 11 6 III. 11'5" 10 12 15 13 14 Stiff moist blue CLAY with silt varves 15 Ď ㅂ 16 4 4 17 6 18 18'6" 19 UL 5 6 20 9 21 Firm to stiff moist blue 22 CLAY with silt and sand lenses 23 24 25 25 3 REMARKS: GROUND WATER OBSERVATIONS TYPE OF SAMPLE D. - DISTURBED G.W. ENCOUNTERED AT INS. - UNDIST. LINER G.W. ENCOUNTERED AT INS. FT S.T. - SHELBY TUBE **G.W. AFTER COMPLETION** FT. INS. S.S. - SPLIT SPOON R.C. - ROCK CORE Standard Penetration Test - Driving 2" 00 Sampler 1' With G.W. AFTER HRS. FT. INS.

140# Hammer Falling 30"; Count Made At 6" Intervals

G.W. VOLUMES

Tt. 0		
IW-2 (CONT	inued

McDOWELL & ASSOCIATES Geotechnical Engineers

PROJECT Hi Mill Facility

LOG OF SOIL BORING NO. ___

89-630 JOB NO.___

LOCATION M-59 & Waterbury

NATE 12-12-89 Highland Township, Michigan SURFACE FLEY

	SURF	ACE ELEV.	OATE 12-12-89		нідп			p, Michie	<u>jan</u>	
S. et Centh	Legend		SOIL DESCRIPTION BK	enetration over for 5	Moisture	Natural VI. P.C.F	On Can Wt. P.O.F	Unc. Coma. Strength PSF.	Str.	7
				15						_
26			Firm to stiff moist blue							┚
			CLAY with silt and sand	-	1	<u> </u>	<u> </u>	<u> </u>	<u> </u>	4
1 27			lenses		<u> </u>	<u> </u>	!		 	4
					 	<u> </u>	 	<u> </u>	├	-
1 23	444	28'0"		<u> </u>	 	1	 	!	 	4
129		1				<u>!</u>	<u> </u>	!	 	\dashv
1 23				-	<u> </u>	<u>!</u>	<u> </u>	1	 	╣
: 30				-	1		 		<u> </u>	1
G				3			İ		i	1
UL. 31				3]
				4]
32			Minney 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5			<u>!</u> !	<u> </u>		1
			Firm moist blue CLAY with varved lenses of silt	<u> </u>	<u> </u>					4
			varved lenses of silt	-	 	<u> </u>	<u> </u>			┨,
1 1 2 2					<u> </u>		! !			┨`
34					1		<u> </u>			1
1 35					<u> </u>		<u> </u>			1
		•					i	<u></u>		1
#1 1 ST \ 36				<u> </u>						1
]
IN 37				L	<u> </u>		<u> </u>			1
41				ļ	<u> </u>					ļ
1 38		38'0"			1		<u> </u>	<u> </u>		1
1 20				}	<u> </u>		<u>'</u>			
1 39				 				·		
1 40			Medium compact wet gray							
Н			medium to coarse SAND	3			i			
UL 41				5						ĺ
				2						l
42		42'0"		8						
				 						
43				-			- !			ĺ
				-			1			
44								1		
45					 					ļ
			Logged by Robert Erp,		 		i			ĺ
46	'		Techna Corporation		 					ı
			-					·		
47										
										
48]									
					 				—	
49				-						
1 50	{	`			-	- 1				
1 1 30	 				 				$\overline{}$	
TYPE OF SAM	015	REMARKS:		+	cau	UND WATE	R OBSERVA	TIONS		
0. CISTUR	860	**Planceturge		G.W	ENCOUNTER				NS.	
U.L. UNDIST				G.W.	ENCOUNTERE	TA O		FT.	NS.	
SIG - CPUT S	SPOON	Claudant Da	netration Test - Oriving 2" OO Sampler 1' With		AFTER COMP	LETION			NS.	
RIC - ACCX C	ORE ROMETER	Stangard Per 140 # Har	nmer Falling 30"; Count Made At 6" Intervals		VOLUMES		ring.	"	''-3.	
, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			•							_

	Boring No	IW-2			
Job No. 89-630	Well No.	IW-2	Ту	pe2	11
	Piezometer No	·			
Type and Size of Auger	4 ¹ 5" I.D.	From	46'6"	То	Surface
Type and Size of Casir	10" PVC sch. 80	From	17'0"	To	Surface
Wash Boring With	Bit	From		To	
Size of Screen010		Туре	SS		
Bottom of Screen Set A 2" PVC Riser Pipe 41'6" to su		· · · · · · · · · · · · · · · · · · ·			
Filter Natural sand	From	46'6"	То	39'4"	- -
Bentonite 35 gal. bentoni	te slurry From	39'4"	То	38'-	_
Grout Cement/bentonite	From	38'-	To	Surface	<u>. </u>
Well Protector 4" So	uare steel				_
Developed With		· · · · · · · · · · · · · · · · · · ·			_
Remarks Top of Casin	g Elevation 1,01	14.56			
		· · · · · · · · · · · · · · · · · · ·			



Geotechnical Engineers

89-630

PROJECT_	H1	Mill	Facili	ĽУ

LOG OF SOIL BORING NO.__

LOCATION M-59 & Waterbury

1			JOB	10			LOCATION 11-33 & Waterbury							
Service Outh Legaco South Description Service Servic			SURF	ACE ELEV.	DATE 11-29-8			Highland Township, Michigan						
1	Sample & Type	Depth				Pen	etration	Moisture	Natural Wt. P.C.F.	Dry Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.		
Hole drilled through 11'4' of 10" Dia PVC Casing.														
2		11	1		Hala duallad shuamah 1	1 1 7 11		 		<u> </u>		┼─		
3		2					<u> </u>			 		†		
4					01 10 Dia 110 dabing	•								
5 6 6 7 7 8 8 9 9 110 111 11 4 12 13 14 14 14 14 14 15 16 16 16 16 16 16 17 17		3						ļ				 		
5 6 6 7 7 8 8 9 9 110 111 11 4 12 13 14 14 14 14 14 15 16 16 16 16 16 16 17 17	\vdash	4						-	 			+-		
												1		
10		5										 		
7		6						 	 	-		 		
10														
9		7			•							1		
10		R						<u> </u>				+		
10								<u> </u>						
11		9]						
11		10						<u> </u>				┼		
Stiff moist blue silty CLAY with tan silt lenses and plastic 14 15 A 16 17 18 20 20'0" Stiff moist blue silty CLAY with seams of wet gray fine sand, plastic Type of sample sand, plastic Type of sample 0. DISTURBED UI UMDIST LIMER ST. SKULET TUBE ST. SKULET T		1.0	1 1						<u> </u>			 		
Stiff moist blue silty CLAY with tan silt lenses and plastic 14 15 A 16 17 18 20 20'0" Stiff moist blue silty CLAY with seams of wet gray fine sand, plastic Type of sample 0. Disturbed UL UMDST LIMER ST. SHEW TORK THE SHEW THE ST. SHEW TORK THE SHEW THE ST. SHEW TORK THE SHEW THE ST. SHEW TORK THE SHEW THE ST. SHEW TORK THE SHEW THE S		11										I_		
with tan silt lenses and plastic 14 15 A 16 17 18 20 20 20'0" Stiff moist blue silty CLAY with seams of wet gray fine sand, plastic Type of sample sand, plastic Type of sample 0 Disturbed ult - UMOST, IMER ST SHEUR TUBE. REMARKS: GROUND WATER OBSERVATIONS G.W. ENCOUNTERED AT 15 FT. 0 G.W. ENCOUNTERED AT 30 FT. 0 G.W. ENCOUNTERED AT 30 FT. 0	' -+	12	7777	11'4"		_						┼—		
13	, +	12_						 				+		
14		13				lid .								
15	┝─┼	14			F				<u></u>			┼		
18		1 7										-		
16		15	<i>////</i>											
17	Α	16							-			├		
TYPE OF SAMPLE 0 OSTURGE OUL UNIONS LINER S.I SHELBY TIBE S.S SHELBY TIBE S.		10					_							
20 20'0" Stiff moist blue silty CLAY with seams of wet gray fine sand, plastic 179E OF SAMPLE 0 DISTURBED UL UNDOST. LINER S.T SHELBY TUBE S.S SHELBY T		17					4					\Box		
20 20'0" Stiff moist blue silty CLAY with seams of wet gray fine sand, plastic 179E OF SAMPLE 0 DISTURBED UL UNDOST. LINER S.T SHELBY TUBE S.S SHELBY T	┝─┤	18										┼		
20 20 20 20 20 20 20 20 20 20 20 20 20 2		1.0												
Stiff moist blue silty CLAY with seams of wet gray fine sand, plastic 23 24 TYPE OF SAMPLE 0 DISTURBED UL - UNDUST. LINER S.T SHELBY TUBE c. SCRUT SDROWN ST SHELBY TUBE c. SCRUT SDROWN ST SHELBY TUBE C. SCRUT SDROWN G.W. AFTER COMPLETION G.W. AFTER COMPLETION FI.		19										\Box		
Stiff moist blue silty CLAY with seams of wet gray fine sand, plastic 23 24 TYPE OF SAMPLE 0 DISTURBED UL - UNDUST. LINER S.T SHELBY TUBE c. SCRUT SDROWN ST SHELBY TUBE c. SCRUT SDROWN ST SHELBY TUBE C. SCRUT SDROWN G.W. AFTER COMPLETION G.W. AFTER COMPLETION FI.	 	20		2010!!					 			┼		
with seams of wet gray fine 22 sand, plastic 23 TYPE OF SAMPLE 0 DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S		20		20.0		67 A37						<u> </u>		
22 sand, plastic 5 7 23 5 24 25 0" TYPE OF SAMPLE 0 DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S SHELBY TUBE S.S SHELBY TUBE S.S SHELBY TUBE G.W. AFTER COMPLETION FT.	D	21										<u> </u>		
23 24 25 25 0" TYPE OF SAMPLE D DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S SRUIT SROOM S.S. SRUIT SROOM G.W. ENCOUNTERED AT 30 FT. 0 G.W. ENCOUNTERED AT 30 FT. 0 G.W. AFTER COMPLETION FT.	-	22	<i>\///</i>					-				 		
25 TYPE OF SAMPLE D DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S SHELBY TUBE S.S. SPILT SHOOM G.W. AFTER COMPLETION FT.			////		-		7							
TYPE OF SAMPLE D DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S. SPILT SHOOM G.W. ENCOUNTERED AT 15 FT. 0 G.W. ENCOUNTERED AT 30 FT. 0 G.W. AFTER COMPLETION FT.		23					5					 		
TYPE OF SAMPLE D DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S. SPILT SHOOM G.W. ENCOUNTERED AT 15 FT. 0 G.W. ENCOUNTERED AT 30 FT. 0 G.W. AFTER COMPLETION FT.		24	<i>{////</i>						<u> </u>			 		
TYPE OF SAMPLE D DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S. SPILT SPROM	<u> </u>													
D DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S SPUT SPOOM G.W. ENCOUNTERED AT 15 FT. 0 G.W. ENCOUNTERED AT 30 FT. 0 G.W. AFTER COMPLETION FT.	, Д	25		25'0''								 		
D DISTURBED U.L UNDIST. LINER S.T SHELBY TUBE S.S SPUT SPOOM G.W. ENCOUNTERED AT 15 FT. 0 G.W. ENCOUNTERED AT 30 FT. 0 G.W. AFTER COMPLETION FT.	TVP	E OF SAM	PLE	REMARKS:				GRO	L	R OBSERV	ATIONS	<u> </u>		
S.T SHELBY TUBE G.W. AFTER COMPLETION FT.	D.	- DISTUR	IBED					ENCOUNTER	ED AT	15	FT. 0	INS.		
R.C ROCK CORE Standard Penetration Test - Oriving 2" 00 Sampler 1' With 6.W. AFTER HRS. FT.	S.T.	- SHELBY	Y TUBE				G.W.	AFTER COM	PLETION		• • •	INS. INS.		
1 i orant tonacted 1 140 th Hammer Falling 30" Count Made At 8" Intervals GW VOLUMES 10110W AUGET	R.C.	- ROCK (CORE	Sta	ndard Penetration Test - Driving 2" 00 Sampler ID # Hammer Falling 30" Count Made At 8" Int	l' With ervals	6.W.	AFTER VOLUMES	Hollow	HRS. Auger	FT.	ins.		

I W - 3	cont	inued
T.14 2		11100

LOG OF SOIL BORING NO.____



McDOWELL & ASSOCIATES

Geotechnical Engineers

JOB NO. _____89-630

PROJECT Hi Mill Facility

LOCATION M-59 & Waterbury

DATE ___11-29-89 SURFACE ELEV.___ Highland Township, Michigan Natural Wt. P.C.F. Penetration Moisture Ory Cen Unc. Comp. 6 Type | Depth SOIL DESCRIPTION Legend Blows For 6' Wt. P.C.F. Strength PSF. 26 28 Stiff moist blue silty CLAY, with wet gray silt lenses 30 4 32 5 6 34 36 3 38 6 40'0" **Sampler sank under own weight from 40' to 42' 42 44 46 48 Well graded wet medium to coarse gray SAND, with a 50 trace of fine gravel 52 54 56 58 60 60'0" 62 64 66 68 70 72 74 76 GROUND WATER OBSERVATIONS TYPE OF SAMPLE REMARKS: 15 - DISTURBED FT. G.W. ENCOUNTERED AT INS. 30 0 - UNDIST. LINER G.W. ENCOUNTERED AT FT. INS. - SHELBY TUBE - SPLIT SPOON INS. G.W. AFTER COMPLETION FT. - ROCK CORE Standard Penetration Test - Driving 2" 00 Sampler 1' With G.W. AFTER HRS FT. INS. 140 # Hammer Falling 30"; Count Made At 6" Intervals G.W VOLUMES

IW-3 Boring No. Job No. ___ 89-630 Well No. _____ IW-3 Type 2" SS/PVC Piezometer No. Type and Size of Auger 44" I.D. To Surface From 60'0" Type and Size of Casing 10" PVC From 11'4" Surface To Wash Boring With _____ Bit From ____ To ____ Size of Screen _____.010 Type _____2" SS Bottom of Screen Set At Riser Pipe 2" I.D. PVC from 42'0" to Surface Filter Natural Sand & #3 Tan Sand From 47'6" 39'7" From 39'7" 35'0" Bentonite ½" Pellets Surface 35'0" Cement/Rentonite

Grout Cement/Bent	From 10	
Well Protector	4" I.D. Steel with hinged top	
Developed With		
Remarks Top of	Casing Elevation 1,011.90	
		<u>.</u>
	Contachnical & Hydrogeological Services	

TW	_	4

LOG OF SOIL BORING NO. _



McDOWELL & ASSOCIATES

Geotechnical Engineers

n	89-63
11	

PROJECT	Ηi	Mill	Fac	ili	.ty

LOCATION M-59 & Waterbury

11-15-89 Highland Township, Michigan DATE SUBSACE SLEV

			SURF	ACE ELEV DATE		 <u> </u>			, MICHI	
Sample & Type		Depth	Legend		etration s For 6"	Moisture %	Natural Wt. P.C.F.	Dry Oen Wt. P C.F.	Unc. Comp. Strength PSF.	Str.
<u> </u>	1									 ``
				Drilled to 8' with 12" Dia						
	_			Continous Flight Auger, set	<u> </u>	<u> </u>				
1				10" Dia PVC threaded casing to		<u> </u>				
	4			to 13' depth by pushing. Clea						<u> </u>
	4			Cleaned out inside of casing	<u></u>	<u> </u>				<u> </u>
	4			with 4.25" dia hollow auger		ļ	ļ			ļ
	4			during advancement of casing.	<u> </u>		 			<u> </u>
	4			3" standing water in casing		ļ	ļ			
	4			after installation. Placed	 	-				
	4			1/3 bucket of Pelletized	}	ļ				
	┥			Bentonite to absorb standing		 	<u> </u>			
	4			water.			-	 		
	4					 				
	┩				 					
	\dashv				 					
	Н				 	 				
	\dashv				<u> </u>					
	Н				\vdash	 				
	H									
\dashv	٦				•	<u> </u>				
	٦					 				
						1				
/				·		<u> </u>				
						ļ				
	Ц					<u> </u>				
	Ц			<u>.</u>		ļ <u> </u>				
	L				ļ	ļ <u>.</u>				
	L				<u> </u>	 				
	L	 -			 				··	
	H				 	 				
	Н	 			 -	 		 		
	-	 	}		}	 	-			
	-				 	 				
	\vdash				 	 				
	+				├──					
	H		i		 	 				
	H	 	1		<u> </u>					
	T		1		<u> </u>	 				
	T	 	Ì		\vdash					
	H		1		<u> </u>	1				
TYE) E	OF SAM	PLE	REMARKS:	 	GRI	UND WAT	ER OBSERV	ATIONS	
0.		- DISTUR	BED		l ww	ENCOUNTER			न.	INS.
		- UNDIST			G.W.	ENCOUNTER	ED AT		FI.	INS.
S.S		- SPLIT S	POON	Chandrad Banatania Tona Philip 90 000 0 17 1854		AFTER COM	PLETION	noc	ff.	INS. INS.
RC		- ROCK (ORE	Standard Penetration Test - Driving 2" 00 Sampler 1' With		AFTER		HRS.	f ī.	ITI 3.

LOG OF SOIL BORING	NO.	IW-4A



Geotechnical Engineers

89-630 JOB NO.__ ____ LOCATION_

PROJECT Hi Mill Facility

M-59 & Waterbury

DATE 11-28-89 Highland Township, Michigan

SURFACE ELEV.		DATE	11-28-89		Highland Township, Michi					
S Type Depth	Legend	SOIL DESCRIPTION			etration s For 6"	Moisture %	Natural Wt. P.C.F.	Ory Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
<u> </u>	4				<u> </u>	ļ	ļ		[igspace
2	-					<u> </u>	-			
 	1	0'0" to 14"			 -			 		├
3	1	Cement Bentonite	Grout	inside	-					
	1	10" I.D. PVC Casi								
4]		J							
	_									
5	-					ļ				\vdash
6	-{									
 	1									
7	1									
]									
8	4									'
	4					-				<u> </u>
9	┪									$oldsymbol{oldsymbol{arphi}}$
10	1									
11]									
H.	4									
12	-									
13	1					<u> </u>				
	1									
14	7,77	14'0"								
	<i>\////</i>			i				-		<u></u>
A 15	V///				P					-
ST 16	\///	Firm moist blue s	ilty (CLAY,	Ū	28			i	
	V///	plastic			S			*	(3500)	
17	<i>\///</i>	P/P. 0.75 - 1 TSF	•		Н		_			
	1///	SHELBY TUBE pushe	d from	n		·				
18	-	15'0" to 17'6"								
19	1									——
]									
20	4									
 	4									
21	1	,							- 	
22	1	**See log of IW-4	for	Soil						
]	Descriptions be	tween	17'6"						
23	4	and 30'0"								
	4									
24	1									
25	1									
	1									
TYPE OF SA		REMARKS:						R OBSERVA		
U.L UNDIS	T. LINER	* Calibrated Penetrome	cer			ENCOUNTERE ENCOUNTERE		47 50		INS. INS.
S.T SHELI S.S SPLIT	SPOON			, tera	G.W.	AFTER COMP			FT.	INS.
R.C ROCK		Standard Ponetration Test - Driving 2" OC 140# Hammer Falling 30"; Count Med	r Sampler 1 e At 6" Into	· With rvals		after Volumes	Ho11	HRS. OW Auge		INS.
I () - TEME		I The state of the			<u></u>					

LOG	OF	SOIL	BORING	NO	IW-4A	continued
LUU	UF	201 L	BURING	NU		



Geotechnical Engineers

JOB NO. 89-630

	Ηi	Mill	Facilit	: 3
PROJECT				

LOCATION M-59 & Waterbury

Highland Township, Michigan

		Juni	ACE ELEV	DATE				I Name			
apte & Type	Depth	Legend	-51 C	SOIL DESCRIPTION		netration rs For 6"	Moisture %	Natural Wt. P.C.F.	Ory Oen Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
	100			- -		├ ─					
	26						<u></u>	<u> </u>			
	27					 -					
	12/					-		1			
	28										
	29										
	30		30'0"								
В		7///				3					ļ
	31					3					ļ. <u>-</u> -
	22			Firm moist blue silty CL	AY,	8					
	32			plastic		 -					
	33		}					-	—		
\mathcal{I}	 		t						 		<u> </u>
1	34		[
			}								
	35		Ì								
С						1					
	36					2			 	·	
	27					3					
_	37					3					
r—	38										
 	100		Ì								
	39										
	40		40'0"							· · · · · · · · · · · · · · · · · · ·	
D						2					
	41			Stiff moist blue silty (LAY,	4	31_			2185	ļ
	40		ł	plastic		5	31	120	*	(1500)	
Y	42		Í			5				(2185)	
E	43					3					
	70	Y////	Í			6				7.77	
	44		1			7					
F		Y///	Į.			3					
	45	<i>\////</i>	1			5					
		V///	1			1				-	
	46	<i>\///</i>	1	•		7		-	ļ		
G	47	<i>{////</i>	1			3	22		 		
-	47	V///]	•	1	4	22		*	(1500)	
	48		47'6"	Compact wet fine gray s:	тту	12				(1.700)	
			48'0"	SAND, well graded							
	49			Attempt to push Shelby	lube						
	\Box			below 48' unsuccessfull	, drove						
	150		50'0"	Split Spoon instead,							
	E OF SAM		REMARKS:		·- ·-		GRO	UND WATE	R OBSERV		
O.	- Distur - U ndi st		*	Continued			ENCOUNTER		\$ 8	FT. 8	INS.
S.T.	- SHELBY	Y TUBE	*	Calibrated Penetrometer			ENCOUNTER AFTER COM		50	हर. ^U हर.	INS. INS.
R.C.	- SPLIT :	CORE	SI	andard Penetration Test - Driving 2" 00 Sampler 1" \	Vith	G.W	AFTER		HAS W Auge		INS.
	- PENETI		<u> </u>	140# Hammer Falling 30"; Count Made At 6" Intervi	ils	G.W.	VOLUMES	HOTIC	w Auge	-	

IW-4A	continued
-------	-----------

LOG	ΩF	SOIL	BORING	NO
LUG	vı	3016	DUNING	140



McDOWELL & ASSOCIATES
Geotechnical Engineers

JOB NO. 89-630

PROJECT Hi Mill Facility

M-59 & Waterbury

LOCATION

SURFACE ELEV. DATE 11-28-89 Highland Township, Michigan

Sample & Type	Depth	Legend	-	SOIL DESCRIPTION	Pen Blow	etration s For 6"	Moisture %	Natural Wt. P.C.F.	Ory Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.	
				Sampler advanced from 48'	to]
	51			50' with weight of hammer	only	5					 	1
H	50				•	5		 			├ ──	4
\vdash	52			-		7	<u> </u>			·	├	┪
	53					13					 	4
\vdash	23					12					├	┨
	54 -			Very compact wet gray medi	Lum :						 	1
	1,54		·	grained SAND, unifrom size	≥,						 	1
1	55			angular			-				 	忊
	-											1
	56											1
]
	57											
												1
	58			-	ĺ							_
												1
	59			-								1
											<u> </u>	Į.
	60		60'0"	· 		ļ				,		
	1			-		<u> </u>						ł
	61	Į I				 -			-			ł
	 	1		_		 						ł
	62					 						ŀ
 	10	}		-			-					ł
 	63_	1		-			 					ł
	+			-								
	64_											l
	65	 		-								-
 	+	1			1							
	66	1										i
	1			-								
	67			-								
		1										
	68	1										İ
				·	ļ							l
	69		}	·	;							
	-		}	-						•		
	70	1		-								-
		1										
	71	4		_								
	<u> </u>	4		-								İ
	72	4		÷		<u> </u>			<u> </u>	· ·		
	 _	4	1	-		 						i—
-	73	-	1						·	<u> </u>		ĺ
╂╾╌┤	+	1		•								ĺ
¹ - =	74	1		-								l
	75	┪		•		 						l
\vdash	75	1	ļ	-		 						-
	5 05 555	1015	9544.546			 	Car	IIIM WATE	R OBSERVA	TIONS		l
	E OF SAN		REMARKS:			, w	ENCOUNTER				1845	l
U.L.	- UNDIS	T. LINER		~			ENCOUNTER		47 50	fī. 6 fī. 0	ins. Ins.	l
l s.s	- SHELB - SPLIT	Spoon				G.W.	AFTER COM	PLETION		f f	ins.	ĺ
I Ří	- ROCK	CORE	j Sta	ndard Penetration Test - Oriving 2" 00 Sampler 1' Wi	TI .	G.W	AFTER		ḤRS	អ	INS.	

	• *					
	Boring	No	IW-4A			
Job No. 89-630) Well N	o	IW-4A	Туг	e 2" SS/	PVC
	Piezom	eter No.				
Type and Size of	Auger	I.D.	From _	0	To)
Type and Size of	Casing 10"	PVC	From _	13'0"	To	rface
Wash Boring With	n	Bit	From _		To _	
Size of Screen	.010		Type _	ss		·····
Bottom of Screen	n Set At	54	.'0"			
Riser Pipe 49'	0" to Surface	PVC				
FilterSand cav	e in	From _	54'0"	To _	46'6"	
Bentonite	" Pellets	From _	4616"	To _	45'0"	
GroutCement/E	Sentonite	From _	45'0"	To _	Surface	
Well Protector	4" I.D. Ste	el with h	inged top			
Developed With		·				
Remarks	SS drive point	for scree	n provided	by McDowe	ll & Assoc	iates.
Top of o	casing elevation	1,010.06				
					·	

IW-S

LOG O	SOIL	BORII	NG NO.
-------	------	-------	--------

McDOWELL & ASSOCIATES Geotechnical Engineers

PROJECT	Hi-Mill Manufacturing	
1 1100201		

JOB NO._____ 89-630

LOCATION M-59 & Waterbury

		SURF	ACE ELEV.	DATE <u>1-10-9</u> 0		High]	land To	ownship	, Michi	gan
Sample	Oeath	Legend			Penetration lows For 6"	Moisture	Natural Wt. P.C.F	Orv Den Wt. P C.F.	Unc. Comp.	Str.
& Type	-				DWS 70F0	1	WL. F.G.F	144. F G.F.	Strenath PSF	*
 	20	1 1				 				<u> </u>
	1	1				i				
	1 21	}				i .				
						<u> </u>				
	1 22					<u> </u>				
	 	1			<u> </u>	<u> </u>				
 	1 23	1						l i		
-	24	{				1				-
1	1 24	i		•	<u> </u>	İ				
	25	i]	25'0"							İ
A		1111		Chies maint blue milks	P					
ST	26			Stiff moist blue silty CLAY, plastic	U					
				CLAI, plastic	s	<u> </u>				
	27				H	<u> </u>		<u> </u>		
1					<u> </u>	<u> </u>				<u> </u>
B	28	////	28'6"	Command that commandian	5	1	-			<u> </u>
SS	29			Compact wet gray medium to coarse SAND, with a	7	1				
	23		29'3"	trace of fine gravel	8	i				
	30			22400 01 1210 92401						
				Compact wet gray fine						
	1 31			to medium SAND						
	 					!				
	1 32					! 				
 	+		2210#			<u> </u>				
-	33		33'0"			<u> </u>				
	34				-	ĺ				
						1				
	35			Extremely compact wet gray				<u> </u>		
С				medium to coarse SAND, with	<u> </u>					
SS	36			a trace of fine gravel	22					
					17					
	37			•	10				-	
 	38	1			-					
	1									
	39		**							
				•	<u> </u>	<u> </u>				
	40				1	<u> </u>				
D					10					
SS	41				18				<u>.</u>	
	42		4210		18	-	-			
-	44		42'0"		<u></u>					
	43								i	
	44	_								
	E OF SAI		REMARKS:					ER OBSERVA		
D. U.L.	- distu - undis	T. LINER				ENCOUNTER ENCOUNTER			हा. हा	INS.
SI	- SHELE - SPLIT	spoon			G.W.	AFTER COM			F	INS
3 3			Standard	Penetration Test - Oriving 2" 00 Sampler 1' With	I GW	AFTER		HRS	អ	INS.

Boring No. IW-5 89-630 Type 2" Well No. _ IW-5 Job No. Piezometer No. To Surface Type and Size of Auger ___41" I.D. From 42'0" To Surface Type and Size of Casing 10" I.D. From _20'0" Wash Boring With ______ Bit From ____ To ____ Size of Screen .010" Type Pottom of Screen Set At 35'0" Riser Pipe ___ PVC from 30'0" to Surface From 35'0" 26'6" Filter #3 Tan Sand From 26'6" 25'3" Bentonite 1 Pellets To From 25'3" Surface Grout Cement/ Bentonite To Well Protector _____4" Square Steel Developed With ____ Remarks _____Top of casing elevation 1,009.39

LOC	ne	con	BUBING	мп	DW-1
LUG	U٢	SOIL	BORING	NU.	DM-I



- PEN

" IFTER

McDOWELL & ASSOCIATES

Geotechnical Engineers

PROJECT Hi Mill Facility

JOB NO. 89-630

LOCATION M-59 & Waterbury

DATE 12-18-89 Highland Township, Michigan SURFACE ELEV._ Dry Den Penetration Moisture Natural Unc. Come. (voe | Gepth SOIL DESCRIPTION Blows For 6" WL P.C.F. WL P.C.F. Strength PSF. 26 28 30 32 Ì Water in augers to 20' - ; 34 at start of drilling (Boring drilled to 40' 36 12-15-89) 38 40'0" 40 - 1 Compact wet gray medium 42 grained SAND, with some fine gravel 44 46 UL 48'0" 5 48 50 Extremely compact wet gray 26 medium grained SAND 27 52 29 53'0" 54 Slightly compact wet gray medium SAND, with trace of 3 56 K fine gravel UL 58 59'0" 60 Compact wet gray medium UI 62 5 SAND 6 10 65'6" Extremely stiff moist blue 13 M 66 66'6" silty CLAY 111 13 68 68'0" Moist gray SILT 20 22 Extremely compact wet gray 70 10 medium SAND 71'0" 11 N 21 72 Extremely compact wet gray fine silty SAND 74'0" 74 11Extremely compact wet gray fine grained SAND 23 54 76 REMARKS: GROUND WATER OBSERVATIONS TYPE OF SAMPLE - DISTURBED G.W. ENCOUNTERED AT INS. FT. 20 0 - UNDIST. LINER U.L G.W. ENCOUNTERED AT IMS. · SHELBY TUBE G.W. AFTER COMPLETION FT. INS. - SPLIT SPOON - ROCK CORE Standard Penetration Test - Oriving 2" 00 Sampler 1' With G.W. AFTER HRS FT. INS R C.

140# Hammer Falling 30"; Count Made At 6" Intervals

G.W. VOLUMES



PROJECT Hi Mill Facility Geotechnical Engineers LOCATION M-59 & Waterbury 89-630

		SUHF	ACE ELEV.	DATE 12:	<u>-18-9</u> 0		Highi	and to		, Michig	an
mple Type	Depth	Legend		SOIL DESCRIPTION	Pen Blow	etration s For 6"	Moisture %	Natural Wt. P.C.F.	Dry Den Wt. P C.F.	Unc. Como. Strength PSF	Str %
UL.	77										
			-								
	79			Extremely compact we	t gray	ļ					
_	81			fine grained SAND		15	<u> </u>	 			
P UL						33					\vdash
01	83					63	<u> </u>				
			84'0"								
	85			Extremely compact wet	orav						
Q				fine sandy SILT	6)	17					<u> </u>
ŮL	87	11111		22 22		21_					
	89		88'6"			32	<u> </u>			<u>.</u>	
-+	1 89			Extremely compact wet	grav	 					┼─-
R	91			SILT	07	17					
UL			92'0"			22					
	93) <u> </u>			29					
	95										
										·· - ·	
	97										
 +	99										
	- 33										
	101										
										· · · · · · · · · · · · · · · · · · ·	
	103										
											<u> </u>
	105										
	107										
	1										
	109							į.			
	111					_,					
-+	113										
- 	113						<u> </u>			-	-
-	115										
	117										
			,								
	119		ĺ								
 	121					<u> </u>					
$\vdash \vdash \vdash$	121										
	123										
	125			•					I		
' →	1										
ــــــــــــــــــــــــــــــــــــــ	127				-		<u></u>			11000	
TYPE D.	OF SAMI - DISTURI		REMARKS:			, w			R OBSERVA		IMC
Ü.L.	- UNDIST.	LINER					ENCOUNTER ENCOUNTER		20	हा. 0 हा.	INS. INS.
SS.	- SHELBY	POON	Chande	4 Constration Test - Chining 99 60 Committee 11 1	Afiab	G.W.	AFTER COM		uec	FI.	INS.
R C.	- ROCK C - PENETR	ORE		f Penetration Test - Driving 2" 00 Sampler 1" \ Hammer Falling 30"; Caust Made At 6" Interv			AFTER VOLUMES		HRS.	FT.	INS.

4

Boring NoDW-1								
Job No. 89-630 Well No. Dw-1	Туре	2"						
Piezometer No.								
Type and Size of Auger 44" I.D. From 92'0'	<u>'</u> T	O Surface						
Type and Size of Casing Sch. 80 PVC From 15'0'	<u>'</u> т	o Surface						
Wash Boring With Bit From	T	o						
Size of Screen010" TypeSS	5							
Bottom of Screen Set At 83'0"	·							
Riser Pipe 2" PVC from								
Filter Natural sand From 92'0" To 41'6"								
Bentonite 30 gal. bentonite slurryFrom 41'6" To 39'6"+								
Grout Cement/bentonite From 39'6" To Surface								
Well Protector 4" square steel								
Developed With								
Remarks Top of Casing Elevation 1,014.62								
								

LOG OF SOIL BORING NO	1

Нi	Mill	Faci	lit	Ľ٧

DW-2

PROJECT____Hi Mill Fac

Geotechnical Engineers JOB NO._____89-630

LOCATION M-59 & Waterbury

	SURFACE ELEV DATE				DATE 11-30-89	11-30-89			Highland Township, Michigan					
pte	Depth	Legend		SOIL DESCRIPTION	Pen	etration is For 6"	Moisture K	Natural Wt. P.C.F.	Ory Den Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.			
	26			See log of IW-3	for Soil	<u> </u>				 	-			
1	20		-	Description abov						 	 			
	27			Top 13' of Borin										
	<u></u>			10" I.D. PVC Cas	ing.		ļ							
	28		ı				<u> </u>		<u> </u>	<u></u>	 			
\vdash	29					 			<u>. </u>		 			
 	123					 					 			
	30													
]												
	31_										 			
\vdash	32						<u> </u>				 			
	32					 					-			
	33	1												
]												
1	34	!									ļ			
	35				_									
A	39	7777	35'0"	Pushed Shelby Tu	be from	P								
ST	36			35' to 37'6", pi present in botto		U								
				present in botto	m or cape	S								
l _	37			Criff major blue	adlam CTAV	H					ļ			
	38			Stiff moist blue with silt lenses		4								
SS	30			WICH SIIC TENSES	, practic	7								
	39					8								
						9								
	40					<u> </u>					-			
-	41													
	171													
' 🗆	42													
Γ	1					<u> </u>	·							
	43		L 43'0"											
	44			Wet gray coarse	SAND, with	 								
				stones & lenses										
	45]		clay, well grade	ed.						ļ <u>.</u>			
C	46					<u> </u>					<u> </u>			
-	46					-					·			
	47													
	48													
\vdash	49		, , , , , ,			-								
	173		49'0"				 							
	50		[
.]														
1	E OF SAN		REMARKS:	Water inside cas	ing at start				ER OBSERVA	^				
	- UNDIS	T. LINER	1	of drilling.	-		ENCOUNTER ENCOUNTER		•	П. U.	ins. Ins.			
S.S.	- SHELB - SPLIT	SPOON			On Complex 1' Mich	G.W.	AFTER COM AFTER		HRS.	FT. FT.	INS.			
R.C.	- ROCK - PENET	CORE ROMETER		idard Penetration Test - Driving 2" 0# Hammer Falling 30"; Count M			VOLUMES	Holle	ow Auge					

	LOG OF SOIL BORING NO.
McDOWELL & ASSOCIATES Geotechnical Engineers	PROJECT Hi Mill Faci
89-630	LOCATION M-59 & Water

SOIL B	ORIN	G NO	DW-2	continued
PROJECT	Hi	Mill	Facility	

bury __ LOCATION _

	SURFACE ELEV.		DATE11-3	<u>0</u> –89	·	Highl	and,	Michigan			
& Type	Depth	Legend		SOIL DESCRIPTION		etration s For 6"	Moisture	Natural Wt. P.C.F.	Orv Gen Wt. P C.F.	Unc. Coma. Strenath PSF.	Str.
D	<u> </u>	***************************************	-			3					<u> </u>
	51		-	Command and modified to		4					
				Compact wet gray medium to		6	<u> </u>	ļ	ļ		
	52			coarse SAND, well graded		14	1	ļ			<u> </u>
┝╼┼	1 52						ļ 	<u> </u>	 	,	
 	1 53								 		
 	1 54								 		
	1										
	55										
	1								<u> </u>		
	1 56					-					
E	5.7		57'0"			5	12				
	_57		57.0.			3	14.		 		
	_58			Compact wet gray fine to		1					
	1			medium grained SAND, with soft blue clay in bottom							
!	1 59			of sample							
	1			**Hard drilling indicates							
	60		6'0"	possible presence of stiff		8	<u> </u>				
F				clay between these depths.		2	! 				
	61			Slightly compact wet gray fi	ne	1					
-	62		62'0"	to medium grained SAND, with		1					
. 1		////	D2 0	stiff moist blue clay seams							
	1 63										
<u> </u>	<u> </u>	<i>\$///</i>		Extremely stiff moist blue		-					
<u> </u>	64	1///		silty CLAY HARDPAN, with			<u> </u>				
	1_65	<i>\///</i>		sandy clay in tip of sampler							
G	1_05	V///				12				<u>-</u>	
	66	Y/// X			-	30	15				
						47					
	67					80	· ·				<u> </u>
	+	<i>\///</i>			!						
	68		68'0"								
 	69	<i>\///</i>				<u> </u>					
	1 09	V///		Extremely stiff moist blue						i	
	70	<i>Y///</i>		silty sandy CLAY HARDPAN							
Н		1////				34					
	71	<i>\///</i>				46				\	
	72	Y///				60					
-	1 12	*////									
1	73	1///									
		3////			:						
	74	<i>\$///</i>								!	
I	<u> </u>	<i>\///</i>				<u></u>				<u> </u>	
	75	<i>{////</i>									\dashv
-	E OF SA	5///	REMARKS:				C Pr	DUND WATE	ER OBSERV	ATIONS	
0.	- DISTU	IRBED .	-1 F 1041-111 L/10-			G.W.	ENCOUNTER		7	_	INS.
U L. S T	- UNDIS - SHELL					G.W.	ENCOUNTER	ED AT	•	ਜ	INS.
s s		SPOON		ndard Penetration Test - Driving 2" 00 Sampler 1' With		l .	AFTER COM	rtiiUN	HRS		INS.
		TROMETER		10# Hammer Falling 30", Count Made At 6" Intervals			VOLUMES				

1	DW	-2	Co	nt	inu	ed

	M
	G
	.lſ

McDOWELL & ASSOCIATES

Geotechnical Engineers

JOB NO. _____89-630

PROJECT Hi Mill Facility

LOG OF SOIL BORING NO.

LOCATION M-59 & Waterbury

_	_	SURF	ACE ELEV	DATE 11-31-89		Highl	and To	wnship	, Michi	gan
Sample & Type	Depth	Legend			netration vs For 6"	Moisture %	Matural Wt. P.C.F.	Ory Cen Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
	76		-		ļ	<u> </u>	ļ	 		ļ
├ ── ┶	/6		,		28	_	 			┼
-	77	<i>////</i>	77'0"		42	 	 	<u> </u>		┼─
-			/ / · · · · · · · · · · · · · · · · · ·		65	 	 			
	78			Entranal and 66 mater blue	100			 		_
	1	Y///		Extremely stiff moist blue silty sandy CLAY HARDPAN, with			 			
	79	Y////		fine gravel						
h	1	V///		Time Araver						
	80	V///	•	_						
		<i>Y///</i>								
	81		,		L					<u> </u>
J			,		58					<u> </u>
	82		82'0"		108					↓
				Extremely compact wet gray			ļ			
 	83			fine to medium grained SAND,	<u> </u>					 -
				well graded	-					
	84				-					
	05					-				-
	85				-		-			
}	86				\vdash					
K	- 00				13				· · · · · · · · · · · · · · · · · · ·	
	87	1	87'0"		28	15				
. —	. 07	Davi		Boulders encountered below	52					
	88	000		87'0"					_	
		1000				}_				
	89	0.6								
		300								
	90	16.00	90'0"		<u></u>	ļ				
	<u> </u>	4	l			 				ļ
	91	4								
╂┷╅	1 00	-	\	- 1 c 2		 	 			
 	92	-		End of Boring 90'0"	-					
-	93	†		Screen 86'6"	1	†	<u>† </u>			
	3-3-	1		Sand to 77'4 Bentonite 30 gallons						
\Box	94	1	j	Grout garrons		<u> </u>				
		1		Glode						
	95]								
	Ш				<u> </u>					
	96	4			-	<u> </u>				<u></u>
	 	4				 	ļ			
<u> </u>	97	4		•		 	 			
 		4				 				
 	98	4			\vdash	 	 			
	100	┪			-		 	<u> </u>		
	1100	1			-		†			
`	101	1								
1	1	1								
TYP	PE OF SA	MPLE	REMARKS:			GR	OUND WAT	ER OBSERV		
O.	- DISTU	RBED				ENCOUNTER		7	_{FT.} 0	INS.
ST		BY TUBE				ENCOUNTER AFTER COM			हा. हा.	INS. INS.
SS	- SPLIT - Rock	SPOON Core	s	tandard Penetration Test - Oriving 2" 00 Sampler 1' With		AFTER CUM		HRS	FT.	INS.
1 7	, PENE	TROMETER		140# Hammer Falling 30"; Count Made At 6" Intervals		VOLUMES	Hollo	w Auge	r	

McDOWELL & ASSOCIATES Geotechnical Engineers 21355 Hatcher Avenue Ferndale, Michigan 48220 Phone: (313) 399-2066

.

Boring	No	J- 2	_		
Job No. 89-630 Well No	. <u>DV</u>	J -2	Тур	ss/P	VC
Piezome	ter No.				
Type and Size of Auger 44"	I.D.	From	Surface	То	90'0"
Type and Size of Casing 10" I	.D. PVC	From _	Surface	To	13'0"
Wash Boring With	Bit	From _		To	
Size of Screen010		Type	SS		
Bottom of Screen Set At	86'6"	_		٠	
Riser Pipe 81'6" to Surface					
Filter #3 Tan Sand	From	81'6"	То _	77'4"	
Bentonite		77'4"	To _	?	
Grout Cement/Benotnite	From Be	op of entonite	То	Surface	
Well Protector 4" I.D. Stee	el with hir	nged top			
Developed With					
Remarks Top of Casing Elevat	tion 1,011.	.99			a.a. p. q. e.



McDOWELL & ASSOCIATES

Geotechnical Engineers

18	NO		 89-	630

PROJECT_

Hi-Mill Manufacturing

___ LOCATION _

M-59 & Waterbury

DATE ___1-10-90 Highland Township, Michigan SURFACE ELEV.____ Penetration Moisture Natural Orv Den Unc. Come. vper Depth Legend SOIL DESCRIPTION WIL P.C.F. Blows For 6" WE POF Strength PSF. 4, 1 | 26 Top 20' of Boring inside 1 | 27 10" Dia schedule 80 PVC casing. See IW-5 for 1 1 28 soils description to 42' 1 | 1 | 29 1 | 30 | | 31 1 32 | 33 34 35 1 | 36 | | 37 1 38 | | 39 1 40 1 41 42 42'0" 43 44 45 4 Compact to extremely 46 5 compact wet gray fine 8 silty SAND 47 11 48 49 1 50 REMARKS: GROUND WATER OBSERVATIONS TYPE OF SAMPLE - DISTURBED 0. G.W. ENCOUNTERED AT INS. - UNDIST. LINER - SHELBY TUBE FT. INS. G.W. ENCOUNTERED AT G.W. AFTER COMPLETION FT. INS. - SPLIT SPOON - ROCK CORE Standard Penetration Test - Driving 2" 00 Sampler 1' With HRS. FT. INS. G.W AFTER 140 # Hammer Failing 30"; Count Made At 6" Intervals G.W. VOLUMES 1 - PENETROMETER

	DW-3	continued
--	------	-----------

.0G OF	SOIL	BORING	NO.

McDOWELL & ASSOCIATES Geotechnical Engineers

Hi-Mill Manufacturing PROJECT

89-630

LOCATION M-59 & Waterbury

		SURF	ACE ELEV		DATE1-10		M <u>M-59</u> High!	_	-	, Michi	gan
.mpie & Tvoe	Death	Legend		SOIL DESCRIPTION		Penetration Blows For 6"	Moisture %	Natural Wt. P.C.F.	Orv Cen Wt. P.C.F.	Unc. Comp. Strength PSF.	Str.
В			•			8					<u> </u>
SS	51	7777	51'0"			15 20	 	 	<u>{</u>		┼
	52			Eutromolu stifi	f wat blue	22	i 			 	
	Ī .			Extremely stif: silty CLAY, with							
	53			and lenses of			<u> </u>	ļ			
	1 54				-	<u> </u>	<u> </u>				<u> </u>
1	!			•		-	<u>. </u>				
	55						<u> </u>				
	1					<u> </u>	<u> </u>				<u> </u>
С	56			•		19	<u> </u>				
SS	57					20	i				
				•		32					
	58						1				
+	1 59						<u> </u>				
	1						i			-	
	1 60						<u> </u>				
D						31	 				
SS	61					_31_ _47	 				
	62										
,	1		•				<u> </u>			<u> </u>	
 	63		63'0"		•	 	<u> </u>				
	64				_		İ		į		
				Extremely compagnay clayey SA			<u> </u>				
	65			seams of fine	blue clay		1	<u> </u>			
-	66			and a trace of	fine grave	1 .	Ì		i		
E						8					
SS	67					13	<u> </u>				- Ĭ
	68		68'0"			19	 			•	
	1 00	////	. 00 0	•			i				
	69										
	+			Extremely stif		ie	1			<u> </u>	
F	70	<i>\///</i>		silty sandy CL seams & layers		19	 	<u> </u>			
SS	71	Y///		clayey sand	-= 31	30					
		<i>\///</i>				44					
	72	<i>{////</i>				-	<u> </u>			<u>_</u> !	
	73	V///					i				
		Y///	:								
	74	V///					<u> </u>			<u> </u>	
I	75	////				-	 				
, -											
1	E OF SAN		REMARKS:				GR	OUND WATE	R OBSERVA	TIONS	
D. V L.	- Distur - Undist	T. LINER					ENCOUNTER				INS.
\$ T \$ S	- SHELB	Y TUBE			. , , , , , , , , , , , , , , , , , , ,	G.W.	AFTER COM			F	IMS.
A C	- ROCX	CORE	Standa (40 st	d Penetration Test - Orlying 2" OX F Harr - Falling 30", Count Mad	I Sampler 1" With a Al 6" Intervals		AFTER VOLUMES		HRS	FT	INS.
_!'	, FERE	INDING I CIT							=		

LOG OF SOIL BORING NO.	LOG	OF	SOIL	BORING	NO.
------------------------	-----	----	------	--------	-----



McDOWELL & ASSOCIATES

Geotechnical Engineers

JOB NO._____

PROJECT Hi-Mill Manufacturing

LOCATION M-59 & Waterbury

SURFACE ELEV. DATE 1-11-90 Highland Township, Michigan

Penetration Mousture Natural Or Car Unic Comp. | Str.

ennie Frype	Depth	Legend	ACE ELEV.	SOIL DESCRIPTION	Penc	tration	Moisture	Matural	Orv Cen Wt. 9 C.F.	Unc. Come.	Str.
& Type	1	////	The second secon	white measure items	Riows	For 6"	<u> </u>	Wt. P.C.F.	Wt. 9 C.F.	Strength PSF.	1 %
	76							 	 		┼
SS	/6					38 42					
-	77			•		4)					
-	 		771611								
-	78		77 '6"						İ		
 	11 /0							 	 		-
-	1 79	////						-			
	1 19			Extremely stiff moist	hlue			 		<u> </u>	-
	80			silty CLAY, with lense							-
H_	1 80			of gray silt		30					
SS	- 01			or gray sire							-
-	81	////				45 59					-
	00					_54_		<u> </u>			
	82										
-	1 02		83'0"				<u> </u>				-
	83		. 55 5						 		
<u> </u>	1 04	////									├──┤
	84	<i>////</i>		Extremely stiff moist	blue				-		
 	11 05			sandy CLAY HARDPAN, w							
 	85			a trace of fine grave:				-		-	
I	2.5			•		67		i ·			
SS	86					86					
						77/	5"				 -
_	87								- !		
-	1 1										
	1 88			•							
 	1										 -
 	89							<u> </u>	<u> </u>		
	 										
-	90	<i>{///</i> //				70					
J_	91	<i>{////</i>	90'10"			70	/ 4 !!				
SS	91	1224	70 22			190	74"				
	1100	 									
}	92	1									
	1 03	1									
	1 93		•	•							
	1 1 04	{									
<u> </u>	1 94	-						 			
	1 05	-{						-	<u> </u>		
	95	-									;
	1100	-		•				 			
	1 96	-						 			
	++	1									
	97	1									
	1 98	-				 		-		<u>.</u>	
	1 38	1				 		-			
	1 00	1							 		
	99	1				 				<u> </u>	-
L	1100	1				}		 	 		
_	100	1				 -			 		
-		<u> </u>				<u> </u>				ATIONS	
	PE OF SAN OISTUR		REMARKS:			_			ER DBSERV		
D.	L UNDIS	t. Liner					ENCOUNTER ENCOUNTER			គ. រា	INS.
S	T - SHELB	Y TUBE					AFTER COM			អ	INS.
i R	S - SPLIT	CORE	Standard	Penetration Test - Driving 2" 00 Sampler 1' W	fith	G.W	AFTER		HRS	FT.	INS.
Ü	I PENET	ROMETER	140#	Hammer Falling 30", Count Made At 6" Interva	ls	GW	VOLUMES				

McDOWELL & ASSOCIATES Geotechnical Engineers 21355 Hatcher Avenue Ferndale, Michigan 48220 Phone: (313) 399-2066

DW-3 Boring No. Well No. DW-3 Job No. 89-630 Type Piezometer No. From 90'10" Surface Type and Size of Auger 41" ID To From ²⁰' Surface Type and Size of Casing 10" ID Wash Boring With _____ Bit From To Size of Screen _____.010" Type Bottom of Screen Set At 70'0" Riser Pipe PVC from 65;0" to surface 63'0" 69'4" Filter No.3 Tan Sans From Bentonite !" Pellets 61'4" 63'0" From Grout Cement/Bentonite Surface 61'4" From Well Protector ____ 4" Square Steel Developed With Remarks Top of Casing Elevation 1,009.41

S.S. - SPLIT SPOON

LOG OF SOIL BORING:

PROJECT: Hi Mill Manufacturing Co. RI/FS

LOCATION: 1704 Highland Road

G.W. ENCOUNTERED AT:

JOB NO.: 201-8058-13

Highland, Michigan

140# Hammer Falling 30"; Count Made At 6" Intervals

LOG OF SOIL BORING:

A2

PROJECT: Hi Mill Manufacturing Co. RI/FS

LOCATION: 1704 Highland Road

JOB NO.: 201-8058-13

JRFACE ELEVATION: 1010.99 DATE: 01-24-90

Highland, Michigan

SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION		PENETR BLOWS 1	
A	1 2		6" 1'6" 2'0"	Frost Sandy clay with fine gravel, moist, Brown sandy topsoil, moist, vegeta Sandy clay, moist, plastic, trace fin	ation fill		
В	3		3'6"	Clayey silt, low plasticity, dilatent, or brown with vegetation	moist to saturated	,	
С	5		5'0 " 5'6"	Silty clay, plastic, moist, trace sand chalky white streaks Clayey silt, low plasticity, brown, m	_	Jular	-
D	7.		6'6*	Silty clay, moderate plastic, oxidize of brown saturated silt	d brown with sea	ms of	
	9		8'0 "	Soil Clay Interace at 6'6"			
	10						
	12						
	14						
	15						
	17						
	19						
	21						
	22						
	24						
	OF SAMPLE HELBY TUBE	Standar	d Penetratio	by G. DeWitt Test - Driving 2" OD Sampler 1' With 30"; Count Made At 6" Intervals	GROUND WATER G.W. ENCOUNTER		TION

S.S. - SPLIT SPOON

PROJECT: Hi Mill Manufacturing Co. RI/FS

LOCATION: 1704 Highland Road

G.W. ENCOUNTERED AT:

OR NO	201-8058-13
OR NO:	201-0050-13

PEACE EL EVATION: 1010.58 DATE: 01-24-90 Highland, Michigan

SAMPLE AND TYPE		7.5				T	
	DEPTH	L e gend		SOIL DESCR	RIPTION	PENET	
				Clayey topsoli, some	rsand, molst, brown with veg	etation	T
A	1				_		-
			6"	Silty clay, moist, mo	derately plastic, variegated w e lenses and fine silty sand	ith	
	2	j		irregular chalky white	e lenses and fine silty sand		\vdash
		i					_
8	3	1	3'0"	Silty clay, plastic, mo	pist, thin lamina with seams o	f brown	
				wet silt			
	4						
				Soil Clay Interface a	it 3'0"		
<u> </u>	5		EOB				
			EOB 5'6"				
	6		30				
	7						
							<u> </u>
	8						-
	9						<u> </u>
							
	10						-
							\vdash
	11						
							\vdash
	12						
							_
	13						
	14						
		1					
	15	ļ					
	16	:					<u></u>
							<u> </u>
	17						<u> </u>
							
	18				•		<u> </u>
							<u> </u>
	19						<u> </u>
	20						
							\vdash
	21						\vdash
	22_						
]					
	23	ĺ					
		•					
	24						
		ľ					
	25	1					
							<u></u>
TYPE OF S.T SHEL			RKS: Logged I	by G. DeWill Test - Driving 2" OD Samp	GROUND WATE	er observ	AOITA'

140# Hammer Falling 30"; Count Made At 6" Intervals

S.S. - SPLIT SPOON

LOG OF SOIL BORING: Hi Mill Manufacturing Co. RI/FS PROJECT:

IOB NO.: 201-8058-13 LOCATION:

1704 Highland Road

G.W. ENCOUNTERED AT:

ND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION	PENETI	
		 		3 rost, sandy topsoil, moist with vegetation	1,,,,,,,	1000
A	1	1	6*	Sandy clay, plastic, moist, trace fine sand, oxidized	d brown	
]	Olon.	Observe and regards of sales		
	2	4	2'0"	Clayey sand, predominately medium, trace fine g saturated with 1" discolored streak at 3'2"	ravel,	
- B	3	-{		saturated with 1" discolored streak at 3.2"		
	 	1 1	3'4"	Silty clay, plastic, moist, thin lamina, with seams o	f brown	
	4	1		wet silt		
]]				
C	5	4	EOB	Soil Clay Interface at 3'4"		
	6	-	5'6"	Con Clay Interface at 5 4		<u> </u>
		-				 -
	7	1 1				
]				
	8					
	9	-{ 1				<u> </u>
	 	┪				
	10	1				
]				
	11	4				
	 	-{		•		
	12	-{				
	13	┪ [
]				
	14]				
	1.	-				
	15	1 1			I	<u> </u>
	16	1				
]				
	17]				
	 	∤ 				
	18	-				
	19	i I				
		1			ļ	
	20]				
		4				
	21	-{				
	22	1 .				
	23]			j	
		4 1				
 -	24	-				
	25	- 				
	 	1 1				

140# Hammer Falling 30"; Count Made ∧1 6" Intervals

PROJECT: Hi Mill Manufacturing Co. RI/FS

	rkojeci	
OB NO.: 201-8058-13	LOCATION:	1704 Highland Road
JRFACE ELEVATION: 1010.58 DATE:	01-24-90	Highland, Michigan

KI'ACE EL	CANHON: -	1010.58 DATE:		
SAMPLE AND TYPE	DEPTII	LEGEND	SOIL DESCRIPTION PENET BLOWS	FOR 6
			3° flost, sandy day, molst, trace fine gravel oxidized brown	1
A	1	1	to brown	
		1		
	2	i		
		7 }		
	3	1 !		—
	- 	1 1	3'8" Silty clay, low plasticity, moist to saturated, seams of wet	-
В	4	-{	silt, brown with irregular white streaks	
		-{ }	EOB	
	5	-	4'0" Soil Clay Interface at 3'8"	
		- 1	To on only monato at o o	
		-		ļ
	6	-l -l		<u> </u>
	- 	-		<u> </u>
	7			
		.i		<u> </u>
	8	<u> </u>		
]		L
	9] }		
]		
	10]		
		1		
	11	1 , I		
	<u> </u>	i 1		
	12	1		\vdash
		1 1		
	13	1 1		
		-		├
	+	-		
	14	-		-
	-	-		-
	15			
		4 1		<u> </u>
	16	_		<u></u>
		_		<u> </u>
	17			<u></u>
	18	_		L
1.]		
1	19	<u>.</u>		
]		
	20] [
]		
	21	7 l		
	1	7 l		
	22	1		
		1		
	23	1		-
	+	1		-
	24	1 l		
	- 49	- I		-
	25	- 		-
	- 23	4 l		L
	1			

S.T. - SHELBY TUBE S.S. - SPLIT SPOON Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT: 3'6"
G.W. ENCOUNTERED AT:

LOG OF SOIL BORING: PROJECT: Hi Mill Manufacturing Co. RI/FS

JOB NO.: 201-8058-13	LOCATION:1704 Highland Road
	145-61

LOG OF SOIL BORING: Hi Mill Manufacturing Co. RI/FS PROJECT:

OR NO	201-8058-13
., 114 121 1	

S.S. - SPLIT SPOON

1704 Highland Road

G.W. ENCOUNTERED AT: _

3 NU.:	8058-13			LOCATION: 1704 Highland Roa				
RFACE ELE	VATION:	1009.51 DATE:		01-24-90 Highland, Michigan				
SAMPLE ND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION	PENETRATION BLOWS FOR			
		 		Sandy clay, exidized brown to brown,	- 10.0 W3 TOR			
	1]	8"	moist Silty clay, moist, variegated tan with trace				
	ļ	1		sand	<u></u>			
	2	1	1'6"	Silty clay, moist, variegated brown wit chalky white lenses and layers of silt,	<u> </u>			
B	3	<u> </u>		chalky white lenses and layers of silt, dilatent				
6]		Cilaterit				
	4			Soil Clay Interface at 1'6"				
	5	1						
- D -	6	-	EOB					
	-	-	6'0"		 			
	7	1						
	8	4						
	 	1						
	9]						
								
	10	 		•				
	11	1						
	12	1			 			
	13	1						
		-						
	14	1			·			
	15	1						
	12	1						
	16	┨			<u> </u>			
	17	1						
]						
	18	1 1						
	19	1						
	20	1			 			
	21]						
	22	4 .			 			
		1 1			 			
	23]						
	24	1			 			
		1 1			 			
	25							
	F SAMPLE	1	S: Logged b		ATTER OBSERVATIO			

140# Hammer Falling 30"; Count Made At 6" Intervals

LOG OF SOIL BORING: Hi Mill Manufacturing Co. RI/FS

10B NO.: 201-8058-13			LO	LOCATION: 1704 Highland Road			
JURFACE ELEVATION: 1010.55 DATE: _		TE:01-26-90	01-26-90				
SAMPLE AND TYPE	DEPTH	LEGEND		DESCRIPTIO	N	PENETRATION BLOWS FOR	

JRFACE ELE	ير:VATION	1010.55 DA	TE:	01-26-90 	nightanu, N	neriigan		
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCR	IPTION	1	PENETR BLOWS	ATION
				Medium stiff, moist, p brown clay fill with tra	plastic to very plast ace sand and gray	ic, oxidized s	silty	
]		vegetation	,			
	2		3'0•	Medium stiff moist, va	arienated ovidized	hrown eilty c	rlav	
	3	1		with interlacing vein	s of chalky white in	terval and tra	ace	
	4	-	EOB	gravel				
	5		4'0"	Soil Clay Interface a	t 3'0"			
	6	1 1						
	7]						
	8]						
	9	1						
	10							
	11	1						
	12	1						
	13							
	14]						
	15	_						
	16	}						
	17	}						
	18							
	19							
	20	1 1						
	21	1 1						
	22	1					}	
	23	1					}	
	24]					ł	
	25	<u> </u>					-	
TYPE	OF SAMPLE	REMA	RKS: Logged b	y G. DeWitt	GRO	DUND WATER O)BSERV/	YTIONS

S.T. - SHELBY TUBE

S.S. - SPLIT SPOON

Standard Penetration Test - Driving 2" OD Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

O.W. ENCOUNTERED AT:

O.W. ENCOUNTERED AT:

G.W. ENCOUNTERED AT:

LOG OF SOIL BORING:

PROJECT:

Hi Mill Manufacturing Co. RI/FS

G.W. ENCOUNTERED AT: 3'0"

G.W. ENCOUNTERED AT:

S.T. - SHELBY TUBE

S.S. - SPLIT SPOON

1704 Highland Road LOCATION:

JOB NO.: 201-8058-13 Highland, Michigan 01-26-90 1011.17 DATE: _ **RFACE ELEVATION:** SAMPLE PENETRATION LEGEND DEPTH SOIL DESCRIPTION AND TYPE BLOWS FOR 6" Soit, moist, oxidized brown slity clay fill with trace sand and gravel ī Brown clayey topsoil, moist with trace sand and gravel and 1'0" vegetation 2 Medium stiff, moist, oxidized silty brown clay with trace 2'6" gravel and pebbles, plastic 2" layer of oxidized brown B 3 clayey silt, very moist at 3'4" 3'6" Medium stiff, variegated oxidized brown and brown and and chalky white, silty clay very plastic D 5 EOB Soil Clay Interface at 3'6" 6 6'0" 7 8 9 10 H 13 14 15 16 17 18 19 20 22 23 24 25 TYPE OF SAMPLE REMARKS: Logged by G. DeWitt **GROUND WATER OBSERVATIONS**

Standard Penetration Test - Driving 2" OD Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

PROJECT: Hi Mill Manufacturing Co. RI/FS

1704 Highland Road

IOB NO.:	LOCATION:	1704 Highland Road	
м /В (NO.;	01-26-90	Highland, Michigan	

RFACE ELE	VATION: _	DATE:		01-26-90 	nighland, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRI	PTION	PENETRATIO
A	1 2		2'0°	Fill soft, very soft, mois silty clay with trace sa vegetation, plastic Dark brown clayey top and vegetation	nd and gravel and	BLOWS FOR 6
В	3		3'9"	Medium stiff, moist va oxidized brown, grey a	aligated with and dark brown silty and trace S.H. gravel	
0	7		6'0°	V. stiff, moist, varizgate and grey silty clay into white material, trace s plastic	erfaced with chalky	
	9			Soil Clay Interface at	3'9"	
	12					
	15					
	17					
	20					
	22					
	24					

S.T. - SHELBY TUBE S.S. - SPLIT SPOON Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT: 3'6'
G.W. ENCOUNTERED AT: _____

PROJECT: Hi Mill Manufacturing Co. RI/FS

				PROJECT: _	1704 Highland Road	
∩B NO.:				_ LOCATION:	Highland, Michigan	
JRFACE ELE	EVATION:	DATE	E:	01-26-90	- Ingiliaria, Micrigari	
SAMPLE AND TYPE	DEPTII	LEGEND		SOIL DESCRIPTION		PENETRATIO BLOWS FOR 6
				Sity clay with sand and v Fill with concrete and asp	regetation	
	1			i iii waa oonorete ana asp	Ji lait	<u> </u>
	2					
 	3		3'0"	Medium stiff, moist, varied	gated oxidized	
		1		brown and grey silty clay white chalky material, pla	interfaced with estic (tope 3" has	
	4			apparent reddish veneer	on clay clumps)	
0	5	1 1				
	6	1	EOB	Soil Clay Interface at 3'0"		
		1				
<u> </u>	7					
	8					
	9					
	10					
	10					
	11]				
	12]				
	13					
		j				
	14					
	15					
	16	}				ļ
/	17	1				
	18]]				
	19					
	20	1				
	21					
	22					-
	23					
	23					
	24					
	25]				
TYPE	OF SAMPLE	[KEMAR]	KS: Logged	by G. DeWitt	I GROUND WAT	ER OBSERVATION

S.T. - SHELBY TUBE S.S. - SPLIT SPOON Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals G.W. ENCOUNTERED AT: 3'6' G.W. ENCOUNTERED AT:

S.S. - SPLIT SPOON

PROJECT: Hi Mill Manufacturing Co. RI/FS

G.W. ENCOUNTERED AT:

				PROJECT:		and acturing of	
)B NO.:				LOCATION: _		lighland Road	
RFACE ELE	EVATION:	1010.18 DATE: _		01-26-90	Highla	nd, Michigan	· · · · · · · · · · · · · · · · · · ·
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION	N		PENETRATION BLOWS FOR
				Stiff, moist, oxidized brow with trace sand and grave	n silty fill el, plastic	clay with	
	2		2'0"	vegetation V. stiff, moist, variegated of	oxidized	brown	
- B	3			grey silty clay interlaced material, v. plastic with tra	with whit ace sand	e chalky I	
	4		ЕОВ	Soil Clay Interface at 3'0"			
	5		4'0 "				
	6						
	7						
	8						
	9						
	10						
	11						
	12						
	13						
	14					·	
	15						
	16						
	17						
	18						
	19						
	20						
	22						
	23						
	24						
	25						
2007 10	N. CANADI D	100111000	1	C D W.		L angues	
	OF SAMPLE IELBY TUBE	REMARKS: Standard Pen		oy G. DeWitt Test - Driving 2° OD Sampler 1' V	Vith	GROUND WATE G.W. ENCOUNTE	

140# Hammer Falling 30"; Count Made At 6" Intervals

F3 LOG OF SOIL BORING:

			PROJECT:	Hi Mill Manufacturing Co	. RI/FS
JOB NO.: 201-8058-13			LOCATION:	1704 Highland Road	
/RFACE ELEVATION	N: DATI	E:	01-26-90	Highland, Michigan	
SAMPLE DEPT	II LEGEND		SOIL DESCRIPTION		PENETRATION BLOWS FOR 6"
		- 6	Medium stiff moist oxidize	d brown silty clay fill with	Tirace
			sand and gravel and vege	etation	
			Brown clayey topsoil fill w	ith trace sand, plastic an	ıd
2		2'0"	vegetation	:	
B-		20	Stiff moist variegated oxid fill with trace sand and da	ized brown and grey siit rk brown strooks	y clay
3	i	3'6*	Very stiff, moist variegated	t brown and grov eilty of	au with
		•	interlaced white chalky m	esterial very plactic	ay with
1	 i		michaee wine chary in	iaterial, very plastic	
	i		Soil Clay Interface at 3'6"		<u> </u>
5			our only intollace at 0 0		
6	 -∤				
					
	 				<u> </u>
 	 i		·		
8					
,					<u> </u>
9					**************************************
10	 -				
					
11					
12					
13					
14					
 					
15	 				
16	- 				
	 				
17	-				
·	-				
18	-				
	 				-
19					
	-				· ·
20					
21					
22					
ļ—————————————————————————————————————	I				

TYPE OF SAMPLE S.T. - SHELBY TUBE S.S. - SPLIT SPOON

24

25

REMARKS: Logged by G. DeWitt Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30°; Count Made At 6° Intervals

GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT:

None G.W. ENCOUNTERED AT:

LOG OF SOIL BORING: Hi Mill Manufacturing Co. RI/FS PROJECT

¹OB NO.:	LOCATION:	1704 Highland Road	
URFACE ELEVATION: DATE:	02-01-90	Highland, Michigan	
SAMPLE DEPTH LEGEND	SOIL DESCRIPTION	N	PENETRATIO!

SAMPLE AND TYPE	VATION: JEPTII	LEGEND		SOIL DESCRIPTION	PENETRATION
AND TYPE		3303,10			BLOWS FOR 6
			0	Brown oxidized silty medium fine, v. moist	
	1	1		sand, trace gravel - loose v. moist dark	
		1		brown clayey topsoil with vegetation, soft	
	2	1 1		slightly plastic, trace oxidation and sand	
	 	1 1	1'8"	Medium stiff plastic variegated oxidized brown and grey silty clay, moist, trace	
	3	1		brown and grey silty clay, moist, trace	
	 	1		vegetation and sand fill	
	 	ł /	4'0"	V. stiff, moist, v. plastic variegated oxidized	
	1	- I		brown and grey silty clay with trace of	
		1 1		white chalky material interlaced and tan?	
	5	1 1		of greyish silt and trace vegetation	
	ļ	1 1		' graylori and made regolation	
	6	j		Soil Clay Interface at 4'0"	
] [EOB	Son Clay Interface at 4 0	
	7] !			
]	7'6"		
	8	1 1			
		1 i			
	9	1			
		1			
	10	1			
	<u>'</u> -	1			_
	11	ł I			
		1 1			-
		·			<u> </u>
	12				
		↓			
	13	1 1			
	ļ]			
	14]			
]]			
	15]			
		1			
	16	1			1
	 	1 1			-
	17	1 1			
		<u> </u>			
	18	!			
<u></u>	 	1 1		•	
	 	.			
	19	1 1			<u> </u>
	ļ	1 1			
	20	j j			
]			
	21]			
]		ı	
	22] : [<u> </u>
	1	1			
	23	1 1			
		1 1			
	1 24	1			ļ
 -	24	i I		•	
		1			<u> </u>
	25				

S.T. - SHELBY TUBE S.S. - SPLIT SPOON

REMARKS: Logged by G. DeWitt Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS None G.W. ENCOUNTERED AT: G.W. ENCOUNTERED AT:

PROJECT: Hi Mill Manufacturing Co. RI/FS

100.110				LOCATION: 1704 H	Highland Road	
OB NO.:	EVATION:	1008.98 DATE:			ınd, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION		PENETRATION BLOWS FOR 6"
	 	 	6 -	Brown clayey topsoil with little sai	nd _	W. 6 . 7 C K 9
^	1	†		trace gravel flost		
]				
	2	_				
}B -	3	_}	3'0"	Stiff moist variegated oxidized bro	wn and	<u> </u>
	 	1		grey silty clay fill trace sand and g		
	4	1 1		trace dark brown silty clay, plastic	;	
6						
<u> </u>	5	4	5'6"	Medium stiff, moist, organic green	nish blue	
	6	- 1		gray silty clay fill, trace sand and	gravel	ļ
 	 	1				
D	7]	EOR	V stiff maist variageted evidined	brown	
	ļ <u>.</u>	↓	EOB 7'6 "	V. stiff, moist variegated oxidized and grey silty clay, with interstitia	orowri I chalkv	
 	8	-	, ,	white material, some stratification	n at	
	9	┪		bottom 6"		
		1		Only Ole Than form at 1910.		
	10			Soil Clay Interface at 5'6"		
<u></u>	ļ	_				
	11	-				<u> </u>
	12	- !				
	13]				
	14	-				<u> </u>
	+	-				
	15					
]				
	16	4				
 	17	-				
1		j				
	18]				
	 	-				ļ
	19	-				
	20	†				
]				
	21	-				<u> </u>
	22	- 1				
	23]				
	 	-				
 	24	-				
	25	1 1				
		ll				
	OF SAMPI,E			by G. DeWitt	GROUND WATE	R OBSERVATIONS
	HELBY TUBE			Test - Driving 2" OD Sampler 1" With	G.W. ENCOUNTE	RED AT:
3.3. • 3	I LI I SPOON	14U# 118###	er Calling	30"; Count Made At 6" Intervals	G.W. ENCOUNTE	KBDAL

LOG OF SOIL BORING:
Hi Mill Manufacturing Co. RI/FS
PROJECT:
1704 Highland Road

OB NO.:					LOCATION:	ighland Road	
JRFACE EL	.E.	VATION: _	DA DA	TE:	02-05-90 Highlar	nd, Michigan	
SAMPLE AND TYPE		DEPTH	LEGEND		SOIL DESCRIPTION		ETRATION
7117	Н				V. Moist, strong brown topsoil fill, to	race	WS FOR 6"
	H	1	1		gravel		}
	\Box		İ	8"	Fine gravel with trace sand fill, loos	se	
	\Box	2		2.'2"	Grevish brown medium dense very	, moist	
	\vdash	3			Greyish brown medium dense very to saturated fine silty sand fill with	trace	
	H	<u> </u>			gravel		— —
		4					
	Н	5					
	H	6	1				
			1				
	\sqcup	7					
	╟┤	8					
	\Box						
		9					
	Н	10					<u> </u>
	H	10		441	Cate and a local and a site and a		
		11		11'	Stiff moist plastic gray silty clay value with thin lamina of tan and opey sil	rvea It	
	\Box				with this faith and opey si		
' 	Н	12	1		Soil Clay Interface 11'10"		
	H	13					
	\sqcup	14					
	Н	15					
				EOB			
	Ц	16		16'0°			
	╌	17					
	Н		1				-
		18					
	Ц						
	dash	19					
	H	20					
	口						
	Ц	21					
	Н	22	,				
	Ц	23					
	${\mathbb H}$	24					
;	H	24					
		25					
		P SAMPLE		RKS: Logged b		GROUND WATER OBSE	RVATARHE
		ELBY TUBE			Test - Driving 2" OD Sampler 1' With 30"; Count Made At 6" Intervals	G.W. ENCOUNTERED AT G.W. ENCOUNTERED AT	

PROJECT: Hi Mill Manufacturing Co. RI/FS

IOB NO.:		LOCATION:		
JRFACE ELEVATION:	DATE:	01-23-90	Highland, Michigan	

RFACE ELE	ATION:		TE:			
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION		PENETRATION BLOWS FOR 6
A	1		1'0"	Clayey sand, predominantly me with trace fine gravel, moist, we	dium, tan Il graded	
В	3		2'6*	Clayey sand with some clayey proderate plasticity, organic bro	peat, own black	
	4		3'0•	Silty clay, slightly moist, plastic grey and oxidized brown with in white grey lenses	, variegated regular	
С	5		EOR	Soil Clay Interface at 3'0"		
	7		EOB 6'0"			
	8					
	9					
	10					
	11					
	13					
	14					
	15					
	17					
	18					
	19					
	20					
	22					
	23]				
	25					
		1)				

S.T. - SHELBY TUBE S.S. - SPLIT SPOON REMARKS: Logged by G. DeWitt Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT:
G.W. ENCOUNTERED AT:

11

12

13

14

15

16

17

18

19

20

21

22

23

24

TYPE OF SAMPLE

S.T. - SHELBY TUBE

S.S. - SPLIT SPOON

TECHNA CORPORATION LOG OF SOIL BORING: PROJECT: Hi Mill Manufacturing Co. RI/FS LOCATION: 1704 Highland Road JOB NO.:__ Highland, Michigan 01-22-90 DATE: **SURFACE ELEVATION:** SAMPLE PENETRATION DEPTH LEGEND SOIL DESCRIPTION AND TYPE BLOWS FOR 6" Clayey sand, predominately medium, well graded, moist with wood trace fine gravel 2 3 В 3'6" Silty clay, plastic, moist, variegated - dark grey and oxidized brown with white streaks 6'0" Silty clay, brown, moderate plasticity, with thin silt streaks and irregular white-grey lenses and discolored zones Δ. EOB Soil Clay Interface at 3'5" 8,0, 10

Standard Penetration Test - Driving 2" OD Sampler 1" With

140# Hammer Failing 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS G.W. ENCOUNTERED AT: None

G.W. ENCOUNTERED AT:

REMARKS: Logged by G. DeWitt

JOB NO.: 201-8058-13

LOG OF SOIL BORING:

G3/H4

PROJECT: Hi Mill Manufacturing Co. RI/FS

LOCATION: 1704 Highland Road

IRFACE ELE	VATION: 1	009.88 DA	TE: 01-23-9	90 Highland, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND			TRATIO
A	2		2'0"	Clayey sand, tan, predominately medium, some fine grave moist to saturated, well graded	el,
В	3			Same	
C	6			Same	
D	8			Same	
E	10			Same	
F	11		11'6"	Same Sitty clay with lenses of oxidized silt, plastic, moist, varved brown	
G	13			Same	
H	16		15'6"	Soil Clay Interface at 11'6"	
	17				
	20				
	22				
	24				
	F SAMPLE ELBY TUBE			by G. DeWitt GROUND WATER OBSE Test - Driving 2" OD Sampler 1' With G.W. ENCOUNTERED AT	

LOG OF SOIL BORING: PROJECT: Hi Mill Manufacturing Co. RI/FS LOCATION: __1704 Highland Road

IOD NO .	201-8058-13
$\mathbf{M} \mathbf{M} \mathbf{M} \mathbf{M} \mathbf{M} \mathbf{M} \mathbf{M} \mathbf{M} $	20.0000 10

RFACE ELE	VATION: _	DATE	Ŀ	03-05-90 Highla	and, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION		PENETRATIO BLOWS FOR 6
			3	Frost		
	1			Brown very sand topsoil with trace	e vegetation and or	avel
	2	1		Stom very scale topoon with tract	o regelation and gi	-
		1 1				<u> </u>
	3	1				
		1				
	4	1		•		<u> </u>
	5	1 1	5'0"	Loose wet to saturated brown me	dium silty sand with	1
]		trace gravel		
	6	4				
	7		7'6"	Moist slightly plastic, medium stiff	, variegated oxidize	ed
	 	i		brown and grey silty clay with inte material with occasional thin lami	erlacing of white ch	alky
	8	1		material with occasional thin lami	na of grey silt ,	
		1 1		208		
	9	,				}
	10	1 1				
]]				
	11					<u> </u>
	12	1 1				
		1				} -
	13] }				
	14	1				
	 					
	15	i				
		i i				
	16	i i				
	17	1 1				-
] }				
	18	}				
	19	}				
		1				
	20]				
						
	21	1 1				
	22	j ,				
	23	{				
	24	1				
		j				
	25] [
'PVBR C	F SAMPLE	DEMARK	S. Lagge	by G. DeWitt	GROUND WATER O	DORDVA
	ELBY TUBE			Test - Driving 2" OD Sampler 1' With	G.W. ENCOUNTERE	
	LIT SPOON			g 30"; Count Made At 6" Intervals	G.W. ENCOUNTERE	

LOG OF SOIL BORING: Hi Mill Manufacturing Co. RI/FS PROJECT: 1704 Highland Road

IOB NO.: 201-8058-13

LOCATION: Highland, Michigan 1007 34 02-01-90

SAMPLE AND TYPE DEPTH LEGEND SOIL DESCRIPTION Brown toppsoil with vegetation 1
Brown topsolf with vegetation 1

S.T. - SHELBY TUBE S.S. - SPLIT SPOON

Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

G.W. ENCOUNTERED AT: ______ G.W. ENCOUNTERED AT:

TECHNA CORPORATION LOG OF SOIL BORING: PROJECT: Hi Mill Manufacturing Co. RI/FS LOCATION: 1704 Highland Road JOB NO .:_ Highland, Michigan 01-19-90 SURFACE ELEVATION: 1006.11 DATE:

SAMPLE ND TYPE	DEPTH LE	GEND	SOIL DESCRIPTION	PENETR BLOWS	
		5'	Black Topsoil		<u> </u>
	1				f
		1	•		
_A	2				
		2'	5" Silty clay, moist, plastic, grey, van trace vegetation	ved with	
_B	3		trace vegetation	•	
		į			ļ
					<u> </u>
	5				
		e:	I 11. Condu player post moist block	situ olov	
	6	l ³	11" Sandy, clayey peat, moist, black s grey, plastic, moist, varved with or streaks, trace vegetation, fine gra	sity ciay,	├
		1	grey, plastic, moist, valved with or	kidized wel and	<u> </u>
_ n	7	1	two seams (1") of medium sand	ver and	
			two seams (1) of mediam sand		—
	8		Soil Clay Interface at 5'11"	•	
	9				
		1	•		
	10	E	OB ·	•	
	11	10	•		
					
	12				
	13				
			•		
	14			i	
		i i			
	15				
	16				
 -				ł	
	17				
	18			i i	
		i		Ì	
	19	1		ì	
				1	
	20	1		ſ	
		1			
	21	J		ļ	
	22	j			
				ŀ	
	23				
1-1				ŀ	
	24			ŀ	
		ĺ		•	
	25	j		,	
TYPE OF	SAMPLE	REMARKS: Lo	gged by G. DeWitt	GROUND WATER OBSERVA	TION
	LBY TUBE		ration Test - Driving 2° OD Sampler 1' With	G.W. ENCOUNTERED AT: _	

S.S. - SPLIT SPOON

140# Hammer Falling 30"; Count Made At 6" Intervals

G.W. ENCOUNTERED AT:

S.S. - SPLIT SPOON

LOG OF SOIL BORING:

G.W. ENCOUNTERED AT: ___

				PROJECT: _			
IOB NO.: 20	1-8058-13			LOCATION:	1704 Hi	ghland Road	
	EVATION: _	DATE: _		03-05-90	Highlar	nd, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND	- :	SOIL DESCRIPTION	-		PENETRATION BLOWS FOR 6*
				Wet brown very loose med sand and trace silt and ve	dium sam	d fill with little c c	arse
	1			Saile and dace sill and ve	geration		
	2			Same wet to saturated			
	3]		Same saturated			
				Compa agti mata d			-
	4			Same saturated			
	5			Same saturated			
	6						
	7		7'3"	Moist very stiff to hold varie and grey silty clay with int	egated ox redacing	idized brown, b of white chalky	rown
,	8			material		or will or ally	
			9'0"	EOB			
	9						
	10			Soil Clay Interface at 7'3"			
	11						
	12]					
	13						
	14						
	15						
	16						
L	17	}		•			
	18						
	19						
	20						-
	21						
	22						<u> </u>
 	23	1					<u> </u>
]					
	24						
	25]					<u></u>
		<u> </u>					
	OF SAMPLE SHELBY TUBE			by G. DeWitt a Test - Driving 2" OD Sampler 1' '	With	GROUND WATER G.W. ENCOUNTER	ROBSERVATIONS Surface RED AT:

Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

'^B NO.:____201-8058-13

LOG OF SOIL BORING:

PROJECT:

Hi Mill Manufacturing Co. RI/FS

1704 Highland Road

Highland, Michigan

PENETRATION

JURFACE EL	E١	VATION: .=	DATE	:				
SAMPLE	_		- '			· 	PENETR	ATION
AND TYPE	ļ	DEPTII	LEGEND		SOIL DESCRIPTION		BLOWS	
	+		-		Very loose saturated brown multi-c	olors		1
	┥	1			medium sand fill with trace gravel	and little silt		
	+				and trace vegetation with veneer of	sandy clay at s	urface	ļ
	┥	2			•	, ,		<u> </u>
	┥							
	-	3						
 	+							
	+	4		4'6"	Loose very moist brown fine clayey	sand fill with tra	ce	
	\dashv				gravel			
	+	5		5'6"	Very loose, saturated, brown multi-	colored medium	sand fill	
	╡				with trace gravel and little silt and	trace vegetation	with	
	┪	6			veneer of sandy clay	•		
	+							}
	┪	7						
	┪			7'6"	Soft, slightly plastic, very moist, gra	yish brown silty	clay fill,	
 	+	8			Soft, slightly plastic, very moist, gra trace sand and gravel, some with 4	layer black org	aníc	\vdash
	╅	`			peat at bottom of drive			
	┪	9						
	7							
	7	10						
	7							
	7	11						
	寸							
	寸	12		12'4"	Same with 3" layer of moist, slightly	plastic, variegat	ted,	
	-				oxidized blue and oxidized brown cl	ay with trace silt	and	
ı 	7	13			peat at 11'0"	•		
	┪		1		Medium stiff, moist, plastic, grey sill	ty clay varved lar	mina	
	7	14	j		with thin lamina of oxidized brown, t	an and greyish	silt	
	7					- ,		
	7	15						
	7		j					
	┪	16	l					
	✝							
	寸	17	1	17'6"	Stiff wet plastic grey silty clay with v	ery thin beds of	j	
	7				grevish silty clay slightly plastic clay	ey silt and varve	ed l	
	十	18			lamina of moist greyish silt	· -	Ì	
	7		J				ŀ	
 	寸	19					ł	
	7						ł	
 	7	20					}	
	十		İ				ł	
	7	21					ŀ	
	7]				ŀ	
	寸	22	i				ŀ	
	寸						ŀ	
	7	23					j	
	7		1				Ì	
	T	24					Ì	
	7]					
	7	25					ł	
	1						ŀ	
TYPE	OI	SAMPLE	REMARK	S: Logged	by G. DeWitt	GROUND WATER	ORSERVA	PAOLL

S.T. - SHELBY TUBE S.S. - SPLIT SPOON Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT:
G.W. ENCOUNTERED AT:

PROJECT:	
1704 Highland Road	
LOCATION:	

	LOCATION:	1704 riigiliano riodo
JOB NO.:02-05-9		Highland, Michigan
	•	

SAMPLE AND TYPE	DEРTH	LEGEND		SOIL DESCRIPTION Moist clayer topsoil, brown, trace sa	1.	PENETRATIO BLOWS FOR 6
				and vegetation with a very thin BOD		
	11	4 1		oxidized brown silty clay, moist		
	2	1				-
	 	1				
	3]	3'8"	Asphalt		
]	4'0"	Medium stiff, moist, very plastic, vari	egated	
	4	- 1		ovidized brown and grey silty clay wi	th	-
<u> </u> -	5	1 1		trace vegetation, thin? of greyish si shatification	t, slight	
		1				
	6]		4		
	7					ļ
	 '	1 1				
	8]				
]				
	,	4 1				ļ
	10	1			• -	
		1		Same with thin lamina of grey sand a	and tan	
	11]	10.6.	silt 1silt layers		
	ļ	↓				
	12	{				
	13	1				
		1				
	14]				
	15	1				
		1 1		•		
	16	1				
	17	.				<u> </u>
	1,	1				
	18]				
]				
	19	{ I				ļ
	20	1 1				
		jĺ				├
	21] [
		4 1			•	<u> </u>
	22	1 1				
	23	j				
]				
	24	4			•	<u> </u>
	25	1 ·			•	
		1				
TYPEC	OF SAMPLE			ed by G. DeWitt	GROUND WATER O	BSERVATIO
S.T. · SH	ELBY TUBE	Standar	d Penetrati	on Test - Driving 2" OD Sampler 1' With	G.W. ENCOUNTERE	D AT.

S.S. - SPLIT SPOON

LOG OF SOIL BORING: 13

PROJECT: Hil	Mill Manufactu	iring C	o. RI/FS
--------------	----------------	---------	----------

JOB NO.: 201-8058-13

LOCATION: 1704 Highland Road

Highland, Michigan 02-05-90 **JURFACE ELEVATION:** DATE: SAMPLE PENETRATION LEGEND DEPTH SOIL DESCRIPTION AND TYPE BLOWS FOR 67 Moist, dark brown clayey topsoil with trace sand and gravel and vegetation Moist to saturated (wetness increases with depth), medium 2 multi-colored brown sand fill with trace gravel and silt 3 4 5 6 7'0" Loose, brown, very moist, fine clayey sand trace gravel and 7 vegetation 8 8'6" Soft, very moist, slightly plastic sandy clay fill with some silt greyish brown soft to very soft 10 11 12 13 13'2" Stiff moist plastic brownish grey silty clay with thin lamina of tan and grey silt 14 15 16 17'6" Stiff, moist, plastic, grey silty clay varved thin lamina to 17 lamina of grey clayey silt 18 Soil Clay Interface at 13'2" 19 20 21 22 23 24 25 TYPE OF SAMPLE REMARKS: Logged by G. DeWitt GROUND WATER OBSERVATIONS S.T. - SHELBY TUBE Standard Penetration Test - Driving 2" OD Sampler 1' With G.W. ENCOUNTERED AT! '6"

140# Hammer Falling 30°; Count Made At 6" Intervals

G.W. ENCOUNTERED AT:

LOG OF SOIL BORING: Hi Mill Manufacturing Co. RI/FS PROJECT:

1704 Highland Road LOCATION:

JOB NO.:__201-8058-13 Highland, Michigan 02-05-90 **RFACE ELEVATION:** DATE: SAMPLE PENETRATION DEPTH LEGEND SOIL DESCRIPTION AND TYPE BLOWS FOR 6° Molst dark brown clayey sand topsoil fill with trace gravel and vegetation 1'6" Moist medium dense multi-colored brown medium sand fill with trace silt and gravel 2 3 5'8" Moist brown sandy clay fill with trace gravel and 5 vegetation 6 8 9'8" Stiff moist plastic grey silty clay varved thin lamina to 9 lamina of tan and oxidized silt 10 11 14 15'0" EOB 15 Soil Clay Interface at 9'8" 16 17 18 19 20 21 22 23 24 25 TYPE OF SAMPLE REMARKS: Logged by G. DeWill

S.T. - SHELBY TUBE S.S. - SPLIT SPOON

Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS G.W. ENCOUNTERED AT: 13 U G.W. ENCOUNTERED AT:

LOG OF SOIL BORING:
Hi Mill Manufacturing Co. Rives
PROJECT:

IOD NO .		LOCATION:	1704 Highland Road
JOB NO.: 1007.42	DATE	01-23-90	Highland, Michigan

SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION		PENETR BLOWS	
		<u> </u>		Clayey sand, predominately mediu,	tan, t.		
- 74	i]	4101	fine gravel moist, well-graded	L		
]	1'3"	Silty clay, slightly moist, valizgated	prown		
	2] ·		with oxidized lenses, plastic			
]					
	3]	3'6"	Clause past MDDT plastic with as			
В]	30	Clayey peat, MDDT, plastic with so vegetation, organic black with 2" la	wer of		
	4			peat at 5'10"	iyer or		
]		pear at 3 10			
	5	1					
		4 1	6'0"	Silty clay, plastic, moist with seams	of silty/		
	6	4	•	fine sand, oxidized brown, thin? pre	esent		
0	ļ <u>.</u>	4 1		mio danaj dinazda di dini i pi	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
	7	4					
	8	4	8'0"	Same with streaks of saturated clay	rev sand.		
	 			medium with T fine gravel	•		
E -	9	1 1		J			
	 	1 !		Soil Clay Interface at 6'0" -			
	10	1	EOB	•			
		1 1	10'	•			
	11	1 1					
	I]					-
	12					ì	
]				ì	****
	13]				- 1	
]				1	
	14]					
		1 1					
,	15	4 1					
		4 1				, <u>,</u>	
	16	- i				-	
	 	-				- 1	
	17	1				}	
	18	-					
		1 1					
	19	1 1				ł	
	 	1				ŀ	
	20	1				ŀ	
		1				<u> </u>	
	21	1				<u> </u>	
]				Ì	_
	22]				ľ	
						ſ	
	23]				[
		1					
	24	1					
		4.			•	[
	25	4 . 1			•	ļ	
	<u> </u>						
	OF SAMPLE			ed by G. DeWitt	GROUND WATT		MO
5.1. • 31	HELBY TUBE	2 gangard	renetrati	ion Test - Driving 2" OD Sampler 1' With	G.W. ENCOUNT	EKED AT: _	

LOG OF SOIL BORING: Hi Mill Manufacturing Co. RI/FS

					PROJECT:	1704 Hi	ghland Road		
^B NO.:					LOCATION:		d, Michigan		
URFACE EL	.EVA	ATION:	1006.82 DATE:		01-22-90				
SAMPLE								PENETI	ATION
AND TYPE		DEPTH	LEGEND		SOIL DESCRIPTION			BLOWS	
	-		 	- 0"	Moist dark brown poat wit	h wood a	nd vegetatien -	1	1
^ -	_	1	1	13"	Same - clayey peat				
			1 1						
		2]	28*	Organic clay with trace fir	a aroual	and agad aloot	io	
	Ц.		1	20	Organic clay with trace in	e graver	ano sano, piasi	IC .	
	ऱ-	3		35"	Clayey sand, medium, mo	ist, trace	fine gravel with	sandv	
			1		clay seam 4'6" to 5'2"		J	··	ļ
	┝╌╂╌	4	}		•				
 6	+-	5	1						
	Η-	<u> </u>	1		A				
	- -	6	1	6'	Silty clay, moist, thin white	e and gre	y lamina		
			1						· · · · ·
- D		7							
		8		8'-10	Same - With varved silt se	eams			
E	Н-		1	• .•					
	⊢-	9	{						
	⊢┼	10	ł I	10'0"	EOB				
		10	}						
		11	1						
	\vdash								
		12	1		Soil Clay Interface at 6'0"				
]						
		13	}						
	Ц.]						
	<u> </u>	14	ļ ļ						
	⊢-	 -	}						
	├-{-	15							
	-	16	1						
			1						
		17]]						
]						
		18]]						
	⊢-								
		19	į į						
		20	1						
		20	1						
		21							
			1						
		22]]						
	\coprod								
	Щ	23]]						
	 	24	 						
	$\vdash \vdash$	24	{						
	\vdash	25							-
	- -		1						
TYPI	E OF S	AMPLE	REMARKS	Lorsed	by G. DeWitt		GROUND WATER	ORSERV	PATIONS
		BY TUBE			Test - Driving 2" OD Sampler 1"	With	G.W. ENCOUNTE	RED AT:	3.6
	r spoon			30"; Count Made At 6" Intervals		G.W. ENCOUNTES			

140# Hammer Falling 30"; Count Made At 6" Intervals

PROJECT: Hi Mill Manufacturing Co. RI/FS

1704 Highland Road

JOB NO.:_	201-8058-13		LOCATION:	1704 Highland Road	
	•	1006.62	01-22-00	Highland, Michigan	

RFACE ELE	VATION: _	1006.62 DATE:	01-22-9	0 Highlar	nd, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND		DIL DESCRIPTION		PENETRATION
A B C C	1 2 3 3 4 4 5 5 6 6 7 7 8 8 9 10 11 12 12 13 14 15 16 17 18 19 20 21 22 23 24		2° Brown sand Silty clay, m vegetation 5° Moist, clayed 11° Grey fine sa 2'0° Very clayey gravel, moid 4'0° Silty oxidize predominate Same color	iy topsoli loist, mottled grey & bri ey peat, trace vegetatio and moist sand, predominately m	own with trace find on nedium with trace stic with seams of	fine
TYPEO	25 P SAMPLE	REMARKS	Logged by G. DeWitt		GROUND WATER O	PRINTERVENIER

S.T. - SHELBY TUBE S.S. - SPLIT SPOON Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT:
G.W. ENCOUNTERED AT:

LOG OF SOIL BORING: Hi Mill Manufacturing Co. AI/FS PROJECT:

ORNO. 2	01-8058-1	3
---------	-----------	---

1704 Highland Road

LOCATION: Highland, Michigan 02-01-90 DATE: JRFACE ELEVATION: SAMPLE PENETRATION LEGEND DEPTH SOIL DESCRIPTION AND TYPE BLOWS FOR 6" Dark brown clayey topsoil with little sand, trace gravel 6" Oxidized brown, moist, silty medium sand, trace gravel ī coarse bed gravel fill 2'0" Slab of concrete 2 Clayey dark brown organic peat moist, plastic, medium stiff, sity clay fill variegated oxidized brown and blue grey 2'8" 3 with trace vegetation 5'0" Stiff, moist, plastic variegated silty clay oxidized brown 5 and grey with interlacing of white chalky material and vegetation and occasional lamina of greyish silt 6 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25

TYPE OF SAMPLE S.T. - SHELBY TUBE S.S. - SPLIT SPOON

REMARKS: Logged by G. DeWitt Standard Penetration Test - Driving 2" OD Sampler 1' With 140# liammer Falling 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS G.W. ENCOUNTERED AT: G.W. ENCOUNTERED AT:

LOG OF SOIL BORING: PROJECT: Hi Mill Manufacturing Co. RI/FS LOCATION: 1704 Highland Road

OB NO.:	201-8058-13
---------	-------------

S.S. - SPLIT SPOON

G.W. ENCOUNTERED AT:

SAMPLE						PENETRA	TIO
ND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION		BLOWS FO	
				Loose medium clayey sand		`	
	1]		oxidized brown, trace vege	tation		
			2'0"	Dark brown moist clayey po	nat		
	22	4 1	2'6"	Moiet elightly plastic mediu	sal Im etiff eilty clay fill yari:	anated -	
		4	20	Moist slightly plastic, mediu oxidized brown and organic	blue grev with trace ve	getation	
	3	-		and sand	g ,	<u> </u>	
	4	-{	3'6"	Brown and grey with trace v	egetation with Interlaci	ng of 📙	
		1		white clayey material	-	_	
	5	1	4'0"	Stiff, moist, plastic to very pl	astic, aariegated silty	clay -	
]	4101	oxidized EOB		<u> </u>	
	6		4'0"	EOB			
		4				<u>_</u>	
	7	-{		Soil Clay Interfac at 5'0"			
	8	1 1				 -	
		1				-	
	9	1 1					
]					
	10	1					
		-} I					
	11	4			•	<u> </u>	
	12	1				-	
		1					
	13	1				-	
]					
	14]					
		4 1				Ļ	
	15	-[j- -	
	16	-				<u> </u>	
		1 1				 -	
	17	1					_
]				<u> </u>	
	18]					
		4 l					
	19	- J				<u> </u>	
	20	-					
	20	 				\vdash	
	21	1 1				 	
]					
	22]					
		4 1					
	23	- I				<u> </u>	
	24	-				<u> </u>	
	24	-					
	25	† İ					
		1				 	
TVPE ()	P SAMPILE	DEMARKS		by G. DeWill	GROUND WATER	40.40.000000000000000000000000000000000	

140# Hammer Falling 30"; Count Made At 6" Intervals

S.S. - SPLIT SPOON

LOG OF SOIL BORING: PROJECT: Hi Mill Manufacturing Co. RI/FS

G.W. ENCOUNTERED AT:

JOB NO.:20	1-8058-13			LOCATIO	N:1704 H	ghland Road		
		DATE:		01-29-90		ıd, Michigan		
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRI	PTION		PENETR BLOWS	
SAMPLE	DEPTH 1 1 2 3 3 4 5 6 7 8 8 9 10 11 12 13 14 15 16 17 18 19 20 21		3' 1'3" 1'5" 1'7" 4'0" 6'0"		race asphalt, stic silty clay with trace si to very plas white chalky ry thin silt become stratifica	dark grey, whit interlaced with it tic silty clay, ox material, trace	e, tan white	
	22 23 24 25							
TVD	E OF SAMPLE	DEMADVE.	100004	by G. DeWitt		GROUND WATE	Oncent	ATIONS
	SHELBY TUBE			n Test - Driving 2" OD Sample	r 1' With	G.W. ENCOUNTE		

140# Hammer Falling 30"; Count Made At 6" Intervals

PROJECT: Hi Mill Manufacturing Co. RI/FS

1704 Highland Road

	NO.: 201-8058-13	LOCATION:	1704 Highland Road
•	110	01.20.00	Highland, Michigan

RFACE ELE	EVATION:	DATE:		01-29-90	Highland, Michigan		
SAMPLE	DEPTH	LEGEND		SOIL DESC	RIPTION		TRATIO
ND TYPE	DEFIN	LEGEND		Sandy gravel fill with	rtrace asphalt dark grey, wi	BLOW	S FOR 6
	ī		1'6"	and red gravel Moist stiff plastic silt chalky material inte	y clay oxidized brown with werlaced and with laminate thi	/hite	
- B	3	-		of tan silt stratifica	tion increases with depth	ii iaiiiiia	
	4		4'0"	EOB			
	5			Soil Clay Interface a			
	6			Repeat Drives A' and sample volume for d	d A" necessary to obtain suff chemical analyses	icient	
	7]					
	8 9						
	10						
	11						
	12						
	13						
	14						
	15						<u> </u>
	17						
	18	}					
	19						
	20						
	21						
	22						
	24						
	25	1					

S.T. - SHELBY TUBE S.S. - SPLIT SPOON

Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals G.W. ENCOUNTERED AT:

G.W. ENCOUNTERED AT:

G.W. ENCOUNTERED AT:

LOG OF SOIL BORING:

BORING:	RS23
Hi Mill Manufa	cturing Co. RI/FS

201-8058-13

PROJECT: LOCATION:

1704 Highland Road

01-29-90 Highland, Michigan SURFACE ELEVATION: ____ DATE:

SAMPLE AND TYPE	DE	PTH	LEGEND		SOIL DESCRIPTION	BLOWS	RATIO FOR 6
				3*	Asphalt, sandy gravel fill		T
		i		9"	Moist, slightly plastic, very sandy cla	ay fill very oxidized	—
					brown		
		2					
							\vdash
		3		3'0"	Very stiff, moist, plastic, silty clay, ox	kidized brown with	-
					interlaced white chalky material		-
	- 	1			·		—
		·					\vdash
	- 	5					
 	- 	' ——					
	- 	6		5'0"	EOB		\vdash
							-
	 -				Soil Clay Interface at 3'0"		-
	 '	7			our oldy monass at 5 s		<u> </u>
	 	, [*Repeat Drive A' necessary to obtai	n sufficient sample	
	 	8			volume for chemical analyses	a camolorit sample	-
					Totalio for orientical allaryses		-
		9			*Repeat Drive B' made in second bo	oring 1'0" courts of	_
					initial boring in order to collect add	itional comple volume	<u> </u>
		<u> </u>			initial boring in order to collect add for chemical analyses from soil clay	rional sample volume	
					ior chemical analyses nom son clay	/ interface depth	<u> </u>
	1	1					<u></u>
							<u></u>
	1	2					
							<u> </u>
		3					
	<u> </u>						<u></u>
	1	4					L
							L
	1	5					
							L
	1	6					
		7					
	1	8					
	1	9					
			ļ				
	2	0					
			1				
	2	:1	j				
· · · · · · · · · · · · · · · · · · ·							
	2	12	,				
	2	3					
	 		1				
	,	4					
	 						-
	i I						
	2	5					

TYPE OF SAMPLE S.T. - SHELBY TUBE S.S. - SPLIT SPOON

REMARKS: Logged by G. DeWitt Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS G.W. ENCOUNTERED AT: G.W. ENCOUNTERED AT:

LOG OF SOIL BORING:

PROJECT: Hi Mill Manufacturing Co. RI/FS

LOCATION: 1704 Highland Road

G.W. ENCOUNTERED AT: 0'6"

G.W. ENCOUNTERED AT:

NO.: 201-8058-13

S.T. - SHELBY TUBE

S.S. - SPLIT SPOON

Highland, Michigan

IRFACE ELE	VATION:	DAT	E:	Highia	nd, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION	PEN BLO	ETRATIO WS FOR 6
A	1 2		6 ° 1'0"	Asphalt sandy clay fill Soft, moist, oxidized brown silty clay of very oxidized brown sandy clay	ay fill, plastic with trac	e
В	3		3'0"	Very stiff, moist, plastic silty clay, o interlacing of white chalky materia	xidized brown with al	
C	6		6'0 °	EOB		
	7			Soil Clay Interface at 3'0"		
	8 9 10 11 12 13 14 15			*Repeat Drives A' and A' necessar sample volume for chemical analy	y to collect sufficient rses	
	18					
	20					
	23					
	24					
	25					

Standard Penetration Test - Driving 2" OD Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

PROJECT: Hi Mill Manufacturing Co. RI/FS

	004.00	50 40					1704 Highland Road		
.' NO.:_	201-80	58-13				LOCATION:	Highland, Michigan		
SURFACE		ATION: _		DATE:		01-30-90	nightano, wichigan		
SAMPLE AND TYPI		DEPTH	LEGEN	D		SOIL DESCRIPTION		BLOWS	RATION FOR 6°
A	++	1	1		6' 1'0'	Asphait wet sandy loose of Very stiff, moist, very plast	ic silty clay oxidized brov	ทา	
						interlaced with white cha	lky material with trace gra	avel	
ļ 		2	{			and vegetation (reddish t	ing		
8		3	1	1					
		4	1						<u> </u>
			1		5'0°				
		5	1		30				
	\Box	6]			Soil Clay Interface at 1'0"			
	+	7	1			*Repeated Drives A' and A	A" necessary to collect su	ufficient	
		8				sample volume for chemi	ical analyses		
			<u> </u>						
		9	}						
<u> </u>		10	1						
		11	1						
			<u> </u>						
	+	12							
	工工	13	1						
ļ	++	14	1						ļ
			1	1					
		1.5	1	}					<u> </u>
	\Box	16]						
		17	<u> </u>						
	+ $+$	18	1						
			1						
		19	1						
	工	20	1	}					
		21	1	1					
]						
		22]						
		23]						
		24	1						
	+	25	1	l					
	YPE OF S			CLAADWO		by G. DaWitt	CROUND WATER		

S.T. - SHELBY TUBE S.S. - SPLIT SPOON Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT: 0 9"
G.W. ENCOUNTERED AT: ______

S.S. - SPLIT SPOON

LOG OF SOIL BORING: ST 2

PROJECT: Hi Mill Manufacturing Co. RI/FS

NO.: 201-8058-13 LOCATION: 1704 Highland Road

Highland, Michigan

G.W. ENCOUNTERED AT:

RFACE ELE	EVATION: _	DATE: _		01-30-90	Highland, Michigan		
SAMPLE AND TYPE	DEPTII	LEGEND		SOIL DESCRIPT	LION	PENETE BLOWS	
A	2		6" 1'3"	Asphalt Wet loose, sandy grave	fill, trace gravel and brick		
В	3			Very stiff, moist, very pla- interlaced with white ch with very moist brown c	stic, silty clay oxidized brov nalky material, trace vegeta layey silt lamina	vn tion with	
С	5						
	6		6'0"	EOB			
	7			Soil Clay Interface at 1'3	3•		
	8	1 1		Repeat Drives A', A" and	A' necessary in order to o	btain	
	9	-		 sufficient sample volume 	e for chemical analyses. Si litted for chemical analyses	ample	
		1 1		(HMS-ST12-2 and HMS-	ST12-D) Drive 'A'" was coll	ected	
	10			trom a second boring loc	cated 14" south from the first	st.	
	11	1 1					
	12	1 1					
	13	{					<u> </u>
	14	}					
	15						
	16]					
	17	<u> </u>					
	18]					
	19						
	20						
	21						
	22					l	
	23						
	24						
	25	1					
TWOF	OF SAMPLE	REMARKS:	Lacrid		GROUND WATER		

140# Hammer Palling 30"; Count Made At 6" Intervals

LOG OF SOIL BORING: ST3

PROJECT: Hi Mill Manufacturing Co. RI/FS

NO.:_	201-8058-13	
110		

LOCATION: 1704 Highland Road

SURFACE ELEVATION: _____ DATE: _____ 01-30-90 Highland, Michigan

SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION	ENETRATION OF THE PROPERTY OF
A	1		6	Asphait Wet loose sandy gravel fill trace gravel	
	2			Loose moist oxidized clayey sand trace gravel mediu	m to
- B	3		3'6 '	fine with very thin beds of oxidized sandy clay and gre Silty clay	y
	4		00		
	5	=			
	6			Very stiff moist plastic silty clay oxidized brown interla with white chalky material, trace vegetation with very	ced moist
С	7			brown clayey silt lamina	
	8		8'0"	EOB	
	9			Soil Clay Interface at 3'6"	
	10			*Repeat Drives A' and A" as necessary in order to obta sufficient sample for chemical analyses	ain
	11	3			
	12				
	13				
	14				
	15				
	16				
	18				
	19				
	20	7			
	21	7			
	22				
	23				
	24	7			
	25	7			
	 - 	⊣ 1			<u> </u>

TYPE OF SAMPLE
S.T. - SHELBY TUBE
S.S. - SPLIT SPOON

REMARKS: Logged by G. DeWitt Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT:
G.W. ENCOUNTERED AT:

LOG OF SOIL BORING: ST)-4
PROJECT: Hi Mill Manufacturing Co. RI/FS

G.W. ENCOUNTERED AT: 0'11"

G.W. ENCOUNTERED AT:

NO ·	201-8058-13	
NO.:	201-0030-10	

S.T. - SHELBY TUBE

S.S. - SPLIT SPOON

LOCATION: 1704 Highland Road

Highland, Michigan 01-30-90 · · · · · DATE: SURFACE ELEVATION: SAMPLE PENETRATION DEPTH LEGEND SOIL DESCRIPTION AND TYPE BLOWS FOR 6" Asphait 1'0" Loose wet sandy gravel fill, trace gravel ī 2'0" Medium stiff, moist, plastic variegated oxidized brown 2 and grey silty clay fill, trace fill Very stiff, moist, plastic silty clay, grey, oxidized brown with 3 interlacing of white chalky material with thin lamina of brownish tan clayey silt very moist 4 5 6'6" **EOB** 6 7 Soil Clay Interface 2'3" *Drives A' and A" were necessary in order to obtain 8 sufficient sample volume for chemical analyses 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 TYPE OF SAMPLE REMARKS: Logged by G. DeWitt GROUND WATER OBSERVATIONS

Standard Penetration Test - Driving 2" OD Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

LOG OF SOIL BORING: WY01
PROJECT: Hi Mill Manufacturing Co. RI/FS

NO.:	201-8058-13	

LOCATION: 1704 Highland Road

URFACE ELE		DATE		01-31-90 Highlar	nd, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION		PENETRATION BLOWS FOR 6"
A	1 2		ъ.	Aspnair Moist very soft brown fine sandy cla gravel and silt	ay fill with trace	
В	3			Same Same wet		
С	5		4'9" 5'0" 5'8"	Wet brown sandy clayey silt with tr Very soft moist variegated organic l silty clay fill with trace peat and ve Grey clayey sand fill with trace of s	blue and oxidized getation	d brown
U	7 8		6'2"	Very stiff moist very plastic variegal and grey with trace silt and white of thin lamina of greyish tan silt and t	ted clay oxidized chalky material in	brown terlaced
E	9		9'6•	EOB		
	10			Soil Clay Interface at 6'2" Repeat Drive B' necessary in order sample volume for chemical analyses	to obtain sufficie	nt de in
	12			second boring located 15" NE of or	iginal WV01 bori	ng.
	14					
	16					
	17					
	19					
	20					
	22	·				
	24					
	DF SAMPLE ELBY TUBE			by G. DeWitt Test - Driving 2" OD Sampler 1' With	GROUND WATER	
	PLIT SPOON			g 30"; Count Made At 6" Intervals	G.W. ENCOUNTER G.W. ENCOUNTER	

LOG OF SOIL BORING:

PROJECT: Hi Mill Manufacturing Co. RI/FS

LOCATION: 1704 Highland Road

Highland, Michigan

NO.: 20	1-8058-13	-		LOCATION: _	1704 Highland Road		
		DATE			Highland, Michigan	-	
SURFACE EL	LEVATION: _	DATE	:				- • •
SAMPLE		1.707.40		4011 0000010010		PENETRATI	ON
ANDTYPE	DEPTII	LEGEND		SOIL DESCRIPTION	l e e e e e e e e e e e e e e e e e e e	BLOWS FOR	
	 	 	4*	Asphalt			
<u> </u>	1	1 (Loose, very moist, oxidized			
		1		with very thin bed of black a	sphaltic appearing ma	terial -	
A	2	1		medium sand fill			
		1	8•	Same discolored dark grey	silty sand fill	<u> </u>	
B	3	1		~ .	•		
	-	1 1				<u> </u>	
	1	1	4'2"	Organic black peat very mo	ist with gradaded conta	act 🗀	
		1		to next layer	_	<u> </u>	
- c	5	1 1	4'6"	Soft moist variegated organi	c blue and oxidized bro	own 💳	
	 	1 1		sifty clay till with trace peat	and vegetation		
	6	1	5'4"	Very moist variegated oxidize	ed brown and grey san	dy -	
	 	1		clay, slightly plastic, stiff, tra	ace vegetation	· -	
0	7	1	5'10"	Very stiff moist very plastic v	ariegated clay oxidized	ı	
		1 1		brown and grey with trace s	ilt and white chalky ma	terial	
	8	1		interlaced, thin lamina of gre	eyish tan silt and trace	 	
		1 1		vegetation			
F =	9	1	9'6"	EOB		-	
		1 1					
	10	1 }		Soil Clay Interface at 5'10"		<u> </u>	
		1)				 	
	11	1		Repeat Drive A' and A' were	necessary in order to o	btain -	
h	- 1	1		sufficient shample volume for	or chemical analyses		
	12	1 1			-	<u> </u>	
		1 1				ļ 	
	13	1				<u> </u>	
		1				<u> </u>	
	14	1					
		1					
	1.5]					_
]					
	16	1 (
		}					
	17	}					
]					
	18						
		1					
	19] }					
]					
	20]					
		İ i					
	21	}					
] .]					
	22	1					
		1					
	23	()					
		!					
	24	1					
]					
	25	1					
l							
TYP	E OF SAMPLE	REMARK	S: Logged I	by G. DeWitt	GROUND WATER	OBSERVATIO	NS
s.r.	SHELBY TUBE			Test - Driving 2" OD Sampler 1" Wi	ik G.W. ENCOUNTER		
S.S	SPLIT SPOON			30"; Count Made At 6" Intervals	G.W. ENCOUNTER		

PROJECT: Hi Mill Manufacturing Co. RI/FS

LOCATION: 1704 Highland Road

Highland, Michigan

NO.: 201-8058-13	LOCATION:	1704 F
1100		Highla

SAMPLE	DEPTH	LEGEND		SOIL DESCRIPTION	PENETI	RATIO
ND TYPE	DEFIII	LEGEND			BLOWS	FOR 6
			4*	Asphalt Concrete		
	1	4 1	8°		امد	
- 		1	0	Medium brown clayey sand very moist trace gra-	/ei	<u> </u>
	2	1				
		1				
	3	- 1				├ ─
	4	1				
		1				}
	5	1 1	5'0"	Same with trace clay very moist to wet		
		1 1				
	6]				
]	7104	Affinal and a self and a self and a self and a self a	·	
U	7] [7'0"	Moderately stiff, moist, variegated organic blue a	ind	
		1		oxidized brown silty clay fill plastic with trace pea	ii and	
	8	1 1		regeration		-
		.				-
	9	-{ }				-
E	10	1		Very stiff to hold, slightly moist, very plastic varie	gated	-
	<u>'°</u>	1 1		clay oxidized brown and grey with trace silt and	white	
	11	1 1		Very stiff to hold, slightly moist, very plastic varie clay oxidized brown and grey with trace silt and chalky material interlaced thin lamina of greyish	silt	
		1 1		and trace vegetation		
	12]	11'0"	EOB		
]]		Call Olay Interface at 7108		
	13	1		Soil Clay Interface at 7'0"		ļ
						<u> </u>
	14	1				
	15	1				
		1				├
	16	1				
		1 1				
	17] [
		1 1				
	18	4 1				
		4	•			
	19	- I				
	20	1 1				-
		1 1				
	21	1				-
	i	1				
	22]				
]				
	23	1 1				
		4				<u> </u>
	24	- I				
	25	1				-
	2.7	J 1				1

S.T. - SHELBY TUBE S.S. - SPLIT SPOON REMARKS: Logged by G. DeWitt

Standard Penetration Test - Driving 2" OD Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

G.W. ENCOUNTERED AT: 3'8'
G.W. ENCOUNTERED AT:

LOG OF SOIL BORING: XW01

PROJECT: Hi Mill Manufacturing Co. RI/FS

	TROJECT
201-8058-13	LOCATION: 1704 Highland Road

NO.: 201-8058-13 LOCATION: 1704 Highland Hoad

SURFACE ELEVATION: 01-31-90 Highland, Michigan

SAMPLE AND TYPE DEPTII LEGEND SOIL DESCRIPTION PENETR, ILLOWS I 4* Asphalt 2'0* Loose moist brown clayey medium sand with trace gravel and vegetation (coarse base fill sand) Same. Wet at end of drive Same. Clayey sand with trace silt and some gravel. Wet at end of drive. Same. Clayey sand with trace silt and some gravel. Wet at end of drive. 7'0* Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of grey/sh tan silt and trace vegetation Same 11'0* EOB Soil Clay Interface at 7'0* *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 11'0* Is 11'0* Is 12'0* Loose moist brown clayey medium sand with trace gravel and very plastic variegated lavel. Wet at end of drive. Same. Clayey sand with trace silt and some gravel. Wet at end of drive. Same of the same of	RFACE ELE	EVATION: _	DATE	:	01-31-90 riiginand, Michigan	
A 1 2 2 3		DEPTH	LEGEND		SOUTONSKER PLICAL	
A 1 2 2 2 2 2 2 2 2 2		T		4"	Asphalt	T
2'0' Loose moist brown clayey medium sand with trace gravel and vegetation (coarse base fill sand) Same. Wet at end of drive Same. Clayey sand with trace silt and some gravel. Wet at end of drive. Same. Clayey sand with trace silt and some gravel. Wet at end of drive. 7'0' Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 110 120 Soil Clay Interface at 7'0' *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 111 115 116 117 118 119 20 21	A	1 1	1		F	
and vegetation (coarse base fill sand) Same. Wet at end of drive Same. Clayey sand with trace silt and some gravel. Wet at end of drive. Same. Clayey sand with trace silt and some gravel. Wet at end of drive. 7'0" Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 11'0" 15 16 17 18 19 20 21		 	1			
and vegetation (coarse base fill sand) Same. Wet at end of drive Same. Clayey sand with trace silt and some gravel. Wet at end of drive. Same. Clayey sand with trace silt and some gravel. Wet at end of drive. 7'0" Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 11'0" 12'0" 13'0" 14'0" 15'0" 16'0" 17'0" 18'0" 19'0" 20'0" 21'0"		 	1	2'0"	Loose moist brown clavey medium sand with trace gravel	—
Same. Clayer sand with trace silt and some gravel. Wet at end of drive. 7'0" Same moist to wet grey clayer sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 15 16 17 18 19 20 21		 	1		and variation (coarse base fill sand)	
Same. Clayer sand with trace silt and some gravel. Wet at end of drive. 7'0" Same moist to wet grey clayer sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 15 16 17 18 19 20 21	 		{		Same Wet at end of drive	
Same. Clayey sand with trace silt and some gravel. Wet at end of drive. 7'0" Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 11'0" IS			{		Carrie. Wet at one of anye	
Same. Clayey sand with trace silt and some gravel. Wet at end of drive. 7'0" Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses		+	1			
end of drive. 7'0" Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11 11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 16 17 18 19 20 21		 	{			
end of drive. 7'0" Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11 110" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 16 17 18 19 20 21			} }		Same Clavey sand with trace silt and some gravel. Mot s	
7'0' Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11'0' EOB 12' Soil Clay Interface at 7'0' *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 19 20 21			1		and of drive	" -
7'0' Same moist to wet grey clayey sand fill fine with trace silt Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11'0' EOB Soil Clay Interface at 7'0' *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 11 15 16 17 18 20 21			}		cità or alive.	
Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 110 Same 111 110° EOB Soil Clay Interface at 7'0° *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 115 116 117 118 119 20 21			{			-
Very still moist very plastic variegated clay oxidized brown and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 110 Same 111 110* EOB Soil Clay Interface at 7'0* *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 19 20 21			1	7'0"	Compared to the supt many blacks and fill flow to the superior the	
and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11		 '	{	70"	Same moist to wet grey clayey sand till tine with trace silt	
and grey with trace silt and white chalky material interlaced thin lamina of greyish tan silt and trace vegetation Same 11		 	.		Many still seeds were already were already to the seed of the	
thin lamina of greyish tan silt and trace vegetation Same 110 Same 111 112 Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 19 20 21		8	1		very still moist very plastic variegated clay oxidized brown	<u></u>
Same 11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 19 20 21		↓	 		and grey with trace silt and white chalky material interlace	d
11'0' EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 20 21		9	1		thin lamina of greyish tan silt and trace vegetation	<u> </u>
11'0" EOB Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 20 21			}			<u> </u>
Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 20 21	E	10	į l		Same	<u> </u>
Soil Clay Interface at 7'0" *Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 20 21		<u> </u>	}			<u> </u>
*Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 20 21		11	1	11′0"	EOB	
*Repeat Drive A' was necessary in order to obtain sufficient sample volume for chemical analyses 14 15 16 17 18 20 21		 	1 1			ļ
14 15 16 17 18 19 20 21		12	1		Soil Clay Interface at 7'0"	
14 15 16 17 18 19 20 21		- 	1		4m - 1m - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	L
15 16 17 18 20 21		13	!		*Repeat Drive A' was necessary in order to obtain sufficien	t
15 16 17 18 19 20		 	1 1		sample volume for chemical analyses	
16 17 18 19 20		14				
16 17 18 19 20			1 1			
18 19 20		15	1			
18 19 20		.[1 1			
18 19 20		16]			
18 19 20 21] [
20		17]			
20			1			
20		18]			
20]			
20		19]			
21		T	1			
21		20	1			
		 	1		·	
		21	1			
22			1			
		22	y .			
		T	i I			
23		23	1 1			
		 	1			
1 24		7.1	1			
		+ -	!			
		75	{			
			<u> </u>			
TYPE OF SAMPLE REMARKS: Logged by G. DeWitt GROUND WATER ORSER VA						

TYPE OF SAMPLE
S.T. - SHELBY TUBE
S.S. - SPLIT SPOON

REMARKS: Logged by G. DeWitt Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals GROUND WATER OBSERVATIONS
G.W. ENCOUNTERED AT: 4'0"
G.W. ENCOUNTERED AT:

S.S. - SPLIT SPOON

PROJECT: Hi Mill Manufacturing Co. RI/FS

LOCATION: 1704 Highland Road

G.W. ENCOUNTERED AT:

NO.: 201	-8058-13			LOCATION:	704 righland Hoad	
	EVATION: _	DATE:		01-31-90	lighland, Michigan	
SAMPLE AND TYPE	DEPTH	LEGEND	· · · · · · · · · · · · · · · · · · ·	SOIL DESCRIPTION	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PENETRATION BLOWS FOR 6*
			2" 4"	Asphalt Concrete		
^	1]	4" 6"	Void		
}	2	1	•	Grey cemented silt and grey	silty clay fill slightly p	lastic.
	 -	1		very moist and medium brow	n sand trace gravel	
8-1	3	1 1				
]		Alternating thin beds of fine of	clay fill and medium sa	and
	4	1		described above continues t continued to near surface	o 6 6° with grey cemei	ited slit
	5	1 1		CONTRICOCO TO TICAL SUITACE		ļ
 	 					
	6	1	6'6"	Very stiff moist very plastic va	ariegated clay oxidized	d brown
]		and grey with trace silt and	white chalky material in	nterlaced
	7			thin lamina of greyish tan sil	t and trace vegetation	
, 	8	1				
 		1 1				ļ
	9	1				
E]	10'6"	ЕОВ		
	10	4 1	100	EOB		
	11	1 1		Soil Clay Interface at 6'6"		
	 	1		•		
	12	1 1				
	13					
	13	1 1				ļ
	14	 				
		1 1				
	15]				
	16	1				
	16	1				ļ
·	17	1 1				
Y]				
	18	4 1				
	19	1				
	 	1 1				
	20]				
	 	[
	21	1				
	22	1				
		1				
L	23	. l				
	24	. J				
		1				
	25	j				
		<u> </u>				
	OF SAMPLE			by G. DeWitt	GROUND WATE	R OBSERVATIONS
S.T S1	HELBY TUBE	Standard P	enetration	Test - Driving 2" OD Sampler 1' Wil	h G.W. ENCOUNTE	RED AT: 3'6"

140# Hammer Palling 30"; Count Made At 6" Intervals

LOG OF SOIL BORING:

PROJECT:

Hi Mill Manufacturing Co. RI/FS

LOCATION:

1704 Highland Road

201-8058-13 Highland, Michigan 01-30-90 DATE: SURFACE ELEVATION:

SAMPLE AND TYPE	DEPTH	LEGEND		SOIL DESCRIPTION PENET BLOWS	
		 	-4*	Asphalt	T
			1'0 "		
	1]	10	Medium sand very moist oxidized brown with trace gravel	i
		7		and clay fine clayey sand oxidized brown with trace gravel,	
- A - 		i !		moist, medium dense	
	2	1	-1		L
		1 i	2'0"	Medium dense, very moist, very dark - appears discolored,	
		1		fine	
	3	1			
		1			
	4	i i	4'2"	Organic peat, very moist	
		1 1		Coft moist verice and evidence become	
		1	4'6"	Soft, moist variegated organic blue and oxidized brown	
 	5	1 1		and grey, medium stiff slightly plastic	
		4 I	5'6'	Sandy clay, very moist, variegated oxidized brown and	Ъ—
		l i	30	oalloy ciay, very moist, variegated oxidized brown and	1
	6	1 1		grey, medium stiff slightly plastic	$\overline{}$
		4 1	6'6"	Silty clay, very stiff, moist, very plastic variegated	
		j !	0.0	and the address and an include the phastic valleyated	L
0	7	7		oxidized brown and grey with trace silt and white chalky	
	<u>'</u>	4 1		material interlaced thin lamina of greyish tan silt and	
]			L
	8] [trace vegetation	
		{		₹	—
		. I			L
E	9				
		1 !			
		4 1	10'0		
1 1	10		10'0"	• u • u • u • u • u • u • u • u • u • u	1
		1		Soil Clay Interface at 6'6"	
		4 !		,	
1 1	11	j l			1
		7 I		*Repeat Drive A' was necessary in order to obtain	
		į l		sufficient sample volume for chemical analyses	<u></u>
	12]		summent sample volume for chemical analyses	1
		7)		**A second boring 17" NE from the first ZY01 boring was	
		1		made in order to collect additional sample from 2'0"-2'6"	
	13_	j l			
		1		for chemical analyses	
		1			
	14	1 1			
]]		} J			
	15	1 1			
	13	-			
]			
	16				
		1 1			\vdash
		<u> </u>			L
	17	[1			
		1 1			-
		4 l			<u> </u>
[]	18	j i			1
		1			
		↓			
1 1	19	1 1			1
		1 1			-
		ł l			
	20	1			1
] I			
		4 I			
	21]]			L
		1 I			
		1 1			
	22	j '			L
]			
	23	1 I			-
	23]			
		1 1			
		1 I			
	24	, l			L
		i l			
	~	1 1			├
	25	į			

S.T. - SHELBY TUBE S.S. - SPLIT SPOON

Standard Penetration Test - Driving 2" OD Sampler 1' With

140# Hammer Falling 30"; Count Made At 6" Intervals

G.W. ENCOUNTERED AT: 8'0"

G.W. ENCOUNTERED AT:

ZY12 LOG OF SOIL BORING:

				PROJECT: Hi Mill Manufacturing Co	」 . RI/FS
NO.: 201،	-8058-13			LOCATION: 1704 Highland Road	
			I liable and Adabian		
SURFACE ELE	DATE:		01-31-90 Highland, Michigan		
SAMPLE AND TYPE	DEPTII	LEGEND		SOIL DESCRIPTION	PENETRATION BLOWS FOR 6"
			2"	Asphalt	
	1		6 " 8"	Concrete Asphalt	
- A	2		O	Medium dense, medium to fine brown clayey sand	verv
	 			moist to wet, trace gravel, some oxidation (base co	oarse
В	3			gravel)	
			3'8"	Same	
С	4				
<u> </u>	5			Soft very moist variegated organic blue and oxidize	ad brown
 	 			silty clay fill, slightly plastic to plastic with trace pe	at and
D	6			vegetation	
				Same	
	7		6'11"	Grey sandy clay fill with trace silt, very moist, sligh	tly plastic
'				Hard, slightly moist very plastic, variegated clay, n	
	•			brown (with trace oxidation) and grey with trace of	silt and
	9			trace of white chalky material interlaced with thin I	amina of
				greyish tan silt and vegetation	
	10				
			1110	EOP	<u> </u>
	11		11'0"	EOB	
L	12			Soil Clay Interface at 7'0"	<u> </u>
	13				
	↓				
	14				
	15				
	1				
	16				
L	ļ				
	17				— —
/	18				
	1				
	19				
		1			
ļ	20				
	21				ļ
 					
	22				
	23	ĺ			
	24	 			
	 	1			
					L

TYPE OF SAMPLE S.T. - SHELBY TUBE S.S. - SPLIT SPOON

REMARKS: Logged by G. DeWitt Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30"; Count Made At 6" Intervals

GROUND WATER OBSERVATIONS G.W. ENCOUNTERED AT: 8'0" G.W. ENCOUNTERED AT:

APPENDIX G

PHYSICAL SOIL CHARACTERISTIC AND SLUG TEST ANALYSIS RESULTS

PERMEABILITY SUMMARY

<u>Sample</u>

IW-4AD

SW-10C

SW-15A

SW-15C

IW-1C

IW-5A

IW-5C

DW-1P

DW-1Q

DW-1T

DW-2K (upper)

* DW-2K (lower)

DW-3C

DW - 3D

DW-3F

<u>Permeability</u>

 $1.4 \times 10^{-6} \text{ cm/sec}$

 $1.05 \times 10^{-7} \text{ cm/sec}$

 $4.95 \times 10^{-7} \text{ cm/sec}$

 $7.46 \times 10^{-8} \text{ cm/sec}$

 $1.14 \times 15^{-2} \text{ cm/sec}$

 $1.39 \times 10^{-7} \text{ cm/sec}$

 $6.98 \times 10^{-3} \text{ cm/sec}$

 $2.41 \times 10^{-5} \text{ cm/sec}$

 $3.63 \times 10^{-6} \text{ cm/sec}$

 $8.12 \times 10^{-6} \text{ cm/sec}$

 $8.24 \times 10^{-3} \text{ cm/sec}$

 $1.12 \times 10^{-3} \text{ cm/sec}$

 $1.44 \times 10^{-2} \text{ cm/sec}$

 $1.96 \times 10^{-3} \text{ cm/sec}$

 $1.67 \times 10^{-7} \text{ cm/sec}$

* DUPLICATE

ATTERBERG LIMITS RESULTS

SAMPLE	LIQUID LIMIT	PLASTIC LIMIT	PLASTICITY INDEX
DW-2GD	25.5	16.0	9.5
IW-4A	36.7	18.9	17.8
SW-7D	32.6	18.2	14.4
IW-4AD	42.9	20.8	22.1
DW-2A	36.9	20.1	19.5
IW-5A	31.1	16.5	14.6
SW-22A	32.2	17.8	14.4
SW-10C	36.0	25.5	10.5

SIEVE ANALYSIS

_	ORING UMBER		SAMPLE	% PASSING #40 SIEVE	% PASSING #60 SIEVE	<pre>% PASSING #100 SIEVE</pre>	% PASSING E #200 SIEVE
D	W -2		E	26.3	15.2	9.0	6.4
D	W-2		K	29.8	10.4	8.3	7.3
S	W-10		С	96.6	94.6	92.6	91.4
	W-15		Α	97.4	96.7	96.0	95.7
S	W-15		С	88.1	84.5	82.3	97.6
I	W-1		С	44.1	39.2	35.9	33.0
	W-5		λ	93.7	92.4	91.4	90.3
I	W- 5		С	17.9	7.0	2.9	1.8
D	W-1		P	99.7	98.9	92.9	59.7
D	W-1		Q	98.5	97.1	93.1	72.7
D	W-1		T	45.8	33.9	24.6	20.5
* D	W-2	K	(UPPER)	22.1	7.3	5.7	5.0
D	W-2	L	(LOWER)	31.4	16.1	12.3	10.3
D	W-3		С	99.0	98.9	98.7	98.5
D	W-3		D	86.4	75.6	67.3	62.6
D	W-3		F	69.1	53.9	44.8	40.4

^{*} DUPLICATE

MOISTURE SUMMARY

SAMPLE DEP	TH IN FEET	% MOISTURE
SW-7D	15	27
SW-10C TOP	6	22
SW-22A BOTTOM	3	15
IW-1C TOP	46	24
IW-4D	41	31
IW-4D DUPLICATE	41	31
IW-4G	47	22
IW-5D TOP	41	15
DW-2E	57	12
DW-2G	66	15
DW-2K	86	15

In-Situ Slug Test Parameters & Results

Well Number	Effective Screen Depth (Feet)	Well Penetration Depth (Feet)	Aquifer Thickness (Feet)	Conductivity (CM/SEC)	Transmissivity (CM*CM/SEC)
SW-4	NA	NA	NA	<.153E-04	<.234E-02
SW-8	5.0	5.0	5.0	.153E-04	.234E-02
SW-9A	0.5	1.5	1.5	.225E-02	.103E+00
SW-9A-D	0.5	1.5	1.5	.207E-02	.946E-01
SW-11	1.0	1.0	1.0	.373E-04	.114E-02
SW-15	5.0	5.0	5.0	.877E-04	.134E-01
SW-17	3.5	3.5	10.5	.946E-03	.303E+00
IW-1	5.0	5.0	23.0	.565E-03	.396E+00
IW-1-D	5.0	5.0	23.0	.686E-03	.481E+00
IW-2	5.0	13.5	26.0	.109E-01	.860E+01
IW-3	5.0	7.5	23.0	.469E-02	.328E+01
IW-4	5.0	6.5	23.0	.361E-02	.253E+01
IW-5	5.0	6.5	22.0	.947E-02	.635E+01
DW-1	5.0	15.0	16.0	.564E-03	.275E+00
DW-1-D	5.0	15.0	16.0	.569E-03	.278E+00
DW-2	5.0	4.5	5.0	.220E-02	.336E+00
DW-3	3.0	5.0	5.0	.104E-03	.158E-01

APPENDIX H

10.3

SUMMARY OF SHORT LIST METAL ANALYSIS RESULTS - SOILS

APPENDIX I

SUMMARY OF TAL INORGANIC ANALYSIS RESULTS - SOILS

SOILS: TALINOS DATABASE

	,							(
AMPLE 10 45-061-0	ALUMINUM 11100.00 *	ANTIMONY 15.00 UN	ARSENIC 3.20	BARIUM 61.40 B	BERYLLIUM 0.47 B	CADMIUM 0.63 U	4050.00 E*	CHROMIUM 18.80
	COPPER	1 RON	LEAD 23.80	MAGNESIUM	MAGNANESE	·	NICKEL	
		5001108 339.00 U	1645110M 1.30 U	VANADIUM 24.10	Z1NC 34.90	CYANIUE 0.78 U		. (
AMPLE 10 MS-0G2-0	ALUMINUM 9370.00 *	ANTIMONY	ARSENIC 3.20 BW	BARIUM 60.90 8	BERYLLIUM 0.36 B	CADM1UM 1.40 B	CALCIUM 1460.00 88*	CHROM1UM .
	10.90 EN*	15100.00 E	33.40 S	2500.00	502.00	0.14 U	NICKEL 11.40 B	POTASSIUM 525.00 (
	SILVER 3.20 UN	SODIUM 381.00 U	THALLIUM 1.40 U	VANADIUM 23.90	ZINC 41.30	CYANIDE 0.88 U	·	(
AMPLE 10	ALUMINUM 6980.00 *	ANTIMONY 14.90 UN	ARSENIC 3.20	BARIUM 30.30 B	BERYLLIUM 0.29 B	CADMIUM 0.80 B	CALCIUM 744.00 BE*	CHROMJUM (
	COPPER 8.00 EN*	1RON 10300.00 E	LEAD 19.30	MAGNESIUM 1610.00	MAGNANESE 223.00	MERCURY 0.13 U	NICKEL 11.00 B	POTASSIUM (
	SILVER 2.60 UN	SODIUM 316.00 U	THALLIUM 1.20 U	MUIDANAV Gf. 3f	Z INC 33.30	CYANIDE 0.73 U		•
SAMPLE ID	ALUMINUM 9770.00 *	YNÖMITNA NU 0E.41	ARSENIC 3.40	BAR1UM 48.70 B	BERYLLIUM 0.35 B	CADMIUM 1.30 B	CALCIUM 8580.00 E*	CHROMIUM 18.CD
			17.50 S		MAGNANESE 521.00		NICKEL 12.50	POTASSIUM 00.878
			THALLIUM 1.10 U		Z1NC 55.50	CYANIDE 0.70 U		
SAMPLE 1D HMS-C4-0	ALUMINUM 8950.00 *	ANTIMONY 15.50 UN	ARSENIC 3.30	BAR1UM 52.90 B	BERYLLIUM 0.34 B		CALC1UM 1920.00 E*	CHROMIUM 14.30
	COPPER 11.20 EN*	1RON 13100.00 E	LEAD 21.10	MAGNES1UM 2090.00	MAGNANESE 442.00	MERCURY 0.15 U	NICKEL 8.50 B	PO1A551UM 778.00
	SILVER 2.90 UN	SOD1UM 352.00 U	THALLIUM 1.30 U	VANADIUM 20.90	Z INC 44.50	CYANIDE 0.81 U		
SAMPLE 10 HMS-E5-0		ANTIMONY 17.20 UN	ARSENIC 3.90 S	BAR1UM 60.20 B	BERYLLIUM 0.44 B	CADMIUM 1,40 B	CALCJUM 3170.00 E*	CHROMIUM 16.50
	COPPER 10.80 EN*	1RON 14800.00 E	LE (9.20	MAGNESIUM 2820.00	MAGNANESE 41570	MERCURY 0.15 U	NICKEL 13.80	PUTASSIUM 943.00
			9	WANA DEBM	7 INC	CYANIDE		i

SOILS: TALINOS DATABASE

SAMPLE 1D HMS-G3/H4-2	ALUMINUM 66.10 *	ANTIMONY 11.80 UN	ARSENIC 5.00				54900.00 E*	CHROMIUM 118.00
	COPPER 222.00 en*	1RON 10800.00 E	LEAD 7.10		MAGNANESE 370.00	MERCURY 0.09 U	NICKEL 12.90	POTASSIUM 723.00
	SILVER 2.10 UN	5001UM 250.00 U	THALLIUM 0.92	VANADIUM 16.10	ZINC 73.10	CYANIDE 0.58 U	2	
	ALUMINUM 2930.00 *	ANTIMONY 12.00 UN	ARSENIC 4.20	BARIUM 10.00 B		CADMIUM 0.52 B	CALCIUM	CHROM1UM 8.70
	COPPER 12.70 EN*	1RON 7520.00 E	LEAD 4.40	MAGNESIUM 14900.00	MAGNANESE 345.00	MERCURY 0.08 U		POTASSIUM 286.00
		50D1UM 255.00 U	THALLIUM 0.94 U		Z1NC 25.80	CYANIDE 0.59 U	•	
SAMPLE 1D HMS-G4-2D	ALUMINUM 2850.00 *	ANTIMONY 13.40 BN		BARIUM 9.90 U	BERYLLIUM 0.24 U	CADMIUM 0.66 B	CALC1UM 88500.00 E*	
	COPPER 0.00 EN*	1RON 6500.00 E	LEAD 8.00	MAGNES1UM 15200.00	MAGNANESE 222.00		NICKEL 9.00 B	
	SILVER 2.10 UN	SODIUM 255.00 U	THALLIUM 0.94 U	VANADIUM 10.20 B	ZINC 23.90	CYANIDE 0.59 U		
SAMPLE ID HMS-G7-0	ALUM1NUM 12100.00 *	ANTIMONY 128.00 UN	ARSENIC 14.00 B	8ARIUM 105.00 U			CALCIUM 10700.00 BE*	
·	COPPER 1480.00 EN*		LEAD 50.00	MAGNESIUM 2270.00 B		MERCURY 0.86 U	NICKEL 27.50 U	
	SILVER 22.50 UN	50D1UM 2710.00 U	THALLIUM 10.00 U	VANADIUM 20.00 U	ZINC 554.00	CYANIDE 6.30 U		
SAMPLE 1D HMS-H3/14-2	ALUMINUM 10800.00	ANT1MONY 12.40 U	ARSENIC 4.20	52.10	0.27 8	CADMIUM 1.10 B	MUIDIAD 30900.00	CHROM1UM 89.50
		1 RON 13700.00	LEAD 15.40	MAGNES1UM 9640.00	MAGNANESE 255.00		NICKEL 15.20	POTASSIUM 1090.00
	SILVER 2.20 U	5001UM 349.00 B	THALLIUM 0.97 U	VANADIUM 23.30	Z INC 84.50	CYANIDE 0.51 U		
SAMPLE 10 HMS-14-2	ALUMINUM 11700.00 *		ARSENIC 5.20 S	62.50	BERYLLIUM 0.46 B	CADM1UM 0.50 U	CALCIUM 28100.00 E*	CHROM1UM 30.70
	COPPER 196.00 EN*	1RCN 17400.00 E	LEAD 22.50 +	MAGNESIUM 10900.00	MAGNANESE 225.00	MERCURY 0.12 U	NICKEL 22.00	POTASSIUM 00.668
	SILVER	50D1UM	THALLIUM	VANADIUM	7 1NC	CYANIDE		· •

ge No. :/30/90

SOILS: TALINOS DATABASÉ

MPLE 10 45-14-0	ALUMINUM 25200.00	ANTIMONY 16.30 U	ARSENIC 2.40 B	BAR1UM 202.00	BERYLLIUM 0.95 B	CADM1UM 2.40	CALCIUM 8240.00	CHROMIUM 49.00
	COPPER 182.00	1 RON 25500.00	LEAD 17.80	MAGNES1UM 7200.00	MAGNANESE 190.00	MERCURY 0.14 U	N1CKEL 29.70	POTASS1UM 1660.00
	51LVER 2.90 U	50DIUM 453.00 B	THALLIUM 1.30 U	MUIDANAV 39.40	Z INC 81.10	CYANIDE 0.80 U		•
AMPLE ID 15-YX12-2	ALUMINUM 18300.00 *		ARSENIC 2.30 B	BARIUM 144.00	BERYLLIUM 0.85 B	CADMIUM 1.30	CALCIUM ! 21900.00 E*	CHROMĴUM 38.90
	COPPER 135.00 EN#	1RON 18500.00 E	LEAD 14.20	MAGNESIUM 10100.00	MAGNANESE 145.00	MERCURY 0.13 U	N1CKEL 23.60	POTASSIUM 856.00
			THALLIUM 1.00 U		Z 1 N C 46.90	CYANIDE 0.64 U		;
	•	•	· · · · · · · · · · · · · · · · · · ·			ing the province of the provin		
			* ***		21 P	in the second of		
		•	e e e e e e e e e e e e e e e e e e e		表1。3 31 152 27 <u>是</u> 32			
				#** •	213e 11 7 - 7 773		12 to 1 to 1	
		: • •	3 7 2					
			: .		* · · ·			
		* *						•

APPENDIX J

SUMMARY OF TCL VOLATILE ORGANIC ANALYSIS RESULTS (SPECIES DETECTED) - GROUNDWATER

VOAGW DATABASE

ENCOTECNO	SAMPLEID	COMPOUND	CAS	AMOUNT	FLAG
149374	HMS-DW01	Methylene chloride	75-09-2	0.014	8
:49374	HMS-DW01	2-Butanone	78-93-3	0.007	J
249374	HMS-DW01	Acetone	67-64-1	0.022	8
49306	HMW-DW02	Toluene	108-88-3	0.001	JB
49306	HMW-DW02	Methylene chloride	75-09-2	0.045	В
:49306	HMW-DW02	Acetone	67-64-1	0.016	В
149310	HMW-DW02-FB	Methylene chloride	75-09-2	0.005	В
49310	HMW-DW02-FB	Acetone	67-64-1	0.029	8
E49308	HMW-DW02-MS	Acetone	67-64-1	0.024	8
E49308	HMW-DWD2-MS	Methylene chloride	75-09-2	0.004	JB
E49701	HMW-DWO3 AND MATRIX	Methylene chloride	75-09-2	0.007	
	HMW-IWD1	Methylene chloride	75-09-2	0.002	JB
E49233	HMW-IWO1	Toluene	108-88-3	0.003	JB
E49233	******	Methylene chloride	75-09-2	0.008	••
E49697	HMW-1W02	- · · · · · · · · · · · · · · · · · · ·	67-64-1	0.018	. В
E49309	HMW-IW03	Acetone Methylene chloride	75-09-2	0.010	8
E49309	HMW-IWO3	•	57-64-1	0.003	JB
E49227	HMW-1W04	Acetone	78-93-3	0.005	JB
149227	HMW-IW04	2-Butanone		0.008	В
149227	HMW-IW04	Methylene chloride	75-09-2		
49705	HMW-1W05	Methylene chloride	75-09-2	0.017	
E49167	HMW-SW01	Trichloroethene	79-01-6	1.100	_
E49167	HMW-SW01	Methylene chloride	75-09-2	0.100	8
E49167	HMW-SW01	1,2-Dichlorosthene (Total)	540-59-0	0.350	
E49167	HMW-SW01	2-Butanone	78-93-3	0.090	7B
E49167	HMW-SW01	Acetone	67-64-1	0.160	8
49168	HMW-SW02	Methylene chloride	75-09-2	0.010	В
E49165	HMW-SW03	Vinyl chloride	75-01-4	0.068	_
E49165	HMW-SW03	Acetone	67-64-1	0.046	8
E49165	HMW-SW03	2-Butanone	78-93-3	0.018	78
E49165	HMW-SW03	Trichloroethene	79-01-5	0.014	_
E49165	HMW-SW03	Methylene chloride	75-09-2	0.026	В
E49165	HMW-SW03	1,2-Dichlorosthens (Total)	540-59-0	0.180	_
E49131	HMW-SW04	2-Butanone	78-93-3	0.015	8
E49131	HMW-SW04	Toluene	108-88-3	0.003	J
E49131	HMW-SW04	Methylene chloride	75-09-2	0.004	JB
E49132	HMW-SW05	Vinyl chloride	75-01-4	0.004	J
E 49 132	HMW-SW05	Methylene chloride	75-09-2	0.009	В
£49132	HMW-SW05	1,2-Dichloroethene (Total)	540-59-D	0.075	
E49132	HMW-SW05	Acetone	67-64-1	0.027	8
249133	HMW-SW05-D	1,2-Dichloroethene (Total)	540-59-0	0.068	
E49133	HMW-SW05-D	Methylene chloride	75-09-2	0.009	В
E49133	HMW-SW05-D	Vinyl chloride	75-01-4	0.003	J
£49133	HMW-SW05-D	2-Butanone	78-93-3	0.028	В
249133	HMW-SW05-D	Acetone	67-64-1	0.033	8
E49134	HMW-SWD6	Methylene chloride	75-09-2	0.009	В
E49134	HMW-SW06	Acetone	67-64-1	0.006	JB
49134	HMW-SW06	2-Butanone	78-93-3	0.001	JB
£49135	HMW-SWD6-FB	Acetone	67-64-1	0.017	В
E49135	HMW-SW06-FB	Methylene chiloride	75-09-2	0.009	В
E49135	HMW-SW06-FB	2-Butanone	78-93-3	0.004	JB
49135	HMW-SWOB	Methylene chloride	75-09-2	0.007	8
E49228	HMW-SW10	Methylene chloride	75-09-2	0.006	В
E49228	HMW-SW10	1,2-Dichloroethene (Total)	540-59-0	0.030	-
E49228	HMW-SW10	2-Butanone	78-93-3	0.004	JB
E49228	HMW-SW10	Acetone	67-64-1	0.004	JB
E49229	HMW-SW10-D	Methylene chloric		0.002	
E49229	HMW-SW10-D		75-09-2	0.	8 8
E-3663	UMM-2M10-D	Acetone	F7-64-1	U.₩.3	0

<i>.</i> *	ENCOTECNO	SAMPLEID	COMPOUND	CAS	AMOUNT	FLAG
-)	E49.)	HMW-SW10-D	1,2-Dichloros ene (Total)	540-59-0	0.035	
7	E49230	HMW-SW10-MS	Methylene chloride	75-09-2	0.002	JB
	E49230	HMW-SW10-MS	Toluene	108-88-3	0.002 、	JB
)	E49230	HMW-SW10-MS	1,2-Dichloroethene (Total)	540-59-0	0.029	
,	E49230	HMW-SW10-MS	Acetone	67-64-1	0.006	JB
	E49049	HMW-SW11	Toluene	108-88-3	0.003	JB
)	E49049	HMW-SW11	Methylene chloride	75-09-2	0.005 E	В
•	E49232	HMW-SW12	Toluene	108-88-3	0.003	1B
	E49232	HMW-SW12	2-Butanone	78-93-3	0.006	JB
)	E49232	HMW-SW12	Methylene chloride	75-09-2	0.002	JB
,	E49232	HMW-SW12	Acetone	67-64-1	0.013 E	В
	E49048	HMW-SW20	Methylene chloride	75-09-2	0.00	В
5	E49048	HMW-SW20	Acetone	67-64-1		В
-1	E49048	HMW-SW20	2-Butanone	78-93-3		В
	E49048	HMW-SW20	Toluene	108-88-3		JB
)	E49706	HMW-SW22	Methylene chloride	75-09-2	0.020	
,	E49707	HMW-SW22-D	Methylene chloride	75-09-2	0.023	
	E49708	HMW-SW22-FB	Methylene chloride	75-09-2	0.029	
)	E49708	HMW-SW22-FB	Acetone	67-64-1		J
J	E49050	HMW-TB-03/15/90	Methylene chloride	75-09-2		В
	E49050	HMW-TB-03/15/90	Toluene	108-88-3		JB
)	E49050	HMW-TB-03/15/90	2-Butanone	78-93-3		JB
,	E49139	HMW-TB-03/16/90	Toluene	108-88-3		 J
	E49139	HMW-TB-03/16/90	Acetone	67-64-1		В
)	E49139,	HMW-TB-03/16/90	2-Butanone	78-93-3		JB
,	E49139	HMW-TB-03/16/90	Methylene chloride	75-09-2		B
	E49171	HMW-T8-03/19/90	2-Butanone	78-93-3		78
)	E49171	HMW-TB-03/19/90	Acetone	67-64-1		8
,	E49171	HMW-TB-03/19/90	Trichloroethene	79-01-6		_ J
	E49171	HMW-TB-03/19/90	Methylene chloride	75-09-2	0.012 E	_
9	E49050	HMW-TB-03/19/90	Acetone	67-64-1		3
,	E49235	HMW-TB-03/20/90	Toluene	108-88-3		JB
	E49235	: HMW-TB-03/20/90	Methylene chloride	75-09-2		JB
)	E49235	HMW-TB-03/20/90	Acetone	67-64-1		18
	E49235	HMW-TB-03/20/90	2-Butanone	78-93-3	0.004	
	E49311	HMW-TB-03/21/90	Acetone	67-64-1	0.013	
•	E49311	HMW-TB-03/21/90	Methylene chloride	75-09-2	0.012	
•	E49311	HMW-TB-03/21/90	Toluene	108-88-3	0.001	- J
	E49375	HMW-TB-03/22/90	Acetone	67-64-1	0.013	- 3
)	E49375	HMW-TB-03/22/90	Methylene chloride	75-09-2	0.014 E	_
,	E49695	HMW-TB-03/23/90	Acetone	67-64-1	0.011	_
	E49695	HMW-TB-03/23/90	Mathylene chloride	75-09-2	0.014	
)			•	· • · · ·		
-						

)

APPENDIX K

SUMMARY OF TAL INORGANIC ANALYSIS RESULTS (SPECIES DETECTED) - GROUNDWATER

					GROUNDWATER:	TALINOGW DATAB	ASE		•
MPLE ID W-SW8	ALUMINUM 85.00 u	ANTIMONY 51.00 U	ARSENIC 3.00 UW	BARIUM 5	BERYLLIUM 1.00 U	CADMIUM 2.00 U	CALCIUM 305000.00	CHROMIUM	Ç
	COPPER 10.00 U	1RON 39.30 E	LEAD 2.00 U	MAGNES1UM 170000.00	MAGNANESE 509.00	MERCURY 0.20 U	NICKEL	MULSSATO9	•
	SILVER 9.00 U	SOD1UM 97600.00	THALLIUM 4.00 UW	VANADIUM 8.00 U	71NC 6.00 U	CYANIDE 10.00 U	71.00	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	· (
MPLE 1D W-5W8-D	ALUMINUM 95.00 U	ANTIMONY 51.00 U	ARSENIC 3.00 UW	BARIUM B	BERYLLIUM 1.00 U	CADMIUM 2.00 U	CALCIUM 294000.00		(
	COPPER 10.00 U	1RON 77.90 B	LEAD 2.00 U	MAGNES1UM 164000.00	MAGNANESE 503.00	MERCURY 0.20 U	294000.00 () NICKEL 11.00 U	15.10. PO1ASS1UM	(
	SILVER 9.00 U	50DIUM 107000.00	THALLIUM 4.00 UW	VANADIUM 8.00 U	Z1NC 5.00 U	CYANIDE 10.00 U	11.00 0	1120.00	Cr
WALE ID	ALUMINUM 85.00 U	ANTIMONY 51.00 U	ARSENIC 3.00 UW	BARIUM .	BERYLLIUM 1.00 U	CADMIUM 2.00 U	CALCIUM 1330.00 U	CHROMIUM	· `7
	10.00 U	1 RON 39.00 U	LEAD 2.20 B	MAGNESIUM 848.00 U	MAGNANESE 5.00 U	MERCURY 0.20 U	NICKEL 11.00 U	21.90 ;	
	SILVER 10.90	SODJUM 1080.00 U	THALLIUM 4.00 U	VANADIUM 8.00 U	Z1NC 5.00 U	CYANIDE 0.00		788.00 (.'

į

: **(** ξ, · z (

			C		-	•		
	51LVER 9.00 U	5001UM 579000.00	THALLIUM 4.00 UW	VANADIUM B.OD U		CYANIDE 37.00		
	COPPER 10.00 U	1RON 39.00 U	LEAD 2.00 U		MAGNANESE 811.00	MERCURY 0.20 U		P01A551UM 11500.00
SAMPLE 1D HMW-SW5	ALUMINUM 85.00 U	ANTIMONY 51.00 U	ARSENIC 3.00 UW	BAR1UM U	SERYLLIUM 1.00 U	CADMIUM 2.00 U	CALC1UM 223000.00	CHROMIUM 21,10
	SILVER 8.00 U	SODIUM 81400.00	THALLIUM 4.00 UW		Z 1 NC 5.00 U	CYANIDE 0.00		
	COPPER 11.00 U	1 RON 29.00 U	LEAD 2.00 U	MAGNESIUM 529000.00	MAGNANESE 110.00	MERCURY 0.20 U	80.30 B	POTASSIUM 962.00
SAMPLE ID IMW-SW22	ALUMINUM 208.00	ANT1MONY 56.00 U	ARSENIC 3.00 UW	BARIUM U		CADM1UM 2.00 U	CALC1UM 280000.00	CHROMIUM 9.00
		SOD1UM 3450.00 B	THALLIUM 4.00 U		Z1NC 6.00 U	CYANIDE 10.00 U		
	COPPER 10.00 U	1RON 87.90 B	LEAD 2:00 U	MAGNESIUM 20300.00	MAGNANESE 65.10	MERCURY 0.20 U	NICKEL 11.00 U	POTASSIUM 905.00
SAMPLE ID MW-SW2			ARSENIC 3.00 UW				CALCIUM 59000.00	
	SILVER 8.00 U	SODIUM 4220.00 B	THALLIUM 4.00 U		ZINC 5.00 U	CYANIDE 0.00		•
	COPPER 11.00 U		LEAD 2.50 B	MAGNES1UM 19100.00	MAGNANESE 49.20		NICKEL 19.00 U	POTASSIUM 962.00
SAMPLE ID IMW-1W5		ANTIMONY 56.00 U		BARIUM B	BERYLLIUM 2.00 U	CADMIUM CADMIUM	CALCIUM 72300.00	CHROMIUM 9.00
	511VFR 9.00 U	10300.00	THALLIUM 4.00 UW	VANADIUM U 00.8	21NC 5.00 U	CYANIDE 10.00 U		· •
	COPPER 10.00 U	1 RON 391.00	LEAD 2.00 U	MAGNESIUM 18000.00	MAGNANESE 57.80	MERCURY 0.20 U	NICKEL 11.00 U	POTASSIUM 5610.00
BAMPLE ID !MW-1W3			ARSENIC 3.00 UW		BERYLLIUM 1.00 U		CALCIUM 69700.00	CHROMIUM 16.00
	SILVER 9.00 U	SODJUM 19400.00	THALLIUM 4.00 UW	MULDANAV U DO.E	Z1NC 5.00 U	CYANIDE 10.00 U		
	COPPER 10.00 U	1RON 47.80 B	LEAD 2.00 U	MAGNES1UM 35600.00	MAGNANESE 497.00	MERCURY 0.20 U	NICKEL 11.00 U	POTASSIUM 1980.00
AMPLE ID	ALUMINUM 85.00 U	ANTIMONY 51.00 U	ARSENIC 3.00 UW	BAR''	BERYLLIUM 1.00 U	CADM1UM 2.00 U	CALCIUM 138000.00	CHROMIUM 20.70

'age No. 2

APPENDIX L

· - 🏂

SUMMARY OF SHORT LIST METALS ANALYSIS RESULTS - GROUNDWATER

5 (15 (1 m : 5) 9 8 (1 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	ក្នុងក្រុង ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត្ត ខេត	11 D
	Hall II II II II II II II II II II II II I	:: :::::::::::::::::::::::::::::::::::
18688888 1990 1990 1990 1990 1990 1990 1990		m m
	addaadaadaaaaaaaaaaaaaaaaaaaaaaaaaaaaa	88
		: : : : : : : : : : : : : : : : : : :
		8 8 8
54.512 0 10 10 10 10 10 10 10 10 10	194-1972 194-19	254-342 254-342

APPENDIX M

SUMMARY OF AMMONIA AND NITRATE/NITRITE ANALYSIS RESULTS - GROUNDWATER

NPNGW DATABASE

NPNFLAG	UAC	UAC	AC	AC	AC	AC	AC	AC	AC	UAC	AC	AC	UAC	UAC	AC	AC	AC	AC	AC	UAC	UAC	AC	UAC
NPACONC	50.00	53.00	50.00	120.00	16300.00	50.00	1500.00	230.00	200.00	50.00	110.00	80.00	20.00	20.00	450.00	290.00	310.00	190.00	840.00	50.00	50.00	150.00	50.00
AMFLAG	AC	AC	AC	٥ ۲	AC	UAC	AC	AC	A C	UAC	AC	UAC	NAC	AC	NAC	UAC	A C	NAC	¥C	UAC	AC	AC	UAC
AMCONC	150.00	50.00	310.00	150.00	1000.00	50.00	2100.00	320.00	300.00	50.00	1200.00	50.00	50.00	80.00	50.00	100.00	130.00	50.00	70.00	50.00	2200.00	50.00	50.00
SAMPLEID	LOWDINKH	HWW-DWD2	HMWINWDG	HMW-SW04	HMMISHOS	30X01XXX	HWW-BWD7	おりよりしまだり	HWW-SWOB-D	HMWIGWORIFE	HMW-NW10	HMW-DE11	TEXT-OF12	HMM-OKIA	HMW-SW15	HMW-UK17	HMK-DK17-D	HMM-NM18	のに主の一名をよ	HMW-SW20	HRK-SKS1	HMK-OKS5	HMW-SW22-FB

·- Ā.

APPENDIX N

· _ 🕏

SUMMARY OF TEMPERATURE, SPECIFIC CONDUCTIVITY AND PH MEASUREMENT - GROUNDWATER

Well	рН	Temperature	Conductivity	Measi		Sample
No.	(Standard Units)	(℃)	(Standard Units)	Field	Lab	Date
SW-1	7.38	7.8	960	/		3-19-90
SW-2	7.99	7.8	380	/		3-19-90
SW-3	7.95 7.05	7.0 5.5	970	/		3-19-90
				1		
SW-4	7.14	7.2	2120			3-16-90
SW-5	7.57	9.4	1750	1		3-16-90
SW-6	6.91	8.9	2620	<i>\(\)</i>		3-16-90
SW-7	5.7	8.3	2610	/		3-17-90
SW-8	5.6	8.3	2490	/		3-16-90
SW-9	6.79	8.3	480	1		3-20-90
SW-9A	6.76	6.5	532		✓	4-12-90
SW-10	7.10	4.4	1340	✓		3-20-90
SW-11	5.0	12.8	780	✓		3-15-90
SW-12	7.4	4.4	730	1		3-20-90
SW-14	5.18	10.6	1260	✓		3-20-90
SW-15	5.5	12.8	480	✓		3-15-90
SW-17	8.48	8.3	600	✓		3-20-90
SW-18	6.33	6.7	390	✓		3-20-90
SW-19	5.82	12.8	560	1		3-14-90
SW-20	4.8	12.8	1850	✓		3-15-90
SW-21	7.22	5.0	1520	✓		3-19-90
SW-22	7.82	1.7	3570		✓	3-23-90
IW-1	7.0	12.2	1020	1		3-20-90
IW-2	7.88	5.0	368		✓	3-23-90
IW-3	N/A	9.4	650	1		3-21-90
IW-4	6.96	8.3	670	1		3-20-90
IW-5	7.80	8.9	414		1	3-23-90
DW-1	7.89	9.4	400		/	3-22-90
DW-2	6.9	10.0	730	1		3-21-90
DW-3	8.17	9.4	391		✓	3-23-90
EW-1	7.16	5.0	898		/	3-23-90
EW-2	8.15	3.3	1648		1	3-23-90
EW-4	7.41	3.3	1174		1	3-23-90
EW-6	<i>7</i> .15	3.9	521		✓	3-22-90

APPENDIX O

· - 📆

MDNR BIOLOGICAL, SURFACE WATER AND SEDIMENT SURVEY

K5-8410-030

REFERENCE 10

SITE NAME HI - MIN MANY

SITE ID MID 005341714

SECEIVED

MAR 0 6 1985

ATER QUALITY DIV.

Michigan Department of Natural Resources
Surface Water Quality Division
Water Quality Surveillance Section
February 1985

A Biological and Water and Sediment Chemistry Survey of Waterbury Lake and Adjacent Harsh Oakland County, Michigan April 26, 1984

Introduction

Surface Water Quality Division staff of the Water Quality Surveillance Section surveyed Waterbury Lake and a marsh east of Hi Mill Manufacturing Company to determine the potential impact of Hi Mill Manufacturing Company discharge on these water bodies (Figure 1). The survey was performed at the request of Hakim Shakir, Detroit District Groundwater Quality Division staff in connection with the groundwater cleanup operation at Hi Mill Manufacturing.

Conclusions

- 1. Waterbury Lake was not connected with the marsh east of Hi Mill Manufacturing and was not impacted by Hi Mill Manufacturing surface water discharges.
- 2. Marsh waters generally contained higher concentrations of heavy metals than the background stations in Waterbury Lake.
- 3. Concentrations of copper in marsh waters exceeded the chronic criteria for warmwater species of freshwater aquatic life.
- 4. Sediment heavy metal concentrations in the marsh exceeded background concentrations in Waterbury Lake and in many cases mean concentrations downstream of industrial and municipal discharges.
- 5. Algae and zooplankton were abundant in marsh waters but bottom dwelling organisms were limited to pollution tolerant forms. The lack of additional species may be due to limited water in the dry season or the nutrient enriched condition of the marsh waters.

Recommendations

- 1. Minimize the sources of heavy metals entering the marsh from the Hi Mill parking lot and roof drainage system.
- 2. Continue to fill the existing lagoon.
- Determine if contaminated groundwater should be purged.

Background

Bi Mill Manufacturing has an aluminum annodizing process and fabricates aluminum and copper parts. Process wastes are discharged to seepage lagoons adjacent to the marsh east of their property. In 1972 elevated levels of copper were found in the adjacent marshland and one of the company's drinking water wells (SWQD File, Hi Mill Mfg. Co.). In 1975 additional water samples collected in the marsh revealed elevated concentrations of nitrates, copper, aluminum, sinc and chromium. File reviews showed lagoon overflows had apparently been occurring and in April of 1978 additional water and sediment sampling was completed in the lagoon and marsh. Recommendations were made to remove lagoon wastes and sludges and fill the lagoon (Grant, 1978). None of the recommendations were accomplished, but no additional discharges were made to the lagoon after 1978. Hi Mill Manufacturing attempted to evaporate the lagoon liquid by spraying it into the air from the top of their building. This resulted in liquids entering the marsh through their roof and parking lot drain system. Groundwater samples collected in 1981 showed migration of elevated concentrations of aluminum, chromium, copper and zinc in the shallow water table (3 to 7 feet) and into the marsh (Sibo, 1982). As of November 1983, lagoon liquids and sludges had been removed and the lagoon itself was being filled.

Methods

Water and sediments for chemical analysis were collected and preserved according to "Quality Assurance for Water and Sediment Sampling" (MDNR 1981) and returned to the Environmental Laboratory in Lansing for analysis. Benthic macroinvertebrates were collected with a petite ponar dredge grab sampler and sieved through a number 30 mesh sieve. Organisms were identified with the naked eye on site and their abundance qualitatively assessed and recorded on stream problem assessment cards (Appendix A). Phytoplankton samples were qualitatively collected with a 64 micron mesh phytoplankton net towed at approximately a 45 degree angle, washed into a vial and returned to the Lansing Biological Laboratory and identified under the microscope at 400x power.

Water

Marshwater samples collected in 1984 contained lower concentrations of heavy metals than marshwaters at similar areas in 1978. However, concentrations of zinc, chromium, and copper were greater than those at the background location sampled in nearby Waterbury Lake. These data suggest that while heavy metal concentrations are decreasing in the marsh water they may still be leaching from the sediments into the water or continuing to enter from surface water discharges or contaminated groundwater. Neither chromium or zinc exceeded the criteria for freshwater aquatic life but the concentration of copper in the marsh water exceeded the chronic criteria (33 ug/1) for warmwater fish. Concentrations of total copper, zinc, chromium, and aluminum in the parking lot and roof

drainage were lower than the mid-marsh samples taken in 1978, but higher than marsh samples collected in 1984 indicating a continuing source of metals to the marsh. The copper concentration in the parking lot and roof drainage water exceeded both the acute and the chronic criteria for aquatic life. Contaminated groundwater resulting from the old seepage lagoons may also be contributing to heavy metals concentrations in marsh waters.

Sediments

Heavy metals in marsh and parking lots and roof runoff drainage sediments were higher than sediments collected in nearby Waterbury Lake Station 4 (Table 2). Total aluminum, total copper, total zinc and total cadmium were an order of magnitude higher while total chromium was two orders of magnitude higher in the marsh than in Waterbury Lake. These data suggest direct inputs of these metals to the marsh system from Hi Mill Manufacturing Company. Sediment total iron, total arsenic, total lead, total manganese and total lithium were also higher in the marsh than in Waterbury Lake. Mercury was detected only in the parking lot and roof drain outfall sediments. Concentrations of heavy metals in the marsh exceed the average concentrations downstream of industrial and municipal locations (Hesse and Evans 1972). It is not known if these sediment metals are leaching into the water column or are causing toxicity to aquatic insects, but bottom dwelling aquatic organisms were limited to tolerant midges in the marsh.

Aquatic Organisms

Only midges were found in the ponar grab samples collected in the marsh. These organisms are generally considered pollution tolerant. No other benthic aquatic insects were noted. The limited bottom dwelling community may be due to marsh water fluctuation (i.e., it may dry up in the summer) or it may be due to elevated concentrations of one or more heavy metals. Zooplankton were present at Stations 1 and 2. Daphnia sp. were very abundant at Station 2 nearest the old lagoon discharge where concentrations of copper in the water exceeded the criterion for aquatic life. It may be that these organisms blew in from another part of the marsh where copper was less concentrated. Other possibilities are that organic materials in the water column bound these copper molecules or that hardness and pH conditions created conditions reducing its toxicity. Daphnia are generally considered sensitive to relatively low copper concentration (Creal and Basch, 1981).

Only one fish was seen. A mudminnow was present near the outlet from the parking lot and roof runoff drainage system. The fish was dead with no evident cause. Mudminnows are tolerant of a wide variety of environmental conditions.

The presence of a variety of filamentous (Spirogyra) green algae, flagellates (Euglena) and other algae (Scenedesmus) Oocystis, Synedra, Oscillatoria and Mougeotia) and macrophytes (Typha, Scirpus, Lemna minor, Elodea and Potamogeton) indicated that the discharge did not have much impact on these aquatic plants (Table 3).

Literature Cited

(

...**.∳**`

- Creal, W. and R. Basch. 1981, Water quality-Based Effluent LImits for Heavy Metals and Cyanide, MDNR, 124 p.
- Environmental Protection Bureau, Michigan Department of Natural Resources, 1981, Quality Assurance Manual for Water and Sediment Chemistry.
- Grant, 1978, Investigation of Bi Mill Manufacturing Treatment Pacility, Vicinity of Highland, Michigan, April 26, 1978.
- Hesse, J. N., and E. Evans, 1972, Heavy Metals of Surface Water, Sediments and Fish in Michigan. Michigan MDNR, 58 pp.
- Sibo, K., 1982. A Hydrogeological Study of the Vicinity of Hi MIll Manufacturing, Highland, Michigan Department of Natural Resources.
- Surface Water Quality Division Files for Hi Mill Manufacturing. MDNR.

John Wuycheck, Aquatic Biologist Survey By:

Dave Kenaga, Aquatic Biologist

Lab Analysis By: Environmental Lab

Algal Analysis By: Carey Johnson

Report By: David Kenaga, District Aquatic Biologist

Michigan Department of Natural Resources

Water Quality Surveillance Section Surface Water Quality Division

Table 1. Concentrations of selected heavy metals in water in the vicinity of Hi-Mill Manufacturing Company, April 26, 1984. Results in µg/l. (1978 Results from Grant 1978)

Location Sampled	Total Aluminum	Total Arsenic	Total Iron	Total Mercury	Total Zinc	Total Cadmium	Total Chromium	Total Copper	Total Nickel	Total Lead	-;
At H-59 Marsh outlet	<400	<0.5	150	<0.5	23	0.2	2.8	48	<4	2.5	
Mid Marsh East of building	<400	<0.4	120	<0.5	22	<0.2	6.5	200	<4	<2.0	
Roof and parking lot runoff	964	1.3	914	<0.5	70	0.6	24	560	<4	<2.0	
Outlet from Waterbury Lake	-	3.6	-	<0.5	-	<0.2	<2	3	<4	<2.0	
Hiddle of Harah (1978)	-2000	-	-	-	2200	-	10	440	<50	< 50	

() Harry

ŀ

,

concentrations of selected heavy metals in sediments in the vicinity of Hi-Hill Manufacturing Company, April 26, 1984. Results in mg/kg dry weight.

ation Sampled	Total Aluminum	Total Arsenic		Total Mercury	Total Zinc	Total Cadmium	Total Chromium	Total Copper	Totel Nickel	Total Lead	Total Kanganese	Total I Solide	Total Lithium	
H~59 sh outlet	29,200	7.5	19,900	<0.5	1,800	11.0	2,350	10,000	50	269	360	13	٠	
Marsh t of building	16,100	4.2	15,600	<0.5	1,500	8.5	5,300°	5,650	19	84	130	24	90	
rking lot and roof runoff	11,890	5.8	17,700	0.7	1,700	11.0	2,240	4,700	18	97	380	32	90	
:let from	7,190	5.5	10,100	<0.5	150	<2.0	50	155	13	91	150	14	15	

1

Table 3. Aquatic plants found in the Marsh, east of Hi-Mill Manufacturing Company, Oakland County, Michigan, April 26, 1984.

Algae

Macrophytes

Spirogyra

Typha

Euglena

Scirpus

Scenedesmus

Lemna minor

Oocystis

Elodea

Oscillatoria

Potamogeton

Mougeotia

Synedra

GAME FISH

ROUGH FISH

FORAGE FISH

ATIC PLANTS	

PERIPHYTON

FILAMENTOUS ALGAE

Typha MACROPHYTES Lemna minor Elodea Potamogeton Periphyton and/or filamentous algae covered everything in this area.

STREAMBANK VEGETATION:

GRASSES

BRUSH

HERBACEOUS

CONIFERS

DEC IDUOUS


BARREN

OTHER

MACROBENTHOS QUALITATIVE SAMPLE CHECK LIST (INDICATE DOMINANT GROUPS)

SPONGES	DRAGONFL I ES	RATTAILED MAGGOTS
HYDRA	DAMSELFLIES	MIDGES C-A
FLATWORMS	TRUE BUGS	STONEFLIES
ROUNDWORMS	BEETLES	MAYFLIES
LEECHES	AQUATIC CATTERPILLARS	-BURROWERS
HATER MITES	ALDERFLIES	-SHIPMERS
SOMBUGS	HELLGRAMITES	-CL INGERS, SPRAWLERS
IDS	CRAMEFLIES	CADOISFLIES
LKAYF1SH	NO-SEE-UMS	-FREE LIVING
SNAILS-LIMPETS	BLACKFLIES	-PURSE CASE MAKERS
CLAMS	DEERFLIES	-TUBE CASE MAKERS
AQUATIC EARTHWORMS	MOSQUITOES	-SADDLECASE MAKERS
	SNIPEFLIES	-NET SPINNERS OR RETREATMAKERS

Zooplankton - Abundant in water column NOTES, ETC.



4 - Profuse

j - Abundant

Station Number 3						
Roof and Parking BODY OF WATER LOCAL	IME 1:00	PHOTOGRAM H1-M111 of LOCATION	PH NUMBER	east edg	e of parki	ng lot
COUNTY Oakland	T 3N	R 7E 5 23	THP Hig	hland		
REASON FOR SURVEY HI-	-Mill Mfg. Co.					
	•••••					
VICINITY LAND USE: Mostly	<u>r Forest</u> Mostl	y Ilrban Mo:	stly Agriculture	Other		
AVE. STREAM WIDTH	S Man AVE. STREAM O	EPTH1	in . VELOCITY . <0.	4 Seps	STREAM km	
STREAM SHADING: Open	Partly Open	Shaded	STREAM TYPE: Co	ldwater	Warmwater	
WATER TEMP °C AIR	TEHP. 65 °F	WEATHER: Sunny	-Partly Cloudy-Clou	idy— Rainy	DAM u/s: Yes	Nokm
CHANNELIZED: Yes No	CHANNEL EROSION:	Mone — Slight	- Moderate - Sev	vere H	IGH WATER MARK	6 ±
SECCHI DISC TRANS:	- m TURBIDITY:	Clear Slight	tly Turbid — Turbid —	- Opaque	MATER COLOR_	
WATER ODORS: Norma	1 Sewage	Petrole	um Chemical	0	ther	
SURFACE OILS: None	e Slick	Sheer	Globs	F	lecks	
			•			
SEDIMENT ODORS: Norma	1 Sewage	Petroleum	Chemical	Anaerobi	c Other_	
SEDIMENT OILS: Absen	t <u>511</u>	ght M	oderate	Profus	•	
DEPOSITS: Sludge	e Sawdust	Paperfiber	Sand Reli	ct Shells	Other	
ARE THE UNDERSIDES OF STON	ES WHICH ARE NOT DE	EPLY IMBEDOED II	N SUBSTRATE BLACK?	YES	NO	
FLOW						
SUBSTRATE VELOCITY TYPE m/sec	CHARACTERISTI OR SIZE	CS PI SAMI	ERCENT IN SUBSTI	RATE CH	ARACTERISTICS OR SIZE	PERCENT IN SAMPLING ARE!
BOULDERS* >1.2 (>3 fps)	256 mm (10") d1a	•	CLAY	Slick	texture	
RUBBLE* >0.6 (>2 fps)	64-256 mm (2.1-1	0") dia.	MARL	Grey,	shell fragment	5
GRAVEL*	2-64 mm (0.1-2.5") día.	DETRIT	US Sticks plant s	, wood, coarse materials	70
SANO >0.2 (>0.7 fps)	0.06-2.00 mm dia. Gritty texture		FIBROU PEAT		lly decomposed material	
SILT >0.12 (>0.4 fps)	0.004-0.006 mm d1	4.	PULPY PEAT	materia	divided plant il, parts inquishable	10
MUCK-MUD -0.12 (-0.4 fps)	black, very find	organic	10 LUGS &	STICKS	uda i zuan i s	
*1MBEDDEDHESS: 0 * NONE	1 - 1/3 OR LESS	2 = 2/3 CR HO	RE			
<u>810T</u> A:						
PHYTOPLANKTON	1 2 3	4	SLIMES	(b) 1	2 3	4
PERIPHYTON O	1 ② 3	4	ZOOPLANKTON	@ 1	2 3	4
FILAMENTOUS ALGAE 0	1 ② 3		MACROINVERTEBRATES	6 1	2 3	4
^				_		
MACROPHYTES (0)	1 2 3	4	FISH	(0) 1	2 3	4

2 - Moderate

CHAPER

ROUGH FISH

FORAGE FISH - one dead mud minnow near parking lot runoff site

QUATIC PLANTS	Section 1	PERIPHYTO	N	FILAMENTOUS ALGAE						
MEROPHYTES										
STREAMBANK VEGETATION: <u>GRASSE</u> S	BRUSH	HERBACEOUS	CONIFERS	_DECIDUOUS_	BARREN	OTHER				
MACROBENTHOS QUALITATIV	E SAMPLE CHECK	LIST (INDICATE DOM	INANT GROUPS)							
SPONGES		DRAGONFLIES		RATTAI	LED MAGGOTS	····				
HYDRA		DAMSELFLIES		HIDGES						
FLATWORMS		TRUE BUGS		STONEF	LIES	·····				
ROUNDWORMS	·	BEETLES	······································	MAYFLI	ES					
LEECHES		AQUATIC CATTERPI	LLARS	-801	RROWERS	····				
HATER MITES		ALDERFLIES		-SW	IMMERS					
SOMBUGS		HELLGRAMITES		-CL	INGERS, SPRA	MLERS				
SCUDS		CRANEFL IES		CADDIS	FLIES					
AYFISH		NO-SEE-UMS		-FR	EE LIVING					
SNA ILS-LIMPETS		BLACKFL IES		-Put	RSE CASE MAK	ERS				
CLAMS		DEERFLIES	·	ועד-	BE CASE MAKE	RS				
AQUATIC EARTHWORMS		MOSQUITOES	 	-SADDLECASE MAKERS						
		SNIPEFL IES		l	SPINNERS OF					

NOTES, ETC. No macroinvertebrates in small trickel

A dead muskrat was
noted near parking lot.

Cause of death unknown
body beginning to decompose

Highli Asa.

Gala
Sampled

Marsh

GAME FISH

ROUGH FISH

FORAGE FISH

- minnows noted in shallow areas

NATIC PLANTS Scirpus	PERIPHYTON Potamogeton	FILAMENTOUS ALGAE
MACROPHYTES Chaga	Nuphar Nymphea	
STREAMBANK VEGETATION: GRASSES	BRUSH HERBACEOUS CONIFERS	DECIDUOUS BARREN OTHER
MACROBENTHOS QUALITATIVE	SAMPLE CHECK LIST (INDICATE DOMINANT GROUPS)	
SPONGES	DRAGONFLIES	RATTAILED MAGGOTS
HYDRA	DAMSEL FL TES	MIDGES
FLATWORMS	TRUE BUGS	STONEFLIES
ROUNDWORMS	BEETLES	MAYFLIES
LEECHES	AQUATIC CATTERPILLARS	-BURROWERS
HATER MITES	ALDERFL IES	-SWIMMERS
SOMBUGS	HELLGRAMITES	-CLINGERS, SPRAWLERS
< <u>CUDS</u>	CRANEFL IES	CADO ISFL IES
AYFISH	NO-SEE-UMS	-FREE LIVING
SNAILS-LIMPETS	BLACKFL IES	-PURSE CASE MAKERS
CLAMS	DEERFLIES	-TUBE CASE MAKERS
AQUATIC EARTHWORMS	MOSQUITOES	-SADOLECASE MAKERS
	SNIPEFLIES	-NET SPINNERS OR RETREATMAKERS
NOTES, ETC.	Mill Miss rever	
	Sample Mich & By Weeks!	MARSH HGH GROUND

. 7

Station Number	4			inv	estiga	tor(s)_	Kenag	a, Wuy	chec	<u>k</u>			
Date 4 / 26 /	84	TIME	2:00		_ PHO	TOGRAPH	NUMBER						
BODY OF WATER WA													
COUNTY Oaklan													
REASON FOR SURVEY													
VICINITY LAND USE:	Mostly	forest	Мо	stly Ur	ban	Most 1	y Agricul	ture	Othe	r	Par	k	
AVE. STREAM WIDTH_	Lake	m AVE	- . STREA	H DEPTH		5_#t	VELOCIT	Y <u>'</u>	n	s S	TREAM ki	•	
STREAM SHADING:	Open	Part	ly Open	Sh	aded	ST	REAM TYPE	: Co	o] dwa t	er	Warmwa ti	er	
WATER TEMP.	*C AIR	TEMP	£5°4	WEAT	HER:	Sunny — P	artly Clo	udy – Clo	udy— R	ainy	DAM u/s:	– Yes	No
CHANNELIZED: Yes	No	CHANNEL	EROSION	: None	s	light —	Moderat	e — Se	vere	HI	GH WATER	MARK_	
SECCHI DISC TRANS:		_5_Mft.	TURBIDI	TY: C1	ear :	Slightly	Turbid —	· Turbid -	- Opaq	ue	HATER CO	DLOR	clear
WATER ODORS:	Norma 1		Sewag	<u> </u>	Pe	troleum		Chemica	1	0t	her		
SURFACE OILS:	None	• -	Slick			Sheen		Globs		FI	ecks		<u> </u>
SEDIMENT ODORS:	Norma1		Sewage		Petrol	eum	Chemic	a)	An	serobic	Oti	ner	
SEDIMENT OILS:													
DEPOSITS:													
ARE THE UNDERSIDES											_	NO.	
												=	
SUBSTRATE VELOC	CITY	CHJ	RACTERI OR SIZ	STICS E		PERCI SAMPL I	ENT IN	SUBSTI TYPI	rate E	СНА	RACTERIST OR SIZE		
BOULDERS*>1	. 2 for \	256 mm	(10")	dia.				CLAY	:	Slick to	exture		
					44.		ļ	MADI	,	?mau e	hall fasa		•
RUBBLE* >0 (>2	fps)	04-230	има (2.	1-10)	31 4.			TOURL	,	arey, s	hell frag	men (3	
GRAVEL* >0 (>)	.3 fps)	2-64 mm	n (0.1-2	.5") 41.	a.		Ì	DETRIT			wood, co aterials	arse	60
SAND >0 (>0.7			.00 mm d texture	ia.			ļ	F1BROU PEAT			ly decomp sterial	osed	
SILT >0 (>0.4	.12 fps)	0.004-0).006 mm	dia.			Ì	PULPY PEAT		natería i	divided p l. parts nquishabl		20
MUCK-MUD >0 (+0.4	.12 fps)	black,	very fi	nd organ	nic		20	LOGS &			mja i sneo i	-	
*IMBEDDEDNESS: 0	- NONE	1 - 1/3	OR LES	S 2	• 2/3 (CR MORE				<u> </u>			
BIOTA:											,		
PHYTOPLANKTON	سسهد	- ₁	2	3	4	SI	.IMES		0	. 1	2	3	4
PERIPHYTON	0	Ö	2	3	4		OPLANKTO!	ч	0		2	3	4
FILAMENTOUS ALGAE	0	0	2	3	4		CROINVER		0	$\frac{1}{1}$	2	j	4
MACROPHYTES	0	ı	2		4		SH		0	1	(2)	3	4
NACHURATICS	U	•	•	٣	7	• •	· ₩**		•	•	0	-	·

7 Moderate

3 - Abundant

4 - Profuse







il- 23

1980

